



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: DMPU1700191H

Date: 25<sup>th</sup> July 2018

Our Ref: CS1/ICS18012694/Uvbs2

**M/s ECICS Ltd**

7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SGV 7979G INSURED VEHICLE: SKS 4771B ACCIDENT DATE: 05/04/2017**

We thank you for your instruction on 12/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGV 7979G from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles SGV 7979G and SKS 4771B.
- c) Colour damaged vehicle photographs of SGV 7979G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGV 7979G
Make & Model	: Mercedes Benz S300L
Year of Registration	: 2010
Chassis Number	: WDD2211542A218069
Engine Capacity	: 2997 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.