



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 7979G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED / TORN	2,056.21	2,056.21
1	FRONT BUMPER RETAINER LH	CRACKED	36.01	36.01
1	FRONT BUMPER PARKING SENSOR LH	NOT NECESSARY	196.56	-
1	FRONT BUMPER CROSS MEMBER SIDE BRACKET LH	BENT	65.70	65.70
1	FRONT BUMPER SIDE GUIDE LH	NECESSARY	20.20	20.20
1	FRONT BUMPER CROSS MEMBER	NOT NECESSARY	1,355.55	-
1	FRONT FENDER LH	DENTED / BENT	1,643.43	1,643.43
1	FRONT FENDER COWLING OUTER LH	NOT NECESSARY	112.73	-
1	FRONT FENDER CHROME MOULDING LH	NECESSARY	98.97	98.97
1	HEADLAMP LH	CRACKED	2,309.64	2,309.64
1	HEADLAMP PANEL LH	TO REPAIR SEE LABOUR	191.48	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	4,038.32	-
1	FRONT TOP ARM LH	NOT NECESSARY	1,010.45	-
1	FRONT LOWER ARM LH	NOT NECESSARY	725.27	-
1	FRONT LOWER CONTROL ARM LH	NOT NECESSARY	939.49	-
1	FRONT STABILIZER BAR	NOT NECESSARY	495.48	-
1	FRONT STABILIZER BAR LINK LH	NOT NECESSARY	162.68	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	1,374.62	-
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	774.92	-
1	STEERING RACK & PINION	SERVICEABLE	7,954.60	-
	LESS 10% DISCOUNT		-2,556.23	-623.02
			23,006.08	5,607.14
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	62.00	62.00
1	SET FRONT FENDER COWLING OUTER CLIP LH (SN)	NECESSARY	40.00	40.00
1	FRONT SPORT RIM LH (SN)	CUT	760.00	760.00
1	FRONT TYRE LH (SN)	SERVICEABLE	450.00	-
			1,312.00	862.00

Report Ref No. CS1/ICS18012694/Uvbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR TO REPAIR & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL LH.		800.00	400.00
	SPRAY PAINTING ON AFFECTED AREA.		800.00	400.00
	REMOVE & REFIX UNDERCARRIAGE.	NOT NECESSARY	450.00	-
	CHECK WIRING SYSTEM.		80.00	40.00
	TO DIAGNOSE & RESET SYSTEM AFTER REPAIR.		420.00	380.00
	SPRAY ANTI RUST ON AFFECTED AREA.		60.00	30.00
	CHECK WHEEL ALIGNMENT.		120.00	100.00
			2,730.00	1,350.00
	GRAND TOTAL		27,048.08	7,819.14
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,250.00

Report Ref No. CS1/ICS18012694/Uvbs2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.