

ASS. REC. BY:

REF: CS/FCI18012701/Kvd3⁰²

Special Instruction:

Surveyor
awsKenneth
Sithara

ASSIGNMENT (Office)

From (Person):

of

FCI

Date/Time: 12/7/18 @ 2:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5009H

Insured:

SHA 8821U

at Workshop m/s:

Trans Carb

Tel:

6287 6666

of

No. 2 AMK St. 63

Policy No:

Claim No:

D18005379 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

2:35pm @ 12/7/2018

Person Contacted:

Ghien Yee

Vehicle IN/OUT

Date/Time

Action/Instruction (/) Estimate

SHC 5009H - CS/FCI18010173/Kvbe2

DUA: 3/6/2018

SHA 8821U - CS/FCI/6012865/M/vbd1

DUA: 09/07/2016

13/7/18

Email preli revised to FCI

14/9/18

LS \$15,000 (Red 59,440-79, 809)

ASS. REC. BY:

REF:

1021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/7

File pass to Catherine

RECEIVED 14 SEP 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

14/9 - typist

Report Format:

cws

Lump Sum / I.B.I.: (\$

15,000k

Days Of Repair:

5

Resurvey No. of Trlp:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

64x15=960

170+960

50

50

34

1264

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012701/Kvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8821U	Veh. Inspected	SHC 5009H
Policy No.		Coverage (\$)	0.00
Claim No.	D18005379MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	12/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/07/2018	Inspection Date	12/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005379MFSH

Our ref: CS/FCI18012701/Kvd3

Date : 13/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5009H


We thank for your instruction on 12/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/7/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$74,440.79
Revised Estimate Amount	: S\$14,298.96
"Check" Items Amount	: S\$13,336.66
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	12-07-2018	Our Ref No. D18005379MFSH
Accident Date	11-07-2018	Claim Type. Third Party
Insured Vehicle	SHA8821U	Third Party Vehicle. SHC5009H
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	GHIEEN YEE LOONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242314)



PRI Documents



Close



PRI Header Details

Claim No	D18005379MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : GHIE YEE LOONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: GHIEYEE.LOONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8821U	TP Vehicle No	SHC5009H
PRI Recieved Date	12-07-2018 03:58:05 PM	Surveyor Appointed Date	12-07-2018 02:27:41 PM	Surveyor Accept Date	12-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 13 July 2018 11:20 AM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005379MFSH/1, SHC 5009H
Attachments: SHC 5009H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 5009H
Date of survey: 12/7/2018
Number of days :5 days

Best Regards,

 **Veron Chen** | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 12 July 2018 2:33 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005379MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

 BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 July 2018 2:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005379MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

7/11/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5009H
Vehicle to be Exported:	Yes
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000599
Chassis No.:	VF1ABL15AUC275183
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Oct 2013
First Registration Date:	30 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2021
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$25,283.00
Total Rebate Amount:	\$34,656.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jul 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5009H**AAD1807-097***Not Authored
Proposed C/Ping \$15,000*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5009H

VF1ABL15AUC275183

RENAULT

LATITUDE

11.7.2018

FCIL**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bt</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>CM</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77 ✓
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Dis</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>CM</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>Bt</i> 914.08 ✓
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Re</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Bt</i> 89.79 ✓
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>Sn</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>CM</i> 1,184.43 ✓
23	1	HEADLAMP RH	\$	<i>23CM</i> 1,184.43 ✓
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>Bt</i> 1,941.63 ✓
27	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61 X

Trans-cab Auto Services Pte Ltd**AAD1807-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5009H

29	1	BONNET STRUT RH	\$	Su	88.61	X
30	1	BONNET HINGE LH	\$	M	348.31	X
31	1	BONNET HINGE RH	\$	M	348.31	X
32	1	BONNET LOCK	\$	M	305.48	
33	1	BONNET CABLE	\$	Su	119.19	
34	1	BONNET CABLE COVER	\$	Su	161.03	
35	1	BONNET SEAL OUTER	\$	Su	92.36	
36	1	BONNET SEAL INNER	\$	Su	157.28	
37	1	FENDER PANEL FRT LH	\$	M	783.83	
38	1	WHEELARCH FRT LH	\$	Su	278.84	
39	1	FENDER BRACKET LOWER LH	\$	Su	15.79	
40	1	FENDER INSULATOR LH	\$	Su	130.84	
41	1	FENDER PANEL FRT RH	\$	M	783.83	
42	1	WHEELARCH FRT RH	\$	Su	278.84	
43	1	FENDER BRACKET LOWER RH	\$	Su	15.79	
44	1	FENDER INSULATOR RH	\$	Su	130.84	
45	1	WIPER RESERVOIR	\$	Su	348.25	
46	1	WIPER RESERVOIR NECK	\$	Su	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	Su	270.06	
48	1	AIR CLEANER LOWER	\$	Su	271.26	
49	1	AIR CLEANER HOSE	\$	Su	76.14	
50	1	BASE BATTERY TRAY	\$	Su	363.40	X
51	1	AIR CLEANER BOX	\$	Su	464.20	X
52	1	TURBO DUCT	\$	Su	1,027.80	X
53	1	A/C HEATER VALVE	\$	Su	484.50	X
54	1	SUBFRAME OUTER FRT	\$	Su	2,652.45	X
55	1	SUBFRAME BRACKET OUTER LH	\$	Su	92.36	X
56	1	ENGINE UNDERTRAY	\$	Su	564.98	X
57	1	A/C CONDENSER	\$	Pu	2,020.37	
58	1	A/C CONDENSER GARNISH LH UPPER	\$	Su	39.67	X
59	1	A/C CONDENSER GARNISH RH UPPER	\$	Su	39.67	X
60	1	A/C CONDENSER GARNISH LH	\$	Su	58.81	X
61	1	A/C CONDENSER GARNISH RH	\$	Su	59.60	X
62	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Su	208.39	X
63	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Su	658.72	X
64	1	A/C PIPE COMPRESSOR	\$	Su	334.29	X
65	1	A/C PIPE	\$	Su	658.72	X
66	1	A/C COMRPRESSOR	\$	Su	2,684.61	X

Trans-cab Auto Services Pte Ltd**AAD1807-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5009H

77	1	AIR COOLER	\$	SL	792.60	X
78	1	AIR INTERCOOLER HOSE (LONG)	\$	SL	1,014.13	X
79	1	AIR INTERCOOLER HOSE (Short)	\$	SL	375.14	X
80	1	TRANSMISSION COOLER	\$	SL	1,219.30	X
81	1	TRANSMISSION COOLER PAD	\$	SL	17.96	X
82	1	RADIATOR	\$	SL/per	1,202.20	X
83	2	RADIATOR STUD UPPER	\$	SL	14.41	X
84	2	RADIATOR BUSH UPPER	\$	SL	50.12	X
85	2	RADIATOR MTG LOWER	\$	SL	55.85	X
86	1	RADIATOR FAN COWLING	\$	CM	820.54	X
87	1	RADIATOR FAN MOTOR LH	\$	TM	967.36	X
88	1	RADIATOR FAN MOTOR RH	\$	TM	1,479.46	X
89	1	RADIATOR TANK	\$	SL	324.62	X
90	1	RADIATOR HOSE UPPER	\$	SL	240.56	X
91	1	RADIATOR HOSE LOWER	\$	SL	491.18	X
92	1	RADIATOR TANK HOSE	\$	SL	61.18	X
93	1	AUTO COMPUTER	\$	SL	5,032.17	X
94	1	INJECTION COMPUTER	\$	CM	4,706.30	X
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	SL	5,154.52	X
96	1	STEERING PUMP ELECTRIC L70Y	\$	SL	2,306.90	X
97	1	STEERING PINION RACK L70Y	\$	SL	4,413.11	X

TOTAL	\$	62,409.21
10%	\$	6,240.92
	\$	56,168.29

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	SL	52.00	X
2	1SET	BUMPER CLIP FRT	\$	SL	66.00	X
3	1	BUMPER BRACKET CLIP FRT LH	\$	SL	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	SL	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	SL	12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	SL	10.50	X
7	1	TOW COVER FRT	\$	SL	14.50	X
8	1SET	RADIATOR GRILLE SCREW	\$	SL	16.00	X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	SL	69.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5009H

10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
13	1	Windscreen moulding	\$	na	100.00	X
14	1SET	Front licence plate with holder	\$	na	80.00	45na
15	1	Front left tyre	\$	na	330.00	X
16	1	Front left tyre rim	\$	na	380.00	X
17	1	Front left fender advertisement	\$	na	300.00	X
18	1	Front right fender advertisement	\$	na	300.00	X

TOTAL \$ 1,872.50**TOTAL PARTS \$ 58,040.79**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	6001
Towing Fees.	\$	120.00	501
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	na X
Putty and spray painting of the affected portion.	\$	6,000.00	6601
To rust-proofing of the affected areas.	\$	170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	na X
To check steering geometry and computer wheel alignment	\$	220.00	na X
To transfer of tire, rim and on wheel balancing.	\$	170.00	na X

Trans-cab Auto Services Pte Ltd**AAD1807-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5009H

To Check Electrical Lighting Concerned.	\$	170.00	201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To lift-up engine with gear box and refit.	\$	nn 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00	X
To remove and refit air bag system and reset.	\$	nn 480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
To replace, refix and top up coolant for radiator	\$	170.00	501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00	X

TOTAL \$ 16,400.00**Over All Total \$ 74,440.79****(LUMP SUM)****20 DAYS**

5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012701/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8821U	Veh. Inspected	SHC 5009H	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005379MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	12/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC275183	Colour	METALLIC WHITE / RED	
Odometer	660265	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2018	Inspection Date	12/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5009H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BENT	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	DISTORTED	150.77	150.77
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	DISTORTED	266.80	266.80
1	BUMPER FOG LAMP GRILLE LH	CRACKED	207.21	207.21
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	BENT	914.08	914.08
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	BENT	89.79	89.79
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	CRACKED	1,184.43	1,184.43
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	BENT	1,941.63	1,941.63
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-

Report Ref No. CS/FC118012701/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	BENT	305.48	305.48
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	PUNCTURE	2,020.37	2,020.37
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-

Report Ref No. CS/FCI18012701/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	BENT / PUNCTURE	1,202.20	1,202.20
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	CRACKED	820.54	820.54
1	RADIATOR FAN MOTOR LH	JAMMED	967.36	967.36
1	RADIATOR FAN MOTOR RH	JAMMED	1,479.46	1,479.46
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	CRACKED	4,706.30	4,706.30
1	RHD HYDRAULIC POWER (ROCK & PINION)	TO REPAIR SEE LABOUR	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	SERVICEABLE	4,413.11	-
	LESS 10% DISCOUNT		-6,240.93	-2,314.91
			56,168.29	20,834.24

Report Ref No. CS/FCI18012701/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	80.00	45.00
1	FRONT LEFT TYRE (SN)	SERVICEABLE	330.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT LEFT FENDER ADVERTISEMENT (SN)	NOT NECESSARY	300.00	-
1	FRONT RIGHT FENDER ADVERTISEMENT (SN)	NOT NECESSARY	300.00	-
			1,872.50	163.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET HINGE LH,BONNET HINGE RH,FENDER PANEL FRT LH,FENDER PANEL FRT RH AND RHD HYDRAULIC POWER (ROCK & PINION).		5,400.00	600.00
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00

Report Ref No. CS/FCI18012701/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			16,400.00	1,560.00
	GRAND TOTAL		74,440.79	22,557.24
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,000.00

Report Ref No. CS/FCI18012701/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.