

ANSS. REC. BY:

REF: CS/FCI/8012704/R/rd3n2

Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 12/07/2018 @ 3:30pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 4694Z Insured: SH 6186R

at Workshop m/s: Prime Auto Tel: 68610908

of: G Benoi place

Policy No: \_\_\_\_\_ Claim No: D18005377MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ (Client's Record) D.O.A. 10/07/2018

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 3:30pm @ 12/7/18 Person Contacted: Chrissy Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 4694Z - CS/7MI18012678/Klad3 DOA: 10/07/2018
	SH 6186R - CS/7MI18012678/Klad3 DOA: 10/07/2018
12/7/18	Revert from email
	confirm L/S \$4000 @ 5 days (Red: 144740, 271.)


Surveyor *Praveen*

REF:

*C*  
2366w

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: *SLT 4894Z*  
 at Workshop m/s: *PRIME AUTO*  
 of \_\_\_\_\_  
 Insured: *ICI*  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *SLT 4894Z* Yr Regn: *2017 / OUT*  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: *HONDA SHUTTLE HB 1.5A c.c 1496*  
 Colour: *BLUE* A/C: Insured / Std / NI / NA  
 Sp. Reading: *070503* T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *GP 7-1116298*  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil /  S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: *185/60R15*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or *GOODRIDE*  
 Front R/Bal: *6* mm Rear R/Bal: *6* mm  
 L/Bal: *6* mm L/Bal: *6* mm  
 D.O.A: *10/07/18* D.O.I: *12/07/18*  
 Survey held at *PRIME AUTO*  
 Des. of Damages: Frt / Rear /  O/S / N/S / U/C / Rooftop or  
*N/S REAR*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 23 AUG 2018	

Date/Time, File Pass to? \_\_\_\_\_  
 1) *typist*  : Preli. Report  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : *TP*  
 Lump Sum / H.B.I: (\$) *4000*  
 Days Of Repair: *2*  
 Resurvey No. of Trip: *1*  
 Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: **280**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012704/R1rd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-07-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6186R	Veh. Inspected	SLT 4694Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18005377MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	12/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	10/07/2018	Inspection Date	12/07/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005377MFSH

Our Ref: CS/FCI18012704/R1rd3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 4694Z**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.07.2018 at the premises of M/s PRIME AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,447.40</u>
Revised Estimate Amount	: S\$ <u>5,017.40</u>
"Check" Items Amount	: S\$ <u>          </u>
Market Value	: S\$ <u>          </u>
LTA Reimbursement Value	: S\$ <u>          </u>
Nett Value	: S\$ <u>          </u>

Description of Damage:  
The vehicle sustained damages  
at n/s rear portion.



Yours faithfully  
RASUL  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	12-07-2018	<b>Our Ref No.</b> D18005377MFSH
<b>Accident Date</b>	10-07-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SH6186R	<b>Third Party Vehicle.</b> SLT4694Z
<b>Survey Location</b>	6 Benoi Place	
<b>Contact Person.</b>	CHRISSEY TEO	
<b>Contact No.</b>	68610908/ 0	<b>Fax No.</b> 65152948
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PRIME AUTO CLAIMS SERVICE PTE. LTD.	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242311)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18005377MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & PRIME AU LTD.
<b>Workshop Name</b>	PRIME AUTO CLAIMS SERVICE PTE. LTD. (Contact Person : CHRISSY TEO)	<b>Survey Location &amp; Contact Details</b>	6 Benoi Place <b>Mobile: 0 , Phone: 68610908 , Fax: 65152948</b> <b>EmailId: CHRISSY@PRIMEAUTOCLAIMS.COM</b>		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SH6186R	<b>TP Vehicle No</b>	SLT4694Z
<b>PRI Recieved Date</b>	12-07-2018 03:08:31 PM	<b>Surveyor Appointed Date</b>	12-07-2018 03:29:25 PM	<b>Surveyor Accept Date</b>	12-07-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	12-07-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
 5 Benoi Place Singapore 629926  
 Tel: 6861 0908 Fax: 6515 2948

Date: 12.07.2018

MS First Capital Insurance Ltd  
 36 Robinson Road #16-01  
 City House  
 Singapore 068877

Attn: Motor Claims Dept

**RE: ESTIMATE COST OF REPAIR TO VEHICLE SLT4694Z HONDA SHUTTLE HYBRID 1.5 (2017)**

### To Supply

1 ) 1pc	Rear bumper	\$	1,350.00	<i>See ✓</i>
2 ) 1set	Rear bumper clip	\$	30.00	<i>See ✓</i>
3 ) 1pc	Rear bumper left side retainer	\$	42.50	<i>See ✓</i>
4 ) 1pc	Left rear fender	\$	1,212.00	<i>PT ✓</i>
5 ) 1pc	Left lower rocker panel garnish	\$	435.00	<i>See ✓</i>
6 ) 1pc	Left rear door	\$	958.50	<i>PT ✓</i>

Sub total parts	\$	4,028.00
Less: 20% discount	\$	(805.60)
	\$	3,222.40

### To supply S.Nett Parts

1 ) 1pc	Left rear wheel cap	\$	195.00	<i>See ✓</i>
---------	---------------------	----	--------	--------------

Sub total S.Nett Parts	\$	195.00
------------------------	----	--------

### L/charges

1 )	To tuff kote.	\$	<del>80.00</del> 60
2 )	To transfer left rear door trim board, handle, weatherstrip & mechanism part	\$	<del>50.00</del> 40

3 ) To remove rear bumper & left rear door. Cut/welding left rear fender. Replace left rear door, left rear fender & rear bumper. Align & adjust.

\$ ~~900.00~~ 800

4 ) To putty, respray painting rear bumper, left rear fender & left rear door inlet & outer/door inlet. To polish.

\$ ~~1,000.00~~ 700

Sub total L/charges	\$	2,030.00
Estimated Grand Total	\$	5,447.40

*Rose*

*Hp 90010068*

*8 days*

*P/P*

*12/07/18 @ 1600*

*Resurvey before paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

*[Signature]*  
*12/7/18*

12-07-18 13:08 From

To: 62650941

# 17 10



### Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
5 Benoi Place Singapore 629926  
Tel: 6861 0908 Fax: 6515 2948

Date: 12.07.2018

MS First Capital Insurance Ltd  
36 Robinson Road #16-01  
City House  
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLT4694Z HONDA SHUTTLE HYBRID 1.5 (2017)

#### To Supply

1 ) 1pc	Rear bumper	\$	1,350.00	See ✓
2 ) 1set	Rear bumper clip	\$	30.00	See ✓
3 ) 1pc	Rear bumper left side retainer	\$	42.50	See ✓
4 ) 1pc	Left rear fender	\$	1,212.00	See ✓
5 ) 1pc	Left lower rocker panel garnish	\$	435.00	See ✓
6 ) 1pc	Left rear door	\$	958.50	See ✓

Sub total parts	\$	4,028.00
Less: 20% discount	\$	(805.60)
	\$	3,222.40 ✓

#### To supply S. Nett Parts

1 ) 1pc	Left rear wheel cap	\$	195.00	See ✓
Sub total S. Nett Parts	\$	195.00		

#### L/charges

1 ) To tuff kote.	\$	800.00	60
2 ) To transfer left rear door trim board, handle, weatherstrip & mechanism part	\$	500.00	40

3 ) To remove rear bumper & left rear door. Cut/welding left rear fender. Replace left rear door, left rear fender & rear bumper. Align & adjust.

\$ ~~900.00~~ 800

4 ) To putty, respray painting rear bumper, left rear fender & left rear door inlet & outer/door inlet. To polish.

\$ ~~1,000.00~~ 700

Sub total l/charges	\$	2,030.00	1600.00
Estimated Grand Total	\$	5,447.40	

6.11%  
 5017.40  
 - 1003.48  
 4013.92  
 ↓  
 414000

Rose  
 Hy 90010068  
 8 days  
 P/P  
 12/07/18 @ 1600

**LXX Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Resurvey by paint



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012704/R1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6186R	Veh. Inspected	SLT 4694Z
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18005377MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	12/07/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE HYBRID 1.5 A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71116295	Colour	BLUE
Odometer	70503	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	GOODRIDE	6 mm
L/H Front Tyre	185/60 R15	GOODRIDE	6 mm
R/H Rear Tyre	185/60 R15	GOODRIDE	6 mm
L/H Rear Tyre	185/60 R15	GOODRIDE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/07/2018	Inspection Date	12/07/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4694Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	SCRATCHED	1,350.00	1,350.00
1	SET REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER LEFT SIDE RETAINER	NECESSARY	42.50	42.50
1	LEFT REAR FENDER	BENT	1,212.00	1,212.00
1	LEFT LOWER ROCKER PANEL GARNISH	SCRATCHED	435.00	435.00
1	LEFT REAR DOOR	BENT	958.50	958.50
	LESS 20% DISCOUNT		-805.60	-805.60
			3,222.40	3,222.40
<b>SPECIAL NETT ITEMS</b>				
1	LEFT REAR WHEEL CAP (SN)	SCRATCHED	195.00	195.00
			195.00	195.00
<b>LABOUR</b>				
	TO TUFF KOTE.		80.00	60.00
	TO TRANSFER LEFT REAR DOOR TRIM BOARD,HANDLE,WEATHERSTRIP & MECHANISM PART.		50.00	40.00
	TO REMOVE REAR BUMPER & LEFT REAR DOOR.CUT/WELDING LEFT REAR FENDER.REPLACE LEFT REAR DOOR,LEFT REAR FENDER & REAR BUMPER.ALIGN & ADJUST.		900.00	800.00
	TO PUTTY,RESPRAY PAINTING REAR BUMPER,LEFT REAR FENDER & LEFT REAR DOOR INLET & OUTER/DOOR INLET.TO POLISH.		1,000.00	700.00
			2,030.00	1,600.00
<b>GRAND TOTAL</b>			<b>5,447.40</b>	<b>5,017.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,000.00</b>

Report Ref No. CS/FCI18012704/R1rd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.