

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM18012717/Kea3e2	
	8 SHENTON WAY TOWERSINGAPOR		Date:	14/01/2021		
	ATTN : OH VALE			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 6205G	Veh. Inspected		GZ 9305S	
	Policy No.	VCA/P2004209	Coverage (\$)		0.00	
	Claim No.	S8M00O2L	Excess (\$)		0.00	
	Assign From	ATTN : OH VALE	Assign Date		12/07/2018	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI FB70ABOSRDEB	c.c		2835	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	FB70ABA00679	Colour		WHITE	
	Odometer	442687 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185 R14X8	FALKEN		9 mm	
	L/H Front Tyre	185 R14X8	FALKEN		9 mm	
	R/H Rear Tyre	165 R13X8 (D)	FALKEN		8/8 mm	
	L/H Rear Tyre	165 R13X8 (D)	FALKEN		8/8 mm	
4. Description of Damages						
	THE VEHICLE SUS	HICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
5.	General Information					
	Accident Date	06/07/2018	Inspect Date / T	ime	25/08/2018 (10:48 AM)	
_	Survey held at	CHENG HOE MOTOR PL		_		
	BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761					
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$10,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					

Report Ref No. CS3/ASM18012717/Kea3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

DEOD Auto Occupitant OAE Licensed Associate

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$