

REF: G9/ATh18012718 / R/vbez

ASSIGNMENT (Office)

From (Person): Shuan Wei of ATh Date/Time: 11-07-08

Estimated Cost: Bill to:

Special Instructions: 45-# 10300-00

Third Parties:

Claimant:

Surveyor: Carlink Consultancy

Workshop: N-51 Automotive

OD (TP Re-inspection) / Evaluation

To Inspect Vehicle No: XE 2148J

at Workshop m/s: N-51 Automotive

of: 2 Koki Bukit Ave 2 #01-17

Insured: SBB 1998E

Tel: 6843 0051

Policy No: Claim No: 976607876856-003

Sum Insured: Excess:

Make of Veh: D.O.A. 31-07-2017

(Client's Record)

18-07-2018 (Wednesday) @ 10am

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 8 days)

Date/Time: 15/8/18 Submit Final Fig LS \$7950, 6 days (Red \$2350 / 23 %; Original days)

Date/Time	Action/Instruction
	16 Tuas South St 7 Singapore 637113 (Mr. Lim - 97240178)
	XE 2148J - 703 / 7006 / 7006 / 7006 / 7006
	SBB 1998E - 703 / 7006 / 7006 / 7006 / 7006
27/8/18	To re-open amend to LS \$7700
31/8/18	1st POZ A/8/18 Reopen ref only.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 15 AUG 2018

Para(3) : Nett Value

Market Value :	Inspected/	Fee Charged:	Date:
Salvage Value :	Evaluated by:	Basic & Add	200
Nett Value :		Transport	
		Photos	
		Others	
		Total	200

1) Date/Time 15/8-14pit File Pass to

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to



**Veron Chen (LKKAUTO)**

---

**From:** Wui, Shawnkaijie <Shawnkaijie.Wui@aig.com>  
**Sent:** Friday, 17 August 2018 5:24 PM  
**To:** Reports (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: <Re-inspection Report>Your Ref :9766028768SG-003 \*Our Ref: CS/AIG18012718/R1vbe2

Dear Elaine,

Able to advise on the Rim Nuts pricing? Is \$ 350.00 reasonable?

Wholesale price - \$ 3.50 per piece.

Thanks and Regards,  
**Shawn Wui**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

[Shawnkaijie.Wui@aig.com](mailto:Shawnkaijie.Wui@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Elaine (LKK Auto) [mailto:report@lkkauto.com]  
**Sent:** Friday, August 17, 2018 5:10 PM  
**To:** Wui, Shawnkaijie  
**Cc:** sur@lkkauto.com  
**Subject:** <Re-inspection Report>Your Ref :9766028768SG-003 \*Our Ref: CS/AIG18012718/R1vbe2

Your Ref : 9766028768SG-003  
Our Ref : CS/AIG18012718/R1vbe2

Dear Shawn Wui,

We refer to the above matter.

Enclosed herewith the re-inspection report and our note of charge for your necessary action.

Thank you.

Best Regards,

**Elaine | Reports**

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18012718/R1vbe2

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 15-08-2018



ATTN : SHAWN WUI

Code : AIG

#### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SBB 1998E	Veh. Inspected	XE 2148J
Policy No.	2100420518-02000	Coverage (\$)	0.00
Claim No.	9766028768SG-003	Excess (\$)	0.00
Assign From	SHAWN WUI	Assign Date	11/07/2018

#### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ ACTROS	c.c	11946
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDB9321612L910329	Colour	MULTI COLOUR
Odometer	72471	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	31/07/2017	Inspection Date	18/07/2018
Survey held at	16 TUAS SOUTH ST 7		
Repairer	N-51 AUTOMOTIVE PL		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd .

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2148J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER SIDE BRACKET LH	SERVICEABLE	135.00	-
1	FRONT BUMPER SIDE LH	REPLACED	3,100.00	3,100.00
1	FRONT BUMPER SIDE SIGNAL LAMP LH	REPLACED	85.00	85.00
1	FRONT LH LOWER STEP	REPLACED	400.00	400.00
2	FRONT LH LOWER STEP BRACKET	SERVICEABLE	450.00	-
1	FRONT LH TOP STEP	REPLACED	410.00	410.00
1	FRONT LH TOP STEP GARNISH	REPLACED	850.00	850.00
1	FRONT LH WHEEL ARCH OUTER GARNISH PROTECTOR	REPLACED	450.00	450.00
1	FRONT LH WHEEL REAR MUDGUARD	REPLACED	680.00	680.00
1	FRONT LH WHEEL REAR MUDGUARD YELLOW REFLECTOR	REPLACED	60.00	60.00
1	FRONT LH WHEEL RIM	REPLACED	1,280.00	1,280.00
10	FRONT LH WHEEL RIM NUT	REPLACED	350.00	350.00 35
1	FRONT LH WHEEL SPLASH SHIELD	REPLACED	510.00	510.00
1	FRONT LH WHEEL NUT GUARD (CHROME)	REPLACED	510.00	510.00
1	HEADLAMP GUARD LH	SERVICEABLE	260.00	-
1	HEADLAMP LH	REPLACED	480.00	480.00
1	LH PERFORATED PROTECTOR SHIELD	SERVICEABLE	410.00	-
	LESS 10% DISCOUNT		-1,042.00	-916.50
			9,378.00	8,248.50
<b>SPECIAL NETT ITEMS</b>				
1	FRONT LH TYRE (SN)	SERVICEABLE	480.00	-
			480.00	-
<b>LABOUR</b>				
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,500.00	900.00
	TO CHECK WIRING AND LIGHT SYSTEM.		200.00	50.00
	TO SPRAY UNDERCARRIAGE ANTI RUST COATING.		200.00	40.00
			3,400.00	1,690.00

Report Ref No. CS/AIG18012718/R1vbe2



GRAND TOTAL		13,258.00	9,938.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,950.00

9655

7700

Report Ref No. CS/AIG18012718/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2148J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER SIDE BRACKET LH	SERVICEABLE	135.00	-
1	FRONT BUMPER SIDE LH	REPLACED	3,100.00	3,100.00
1	FRONT BUMPER SIDE SIGNAL LAMP LH	REPLACED	85.00	85.00
1	FRONT LH LOWER STEP	REPLACED	400.00	400.00
2	FRONT LH LOWER STEP BRACKET	SERVICEABLE	450.00	-
1	FRONT LH TOP STEP	REPLACED	410.00	410.00
1	FRONT LH TOP STEP GARNISH	REPLACED	850.00	850.00
1	FRONT LH WHEEL ARCH OUTER GARNISH PROTECTOR	REPLACED	450.00	450.00
1	FRONT LH WHEEL REAR MUDGUARD	REPLACED	680.00	680.00
1	FRONT LH WHEEL REAR MUDGUARD YELLOW REFLECTOR	REPLACED	60.00	60.00
1	FRONT LH WHEEL RIM	REPLACED	1,280.00	1,280.00
10	FRONT LH WHEEL RIM NUT	REPLACED	350.00	35.00
1	FRONT LH WHEEL SPLASH SHIELD	REPLACED	510.00	510.00
1	FRONT LH WHEEL NUT GUARD (CHROME)	REPLACED	510.00	510.00
1	HEADLAMP GUARD LH	SERVICEABLE	260.00	-
1	HEADLAMP LH	REPLACED	480.00	480.00
1	LH PERFORATED PROTECTOR SHIELD	SERVICEABLE	410.00	-
	LESS 10% DISCOUNT		-1,042.00	-885.00
			9,378.00	7,965.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT LH TYRE (SN)	SERVICEABLE	480.00	-
			480.00	-
<b><u>LABOUR</u></b>				
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,500.00	900.00

Report Ref No. CS/AIG18012718/R1vbe2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND LIGHT SYSTEM.		200.00	50.00
	TO SPRAY UNDERCARRIAGE ANTI RUST COATING.		200.00	40.00
			3,400.00	1,690.00
GRAND TOTAL			13,258.00	9,655.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,700.00

Report Ref No. CS/AIG18012718/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.