

XE2148J [SBB1998E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)


are obliged to read the user's manual so as to acquaint
yourself with the system prior to operating it



1/38: Chassis Number



2/38: Odometer Reading



3/38: Odometer Reading



4/38: Odometer Reading

XE2148J [SBB1998E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



5/38: Front View Left



6/38: Front View Right



7/38: Rear View Left



8/38: Rear View Right

XE2148J (SBB1998E) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



9/38: Front View Left



10/38: PRI PHOTO



11/38: PRI PHOTO



12/38: PRI PHOTO

XE2148J [SBB1998E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/38: PRI PHOTO



14/38: PRI PHOTO



15/38: PRI PHOTO



16/38: PRI PHOTO

XE2148J (5BB1998E) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



17/38: PRI PHOTO



18/38: PRI PHOTO



19/38: PRI PHOTO



20/38: PRI PHOTO

XE2148J [SBB1998E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



21/38: PRI PHOTO



22/38: PRI PHOTO



23/38: PRI PHOTO



24/38: PRI PHOTO

XE2148J ISBB1998E1 - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/38: PRI PHOTO



26/38: PRI PHOTO



27/38: PRI PHOTO



28/38: PRI PHOTO

XE2148J [SBB1996E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



29/38: PRI PHOTO



30/38: PRI PHOTO



31/38: PRI PHOTO



32/38: PRI PHOTO

XE2148J [SBB1998E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



33/38: PRI PHOTO



34/38: PRI PHOTO



35/38: PRI PHOTO



36/38: PRI PHOTO

XE2148J [SBB1998E] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



37/38. TYRE BRAND



38/38. TYRE SIZE

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CLM14139TP/N

1 REFERENCE			
Date of request	: 24th August 2017		
Requested by	: M/S Poh Meng Trading & Cleaning Services Pte Ltd C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18 Singapore 417921		
Type of claim	: Third party		
Workshop	: M/S N-51 Automotive Pte Ltd Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18 Singapore 417921		
Date of survey	: 24th August 2017		
Accident date	: 31st July 2017		
2 DETAILS OF VEHICLE			
Registration No.	: XE 2148 J		
Make & Model	: Mercedes Benz Actros 3336K 6X4 3300 A/T ABS		
Engine No.	: 541972C0956428		
Chassis No.	: WDB9321612L910329		
Year of Registration	: 1st September 2016		
Speedometer reading	: 58447.4 Km		
Transmission	: Manual/automatic		
Colour	: Green		
3 STATIC CHECK			
Steering	: see annex(es)	Paintwork	: Good
Footbrake	: see annex(es)	Modification	: Nil
Handbrake	: see annex(es)	General condition	: Good
4 TYRE CONDITION			
	<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>
Front axle	: 7mm/Bridgestone	7mm/Bridgestone	: 318/80 R12
Centre axle	: 7mm/Bridgestone	7mm/Bridgestone	: 318/80 R12
Rear axle	: 7mm/Bridgestone	7mm/Bridgestone	: 318/80 R12
5 POINT OF IMPACT			
See Annex(es) and Motor Accident Reports			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Report No.

CLM14139TP/N

Vehicle No. XE2148J

Parts and Labour Assesme**PARTS**

Description of part	Repairer's Qty	Qty	Condition		Our adjustment
FRONT BUMPER SIDE BRACKET LH	1	1	BENT/DEI	3,100. +	
FRONT BUMPER SIDE LH	1	1	GRAZED/I	85. +	
FRONT BUMPER SIDE SIGNAL LAMP LH	1	1	GRAZED/I	400. +	
FRONT LH LOWER STEP	1	1	GRAZED/I	410. +	
FRONT LH LOWER STEP BRACKET	2	2	BENT	850. +	
FRONT LH TOP STEP	1	1	GRAZED/I	450. +	135.00
FRONT LH TOP STEP GARNISH	1	1	DISTORTI	680. +	3,100.00
FRONT LH WHEEL ARCH OUTER GARNISH PROTECTOR	1	1	GRAZED/I	60. +	
FRONT LH WHEEL REAR MUDGUARD	1	1	GRAZED/I	1,280. +	85.00
FRONT LH WHEEL REAR MUDGUARD YELLOW REFLECTOR	1	1	GRAZED	350. +	400.00
FRONT LH WHEEL RIM	1	1	DISTORTE	510. +	450.00
FRONT LH WHEEL RIM NUT	10	10	GRAZED/I	510. +	410.00
FRONT LH WHEEL SPLASH SHIELD	1	1	GRAZED/I	480. +	850.00
FRONT LH WHEEL WHEEL NUT GUARD (CHROME)	1	1	DENTED/I	9,165. +	450.00
HEADLAMP GUARD LH	1	1	DISTORTE		
HEADLAMP LH	1	1	DISTORTE		
LH PERFORATED PROTECTOR SHIELD	1	1	DENTED/I		
Percentage discount 10% and 10%					
FRONT LH TYRE	1	1	GRAZED/E		

15/8v

3,100. +

85. +

400. +

410. +

850. +

450. +

680. +

60. +

1,280. +

350. +

510. +

510. +

480. +

9,165. +

x

90. x

8,248.5 x

60.00

1,280.00

350.00

700. +

900. +

50. +

40. +

1,690. +

480.00

410.00

8,248.5 +

1,690. +

9,938.5

480.00

80. x

7,950.8 x

SS 9,858.00

LABOUR

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,500.00 ~~700~~ 900.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00 ~~900~~ 1,200.00

To check wiring and light system

200.00 ~~50~~ 100.00

To spray undercarriage anti rust coating.

200.00 ~~40~~ 80.00

Labour Total **SS 3,400.00** **SS 2,280.00**

Parts & Labour Total **SS 13,258.00** **SS 12,138.00**

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 10,300.00

and the recommended number of working days for the repairs is within 8 day(s).


PATRICK M. SURVEYOR
Automotive Appraiser

8248.50

1690.00

9938.50

20%

7950.80

4/3 - 7,950

6 days















