



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18012725/Uhb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 12-07-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 3653R	Veh. Inspected	SLP 2903E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/07/2018	Inspection Date	12/07/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

Not Allowed
 here
 2/5 @ 23,000
 14 day.
 2/7/18

VEHICLE NO: SLP 2903E

QTY	PARTICULAR (NETT ITEM)			
1 PCS	REAR WINDSCREEN	1200.50	shutterstock	\$1,855.30 ✓
1 PCS	REAR WINDSCREEN MOULDING		ner	\$195.30 ✓
2 PCS	REAR WINDSCREEN INNER SIDE GARNISH @ \$165.00		11	\$330.00 X
1 PCS	TAILGATE	2936.50	Bodypro	\$3,066.20 ✓
1 PCS	TAILGATE OUTER GARNISH	336	Bro	\$450.00 ✓
1 PCS	TAILGATE REAR LOGO		ner	\$38.50 ✓
1 PCS	TAILGATE 'Qashqai' EMBLEM		ner	\$78.50 ✓
2 PCS	TAILGATE REFLECTORS @ \$650.00	320x2=640	one	\$1,300.00 ✓
1 PCS	TAILGATE REAR WIPER MOTOR	766.20	one/ner	\$966.00 ✓
1 PCS	TAILGATE REAR WIPER ARM	185	daye	\$315.00 ✓
1 PCS	TAILGATE REAR WIPER BLADE		daye	\$65.00 ✓
1 PCS	TAILGATE INNER LOCK		one/ner	\$292.00 ✓
1 PCS	TAILGATE INNER TRIM BOARD	466.20	de/one	\$595.30 ✓
1 SET	TAILGATE INNER TRIM BOARD CLIPS		ner	\$30.00 ✓
1 PCS	TAILGATE WEATHERSTRIP		any	\$166.20 ✓
1 PCS	TAILGATE REVERSE CAMERA	300.00	shutterstock	\$485.00 ✓
1 PCS	TAILGATE INNER TOP BOARD	392.30	de/any	\$492.30 ✓
2 PCS	TAILGATE LICENCE PLATE LAMPS @ \$53.00		11	\$106.00 X
1 PCS	REAR BUMPER	717.00	dis	\$891.00 ✓
1 PCS	REAR BUMPER TOW COVER	16.50	ner	\$22.00 ✓
2 PCS	REAR BUMPER REFLECTORS @ \$68.00		ner	\$136.00 1PC
2 PCS	REAR BUMPER SIDE RE TAINERS @ \$25.00		sent	\$50.00 ✓
1 PCS	REAR BUMPER REINFORCEMENT	619.20	dis	\$721.00 ✓
2 PCS	TAILLAMPS @ \$580.00	385x2=770	one	\$1,160.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @ \$265.00		one	\$530.00 1PC
2 PCS	REAR FENDERS @ \$1150.00	1045.30	one/ner	\$2,300.00 1PC
2 PCS	REAR FENDER OUTER PROTECTORS @ \$541.00	966	dis/ner	\$1,082.00 ✓
2 PCS	REAR FENDER INNER TRIMS @ \$481.00	315	one/ner	\$962.00 1PC
1 PCS	REAR FENDER UNDER SHIELD N/S		11	\$266.00 X
1 PCS	REAR FENDER INNER AIR VENT N/S		ner	\$68.00 ✓
1 PCS	REAR FENDER GLASS W/MOULDING N/S	522.50	ner	\$820.00 ✓
1 PCS	REAR END PANEL	482.60	Bodypro	\$720.00 ✓
1 PCS	REAR END PANEL TOP GARNISH	382	ner	\$408.00 ✓
1 PCS	REAR END PANEL LOCK SENSOR	150	one	\$265.00 ✓
1 PCS	REAR FLOOR PANEL	1182.30	one	\$265.00 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD	495	cramped/ner	\$1,288.30 ✓
2 PCS	REAR FLOOR PANEL TOOLS SPONGES @ \$305.00		ner	\$622.00 ✓
			ner	\$610.00 ✓

1070

1 PCS	REAR FLOOR PANEL TOOLS SPONES CENTRE	295.00	111	\$308.30	✓
1 PCS	REAR FLOOR PANEL SPARE TYRE NUT		11	\$62.20	X
1 PCS	REAR EXHAUST ASSY		L	\$1,122.30	X
2 PCS	REAR EXHAUST MOUNTINGS @\$30.00		11	\$60.00	X
1 PCS	REAR EXHAUST HEAT SHIELD		Sub	\$188.00	✓
1 PCS	REAR TAILGATE TOP SPOILER	720	one	\$810.50	✓
1 SET	REAR BUMPER CLIPS		one	\$30.00	✓
2 PCS	REAR DOORS @\$922.00		L	\$1,844.00	X
1 PCS	FRONT BUMPER	676.10	10/De	\$801.00	✓
1 PCS	FRONT BUMPER REINFORCEMENT	742.90	Sub	\$665.00	✓
1 PCS	FRONT BUMPER SPONGE	215.30	111	\$302.00	✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$35.00		Sub	\$70.00	✓
1 SET	FRONT BUMPER CLIPS		one	\$30.00	✓
1 PCS	FRONT BUMPER TOW COVER		11	\$28.00	X
2 PCS	HEADLAMPS @\$2050.00	1617 X 2 = 3234	one	\$4,100.00	✓
1 PCS	FRONT GRILLE	548.20	one	\$803.00	✓
1 PCS	FRONT GRILLE LOGO		one	\$65.00	✓
1 PCS	BONNET		L	\$923.30	X
1 PCS	FRONT SUPPORT PANEL	566.20	Sub	\$792.50	✓
1 PCS	FRONT SUPPORT PANEL TOP GARNISH		11	\$368.40	X
1 PCS	AIRCON CONDENSER	655	Sub/one	\$911.00	✓
2 PCS	AIRCON CONDENSER SIDE GARNISH @\$208.00	145 X 2 = 290	111	\$416.00	✓
1 PCS	AIRCON SUCTION HOSE		11	\$150.00	X
1 PCS	AIRCON DISCHARGE HOSE		11	\$166.00	X
1 PCS	AIRCON PIPE		11	\$105.00	X
2 PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$205.00		Sub	\$410.00	✓
1 PCS	OIL COOLER	450	one	\$620.00	✓
1 PCS	OIL COOLER HOSE		11	\$30.00	X
1 PCS	RADIATOR		Sub	\$885.00	X
1 PCS	RADIATOR FAN ASSY		11	\$820.00	X
2 PCS	FRONT FOG LAMP COVERS @\$95.00		11	\$190.00	X
				\$41,824.40	

107

S.NETT					
1 SET	REAR BUMPER REVERSE SENSOR (4 PCS)		Sub	\$380.00	250
1 PCS	REAR END PANEL SEALANT		one	\$50.00	✓
1 SET	REAR FLOOR PANEL INSULATOR		one	\$300.00	200
1 PCS	REAR WINDSCREEN SEALANT		one	\$50.00	40
1 PCS	REAR FENDER GLASS SEALANT N/S		one	\$50.00	40
1 SET	REAR VIEW CAMERA CAM		one	\$500.00	300
1 PCS	REAR WINDSCREEN SOLAR FILM		one	\$300.00	150
1 PCS	REAR LICENCE PLATE W/HOLDER		Sub	\$50.00	40
1 PCS	FRONT LICENCE PLATE W/HOLDER		Sub	\$50.00	40
1 BOT	RADIATOR COOLANT		one	\$50.00	30

LABOUR CHARGES:

TOWING CHARGE		\$120.00	60
TO CHECK WIRING		\$80.00	30
TO DISMANTLE & REPLACING REAR REVERSE SENSOR		\$80.00	50
TO CONDUCT WHEEL ALIGNMENT	11	\$120.00	X
TO DISMANTLE & REPLACING REAR WINDSCREEN		\$150.00	120
TO DISMANTLE & REPLACING REAR EXHAUST		\$150.00	80
TO DISMANTLE & REPLACING REAR FENDER GLASS N/S		\$150.00	80
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$150.00	80
TO TRANSFER TAILGATE COMPONENTS		\$100.00	60
TO SPRAY RUSF PROOFING		\$180.00	120
TO REFILL AIRCON GAS		\$150.00	100
TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	X
TO DISMENTLE & REFIX REAR UNDERCARRIAGE	11	\$380.00	X
TO DISMANTLE & REFIX PETROL TANK	11	\$100.00	X
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS		\$3,000.00	2200
TO PUTTY & SPRAY PAINTING		\$3,000.00	1800
	TOTAL	\$51,894.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 16 July 2018 1:54 PM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GBF3653R (OI : CAI - SNM18D03444C02) and SLP2903E (TP : LKK REF - CC6/CTI18012725/Uhb3) on 12.07.2018
Attachments: leeSZ_SNM18D03444C01-GBF3653R-LKKDirectSettlementAccidentLtr_CLCR95.846.pdf; MNA118089951-GBF3653R.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Jowyn Tay

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Friday, 13 July, 2018 5:24 PM
To: Claims Dept of CTI
Cc: Jowyn Tay; Admin A; Vic (LKKAuto)
Subject: Direct Settlement - Accident Involving GBF3653R (OI : CAI - TBA) and SLP2903E (TP : LKK REF - CC6/CTI18012725/Uhb3) on 12.07.2018

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLP 2903E at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D03444/C01/3**

Date : **16 JULY 2018**

via Ordinary & Registered Mail

**DUKE BAKERY PTE LTD
230 PANDAN LOOP
#04-02 LIM CHEE GUAN FOOD INDUSTRIES
SINGAPORE 128415**

Dear Sir / Madam

**ACCIDENT INVOLVING GBF3653R AND SLP2903E ON 12 JULY 2018
ALONG LENTOR AVE TOWARDS YIO CHU KANG**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLP2903E**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIC
Ref : CC6/CTI18012725/UHB3
Contact No : 68412096
via Email : VIC@LKKAUTO.COM

CC : Agent - (AN0579A) - ENJ INVESTMENTS PTE LTD(TERMINATED WEF 01.12.17)

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18012725/Uhb3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 26-12-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 3653R	Veh. Inspected	SLP 2903E
Policy No.	DMCVSN3073321700	Coverage (\$)	0.00
Claim No.	SNM18D03444C02/3	Excess (\$)	0.00
Assign From		Assign Date	12/07/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFBAJ11U1908595	Colour	BROWN
Odometer	17586	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45R19	BRIDGESTONE	6 mm
L/H Front Tyre	225/45R19	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45R19	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45R19	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/07/2018	Inspection Date	12/07/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2903E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN (N)	SHATTERED	1,855.30	1,200.50
1	REAR WINDSCREEN MOULDING (N)	NECESSARY	195.30	195.30
2	REAR WINDSCREEN INNER SIDE GARNISH @ \$165.00 (N)	NOT NECESSARY	330.00	-
1	TAILGATE (N)	BADLY DENTED	3,066.20	2,936.80
1	TAILGATE OUTER GARNISH (N)	BROKEN	450.00	336.00
1	TAILGATE REAR LOGO (N)	NECESSARY	38.50	38.50
1	TAILGATE 'QASHQAI' EMBLEM (N)	NECESSARY	78.50	78.50
2	TAILGATE REFLECTORS @ \$650.00 (N)	CRACKED	1,300.00	640.00
1	TAILGATE REAR WIPER MOTOR (N)	CRACKED / JAMMED	966.00	766.20
1	TAILGATE REAR WIPER ARM (N)	DAMAGED	315.00	185.00
1	TAILGATE REAR WIPER BLADE (N)	DAMAGED	65.00	65.00
1	TAILGATE INNER LOCK (N)	DENTED / TWISTED	292.00	292.00
1	TAILGATE INNER TRIM BOARD (N)	DEFORMED / CRACKED	595.30	466.20
1	SET TAILGATE INNER TRIM TRIM BOARD CLIPS (N)	NECESSARY	30.00	30.00
1	TAILGATE WEATHERSTRIP (N)	TWISTED	166.20	166.20
1	TAILGATE REVERSE CAMERA (N)	SHORTED	485.00	300.00
1	TAILGATE INNER TOP BOARD (N)	DEFORMED / WARPED	492.30	392.30
2	TAILGATE LICENCE PLATE LAMPS @ \$53.00 (N)	NOT NECESSARY	106.00	-
1	REAR BUMPER (N)	DISTORTED	891.00	717.00
1	REAR BUMPER TOW COVER (N)	TORN	22.00	16.80
2	REAR BUMPER REFLECTORS @ \$68.00 (N)	N/S CRACKED	136.00	68.00
2	REAR BUMPER SIDE RETAINERS @ \$25.00 (N)	BENT	50.00	50.00
1	REAR BUMPER REINFORCEMENT (N)	DISTORTED	721.00	619.20
2	TAILLAMPS @ \$580.00 (N)	CRACKED	1,160.00	770.00
2	TAILLAMP HOUSING PANELS @ \$265.00 (N)	N/S DENTED	530.00	265.00
2	REAR FENDERS @ \$1150.00 (N)	O/S TO REPAIR SEE LABOUR / N/S DENTED/BUCKLED	2,300.00	1,045.30
2	REAR FENDER OUTER PROTECTORS @ \$541.00 (N)	DISTORTED / TORN	1,082.00	966.00

Report Ref No. CC6/CTI18012725/Uhb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIMS @ \$481.00 (N)	N/S DISTORTED	962.00	315.00
1	REAR FENDER UNDER SHIELD N/S (N)	NOT NECESSARY	266.00	-
1	REAR FENDER INNER AIR VENT N/S (N)	TWISTED	68.00	68.00
1	REAR FENDER GLASS W/MOULDING N/S (N)	NECESSARY	820.00	522.50
1	REAR END PANEL (N)	BADLY DENTED	720.00	482.60
1	REAR END PANEL TOP GARNISH (N)	TWISTED	408.00	382.00
1	REAR END PANEL LOCK SENSOR (N)	CRACKED	265.00	150.00
1	REAR FLOOR PANEL (N)	CRUMPLED / BUCKLED	1,288.30	1,182.30
1	REAR FLOOR PANEL TOP BOARD (N)	TORN	622.00	495.00
2	REAR FLOOR PANEL TOOLS SPONGES @ \$305.00 (N)	TORN	610.00	610.00
1	REAR FLOOR PANEL TOOLS SPONGES CENTRE (N)	TORN	308.30	295.00
1	REAR FLOOR PANEL SPARE TYRE NUT (N)	NOT NECESSARY	62.20	-
1	REAR EXHAUST ASSY (N)	TO REPAIR SEE LABOUR	1,122.30	-
2	REAR EXHAUST MOUNTINGS @ \$30.00 (N)	NOT NECESSARY	60.00	-
1	REAR EXHAUST HEAT SHIELD (N)	BENT	188.00	188.00
1	REAR TAILGATE TOP SPOILER (N)	CRACKED	810.50	720.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	30.00	30.00
2	REAR DOORS @ \$922.00 (N)	TO REPAIR SEE LABOUR	1,844.00	-
1	FRONT BUMPER (N)	DENTED / DEFORMED	801.00	676.10
1	FRONT BUMPER REINFORCEMENT (N)	BENT	665.00	665.00
1	FRONT BUMPER SPONGE (N)	TORN	302.00	215.30
2	FRONT BUMPER SIDE RETAINERS @ \$35.00 (N)	BENT	70.00	70.00
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	30.00	30.00
1	FRONT BUMPER TOW COVER (N)	NOT NECESSARY	28.00	-
2	HEADLAMPS @ \$2050.00 (N)	CRACKED	4,100.00	3,234.00
1	FRONT GRILLE (N)	CRACKED	803.00	548.20
1	FRONT GRILLE LOGO (N)	NECESSARY	65.00	65.00
1	BONNET (N)	TO REPAIR SEE LABOUR	923.30	-
1	FRONT SUPPORT PANEL (N)	BENT	792.50	566.20
1	FRONT SUPPORT PANEL TOP GARNISH (N)	NOT NECESSARY	368.40	-

Report Ref No. CC6/CTI18012725/Uhb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON CONDENSER (N)	BENT / PUNCTURE	911.00	655.00
2	AIRCON CONDENSER SIDE GARNISH @ \$208.00 (N)	TORN	416.00	290.00
1	AIRCON SUCTION HOSE (N)	NOT NECESSARY	150.00	-
1	AIRCON DISCHARGE HOSE (N)	NOT NECESSARY	166.00	-
1	AIRCON PIPE (N)	NOT NECESSARY	105.00	-
2	FRONT BUMPER REINFORCEMENT BRACKETS @ \$205.00 (N)	BENT	410.00	410.00
1	OIL COOLER (N)	PUNCTURE	620.00	450.00
1	OIL COOLER HOSE (N)	NOT NECESSARY	30.00	-
1	RADIATOR (N)	SERVICEABLE	885.00	-
1	RADIATOR FAN ASSY (N)	NOT NECESSARY	820.00	-
2	FRONT FOG LAMP COVERS @ \$95.00 (N)	NOT NECESSARY	190.00	-
	LESS 10% DISCOUNT		-	-2,592.10
			41,824.40	23,328.90
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (4 PCS) (SN)	SHORTED	380.00	250.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	300.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR FENDER GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	SET REAR VIEW CAMERA CAM (SN)	DAMAGED	500.00	300.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	300.00	150.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			1,780.00	1,140.00
<u>LABOUR</u>				
	TOWING CHARGE.		120.00	60.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR.		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR EXHAUST.		150.00	80.00

Report Ref No. CC6/CT118012725/Uhb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACING REAR FENDER GLASS N/S.		150.00	80.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		150.00	80.00
	TO TRANSFER TAILGATE COMPONENTS.		100.00	60.00
	TO SPRAY RUST PROOFING.		180.00	120.00
	TO REFILL AIRCON GAS.		150.00	100.00
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF O/S REAR FENDERS, REAR EXHAUST ASSY, REAR DOORS AND BONNET.		3,000.00	2,200.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,800.00
			8,290.00	4,780.00
GRAND TOTAL			51,894.40	29,248.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				23,000.00

Report Ref No. CC6/CTI18012725/Uhb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.