

22002087

ASS. REP. BY

REF: C81MSG18005727

B

Ad3⁵²

Purge

Paper Survey

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Elaine Ngu

of MSIG

Date/Time: 11/7/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 8098D

Insured: XE 11204

at Workshop in: Reliable Carz

Tel: 8166 9797

of 8 Kaki Bkt Ave 4 # 05-50

Policy No: B28636251MCC

Claim No: 553599

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/03/2018

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Enforcement

Date/Time: 11:46am @ 28/3/18

Person Contacted: Jason

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJR 8098D - NA / INC 18065636/24 D.O.A. 26/3/18
	XE 11204 - NA / INC 18065636/24 D.O.A. 26/3/18
	Dismantle: 29/3/2018
	After repair: 6/4/2018

23/7/18 Submit LS \$8800 (Ref 6003-34, 4070), 12 days

RECEIVED 23 JUL 2018


 20/7/2018

ASS. REC BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR8098D Yr Regn: 2017 AugustType: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel Hybrid cc 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 52156 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU31246756Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 28/03/18Survey held at ReliableDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSL6 PRS.Estimated Repair cost: \$2.5k - \$9.5k. 888. 27/04/18
08 Days.

RECEIVED 27 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 8Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

LKK

RC 3059

MNA116040960 / National Assessment Centre Services - USK
ENTRY DATE & TIME: 26/03/2018 17:32
SUBMITTED BY: Jackson Ho Zhao Tian

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/03/2018 17:32
Date Of Accident 26/03/2018 15:25
Exact Location Of Accident JUNG CORPORATION RD & LAKEPOINT DR
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR8098D
Insured/Policyholder
Name Of Registered Owner RELIABLE RIDES PTE LTD
Co Reg No 201611527N
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-89999999
Vehicle Particulars
Manufacturer HONDA
Model VEZEL HYBRID 1.5X AUTO
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5093728301
Cover Note Number
Driver
Name of Driver SITI MARIAM BINTE HANIFI
NRIC No S8509422Z
Date Of Birth 16/04/1985
Occupation OUTDOOR
Date Of Driving Pass 28/07/2004
Driving Experience 13 YEARS AND 7 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-98765956
Fax Number
Contact Number OFFICE-98765956
Email Address NOEMAIL

Address	BLK 659 JALAN TENAGA #11-140
Postcode	410659
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS MAKING A TURN FROM CORPORATION RD TWDS LAKEPOINT DR. SUDDENLY VEHICLE B HIT ONTO MY VEHICLE REAR PORTION. AFTER AN IMPACT, MY VEHICLE DIRECTLY MOVED ALONG LAKEPOINT DR

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1120U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NIU JIAPU
NRIC/Passport Number	G8393093X
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name	SITI MARIAM BINTE HANIFI
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLR8098D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	ABISHEK
Approximate Age	
Injuries Sustain	HEAD
Injured person in which vehicle?	SLR8098D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. As the signatory of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agent (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRC/STN No.:

Accident Sketch Plan


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Describe circumstances of the accident.

FD-10 1-1 2014-01-01



DECLARATION

Two disjuncts: the foregoing particulars are true in every respect

Applicant's Signature _____
Date & Time _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting CA _____
Name _____
NRIC/ID No _____



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779

Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0035/18

Date of Report : 13 April 18

To : Reliable Rides Pte Ltd

Date of Request : 27 March 18

8, Kaki Bukit Avenue 4
#05-05, Premier Building
Singapore 415875

Report requested by : Reliable Rides Pte Ltd

Date of Accident : 26 March 18

Date of Inspection : 27 March 18

Claim No. : Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No : SLR 8098 D
Make : Honda
Model : Vezel (A)
Year of Manufacture : 2017
Colour : Metallic Grey / Silver
Engine Capacity : 1,496 cc
Engine No : --
Chassis / Frame No : RU3-1246756

Odometer Reading : 52,156 km
Carrying Capacity : 4
Radio / Cassette / CD : Yes
Air-Conditioner : Yes
Wing Mirror : Yes
Clock : Yes
Seat Belts : Yes
Others : Nil

TYRE CONDITION

Front Left : 6mm
Make : Dunlop
Rear Left : 6mm
Make : Dunlop
Spare :

Front Right : 6mm
Make : Dunlop
Rear Right : 6mm
Make : Dunlop
Road Wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools : Intact

Spare Tyre : No

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent engine modification : Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at M/s. Reliable Carz, 8 Kaki Bukit Ave 4 #05-05 Premier Building, Singapore 415875.

Follow-up inspection has been conducted.

Point of Impact

At the rear portion.

Damages

The tailgate, tailgate lock, tailgate lamps, rear bumper, rear side bumpers, end panel, spare tyre panel, rear chassis members, rear fenders, tail-lamps assembly, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.


Our adjusted amount for the cost of repairs is \$14,803.34

Conclusion

The repairer has agreed to undertake repairs at our adjusted amount of \$14,803.34 corresponding to labour charges, spray painting and replacement of parts.

We now revert to you for your decision on repairs.

Very truly yours
PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser


LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

ASSESSMENT

		<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts	:	16,176.62	10,743.34
Labour Charges	:	3,380.00	2,510.00
Paint Work	:	1,850.00	1,500.00
Towing Charges	:	50.00	50.00
Others	:	0.00	0.00
Totals	:	21,456.62	14,803.34

Reduction (S \$) : 6,653.28

Recommended Reserve (S \$) : 14,803.34

Estimated Normal Period of Repairs : 14 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

Vehicle No : SLR 8098 D Honda Vezel (A)

TP/0035/18

Workshop : Reliable Carz

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist. %	Our Recommendation (S S)	Dist. %
To Supply :					
1pc. Tailgate	Dented	1,334.62		✓ 1,334.62	CRAV 20
1pc. Tailgate windscreen glass rubber moulding	Necessary	155.60		✓ 155.60	NECV 20
1pc. Tailgate windscreen glass	Shattered	1,178.50		✓ 1,178.50	BRV 20
1pc. Tailgate windscreen glass wiper motor	Bent / Malfunction	244.56		✓ 244.56	BT 20
1pc. Tailgate windscreen glass wiper blade	Broken / Dislodged / Missing	76.50		✓ 76.50	MISV 20
1pc. Tailgate windscreen glass wiper arm	Broken / Dislodged / Missing	76.60		✓ 76.60	MISV 20
1pc. Tailgate windscreen glass wiper arm cover	Broken / Dislodged / Missing	15.30		✓ 15.30	MISV 20
1pc. Tailgate outer garnish	Dented / Cracked	289.80		✓ 289.80	CRAV 20
1pc. Tailgate centre emblem	Necessary	47.70		✓ 47.70	NECV 20
1pc. Tailgate 'Vezel' emblem	Necessary	48.52		✓ 48.52	NECV 20
1pc. Tailgate lock	Bent / Malfunction	280.42		✓ 280.42	BT 20
1pc. Tailgate lock catch	Bent / Malfunction	30.20		✓ 30.20	BT 20
1pc. Tailgate inner trim board	Cracked	233.40		✓ 233.40	CRAV 20
1pc. Tailgate inner side RH garnish	Deformed	60.90		✓ 60.90	DISV 20
1pc. Tailgate inner side LH garnish	Deformed	60.90		✓ 60.90	DISV 20
1pc. Tailgate inner upper garnish	Deformed / Cut	78.10		✓ 78.10	DISV 20
1pc. Tailgate RH lamp	Broken	528.70		✓ 528.70	BRV 20
1pc. Tailgate LH lamp	Broken	528.70		✓ 528.70	BRV 20
1pc. Tailgate RH number plate lamp	Cracked	68.10		✓ 68.10	CRAV 20
1pc. Tailgate LH number plate lamp	Cracked	68.10		✓ 68.10	CRAV 20
1pc. Tailgate RH absorber stay	Bent	192.10		192.10	SVEX 20
1pc. Tailgate LH absorber stay	Bent	192.10		192.10	SVEX 20
1pc. Tailgate RH hinge	Serviceable	55.20		--	20
1pc. Tailgate LH hinge	Serviceable	55.20		--	20
1pc. Tailgate spoiler with third brake lamp	Loop Cracked	756.30		594.50 756.30	20
1pc. Tailgate weatherstrip	Bent	196.80		135.00 196.80	CUTV 20
1pc. Tailgate open handle sensor	Malfunction	255.40		255.40	CUTV 20
1pc. Tailgate reverse camera	Defaced / Malfunction	1,136.90	250.00	680.00 1,136.90	CUTV 20
1pc. Rear RH side bumper	Dented / Deformed	175.10		✓ 175.10	CRAV 20
1pc. Rear RH side bumper retainer	Cracked	51.50		✓ 51.50	CRAV 20
1pc. Rear LH side bumper	Dented / Deformed	175.10		✓ 175.10	CRAV 20
1pc. Rear LH side bumper retainer	Cracked	51.50		✓ 51.50	CRAV 20
1pc. Rear centre bumper	Dented	508.50		✓ 508.50	DISV 20
1pc. Rear centre bumper RH reflector	Cracked	151.80		✓ 151.80	DT 20
1pc. Rear centre bumper LH reflector	Cracked	151.80		151.80	NNX 20
1pc. RH tail-lamp	Cracked	428.70		✓ 428.70	CRAV 20
1pc. RH tail-lamp panel	Dented / Repair	175.30		--	20
1pc. LH tail-lamp	Broken	428.70		✓ 428.70	CRAV 20

Vehicle No : SLR 8098 D Honda Vezel (A)

TP/0035/18

Workshop : Reliable Carz

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
1pc. LH tail-lamp panel	Dented / Repair	175.30		--	20
1pc. End panel	Dented	566.70		✓ 566.70	DIS ✓ 20
1pc. End panel inner garnish	Deformed	251.30		✓ 251.30	CUT ✓ 20
1pc. Rear keyless sensor	Malfunction	94.80		✓ 94.80	CUT ✓ 20
1pc. Rear compartment panel top board	Dented / Bent	422.90		422.90	NNX 20
1pc. Rear compartment panel	Dented / Repair	752.50		--	20
1pc. Rear compartment panel insulator	Necessary	80.80		✓ 80.80	NEC ✓ 20
1pc. Rear compartment panel luggage tray	Broken	226.40		✓ 226.40	BR ✓ 20
1pc. Rear compartment panel air duct	Dented	195.40		✓ 195.40	DD ✓ 20
1pc. Rear RH fender	Dented / Repair	602.50		--	20
1pc. Rear RH fender inner trim board	Deformed	239.50		239.50	NNX 20
1pc. Rear RH fender wheel arch moulding	Cracked	167.80		✓ 167.80	CUT ✓ 20
1pc. Rear LH fender inner trim board	Deformed	239.50		195.00 239.50	DIS ✓ 20
1pc. Rear LH fender wheel arch moulding	Cracked	167.80		✓ 167.80	CUT ✓ 20
1pc. Exhaust silencer	Bent / Repair	700.20		--	20
Sub-Total :-		15,426.62		10803.78 12,910.42	
Total Discount :-		--		2160.76 2,582.08	
		15,426.62		8643.02 10,328.34	
Special Nett Items :-					
1pc. Rear number plate	Dented	70.00		✓ 35.00	NNX
1pc. Rear view camera	Dented / Malfunction	500.00		380.00	NNX
1pc. Rear compartment rubber tray	Refit	180.00		--	
Total For Parts :-		16,176.62		8678.02 10,743.34	
Labour Charges :					
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re position & re-align, replacement of parts to the original position including adjustment.		1,900.00		1,200.00 1,600.00	
Spray undercoating on the repaired & replaced panels.		150.00		60.00 80.00	
Replace tailgate windscreen glass & sealants.		220.00		120.00	

Vehicle No : SLR 8098 D Honda Vezel (A)
Workshop : Reliable Carz

TP/0035/18

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
Transfer & replace tailgate inner mechanism to new tailgate.		180.00		60.00 100.00	✓
Remove, re-install & replace rear inner trims, garnishes, seats & boards to assist repairs.		350.00		30.00 240.00	✓
Remove, replace & re-adjust rear bumper reverse sensor & wire harness.		80.00		50.00	✓
Remove, replace & re-adjust tailgate reverse camera & view camera.		180.00		80.00 120.00	✓
Remove, re-install & repair exhaust silencer & rubber hangers.		120.00		50.00 80.00	✓
Apply sealant on repaired & replaced panels.		200.00		60.00 120.00	✓
Spray Painting :					
To putty & spray repaired & replaced body panels (pearl colour).		1,850.00		1,000.00 1,500.00	✓
Towing Charges :					
Towing fee.		50.00		50.00	NNX
Grand Total :-		21,456.62		14,803.34	

11508.02

Surveyed By : Lawrence Ng

L/S 9200/2
Repair days 12 days


20/7/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	27 Mar 2018		28 Mar 2018 10:11 Edit Adj Rpt	S\$8,800.00 Edit Estimates	S\$8,800.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH CORPORATION PTE LTD, Co. Reg. No.: 198502202Z		
Main Claimant:	RELIABLE RIDES PTE LTD, Co. Reg. No.: 201611527N		
Vehicle Reg. No.:	SLR8098D	Date of Loss:	26/03/2018 15:00 - :59 [6 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 553599	Policy/Cover Note No.:	B28636251MKC (Comprehensive) Coverage: 02/11/2017 - 01/11/2018
Vehicle Reg. No. (Insured):	XE1120U	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/07/2018]		
Driver/Custodian (Insured):	NIU JIAPU (), NRIC: G8393093X, Tel: +6585757329		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (11/07/2018): Report Send Back Alerts - SLR8098D (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR8098D (553599)**
[XE1120U]
TP
RELIABLE RIDES PTE LTD
Mar 26 2018 3:00PM
[SAMWOH CORPORATION PTE LTD]
Reliable Carz Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/18 16:07	Accident Statement From: SC - Reg. No: XE1120U, Claimant: SAMWOH CORPORATION PTE LTD	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 17:03	General View	Load JPG	☒
2	27/04/18 17:03	General View	Load JPG	☒
3	27/04/18 17:03	General View	Load JPG	☒
4	27/04/18 17:03	General View	Load JPG	☒
5	27/04/18 17:03	General View	Load JPG	☒
6	27/04/18 17:03	General View	Load JPG	☒
7	27/04/18 17:03	General View	Load JPG	☒
8	27/04/18 17:03	General View	Load JPG	☒
9	27/04/18 17:03	General View	Load JPG	☒
10	27/04/18 17:03	General View	Load JPG	☒
11	27/04/18 17:03	General View	Load JPG	☒
12	27/04/18 17:03	General View	Load JPG	☒
13	27/04/18 17:03	General View	Load JPG	☒
14	27/04/18 17:03	General View	Load JPG	☒
15	27/04/18 17:03	General View	Load JPG	☒
16	27/04/18 17:03	General View	Load JPG	☒
17	27/04/18 17:03	General View	Load JPG	☒
18	27/04/18 17:03	General View	Load JPG	☒
19	27/04/18 17:03	General View	Load JPG	☒
20	27/04/18 17:03	General View	Load JPG	☒
21	27/04/18 17:03	General View	Load JPG	☒
22	27/04/18 17:03	General View	Load JPG	☒
23	27/04/18 17:03	General View	Load JPG	☒
24	27/04/18 17:03	General View	Load JPG	☒
25	27/04/18 17:03	General View	Load JPG	☒
26	27/04/18 17:03	General View	Load JPG	☒
27	27/04/18 17:03	General View	Load JPG	☒
28	27/04/18 17:03	General View	Load JPG	☒
29	27/04/18 17:03	General View	Load JPG	☒
30	27/04/18 17:03	General View	Load JPG	☒
31	27/04/18 17:03	General View	Load JPG	☒

Assessment Reports					
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
32	27/04/18 17:03	General View		Load JPG	
33	27/04/18 17:03	General View		Load JPG	
34	27/04/18 17:03	General View		Load JPG	
35	27/04/18 17:03	General View		Load JPG	
36	27/04/18 17:03	General View		Load JPG	
37	27/04/18 17:03	General View		Load JPG	
38	27/04/18 17:03	General View		Load JPG	
39	27/04/18 17:03	General View		Load JPG	
40	27/04/18 17:03	General View		Load JPG	
41	27/04/18 17:03	General View		Load JPG	
42	27/04/18 17:03	General View		Load JPG	
43	27/04/18 17:03	General View		Load JPG	
44	27/04/18 17:03	General View		Load JPG	
45	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
46	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
47	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
48	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
49	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
50	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
51	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
52	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
53	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
54	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
55	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
56	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
57	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
58	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
59	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
60	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
61	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
62	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
63	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
64	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
65	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
66	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
67	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
68	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
69	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
70	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
71	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
72	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
73	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
74	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
75	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
76	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
77	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
78	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	
79	27/04/18 17:04	Photographs of Damaged Parts		Load JPG	

Assessment Reports				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
81	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
82	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
83	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
84	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
85	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
86	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
87	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
88	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
89	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
90	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
91	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
92	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
93	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
94	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
95	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
96	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
97	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
98	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
99	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
100	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
101	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
102	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
103	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
104	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
105	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
106	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
107	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
108	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
109	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
110	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
111	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
112	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
113	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
114	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
115	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
116	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
117	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
118	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
119	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
120	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	
121	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	
122	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	
123	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	
124	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	
125	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	
126	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	
127	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	

Assessment Reports				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
128	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
129	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
130	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
131	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
132	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
133	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
134	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
135	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
136	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
137	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
138	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
139	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
140	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
141	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
142	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	☒
143	27/04/18 17:04	Photo After Spray	 Load JPG	☒
144	27/04/18 17:04	Photo After Spray	 Load JPG	☒
145	27/04/18 17:04	Photo After Spray	 Load JPG	☒
146	27/04/18 17:04	Photo After Spray	 Load JPG	☒
147	27/04/18 17:04	Photo After Spray	 Load JPG	☒
148	27/04/18 17:04	Photo After Spray	 Load JPG	☒
149	27/04/18 17:04	Photo After Spray	 Load JPG	☒
150	27/04/18 17:04	Photo After Spray	 Load JPG	☒
151	27/04/18 17:04	Photo After Spray	 Load JPG	☒
152	27/04/18 17:04	Photo After Spray	 Load JPG	☒
153	27/04/18 17:04	Photo After Spray	 Load JPG	☒
154	27/04/18 17:04	Photo After Spray	 Load JPG	☒
155	27/04/18 17:04	Photo After Spray	 Load JPG	☒
156	27/04/18 17:04	Photo After Spray	 Load JPG	☒
157	27/04/18 17:04	Photo After Spray	 Load JPG	☒
158	27/04/18 17:04	Photo After Spray	 Load JPG	☒
159	27/04/18 17:04	Photo After Spray	 Load JPG	☒
160	27/04/18 17:04	Photo After Spray	 Load JPG	☒
161	27/04/18 17:04	Photo After Spray	 Load JPG	☒
162	27/04/18 17:04	Photo After Spray	 Load JPG	☒
163	27/04/18 17:04	Photo After Spray	 Load JPG	☒

Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/18 16:07	TPD SLR8098D GIA REPORT	 Load PDF	
2	28/03/18 10:06	WORKSHOP DETAIL- SLR8098D.	 Load PDF	
3	09/06/18 17:37	PRIORITY SEVRICES REPORT & BREAKDOWN - SLR8098D.pdf	 Load PDF	
4	09/06/18 17:37	TP SURVYOR PHOTO 1 - SLR8098D.pdf	 Load PDF	
5	09/06/18 17:37	TP SURVYOR PHOTO 2 - SLR8098D.pdf	 Load PDF	
6	09/06/18 17:38	TP SURVYOR PHOTO 3 - SLR8098D.pdf	 Load PDF	
7	09/06/18 17:38	TP SURVYOR PHOTO 4 - SLR8098D.pdf	 Load PDF	
8	09/06/18 17:38	TP SURVYOR PHOTO 5 - SLR8098D.pdf	 Load PDF	
9	09/06/18 17:38	TP SURVYOR PHOTO 6 - SLR8098D.pdf	 Load PDF	
10	09/06/18 17:38	TP SURVYOR PHOTO 7 - SLR8098D.pdf	 Load PDF	
11	09/06/18 17:38	TP SURVYOR PHOTO 8 - SLR8098D.pdf	 Load PDF	
12	09/06/18 17:38	TP SURVYOR PHOTO 9 - SLR8098D.pdf	 Load PDF	

Assessment Reports				☒
No	Finalized On			
MSIG Insurance (Singapore) Pte. Ltd, (HQ)				
13	09/06/18 17:38	TP SURVYOR PHOTO 10 - SLR8098D.pdf		Load PDF
14	09/06/18 17:39	TP SURVYOR PHOTO 11 - SLR8098D.pdf		Load PDF
15	09/06/18 17:39	TP SURVYOR PHOTO 12 - SLR8098D.pdf		Load PDF
LKK Auto Consultants Pte Ltd (HQ)				
No	Relabel/Reorder		Thumbnail	Print
1	27/07/18 08:52	PRS INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005727/BVD3S2-1
Date: 27/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28636251MKC

Claimant Vehicle No : SLR8098D

Insured Vehicle No : XE1120U

Date of Loss: 26/03/2018

Nature of Claim: TP

Claim No: 553599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8098D

Make & Model: HONDA VEZEL, 1.5 X A (A)

Engine No: LEB5946773

Reg. Date: 29/08/2017 (Man. Year: 2017)

Chassis No: RU31246756

Colour: Silver

Odometer: 52156 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,176.62	8,262.58	7,914.04	48.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	2,760.00	2,520.00	47.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,456.62	11,022.58	10,434.04	48.63
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	21,456.62	8,800.00	12,656.62	58.99

INSPECTION

Date of Assignment: 28/03/2018

Date Inspected: 28/03/2018

Inspected At:

Reliable Carz Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #05-50
Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2018)

Parts: M1-SUV HONDA VEZEL 1.5 X A (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR8098D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Crushed	1,334.62 F	*1,100.00 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	155.60 F	*155.60 FL
3	1		*TAILGATE WINDSCREEN GLASS	Broken	1,178.50 F	*1,178.50 FL
4	1		*TAILGATE WINDSCREEN GLASS WIPER MOTOR	Bent	244.56 F	*244.56 FL
5	1		*TAILGATE WINDSCREEN GLASS WIPER BLADE	Missing	76.50 F	*76.50 FL
6	1		*TAILGATE WINDSCREEN GLASS WIPER ARM	Missing	76.60 F	*76.60 FL
7	1		*TAILGATE WINDSCREEN GLASS WIPER ARM COVER	Missing	15.30 F	*15.30 FL
8	1		*TAILGATE OUTER GARNISH	Cracked	289.80 F	*289.80 FL
9	1		*TAILGATE CENTRE EMBLEM	Necessary	47.70 F	*47.70 FL
10	1		*TAILGATE VEZEL EMBLEM	Necessary	48.52 F	*48.52 FL
11	1		*TAILGATE LOCK	Bent	280.42 F	*180.00 FL
12	1		*TAILGATE LOCK CATCH	Bent	30.20 F	*30.20 FL
13	1		*TAILGATE INNER TRIM BOARD	Cracked	233.40 F	*233.40 FL
14	1		*TAILGATE INNER SIDE RH GARNISH	Distorted	60.90 F	*60.90 FL
15	1		*TAILGATE INNER SIDE LH GARNISH	Distorted	60.90 F	*60.90 FL
16	1		*TAILGATE INNER UPPER GARNISH	Distorted	78.10 F	*78.10 FL
17	1		*TAILGATE RH LAMP	Broken	528.70 F	*528.70 FL
18	1		*TAILGATE LH LAMP	Broken	528.70 F	*528.70 FL
19	1		*TAILGATE RH NUMBER PLATE LAMP	Cracked	68.10 F	*68.10 FL
20	1		*TAILGATE LH NUMBER PLATE LAMP	Cracked	68.10 F	*68.10 FL
21	1		*TAILGATE RH ABSORBER STAY	Serviceable	192.10 F	*- FL
22	1		*TAILGATE LH ABSORBER STAY	Serviceable	192.10 F	*- FL
23	1		*TAILGATE RH HINGE	Serviceable	55.20 F	*- FL
24	1		*TAILGATE LH HINGE	Serviceable	55.20 F	*- FL
25	1		*TAILGATE SPOILER WITH THIRD BRAKE LAMP	Loop Cracked	756.30 F	*594.50 FL
26	1		*TAILGATE WEATHERSTRIP	Cut	196.80 F	*135.00 FL
27	1		*TAILGATE OPEN HANDLE SENSOR	Cut	255.40 F	*255.40 FL
28	1		*REAR RH SIDE BUMPER	Cracked	175.10 F	*175.10 FL
29	1		*REAR RH SIDE BUMPER RETAINER	Cracked	51.50 F	*51.50 FL
30	1		*REAR LH SIDE BUMPER	Cracked	175.10 F	*175.10 FL
31	1		*REAR LH SIDE BUMPER RETAINER	Cracked	51.50 F	*51.50 FL
32	1		*REAR CENTRE BUMPER	Distorted	508.50 F	*508.50 FL
33	1		*REAR CENTRE BUMPER RH REFLECTOR	Dented	151.80 F	*151.80 FL
34	1		*REAR CENTRE BUMPER LH REFLECTOR	Not Necessary	151.80 F	*- FL
35	1		*RH TAIL-LAMP	Cracked	428.70 F	*428.70 FL
36	1		*RH TAIL-LAMP PANEL	Repair	175.30 F	*- FL
37	1		*LH TAIL-LAMP	Cracked	428.70 F	*428.70 FL
38	1		*LH TAIL-LAMP PANEL	Repair	175.30 F	*- FL
39	1		*END PANEL	Distorted	566.70 F	*566.70 FL
40	1		*END PANEL INNER GARNISH	Cut	251.30 F	*251.30 FL
41	1		*REAR KEYLESS SENSOR	Cut	94.80 F	*94.80 FL
42	1		*REAR COMPARTMENT PANEL TOP BOARD	Not Necessary	422.90 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR COMPARTMENT PANEL	Repair	752.50 F	*- FL
44	1		*REAR COMPARTMENT PANEL INSULATOR	Necessary	80.80 F	*80.80 FL
45	1		*REAR COMPARTMENT PANEL LUGGAGE TRAY	Broken	226.40 F	*226.40 FL
46	1		*REAR COMPARTMENT PANEL AIR DUCT	Dented	195.40 F	*195.40 FL
47	1		*REAR RH FENDER	Repair	602.50 F	*- FL
48	1		*REAR RH FENDER INNER TRIM BOARD	Not Necessary	239.50 F	*- FL
49	1		*REAR RH FENDER WHEEL ARCH MOULDING	Cut	167.80 F	*167.80 FL
50	1		*REAR LH FENDER INNER TRIM BOARD	Distorted	239.50 F	*195.00 FL
51	1		*REAR LH FENDER WHEEL ARCH MOULDING	Cut	167.80 F	*167.80 FL
52	1		*EXHAUST SILENCER	Repair	700.20 F	*- FL
53	1		*TAILGATE REVERSE CAMERA	Cut	1,136.90 FS	*250.00 FS
54	1		*REAR NUMBER PLATE	Dented	70.00 FS	*35.00 FS
55	1		*REAR VIEW CAMERA	Not Necessary	500.00 FS	*- FS
56	1		*REAR COMPARTMENT RUBBER TRAY	Refit	180.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	16,176.62	10,256.98
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,994.40
Total Parts (S\$)	16,176.62	8,262.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT.	New	1,900.00	1,200.00
2	SPRAY UNDERCOATING ON THE REPAIRED & REPLACED PANELS.	New	150.00	60.00
3	REPLACE TAILGATE WINDSCREEN GLASS & SEALANTS.	New	220.00	120.00
4	TRANSFER & REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE.	New	180.00	60.00
5	REMOVE, RE-INSTALL & REPLACE REAR INNER TRIMS, GARNISHES, SEATS & BOARDS TO ASSIST REPAIRS.	New	350.00	80.00
6	REMOVE, REPLACE & RE-ADJUST REAR BUMPER REVERSE SENSOR & WIRE HARNESS.	New	80.00	50.00
7	REMOVE, REPLACE & RE-ADJUST TAILGATE REVERSE CAMERA & VIEW CAMERA.	New	180.00	80.00
8	REMOVE, RE-INSTALL & REPAIR EXHAUST SILENCER & RUBBER HANGERS.	New	120.00	50.00
9	APPLY SEALANT ON REPAIRED & REPLACED PANELS.	New	200.00	60.00
10	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS (PEARL COLOUR).	New	1,850.00	1,000.00
11	TOWING FEE.	New	50.00	0.00
Gross Labour Cost (S\$)			5,280.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >