

ASS. REC. BY:

REF:

CS/CTI18012758/ Krd3ⁿ²

Special Instruction:

Supervisor:
Munnen

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

13/7/18 @ 11:29am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBC 1594G

Insured:

GY 6706T

at Workshop m/s

Ah Lim Motor

Tel:

6483 1244

of 10 Amk Ind. Park 2A #01-09

Policy No: DMCVSN1422301703

Claim No: SNM18D03292C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

16072018 @ 11am owner waiting

H.O.D. Endorsement:

Date/Time: 11:29am @ 13/7/18

Person Contacted:

Zila

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	GBC 1594G - X
	GY 6706T - X
15/7	L1 Lm 8440d email confirmed with Muh hong. Red: \$8985.02, 67%.)

(08/11/13) wef

REF: CTS

ASS. REC. BY:

ASSIGNMENT

From: Date: 16/7/18

Estimated Cost:

ON ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: GBC 1594C

at Workshop m/s Ah Lim Motor

of 10 AMK Ind. park 2A # 01-09

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: S 23K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBC 1594C Yr Regn: 06, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Urban c.c. 2953

Colour: White / Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 239142 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN14642 2520795481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: B.S. 195R15XJ

R: Rm

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 6 mm

L/Bal. 9 mm

L/Bal. 6 mm

D.O.A. 11/7/18

D.O.I. 16/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/7 File per 12h Carport

RECEIVED 20 NOV 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / L.B. (\$) 4400

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHIEF	INSURANCE (S) PTE LTD	Ref :	CS/CTI18012758/Krd3
3 ANSC	#16-00	Date :	13-07-2018
SPRING	OWERSINGAPORE 079909	Code :	CTI
			
1.	Policy Particulars :- THIRD PARTY CLAIM		
	GY 6706T	Veh. Inspected	GBC 1594C
	DMCVSN1422301703	Coverage (\$)	0.00
	HM18D03292C02	Excess (\$)	0.00
	MERIMEN (IRENE TAY)	Assign Date	13/07/2018
2.	Vehicle Particulars & Condition		
		c.c	0
	MODEN	Year of Reg.	
		Colour	
		Steering	
		Modification	
3.	Conditions of Tyres		
	Size	Make	Balance
			mm
			mm
			mm
			mm
4.	Description of Damages		
General Information			
	07/2018	Inspection Date	16/07/2018
CLIM MOTOR CO			
10 ANG MO KIO IND PK 2A			
-09 AMK AUTOPOINT			
SINGAPORE 568047			
Remarks			
AS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jul 2018		13 Jul 2018 11:29 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM YEOW KIAT, ID: S0092671Z		
Main Claimant:	GAIN CITY ENGINEERING (M & E) PTE LTD, Co. Reg. No.: 199602238M		
Vehicle Reg. No.:	GBC1594C	Date of Loss:	01/07/2018 15:00 - :59
Claim Type:	TP / SNM18D03292C02	Policy/Cover Note No.:	DMCVSN1422301703 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GY6706T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/07/2018]		
Adj Asg. Remarks:	EST \$14,321.97, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Janice Lee (LKKAUTO)

From: muihong@ahlimmotor.com.sg
Sent: Tuesday, November 20, 2018 2:30 PM
To: Janice Lee (LKKAUTO)
Subject: Fw: PHOTO FOR VEHICLE GBC1594G

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: muihong@ahlimmotor.com.sg
Sent: Friday, November 16, 2018 1:36 PM
To: [Kenneth Kong \(LKKAUTO\)](#)
Subject: Re: PHOTO FOR VEHICLE GBC1594G

Dear Kenneth,

We will have to accept the earlier finalisation amount of \$4,400 and will submit as such

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: [Kenneth Kong \(LKKAUTO\)](#)
Sent: Friday, November 16, 2018 8:30 AM
To: muihong@ahlimmotor.com.sg
Subject: RE: PHOTO FOR VEHICLE GBC1594G

The damaged to the tailgate is only at the lower portion, why have to change the absorber? It is likely due to wear and tear due to the age of the van.

From: muihong@ahlimmotor.com.sg [<mailto:muihong@ahlimmotor.com.sg>]
Sent: Thursday, 15 November, 2018 2:16 PM
To: [Kenneth Kong \(LKKAUTO\)](#)
Subject: Fw: PHOTO FOR VEHICLE GBC1594G

Resend the photos and supplier inv on rear gate absorber.

Pls review

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: Eileen Chua
Sent: Saturday, September 8, 2018 11:53 AM
To: LKK - Kenneth Kong
Subject: PHOTO FOR VEHICLE GBC1594G

Hi Kenneth,

Please see attached photo as request.

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	2238M

Vehicle Details

Vehicle No.:	GBC1594G
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	URVAN 3.0 5MT ABS AB 5DR LWB PANEL
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	ZD30280645K
Chassis No.:	JN1MG4E25Z0795481
Maximum Power Output:	-
Open Market Value:	\$29,184.00
Original Registration Date:	13 Jun 2011
First Registration Date:	13 Jun 2011
Transfer Count:	0
Actual ARF Paid:	\$1,460.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	12 Jun 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$21,889.00
COE Rebate Amount:	\$6,402.00
Total Rebate Amount:	\$6,402.00

The information contained herein is correct as at 09 Jul 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **G8115647L**

Name: **YANG LILIANG**

Birth Date: **22 May 1988**

Issue Date: **27 Dec 2013**

Valid Till: **26 Dec 2018**

1002260003D



S PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
GAIN CITY BEST-ELECTRIC PTE LTD

Sector: **SERVICE**

Name:
YANG LILIANG


Occupation:
TECHNICAL SPECIALIST

S Pass No.: **D 57876648**

Date of Application: **31-07-2017**

Date of Issue: **07-09-2017**

Date of Expiry: **07-09-2019**



L8289529

HP: 82968524

Phone: 6460 1734

After Raining / wet floor bi Ji hang

No injury

No video

2 pax -

1/4 和 航 (M).

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg **27 Dec 2013**



Licence No: G8115647L

NP 428A

VISIT PASS
Immigration Regulations

Name:
YANG LILIANG



Date of Birth: **22-05-1988** Sex: **M** Nationality: **CHINESE**

FIN: **G8115647L** Date of Issue: **07-09-2017** Date of Expiry: **07-09-2019**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



Email: Remates @ gaincity.com.

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg No.: M2-0000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine Group



TOKIO MARINE
INSURANCE GROUP

FORM MZ300

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 18-MJ000058-R00 (Comm Vehicle Carry Own Goods)

1. **Index Mark and Registration Number of Vehicle** GBC1594G **Chassis No.:** JN1MG4E25Z0795481
2. **Name of Policyholder** GAIN CITY ENGINEERING (M & E) PTE LTD
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 07/01/2018 *1996 022 38 01*
4. **Date of Expiry of Insurance** 06/01/2019
5. **Persons or Class of Persons entitled to drive***
Any person who is driving on the policyholder's order or with their permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

- 1) Use in connection with the policyholder's business.
- 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholders' business.
- 3) Use for social domestic and pleasure purposes.

The policy does not cover:-

- 1) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 1613DDA

Insurance Plan:	Comprehensive Approved Workshop Plan
Limit for total loss or theft:	Prevailing Market Value
Policy Excess:	Own Damage Claims SGD 600
	Windscreen Excess SGD 100
Financial Interest:	SING INVESTMENTS & FINANCE LTD

Tokio Marine Insurance Singapore Ltd.

Authorised Signature



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GAIN CITY ENGINEERING (M&E) PTE LTD
8 ANG MO KIO INDUSTRIAL PARK 2

Estimate No: MC0913250
Date: 09 Jul 2018
Policy No: MJ000058
Veh Reg No: GBC1594G
Make/Model: NISSAN URVAN 3.0 5MT

SINGAPORE 569500
TEL: 64101754

ATTN:

Your Ref No: -

Claim Type: Third Party

Accident Date: 01/07/2018

TP Veh Reg No: GY6706T

Not Authorized
11 Aug 8 4400h
Recovery After Repair
5 days

Estimate Repair Cost to Vehicle No :GBC1594G

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR WINDSCREEN WITH MOULDING	1 PC	<i>Sm</i> 1,564.00	X
2 TAILGATE	1 PC	<i>B</i> 2,016.30	✓
3 TAILGATE HINGE X2	2 PC	<i>R</i> 143.60	X
4 TAILGATE ABSORBER X2	2 PC	<i>Sm</i> 554.20	X
5 TAILGATE RUBBER (AT BODY)	1 PC	<i>Sm</i> 180.80	X
6 TAILGATE NUMBER PLATE GARNISH CENTRE	1 PC	<i>Red</i> <i>Per</i> 466.30	✓
7 TAILGATE NUMBER PLATE LAMP X2	2 PC	<i>Sm</i> 176.80	X
8 TAILGATE EMBLEM	1 PC	<i>R</i> 59.70	✓
9 TAILGATE INNER TRIM BOARD	1 PC	<i>Sm</i> 252.50	X
10 TAILGATE INNER LOCK	1 PC	<i>Sm</i> 554.50	✓
11 TAILGATE INNER LOCK OUTER COVER	1 PC	<i>Red</i> 56.50	✓
12 TAILAMP LH & RH	2 PC	<i>Sm</i> 661.60	X
13 TAILAMP CLIPS LH & RH	6 PC	<i>in</i> 44.40	X
14 TAILAMP PANEL X2	2 PC	<i>R</i> 693.00	X
15 REAR BUMPER WITH CENTRE STEP GARNISH BLACK	1 PC	<i>B</i> 760.60	✓
16 REAR BUMPER SIDE RETAINERS X 2 - CHECK PRICE	2 PC	<i>Sm</i> 0.00	X
17 REAR BUMPER CLIPS X12	12 PC	<i>in</i> 52.80	✓
18 REAR BUMPER REINFORCEMENT	1 PC	<i>R</i> 269.90	X
19 END PANEL INNER	1 PC	<i>R</i> 553.00	X
20 END PANEL TOP CENTRE ALUMINIUM PLATE	1 PC	<i>Sm</i> 105.30	X
		9,165.80	
	Less 10%	916.58	8,249.22
21 TAILGATE WIPER MOTOR	1 PC	<i>Sm</i> 568.10	X
22 TAILGATE WIPER BLADE	1 PC	<i>Sm</i> 35.70	X
23 TAILGATE WIPER BLADE ARM	1 PC	<i>Sm</i> 89.60	X
24 END PANEL OUTER	1 PC	<i>R</i> 292.40	X
		985.80	985.80
Special Nett			
25 REAR NUMBER PLATE (YELLOW)	1 PC	<i>Sm</i> 35.00	X
26 REAR REVERSE SENSOR	2 PC	<i>Sm</i> 200.00	✓
27 REAR WINDSCREEN INNER SEAL	1 PC	<i>Red</i> 60.00	3050
28 REAR WINDSCREEN SEALANT	1 PC	<i>Red</i> 60.00	4050
29 REAR (70KM/H) STICKER	1 PC	<i>Red</i> 25.00	1550
30 REAR COMPANY STICKER (GAIN CITY)	1 PC	<i>Red</i> 280.00	15050
		660.00	660.00

LABOUR



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : GAIN CITY ENGINEERING (M&E) PTE LTD
8 ANG MO KIO INDUSTRIAL PARK 2

SINGAPORE 569500

TEL: 64101754

ATTN:

Your Ref No: -

Claim Type: Third Party

Accident Date: 01/07/2018

TP Veh Reg No: GY6706T

Estimate No: MC0913250

Date: 09 Jul 2018

Policy No: MJ000058

Veh Reg No: GBC1594G

Make/Model: NISSAN URVAN 3.0 5MT

Estimate Repair Cost to Vehicle No :GBC1594G

Description	Quantity	List Price		Amount	
		SS		SS	
31 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/		
32 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	nn	x	
33 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	150.00		120	
34 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	280.00		60	
35 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	80.00	nn	x	
36 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	nn	x	
37 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00		50	
38 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	180.00		60	
39 TO REALIGN, DISMANTLE AND REINSTALL EXHAUST PIPE, EXHAUST BOX.	1 PC	120.00	nn	x	
40 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL INNER,OUTTER,TAILLAMP PANEL X 2,REAR BUMPER REINFORCEMENT. TO KNOCK & REPAIR SPARE TYRE PANEL,REAR FENDER LH & RH, REAR CHASSIS SIDE PANEL, CHASSIS FRAME	1 PC	1,200.00		600	
41 TO SPRAY TAILGATE,REAR BUMPER,REAR BUMPER REINFORCEMENT,TAILLAMP PANEL LH & RH, END PANEL INNER & OUTTER, SPARE TYRE PANEL. REAR FENDER LH & RH, REAR CHASSIS SIDE PANEL, CHASSIS FRAME	1 PC	1,200.00		600	
		3,490.00		3,490.00	

Total SS 13,385.02

Add GST @ 7% 936.95

Total Amount Payable SS 14,321.97

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND THREE HUNDRED TWENTY ONE AND CENTS NINETY SEVEN ONLY

Please arrange this vehicle to be surveyed **soonest** possible.
Thank You

Insurance Consultants hence notify the Repairer of the following:

- To resurvey before/after repairs
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012758/KRD3N2

Date: 28/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1422301703
Claimant Vehicle No :	GBC1594G	Insured Vehicle No :	GY6706T
Date of Loss:	01/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03292C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC1594G	Engine No:	ZD30280645K
Make & Model:	NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)	Chassis No:	JN1MG4E25Z0795481
Reg. Date:	13/06/2011 (Man. Year: 2011)	Odometer:	239142 km
Colour:	White/Yellow		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Sumitomo 6 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,895.02	4,005.03	5,889.99	59.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,505.00	1,985.00	56.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,385.02	5,510.03	7,874.99	58.83
Approved Total (Overridden) (\$\$)		4,400.00		
(\$\$)	13,385.02	4,400.00	8,985.02	67.13
+ GST 7.00/7.00% (\$\$)	936.95	308.00	628.95	67.13
Nett Amount (\$\$)	14,321.97	4,708.00	9,613.97	67.13

INSPECTION

Date of Assignment: 13/07/2018

Date Inspected: 16/07/2018 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Nov 2018)	
Parts:	N/A	NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC1594G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN WITH MOULDING	Serviceable	1,564.00 FL	*- FL
2	1		*TAILGATE	Bent	2,016.30 FL	*2,016.30 FL
3	2		*TAILGATE HINGE	Repair	143.60 FL	*- FL
4	2		*TAILGATE ABSORBER	Serviceable	554.20 FL	*- FL
5	1		*TAILGATE RUBBER (AT BODY)	Serviceable	180.80 FL	*- FL
6	1		*TAILGATE NUMBER PLATE GARNISH CENTRE	Dented/Scratched	466.30 FL	*466.30 FL
7	2		*TAILGATE NUMBER PLATE LAMP	Serviceable	176.80 FL	*- FL
8	1		*TAILGATE EMBLEM	Necessary	59.70 FL	*59.70 FL
9	1		*TAILGATE INNER TRIM BOARD	Serviceable	252.50 FL	*- FL
10	1		*TAILGATE INNER LOCK	Jammed	554.50 FL	*554.50 FL
11	1		*TAILGATE INNER LOCK OUTER COVER	Dented	56.50 FL	*56.50 FL
12	2		*TAILLAMP LH & RH	Serviceable	661.60 FL	*- FL
13	6		*TAILLAMP CLIPS LH & RH	Not Necessary	44.40 FL	*- FL
14	2		*TAILLAMP PANEL	Repair	693.00 FL	*- FL
15	1		*REAR BUMPER WITH CENTRE STEP GARNISH BLACK	Bent	760.60 FL	*760.60 FL
16	2		*REAR BUMPER SIDE RETAINERS (NPA)	Serviceable	0.00 FL	*- FL
17	12		*REAR BUMPER CLIPS	Necessary	52.80 FL	*52.80 FL
18	1		*REAR BUMPER REINFORCEMENT	Repair	269.90 FL	*- FL
19	1		*END PANEL INNER	Repair	553.00 FL	*- FL
20	1		*END PANEL TOP CENTRE ALUMINIUM PLATE	Serviceable	105.30 FL	*- FL
21	1		*TAILGATE WIPER MOTOR	Serviceable	568.10 FS	*- FS
22	1		*TAILGATE WIPER BLADE	Serviceable	35.70 FS	*- FS
23	1		*TAILGATE WIPER BLADE ARM	Serviceable	89.60 FS	*- FS
24	1		*END PANEL OUTER	Repair	292.40 FS	*- FS
25	1		*REAR NUMBER PLATE (YELLOW)	Serviceable	35.00 FS	*- FS
26	2		*REAR REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
27	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
29	1		*REAR (70KM/H) STICKER	Necessary	25.00 FS	*15.00 FS
30	1		*REAR COMPANY STICKER (GAIN CITY)	Necessary	280.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,811.60	4,401.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	916.58	396.67
Total Parts (\$\$)	9,895.02	4,005.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	-
3	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	280.00	60.00
5	TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS	New	80.00	-
6	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	80.00	-
7	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	80.00	50.00
8	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	180.00	60.00
9	TO REALIGN, DISMANTLE AND REINSTALL EXHAUST PIPE, EXHAUST BOX	New	120.00	-
10	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL INNER, OUTER, TAILLAMP PANEL X2, REAR BUMPER REINFORCEMENT. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH & RH. REAR CHASSIS SIDE PANEL, CHASSIS FRAME	New	1,200.00	600.00
11	TO SPRAY TAILGATE, REAR BUMPER, REAR BUMPER REINFORCEMENT, TAILLAMP PANEL LH & RH. END PANEL INNER & OUTER. SPARE TYRE PANEL. REAR FENDER LH & RH. REAR CHASSIS SIDE PANEL, CHASSIS FRAME	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,490.00	1,505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >