

Surveyor

CWS

Bryn

ASSIGNMENT (Office)

From (Person)

Lettene Jew

of

FCI

Date/Time

13/7/18 @ 12.33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 6800B

Insured:

SHA 0018A

at Workshop n/z

Chynni Motor

Tel:

6542 5119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D18005393MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/07/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.45pm @ 13/7/18

Person Contacted:

Irene

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

SH 6800B - CC3 / AIG 08019954 / VDN

DOA: 07/07/2008

SHA 0018A - X

26A-

Revert email preli reuse

Surveyor


ASSIGNMENT

COE Dec 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SH 6800B Yr Regn: 2016 / Dec
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 C.C. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 227995 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDGU690759
 C/No: KMHLB4UMHU096660
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60 216
 R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. 12/07/18	D.O.I. 13/07/2018

Survey held at Churni AMC
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S Body & N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/8/18	First Capital SH 18A Jinnu 4/5 13.4501 - with 10 days of rep Cred: 6910.88 / 33%

RECEIVED 30 AUG 2018

Date/Time, File Pass to? ☐ : Preli. Report
☒ : Final Report
 1) 30/8 Typist
 Date/Time, File Return to?

Days Of Repair: 10
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format: TP
 Lump Sum / I.B.I: (\$ 13450)

Survey Fee: 10x15=150
 Transportation: 50
 50+50
 132
 580
 580
 50/8/18
 602



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012764/Dtd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 0018A	Veh. Inspected	SH 6800B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005393MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	13/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/07/2018	Inspection Date	13/07/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005393MFSH

Date: 13/7/2018

Our Ref: CS/FCI18012764/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SH 6800B

Please be informed that we had conducted the inspection of the abovementioned vehicle
13/7/2018 at the premises of M/s Chun Ni and have the following to report: -

Workshop Estimate Amount	: S\$ <u>20,360.88</u>
Revised Estimate Amount	: S\$ <u>16,812.88</u>
"Check" Items Amount	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
n/s body and n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-07-2018	Our Ref No. D18005393MFSH
Accident Date	12-07-2018	Claim Type. Third Party
Insured Vehicle	SHA0018A	Third Party Vehicle. SH6800B
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE	
Contact No.	64836016/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242335)



PRI Documents



Close



PRI Header Details

Claim No	D18005393MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 Mobile: 65425119 , Phone: 64836016 , Fax: 65426039 EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0018A	TP Vehicle No	SH6800B
PRI Recieved Date	12-07-2018 09:19:55 PM	Surveyor Appointed Date	13-07-2018 12:32:29 PM	Surveyor Accept Date	13-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 6800 B

Technician:

Mileage: 227995

Time Printed 13.7.18 2:06 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°52'		-3°00' 3°00'
3°51'		-0°19' 5°41'
0°02'		-1°30' 1°30'
20°07'		
19°15'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°39'		-3°00' 3°00'
3°51'		-0°19' 5°41'
-0°43'		-1°30' 1°30'
15°39'		
15°00'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°13'		-3°00' 3°00'
0°00'		-3°00' 3°00'
4°28'		-3°00' 3°00'
-0°41'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
11°22'		-3°30' 2°30'
20°18'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
0°33'		-3°30' 2°30'
-0°17'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
10°49'		-3°00' 3°00'
20°02'		-3°00' 3°00'
10°18'		-3°00' 3°00'

CHUNNI MOTOR WORK PTE LTD

Go Survey by (LKK)

REPAIR ESTIMATE*

VEHICLE NO : SH 6800B

DATE : 12.07.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>distorted</i>			\$ 603.60 ✓
	Rear Bumper Clip 10 pcs <i>Hec</i>			\$ 22.00 ✓
	Rear Bumper Bracket, LH <i>Hec</i>			\$ 49.00 X
	Rear Fender With Housing (LH) <i>Distorted</i>			\$ 4,736.80 ✓ photo
	Rear Fender Inner Lining (LH) <i>Hec</i>			\$ 164.40 X
	Rear Windscreen Moulding <i>Hec</i>			\$ 60.00 ✓
	Rear Door (LH) <i>Distorted</i>			\$ 1,351.10 ✓ photo
	Rear Door Gear/Regulator (LH) <i>Hec</i>			\$ 785.00 ✓
	Rear Door Power Motor (LH) <i>Hec</i>			\$ 530.50 X
	Front Door (LH) <i>Hec</i>			\$ 1,403.05 ✓
	Front Door Rubber <i>Hec</i>			\$ 290.50 ✓
	Front Door Gear / Regulator (LH) <i>Hec</i>			\$ 785.00 ✓
	Front Door Power Motor <i>Hec</i>			\$ 950.90 X
	Front Door Trim Board (LH) <i>Hec</i>			\$ 1,196.90 ✓
	Door Centre Pillar Outer (LH) <i>Distorted</i>			\$ 1,786.20 ✓
	Rocker Panel Outer Garnish (LH) <i>Hec</i>			\$ 483.60 ✓
	Rocker Panel Outer <i>Distorted</i>			\$ 1,380.00 ✓
	Rear Tyre Rim (LH) <i>Hec</i>			\$ 351.90 ✓
	Rear Wheel Hub-Cap (LH) <i>Hec</i>			\$ 150.70 ✓
	Rear Wheelbearing IN & Hub <i>Hec</i>			\$ 401.40 ✓
	Rear Trailing Arm (LH) <i>Distorted</i>			\$ 120.00 ✓
	Rear Assist (LH) <i>Distorted</i>			\$ 120.00 ✓
	Rear Shock Absorber (LH) <i>Distorted</i>			\$ 342.20 ✓
	Rear Shock Absorber Mounting (LH) <i>Hec</i>			\$ 57.70 X
	Rear Upper Arm (LH) <i>Distorted</i>			\$ 335.75 ✓
	Rear Lower Arm (LH) <i>Distorted</i>			\$ 204.35 ✓
	Rear Knuckle Arm (LH) <i>Distorted</i>			\$ 574.80 ✓
			17484.85	
			13987.88	
	SUB TOTAL			\$ 19,237.35
	LESS 20%			\$ 3,847.47
	DISCOUNTED TOTAL			\$ 15,389.88
	Rear Bumper Advertisement Logo <i>Hec</i>			\$ 50.00 Nett ✓
	Rear Bumper Rubber Mat <i>Hec</i>			\$ 50.00 Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>Hec</i>		\$ 100.00	\$ 200.00 Nett ✓
	Rear Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Hec</i>			\$ 80.00 Nett ✓
	Front Door Coloured Comfort Logo (LH) <i>Hec</i>			\$ 75.00 Nett ✓
	Front Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00 Nett ✓
	Rear Tyre (LH) <i>Hec</i>			\$ 216.00 Nett X
			695/-	
				\$ 871.00

SH 6800B

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,500.00 800/-
	Spray Painting Charge			S 1,500.00 800/-
	Wiring Charge			S 50.00 NH
	Tuff Kote			S 100.00 40/-
	Remove/Refix Cushion & Upholstery Rear			S 150.00 80/-
	Remove/Refix Rear Windscreen Glass			S 120.00 80/-
	Remove/Refix Reverse Sensor			S 120.00 40/-
	Transfer of Door		S 120.00	S 240.00 120/-
	Remove/Refix Undercarriage (RR)			S 200.00 150/-
	Rear Wheel Alignment			S 120.00 60/-
	TOTAL LABOUR		2170/-	S 4,100.00
	ESTIMATE TOTAL			S 20,360.88
				16812.88
				4/513450/-
	13/07/2018 @ 1330w HOT Author L15mm 2¹⁰ dgs. ryu LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012764/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 18A	Veh. Inspected	SH 6800B	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005393MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	13/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU096660	Colour	BLUE	
Odometer	227995	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/07/2018	Inspection Date	13/07/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6800B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	603.60	603.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET, LH	NOT NECESSARY	49.00	-
1	REAR FENDER WITH HOUSING (LH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (LH)	NOT NECESSARY	164.40	-
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR (LH)	DENTED	1,351.10	1,351.10
1	REAR DOOR GEAR/REGULATOR (LH)	CRACKED	785.00	785.00
1	REAR DOOR POWER MOTOR (LH)	NOT NECESSARY	530.50	-
1	FRONT DOOR (LH)	BUCKLED	1,403.05	1,403.05
1	FRONT DOOR RUBBER	NECESSARY	290.50	290.50
1	FRONT DOOR GEAR/REGULATOR (LH)	BENT	785.00	785.00
1	FRONT DOOR POWER MOTOR	NOT NECESSARY	950.90	-
1	FRONT DOOR TRIM BOARD (LH)	MOUNTING CRACKED	1,196.90	1,196.90
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	1,786.20	1,786.20
1	ROCKER PANEL OUTER GARNISH (LH)	CRACKED	483.60	483.60
1	ROCKER PANEL OUTER	DENTED	1,380.00	1,380.00
1	REAR TYRE RIM (LH)	BENT	351.90	351.90
1	REAR WHEEL HUP-CAP (LH)	CUT	150.70	150.70
1	REAR WHEELBEARING ING & HUB	DAMAGED	401.40	401.40
1	REAR TRAILING ARM (LH)	DISTORTED	120.00	120.00
1	REAR ASSIST (LH)	DISTORTED	120.00	120.00
1	REAR SHOCK ABSORBER (LH)	DISTORTED	342.20	342.20
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	57.70	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	204.35	204.35
1	REAR KNUCKLE ARM (LH)	DISTORTED	574.80	574.80
	LESS 20% DISCOUNT		-3,847.47	-3,496.97
			15,389.88	13,987.88

Report Ref No. CS/FCI18012764/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			871.00	655.00
	LABOUR			
	PANEL BEATING.		1,500.00	800.00
	SPRAY PAINTING CHARGE.		1,500.00	800.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
			4,100.00	2,170.00
	GRAND TOTAL		20,360.88	16,812.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,450.00

Report Ref No. CS/FCI18012764/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.