

Surveyor

CWS

Marcus

ASSIGNMENT (Office)

From (Person)

Joanne Yang

of

FCI

Date/Time: 13/7/18 @ 5:10pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SDG 22C

Insured:

SHA 1277L

at Workshop n/s:

Ngce Seng Auto

Tel:

96319163

of

Blk 3022 Ubi Rd 1 #01-50

Policy No:

D18088936MFSH

Claim No:

D18005404MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

16/07/2018

H.O.D. Endorsement:

Date/Time:

5:44pm @ 13/7/18

Person Contacted:

Mr. MG

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SDG 22C-X

SHA 1277L - CS/QW/16012072/H/vbd/

DOA: 24/6/2016

12/2/18 @

2:26pm revised to Joanne Yang by email.

08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: Date: 16/7/18

Estimated Cost:

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDG 22C

at Workshop m/s

of Blk 3022 Ubi Rd 1 # 01-50

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDG 22C Yr Regn: 4117

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: BMW 340iM Sport 2998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 22466 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W13AFH1 2030K 443808

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R19

R: 255/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 100708

23/7/18 Confirmed L/S \$6400 with Air/Choon.
(Ref B 15804.60, F12)

RECEIVED 24 JUL 2018

Date/Time, File Pass to?

1) 24/7 11:58

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 7P 6400

☐ : Preli. Report☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

12x15 = 180

170 + 180

50

50

52

502



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012796/Uqd3

30 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Policy No.	SHA 1277L	Veh. Inspected	SDG 22C
Policy Amt		Coverage (\$)	0.00
Policy Code	D18005404MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	13/07/2018

2. Vehicle Particulars & Condition

Model		c.c	0
Condition	HIDDEN	Year of Reg.	
Colour		Colour	
Steering		Steering	
Modification		Modification	

3. Conditions of Tyres

	Size	Make	Balance
Front			mm
Front			mm
Rear			mm
Rear			mm

4. Description of Damages

--

5. General Information

Date	10/07/2018	Inspection Date	16/07/2018
At	NGEE SENG AUTO WORKS BLK. 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716.		

5a. Remarks

INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005404MFSH

Date: 17 July 2018

Our Ref: CS/FCI18012796/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SDG 22C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/07/2018 at the premises of M/s NGEE SENG AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>22,204.60</u>
Revised Estimate Amount	: S\$ <u>8,975.36</u>
"Check" Items Amount	: S\$ <u>3,758.12</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-07-2018	Our Ref No. D18005404MFSH
Accident Date	10-07-2018	Claim Type. Third Party
Insured Vehicle	SHA1277L	Third Party Vehicle. SDG22C
Survey Location	BLK 3022A UBI ROAD 1 #01-50	
Contact Person.	MR MG	
Contact No.	68412276/ 96319163	Fax No. 67439006
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NGEE SENG AUTO WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242348)



PRI Documents



Close



PRI Header Details

Claim No	D18005404MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & NGEE SEN
Workshop Name	NGEE SENG AUTO WORKS (Contact Person : MR MG)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-50 Mobile: 96319163 , Phone: 68412276 , Fax: 67439000 EmailId: NGEESENGAUTOWORKS@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1277L	TP Vehicle No	SDG22C
PRI Recieved Date	13-07-2018 05:04:53 PM	Surveyor Appointed Date	13-07-2018 05:09:08 PM	Surveyor Accept Date	13-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 17 July 2018 2:26 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005404MFSH/1
Attachments: CSFCI18012796Uqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SDG 22C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 13 July 2018 5:48 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005404MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 16/07/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 13 July 2018 5:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005404MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6448Z

Vehicle Details

Vehicle No.:	SDG22C
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	340I M SPORT AUTO
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	13579733
Chassis No.:	WBA8H12030K443808
Maximum Power Output:	240.0 kW (321 bhp)
Open Market Value:	\$55,282.00
Original Registration Date:	27 Sep 2016
First Registration Date:	05 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$71,508.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2026
PARF Rebate Amount:	\$53,631.00

Intended COE Rebate Details

COE Expiry Date:	04 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$47,077.00
Total Rebate Amount:	\$100,708.00

The information contained herein is correct as at 16 Jul 2018

OK



NGEE SENG AUTO WORKS 誼盛摩托

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

FIRST CAPITAL INSURANCE LTD

36, Robinson Road

#16-01, City House

Singapore 068877

RE : VEHICLE NO. SDG 22 C BMW 340I M

ESTIMATE : TP18013

Date : 13/07/2018

Ref No : SDG 22 C

Policy No. :

Page : 01

Qty	Description	Unit Price	Amount
1	REAR BUMPER 1466.30	Deep cut	\$2,175.00
1	REAR BUMPER CLIPS (SET)	new	\$90.00
2	REAR BUMPER SIDE BRACKET 199.20	0/5 shot	\$284.20
1	REAR FENDER RH 1866.20	Sub 500/500	\$2,750.00
1	REAR FENDER INNER SHIELD RH 325.40	to n	\$363.20
1	REAR FENDER INNER SHIELD CLIPS (SET) 60.00	new	\$90.00
1	REAR FENDER TOP MOULDING RH 295.00	new	\$935.20
1	REAR FENDER QUARTER GLASS RH	11	\$886.30
1	REAR FENDER MOULDING RH 161.00	new	\$326.00
1	REAR KNUCKLE ARM	11	\$1,456.70
1	REAR KNUCKLE ARM BEARING	11	\$560.20
1	REAR LOWER ARM	11	\$702.40
1	REAR CONTROL ARM	11	\$681.20
1	REAR SHOCK ABSORBER	11	\$1,540.00
1	SPORT RIM 0/5 15005.2	cut	\$2,650.00
1	TYRE 0/5	11	\$800.00

P-4463.1

4239.54

TOTAL (1)

\$16,574.60

LABOUR

TO REMOVE & REFIX CUSHION

TO REMOVE & REFIX QUARTER GLASS

TO REMOVE & REFIX REAR BUMPER SENSOR

TO REMOVE & REFIX UNDERCARRIAGE

TO REMOVE & REFIX RIM, TYRE & BALANCING

TO CONDUCT COMPUTERISED WHEEL ALIGNMENT

TO CHECK WIRING & SETING

TO PANEL BEATING

TO SPRAY PAINTING

TOTAL SPARE PARTS & LABOUR CHARGES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before LABOUR CHARGES
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$280.00 100

\$350.00 100

\$150.00 50

11 \$800.00 2

11 \$200.00 2

\$200.00 80

\$400.00 150

\$1,850.00 1000

\$1,400.00 800

\$5,630.00

\$22,204.60

2280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012796/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1277L	Veh. Inspected	SDG 22C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005404MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	13/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 340I M SPORT (A)	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA8H12030K443808	Colour	BLUE	
Odometer	22466	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R19	BRIDGESTONE	6 mm	
L/H Front Tyre	225/40 R19	BRIDGESTONE	6 mm	
R/H Rear Tyre	255/35 R19	BRIDGESTONE	6 mm	
L/H Rear Tyre	255/35 R19	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/07/2018	Inspection Date	16/07/2018	
Survey held at	NGEE SENG AUTO WORKS BLK. 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDG 22C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEEP CUT	2,175.00	1,466.30
1	SET REAR BUMPER CLIPS	NECESSARY	90.00	90.00
2	REAR BUMPER SIDE BRACKET @\$284.20	O/S BENT	568.40	199.20
1	REAR FENDER RH	BADLY DENTED / BENT	2,750.00	1,866.20
1	REAR FENDER INNER SHIELD RH	TORN	363.20	325.40
1	SET REAR FENDER INNER SHIELD CLIPS	NECESSARY	90.00	60.00
1	REAR FENDER TOP MOULDING RH	NECESSARY	935.20	295.00
1	REAR FENDER QUARTER GLASS RH	NOT NECESSARY	886.30	-
1	REAR FENDER MOULDING RH	NECESSARY	326.00	161.00
1	REAR KNUCKLE ARM	NOT NECESSARY	1,456.70	-
1	REAR KNUCKLE ARM BEARING	NOT NECESSARY	560.20	-
1	REAR LOWER ARM	NOT NECESSARY	702.40	-
1	REAR CONTROL ARM	NOT NECESSARY	681.20	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	1,540.00	-
1	REAR TYRE O/S	NOT NECESSARY	800.00	-
	LESS 5% DISCOUNT		-	-223.16
			13,924.60	4,239.94
SPECIAL NETT ITEMS				
1	REAR SPORT RIM O/S (SN)	CUT	2,650.00	1,500.00
			2,650.00	1,500.00
LABOUR				
	TO REMOVE & REFIX CUSHION.		280.00	100.00
	TO REMOVE & REFIX QUARTER GLASS.		350.00	100.00
	TO REMOVE & REFIX REAR BUMPER SENSOR.		150.00	50.00
	TO REMOVE & REFIX UNDERCARRIAGE.	NOT NECESSARY	800.00	-
	TO REMOVE & REFIX RIM, TYRE & BALANCING.	NOT NECESSARY	200.00	-
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT.		200.00	80.00
	TO CHECK WIRING & SETING.		400.00	150.00
	TO PANEL BEATING.		1,850.00	1,000.00

Report Ref No. CS/FC18012796/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING.		1,400.00	800.00
			5,630.00	2,280.00
GRAND TOTAL			22,204.60	8,019.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,400.00

Report Ref No. CS/FCI18012796/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.