

22/03/2002

ASS. REC. BY:

REF: CS3/CTI18012837/GZ4d32 Special Instruction:

Surveyor: Guo Qing

ASSIGNMENT (Office)

From (Person): Chong Boon Sun

of

CTI

Date/Time: 16/7/18 @ 1.25pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 6843Z

Insured:

SLN 6894G

at Workshop m/s

Everdawn Auto

Tel:

9817 4178

of

8 Keeki Bukit Ave 4 # 01-02 premier

Policy No:

DMPCSN1735121801

Claim No:

SNM18D03468C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/07/2018

CA / REV / REP. / REV 24 HRS

up

17/07/18

H.O.D. Endorsement:

Date/Time: 2.29pm 16/7/18

Person Contacted:

Mr. Lee

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SKV 6843Z - CS3 / INC16007141 / Gh3c2 DOA: 16/04/2016
	SLN 6894G - X
17/7/18	Disassembled
20/7/18	After Repair



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018		16 Jul 2018 13:25 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:				[Created by insurer]	
Main Claimant:	LIN MINGXING				
Vehicle Reg. No.:	SKV6843Z		Date of Loss:	14/07/2018 00:00 - :59	
Claim Type:	TP / SNM18D03468C02		Policy/Cover Note No.:	DMPCSN1735121801	
Vehicle Reg. No. (Insured):	SLN6894G		Policy No. (Claimant):		
			Excess:	S\$0.00	
Repairer:	Everdawn Auto Service (KAKI BUKIT) 8 Kaki Bukit Ave 4, #01-02 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/07/2018]				
Adj Asg. Remarks:	NO EST, CASE W/O SJE.				

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

PDX Intercompany Exchange Pte Ltd



010808474816

FROM TEO KENG SIANG LLC  
PDX Box No. 8802  
PDX Document 010808474816

张景祥大律師樓  
(律師公會及庭室登記)

# TEO KENG SIANG LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098. Tel: 6333 4222 Fax: 6333 5676/5688  
ROC: 201510228C GST Reg No.: 201510228C Email: KSTEOCO@singnet.com.sg  
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKS/A556-ACC-MISC.18/cc  
Your Ref : SLN 6894 G  
Date : 16<sup>TH</sup> July 2018

Secretary In charge: Charlotte  
Tel : 6333 4222 (63)  
Fax : 6333 5676/6333 5688  
Email: Charlotte.choy@ksteoptr.com

CHINA TAIPING INSURANCE SINGAPORE PTE LTD  
105 Cecil street  
#19-00, the Octagon  
Singapore 069534  
Attention: Motor Claims Department

BY PDX# (8178) & BY FAX (6224 7478)

SEAH LEE YONG EILEEN  
99 Pasir Ris Heights  
#04-29  
Singapore 519291

BY POST ONLY

**NOTIFICATION OF ACCIDENT**  
**ACCIDENT INVOLVING SKV 6843 Z / SLN 6894 G ON 14/07/18 ALONG DEFU FLYOVER (TOWARDS KPE)**

We act for LIN MINGXING in an accident above.

We are instructed by the abovenamed to notify you of a road traffic accident on 14/07/18 at about 11:45 AM ALONG DEFU FLYOVER (TOWARDS KPE) involving our client's motor vehicle SKV 6843 Z and motor vehicle SLN 6894 G driven by you or your authorized driver at the material time. A copy of the GIA/Traffic Police Report is enclosed. Kindly also let us have your GIA/Traffic Police report for our necessary.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle SKV 6843 Z is now at the following workshop: -

**EVERDAWN AUTO SERVICE**  
8 Kaki Bukit Avenue 4  
#01-02, Premier @Kaki Bukit  
Singapore 415875  
Contact Person: Mr Lee 9817 4178

Yours faithfully

M/S TEO KENG SIANG LLC  
c.c. Workshop by Fax: 6382 2839

Teo Keng Siang  
LL.M(Singapore),  
LL.B (Hons) (Singapore)

\*\*Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

Wong Yong Sheng, Kenneth  
LL.B (Hons) University of Bristol




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18012837/Gz4d3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 16-07-2018		
		Code : CTI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLN 6894G	Veh. Inspected	SKV 6843Z	
Policy No.	DMPCSN1735121801	Coverage (\$)	0.00	
Claim No.	SNM18D03468C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	16/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	14/07/2018	Inspection Date		
Survey held at	EVERDAWN AUTO SERVICE 8 KAKI BUKIT AVE 4 #01-02 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

> [Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKV6843Z		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	JETTA 1.4 TSI AT 1622G5		
Chassis No. :	WVWZZZ16ZCM095013		
Propellant :	Petrol		
Engine No. :	CAX987351		
Engine Capacity :	1390 cc		
Maximum Power Output :	90.0 kW ( 120 bhp )		
Maximum Laden Weight :	1870 kg		
Unladen Weight :	1417 kg		
Year Of Manufacture :	2012		
Original Registration Date :	13 Apr 2012		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$54,887.00		
COE Expiry Date :	12 Apr 2022		
Road Tax Expiry Date :	12 Oct 2018		
PARF Eligibility Expiry Date :	12 Apr 2022		
Inspection Due Date :	12 Apr 2019		
Intended Transfer Date :	24 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 12 Oct 2018. You may renew the road tax from 13 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 12 Oct 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 13 Oct 2018 to 12 Apr 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	310.00	-	310.00
Total Amount Payable :			335.00
Amount Payable (From 13 Oct 2018 to 12 Oct 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	620.00	-	620.00
Total Amount Payable :			645.00

You may print this page for reference.

[OK](#)

[Print](#)






































### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jul 2018		16 Jul 2018 13:25 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>LIN MINGXING</b>								
Vehicle Reg. No.:	<b>SKV6843Z</b>	Date of Loss:	14/07/2018 00:00 - :59						
Claim Type:	<b>TP / SNM18D03468C02</b>	Policy/Cover Note No.:	DMPCSN1735121801						
Vehicle Reg. No. (Insured):	<b>SLN6894G</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Everdawn Auto Service (KAKI BUKIT)</b> 8 Kaki Bukit Ave 4, #01-02 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 25/07/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






## Claim Documents

\*SKV6843Z (SNM18D03468C02)  
[SLN6894G]  
TP  
LIN MINGXING  
Jul 14 2018 12:00AM  
[-]  
Everdawn Auto Service

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	23/07/18 11:22	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	23/07/18 11:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	23/07/18 11:23	Photo After Spray	 Load JPG	✓
89	23/07/18 11:23	Photo After Spray	 Load JPG	✓
90	23/07/18 11:23	Photo After Spray	 Load JPG	✓
91	23/07/18 11:23	Photo After Spray	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/07/18 13:24	PRS	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

^  
v

**Show Remarks To:** ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18012837/GZ4D3E2

Date: 27/07/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN1735121801

Claimant Vehicle  
No : SKV6843ZInsured Vehicle  
No : SLN6894G

Date of Loss: 14/07/2018

Nature of Claim: TP

Claim  
No: SNM18D03468C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV6843Z**

Make &amp; Model: VOLKSWAGEN JETTA TSI, 1.4 (A)

Engine No: CAX987351

Reg. Date: 13/04/2012 (Man. Year: 2012)

Chassis No: WWWZZZ16ZCM095013

Colour: Silver

Odometer: 109384 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 17/07/2018 Inspected At:

 Everdawn Auto Service (KAKI BUKIT)  
 8 Kaki Bukit Ave 4, #01-02 Premier @ Kaki  
 Bukit  
 Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2018)
<b>Parts:</b> 143	VOLKSWAGEN JETTA TSI 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKV6843Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >