



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 3930B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR POWER GATE (SN) (CONSISTENT)	BENT	12,000.00	10,500.00
4	REAR POWER GATE PUMP (SN) (CONSISTENT)	JAMMED	11,000.00	6,000.00
1	REAR POWER GATE HINGES (SN) (CONSISTENT)	BENT	3,000.00	1,800.00
4	REAR POWER GATE PUMP DUST COVER	CUT	800.00	500.00
4	REAR POWER GATE HYDRAULIC FLUID (SN) (CONSISTENT)	NECESSARY	200.00	200.00
1	REAR POWER GATE 60KMPH EMBLEM (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET REAR POWER GATE STICKER (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	REAR POWER GATE ADVERTISEMENT (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	REAR POWER GATE 45PAX EMBLEM (SN) (CONSISTENT)	NECESSARY	20.00	20.00
2	REAR POWER GATE ZEPRO FLAP (SN) (CONSISTENT)	NOT NECESSARY	360.00	-
			27,640.00	19,280.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE REAR POWER TAIL-GATE PUMP.		3,000.00	2,000.00
			3,000.00	2,000.00
	<b>GRAND TOTAL</b>		<b>30,640.00</b>	<b>21,280.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>17,000.00</b>

Report Ref No. CC4/ASM18012849/T1ga3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.