


John

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: **SH 6TY**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SHF 1025X** Yr Regn: **2014 / AK**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or
 Make: **TOYOTA PRIMS** C.C: **1798**
 Colour: **MAROON** A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **STOKN 364 305 754 566**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ Order / Jammed / Leaked / Burnt or
 Brake: ☒ Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **195/65R15**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FALKEN**

Front		Rear
R/Bal. 5 mm		R/Bal. 5 mm
L/Bal. 5 mm		L/Bal. 5 mm
D.O.A. 12/01/18		D.O.I. 16/07/18

Survey held at: **SHAF**
 Des. of Damages: ☒ Front / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHF 1025X - CC3/MS618012A11/Klyg362
SHH 6TY - X

DA: 26/11/18

07/12/2017

24/07/18 @ 16:04 p.m. revised IA to Christina Wong via mui men.

MSH

(\$ 8,682.76 Red - 53%)

SHH 6TY

RECEIVED 11 AUG 2018

Date/Time: File Pass to?

15/08/18
Tyast

Date/Time: File Return to?

☐ : Prel. Report
☒ : Final Report

Days Of Repair: **10**

Resurvey No. of Trip: **2**

Survey Fee:

Transportation:

1. \$ + RS. \$

2. Photos

3. Other:

TOTAL:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 7,650.00 L/S)

200
10
210

Shirley Hiew (LKK Auto)

From: Hasrianah Binte Hassan <hasrianah@sg.msig-asia.com>
Sent: Tuesday, 24 July 2018 1:09 PM
To: 'Shirley Hiew (LKK Auto)'; Christina Wong
Cc: 'KKLau'; account@lkkauto.com; "SUR"
Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 12/07/2018 , SHF 1025X (TP VEHICLE), SJH 67Y (OI VEHICLE)

Hi Shirley

Merimen has already created. Our ref no is 564992.

Have A Great Week Ahead!

Hasrianah Hassan (Ms)

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2587 | Direct fax +65 6225 7402 | hasrianah@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 24 July, 2018 12:08 PM
To: Christina Wong <Christina_Wong@sg.msig-asia.com>; Hasrianah Binte Hassan <hasrianah@sg.msig-asia.com>
Cc: 'KKLau' <kklau@lkkauto.com>; account@lkkauto.com; "SUR" <sur@lkkauto.com>
Subject: FW: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 12/07/2018 , SHF 1025X (TP VEHICLE), SJH 67Y (OI VEHICLE)

Dear All,

Merimen not created. Kindly assist to create.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 17 July 2018 4:14 PM
To: Christina Wong <Christina_Wong@sg.msig-asia.com>; hasrianah@sg.msig-asia.com

Cc: kklau@lkkauto.com; account@lkkauto.com; sur@lkkauto.com

Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 12/07/2018 ,
SHF 1025X (TP VEHICLE), SJH 67Y (OI VEHICLE)

Dear Christina/Hasrianah,

Please be informed that we had inspected the vehicle SHF 1025X M/s: SMRT AUTOMOTIVE SERVICE PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE 757705 on 16/07/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, 13 August 2018 2:01 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Subject: RE: SHF1025X

Hi Poh Suan,

Finalised amount confirmed

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Sunday, 12 August, 2018 8:55 AM
To: Rasul (LKKAuto)
Cc: SUR; CS A Team; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Subject: SHF1025X

Hi Rasul,

Attached herewith the repair estimate of SHF 1025X having Case No: TAX/07/18/2047.

There is no change to the approved amount of \$7,650 @ 10 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Sunday, 12 August 2018 8:57 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 24 Jul 2018

Preliminary Advice

Insured Vehicle No	: SJH67Y	Accident Date	: 12/07/2018
TP Vehicle No	: SHF1025X	Assignment Date	: 24/07/2018
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 8 days
Date of Inspection	: 16/07/2018		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,332.76
Revised Amount	:S\$	3,674.00
Check Items (Estimated)	:S\$	9,680.47
Total	:S\$	13,354.47

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2018 15:55
Date Of Accident	12/07/2018 14:10
Exact Location Of Accident	UPPER SERANGOON RD SLIP RD TO SERANGOON AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF1025X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	CHUA KUAN STEVEN
NRIC No	S0105519D
Date Of Birth	01/11/1953
Occupation	OUTDOOR
Date Of Driving Pass	17/07/1972
Driving Experience	45 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	556
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG THE SLIP ROAD OF UPPER SERANGOON ROAD AND HAD STOPPED BEHIND THE VEHICLE SJH67Y TO LOOK FOR THE ONCOMING VEHICLE ON SERANGOON AVE 2. WHILE STATIONARY, SUDDENLY THE FRONT VEHICLE SJH67Y ENGAGED REVERSE GEAR, REVERSED AND COLLIDED ONTO THE FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH67Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SOK FUNG
NRIC/Passport Number	S7914935G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: :

GENDER: :

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No	:	SHF1025X
Ref. No	:	TAX/07/18/2047
Reg. Date	:	17/12/2014
Vehicle Type	:	TAXI
Make	:	TOYOTA PRIUS
Model	:	PRIUS
Name of Driver	:	CHUA KUAN STEVEN
Type of Accident	:	OTHERS
Date / Time of Accident	:	12/07/2018 02:10:00 PM
Accident Reported Date / Time	:	12/07/2018 12:00:00 AM
Surveyor is Required?	:	Yes
Survey by	:	
Vehicle is Towed Back?	:	No
Towed Back Date/Time	:	
Replacement Vehicle issued?	:	No
Accident Repair Job Card No	:	000024096982
Special Instruction to ARC, if any	:	
SJH67Y / <i>MSNH</i> <i>Recovery after repair</i>		
Prepared Date	:	13/07/2018 04:54:32 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305754566

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	0.00
Total Spray Painting Charges	: 2,052.00	0.00
Total Material Charges	: 12,059.76	12,059.76
Other Charges	: 700.00	0.00
TOTAL	: 16,332.76	0.00
Lum Sum Total	: 16,350.00	0.00
No. of Repair Days	: 10.00	0.00 <i>8 days - Lump</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 13/07/2018 06:57:36 PM	01/01/1900 12:00:00 AM



16/07/18

P 1610



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/07/2018 06:57:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 7/13/2018 6:57:24 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REPAIR FRONT PORTION	1,521.00	0.00 700 900
Total Labour	1,521.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REPSRAY FRONT BUMPER	378.00	0.00 200
RESpray FRONT BUMPER LOWER GRILLE	180.00	0.00 100
REPRAY LOWER RADIATOR SUPPORT	180.00	0.00 100
REPSRAY FRONT HOOD	378.00	0.00 200
RESpray FRONT SUPPORT PANEL	180.00	0.00 100
RESpray FRONT FENDER LH	378.00	0.00 200
RESpray FRONT FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,052.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 60
APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TOP UP A/C GAS	120.00	0.00 80
REMOVE & REFIT RADIATOR LOWER SUPPORT	120.00	0.00 X
CONDUCT RADIATOR PRESSURE CHECK	120.00	0.00 30
REPLACE SUNDRY PARTS	100.00	0.00 X 00
WASH AND VACUUM	60.00	0.00 X 00
Total Other Costs	700.00	0.00

6273

23798162

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-17930		6505517	BUMPER FRT	1	482.00	25.00	361.50	1 Replace	Replace <i>DE</i>	No <i>55740</i>
50467-37211			BUMPER CLIPS	10	2.10	25.00	15.75	2 Replace	Replace <i>DE</i>	No <i>1470</i>
52116-17040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	3 Replace	Replace <i>DE</i>	No <i>5348</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	4 Replace	Replace <i>DE</i>	No <i>5348</i>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	5 Replace	Replace <i>DE</i>	No <i>5516</i>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	6 Replace	Replace <i>TH</i>	No <i>34838</i>
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00 <i>BT</i>	187.80	7 Replace	Replace <i>?</i>	No <i>17528</i>
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00 <i>BT</i>	187.80	8 Replace	Replace <i>?</i>	No <i>17528</i>
53294-47030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	25.00 <i>SVC</i>	57.75	XX Replace	Replace <i>DE</i>	No
53293-47040		6505574	DEFLECTOR, RADIATOR RH	1	83.50	25.00 <i>SVC</i>	62.62	XX Replace	Replace <i>DE</i>	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00 <i>NRG</i>	82.80	9 Replace	Replace <i>DE</i>	No <i>7723</i>
			NUMBER PLATE	1	15.00	0.00	15.00	91 Replace	Replace <i>DE</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	92 Replace	Replace <i>DE</i>	No
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	X Replace	Replace <i>Repair</i>	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	X Replace	Replace <i>Repair</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	10 Replace	Replace <i>DE</i>	No <i>21777</i>
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	11 Replace	Replace <i>DE</i>	No <i>6055</i>
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00 <i>SVC</i>	26.62	X Replace	Replace <i>DE</i>	No
53289-47032			COVER, RADIATOR	1	122.80	25.00 <i>SVC</i>	92.10	X Replace	Replace <i>DE</i>	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	12 Replace	Replace <i>DE</i>	No <i>21743</i>
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	13 Replace	Replace <i>DE</i>	No <i>6622</i>
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00 <i>COA</i>	104.70	✓ 14 Replace	Replace <i>DE</i>	No <i>7872</i>
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00 <i>COA</i>	95.77	✓ 15 Replace	Replace <i>DE</i>	No <i>8989</i>
51410-12105			UNDER COVER CENTER	1	448.30	25.00 <i>SVC</i>	336.22	X Replace	Replace <i>DE</i>	No
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00 <i>SVC</i>	657.22	XX Replace	Replace <i>DE</i>	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	X Replace	Replace <i>Repair</i>	No
53341-47020			HOOD PANEL INSULATOR	1	390.50	25.00 <i>SVC</i>	292.87	X Replace	Replace <i>DE</i>	No
53410-47070			HOOD HINGE RH	1	55.90	25.00 <i>SVC</i>	41.92	X Replace	Replace <i>DE</i>	No
53420-47070			HOOD HINGE LH	1	55.90	25.00 <i>SVC</i>	41.92	X Replace	Replace <i>DE</i>	No

5872 R

Part Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Recommen d	Approved	Attached
5708-7101	WIPER GARNISH	1	614.00	25.00	460.50 <i>SVC</i>	Replace	Replace <i>X</i>	No <i>old damage</i>
5084-7011	WIPER GARNISH COVER, LH	1	23.80	25.00	17.85 <i>SVC</i>	Replace	Replace <i>X</i>	No
5083-7011	WIPER GARNISH COVER, RH	1	23.80	25.00	17.85 <i>SVC</i>	Replace	Replace <i>X</i>	No
3510-7102	HOOD LOCK	1	128.90	25.00	96.67 <i>SVC</i>	Replace	Replace <i>X</i>	No
3630-7050	CABLE ASSY, HOOD	1	52.20	25.00	39.15 <i>SVC</i>	Replace	Replace <i>X</i>	No
3557-7010	HOOD AUXILIARY CATCH	1	8.60	25.00	6.45 <i>SVC</i>	Replace	Replace <i>X</i>	No
3614-7030	CLAMP, HOOD LOCK	1	5.90	25.00	4.42 <i>SVC</i>	Replace	Replace <i>X</i>	No
6510-8130	HORN ASSY, HIGH	1	110.40	25.00	82.80 <i>SVC</i>	Replace	Replace <i>X</i>	No
6520-8180	HORN ASSY, LOW	1	110.40	25.00	82.80 <i>SVC</i>	Replace	Replace <i>X</i>	No
3201-7902	SUPPORT SUB-ASSY	1	1,460.40	25.00	✓ 1,095.30 <i>BT</i>	Replace	Replace <i>X</i>	No <i>1,022.30</i>
1170-7500	6505436 HEAD LAMP LH	1	945.20	10.00	X 850.68 <i>SVC</i>	Replace	Replace <i>X</i>	No
1130-7500	6505437 HEAD LAMP RH	1	945.20	10.00	X 850.68 <i>SVC</i>	Replace	Replace <i>X</i>	No
8460-7150	A/C CONDENSER	1	1,181.90	25.00	✓ 886.42 <i>BT</i>	Replace	Replace <i>X</i>	No <i>827.33</i>
8710-7150	TUBE & ACCESSORY	1	631.90	25.00	X 473.92 <i>SVC</i>	Replace	Replace <i>X</i>	No
8703-7040	HOSE SUB-ASSY, DISCHARGE	1	386.90	25.00	X 290.17 <i>SVC</i>	Replace	Replace <i>X</i>	No
9010-7031	RADIATOR ASSY, UPPER	1	679.60	25.00	✓ 509.70 <i>BT</i>	Replace	Replace <i>X</i>	No <i>475.72</i>
9225-7021	HOSE, INVERTER NO.1	1	80.00	25.00	X 60.00 <i>SVC</i>	Replace	Replace <i>X</i>	No
9229-7020	HOSE, INVERTER COOLING NO.5	1	125.30	25.00	X 93.97 <i>SVC</i>	Replace	Replace <i>X</i>	No
6400-7230	6505302 RADIATOR ASSY	1	1,496.90	25.00	✓ 1,122.67 <i>BT</i>	Replace	Replace <i>X</i>	No <i>1,042.8</i>
6523-1050	CUSHION, RADIATOR	2	11.30	25.00	X 16.95 <i>SVC</i>	Replace	Replace <i>X</i>	No
6534-7010	SUPPORT, RADIATOR, LH	1	17.70	25.00	X 13.27 <i>SVC</i>	Replace	Replace <i>X</i>	No
6533-3051	SUPPORT, RADIATOR, RH	1	54.50	25.00	X 40.87 <i>SVC</i>	Replace	Replace <i>X</i>	No
6535-3030	SUPPORT, RADIATOR,	2	18.50	25.00	X 27.75 <i>SVC</i>	Replace	Replace <i>X</i>	No
6572-7120	RADIATOR HOSE LOWER	1	42.40	25.00	X 31.80 <i>SVC</i>	Replace	Replace <i>X</i>	No
9010-7031	RADIATOR ASSY, UPPER	1	679.60	25.00	X 509.70 <i>SVC</i>	Replace	Replace <i>X</i>	No
6571-7140	6505303 RADIATOR TOP HOSE NO 1	1	42.40	25.00	X 31.80 <i>SVC</i>	Replace	Replace <i>X</i>	No
3261-7070	RADIATOR HOSE, BYPASS NO.1	1	37.20	25.00	X 27.90 <i>SVC</i>	Replace	Replace <i>X</i>	No
3264-7080	RADIATOR HOSE, BYPASS NO.2	1	29.00	25.00	X 21.75 <i>SVC</i>	Replace	Replace <i>X</i>	No
3267-7030	RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	X 27.90 <i>SVC</i>	Replace	Replace <i>X</i>	No
3281-7030	RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	X 27.90 <i>SVC</i>	Replace	Replace <i>X</i>	No

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	LT Check Attached
	•COMMO N.	COOLANT	1	12.32	0.00	12.32	Replace	Replace <i>re</i>	No
6711-7040		FAN SHROUD	1	244.50	25.00	183.37	Replace	Replace ?	No 171.15
6712-7030		FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace ?	No 69.72
6361-7010		FAN BLADE	1	158.60	25.00	118.95	Replace	Replace ?	No 111.02
6361-8360		FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Replace ?	No 142.74
6363-7010		FAN MOTOR NO 1	1	538.30	25.00	403.72	Replace	Replace ?	No 376.81
6363-7020		FAN MOTOR NO 2	1	538.30	25.00	403.72	Replace	Replace ?	No 346.31
3801-7050	6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>repair</i>	No
5374-7051		NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>re</i>	No 36.33
3875-7030	6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace X	No
3851-7040		FENDER LINER PAD, FR WHEEL RH	1	49.30	25.00	36.97	Replace	Replace X	No
3802-7050	6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>repair</i>	No
5374-7051		NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>re</i>	No 36.33
3876-7030	6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace X	No
3852-7020		FENDER LINER PAD, FR WHEEL LH	1	49.30	25.00	36.97	Replace	Replace X	No
TOTAL MATERIALS				3703.42			15,074.86	15,074.70	
TOTAL MATERIALS(Discounted)							12,059.76	12,059.76	

dded Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

25-7-18/12:33


25-7-18/16:33

SMRT Accident Vehicle Repair Estimates

16-7-18/16:33

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF1025X
Ref. No : TAX/07/18/2047
Reg. Date : 17/12/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : CHUA KUAN STEVEN
Type of Accident : OTHERS
Date / Time of Accident : 12/07/2018 02:10:00 PM
Accident Reported Date / Time : 12/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Rasul
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096982
Special Instruction to ARC, if any :
SJH67Y mslk 45
Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL
/ HP : 9001 0068, email: rasul@lkkauto.com
LUMPSUM REPAIR
Prepared Date : 13/07/2018 04:54:32 PM



QC 28/7/18 9:20 Pass

381862

$$\frac{1}{4} \quad \frac{1}{2} \quad \frac{3}{4} \quad 1$$

Recording Camera

☒ ☐

Radio Antenna

☒ ☐

1st witness

2nd witness

Date 16-7-18

Date

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 27/7/18

Vehicle Return Time: 18:15

SMRT sign:

Supplementary

to Refer to the Supplementary part list

381895

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305754566

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	900.00
Total Spray Painting Charges	: 2,052.00	1,100.00
Total Material Charges	: 8,626.68	5,418.88
Other Charges	: 700.00	230.00
TOTAL	: 12,899.68	7,648.88
Lum Sum Total	: 12,900.00	7,650.00
No. of Repair Days	: 10.00	10.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 13/07/2018 06:57:36 PM	16/07/2018 04:33:58 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/07/2018 06:57:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : GN-1808-0020

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00



Prepared Date : 7/13/2018 6:57:24 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,521.00	900.00
Total Labour	1,521.00	900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100.00
TO REPRAY LOWER RADIATOR SUPPORT	180.00	100.00
TO REPSRAY FRONT HOOD	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY FRONT FENDER RH	378.00	200.00
Total Spray Painting & Panel Beating	2,052.00	1,100.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	60.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO TOP UP A/C GAS	120.00	80.00
TO REMOVE & REFIT RADIATOR LOWER SUPPORT	120.00	0.00
TO CONDUCT RADIATOR PRESSURE CHECK	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	700.00	230.00

2230

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	30.00	337.40	Replace	Replace <i>DE</i>	No <i>✓</i>
90467-07211			BUMPER CLIPS	10	2.10	30.00	14.70	Replace	Replace <i>DE</i>	No <i>✓</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	30.00	53.48	Replace	Replace <i>DE</i>	No <i>✓</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	30.00	53.48	Replace	Replace <i>DE</i>	No <i>✓</i>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	30.00	55.16	Replace	Replace <i>DE</i>	No <i>✓</i>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	30.00	348.88	Replace	Replace <i>DE</i>	No <i>✓</i>
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	30.00	175.28	Replace	Replace <i>DE</i>	No <i>✓</i>
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	30.00	175.28	Replace	Replace <i>DE</i>	No <i>✓</i>
53294-47030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	30.00	53.90	Replace	Check	No <i>✓</i>
53293-47040		6505574	DEFLECTOR, RADIATOR RH	1	83.50	30.00	58.45	Replace	Check	No <i>✓</i>
52114-47140			BRACKET, FR BUMPER	1	110.40	30.00	77.28	Replace	Replace <i>DE</i>	No <i>✓</i>
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>DE</i>	No <i>✓</i>
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>DE</i>	No <i>✓</i>
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	100.00	0.00	Replace	Repair	No <i>✓</i>
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	100.00	0.00	Replace	Repair	No <i>✓</i>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	30.00	217.77	Replace	Replace <i>DE</i>	No <i>✓</i>
75310-47010		6505638	EMBLEM FRONT	1	86.50	30.00	60.55	Replace	Replace <i>DE</i>	No <i>✓</i>
53395-47020			HOOD END PANEL SEAL	0	35.50	30.00	0.00	Replace	Not given	No <i>✓</i>
53289-47032			COVER, RADIATOR	0	122.80	30.00	0.00	Replace	Not given	No <i>✓</i>
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	30.00	217.42	Replace	Replace <i>DE</i>	No <i>✓</i>
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	30.00	66.22	Replace	Replace <i>DE</i>	No <i>✓</i>
76851-47020		6505616	BUMPER LIP FRT	1	139.60	30.00	97.72	Replace	Replace <i>DE</i>	No <i>✓</i>
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	30.00	89.39	Replace	Replace <i>DE</i>	No <i>✓</i>
51410-12105			UNDER COVER CENTER	0	448.30	30.00	0.00	Replace	Not given	No <i>✓</i>
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	30.00	613.41	Replace	Check	No <i>✓</i>
53301-47060		6505555	HOOD PANEL	1	748.10	100.00	0.00	Replace	Repair	No <i>✓</i>
53341-47020			HOOD PANEL INSULATOR	0	390.50	30.00	0.00	Replace	Not given	No <i>✓</i>
53410-47070			HOOD HINGE RH	0	55.90	30.00	0.00	Replace	Not given	No <i>✓</i>
53420-47070			HOOD HINGE LH	0	55.90	30.00	0.00	Replace	Not given	No <i>✓</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
55708-47104			WIPER GARNISH	0	614.00	30.00	0.00	Replace	Not given	No
55084-47011			WIPER GARNISH COVER, LH	0	23.80	30.00	0.00	Replace	Not given	No
55083-47011			WIPER GARNISH COVER, RH	0	23.80	30.00	0.00	Replace	Not given	No
53510-47102			HOOD LOCK	0	128.90	30.00	0.00	Replace	Not given	No
53630-47050			CABLE ASSY, HOOD	0	52.20	30.00	0.00	Replace	Not given	No
53557-47010			HOOD AUXILIARY CATCH	0	8.60	30.00	0.00	Replace	Not given	No
53614-47030			CLAMP, HOOD LOCK	0	5.90	30.00	0.00	Replace	Not given	No
86510-28130			HORN ASSY, HIGH	0	110.40	30.00	0.00	Replace	Not given	No
86520-28180			HORN ASSY, LOW	0	110.40	30.00	0.00	Replace	Not given	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	30.00	1,022.28	Replace	Replace	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Check	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Check	No
88460-47150			A/C CONDENSER	1	1,181.90	30.00	827.33	Replace	Replace	No
88710-47150			TUBE & ACCESSORY	1	631.90	30.00	442.33	Replace	Check	No
88703-47040			HOSE SUB-ASSY, DISCHARGE	1	386.90	30.00	270.83	Replace	Check	No
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	30.00	475.72	Replace	Replace	No
G9225-47021			HOSE, INVERTER NO.1	1	80.00	30.00	56.00	Replace	Check	No
G9229-47020			HOSE, INVERTER COOLING NO.5	1	125.30	30.00	87.71	Replace	Check	No
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	30.00	1,047.83	Replace	Replace	No
16523-21050			CUSHION, RADIATOR	2	11.30	30.00	15.82	Replace	Check	No
16534-37010			SUPPORT, RADIATOR, LH	1	17.70	30.00	12.39	Replace	Check	No
16533-28051			SUPPORT, RADIATOR, RH	1	54.50	30.00	38.15	Replace	Check	No
16535-20030			SUPPORT, RADIATOR,	2	18.50	30.00	25.90	Replace	Check	No
16572-37120			RADIATOR HOSE LOWER	1	42.40	30.00	29.68	Replace	Check	No
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	30.00	475.72	Replace	Check	No
16571-37140		6505303	RADIATOR TOP HOSE NO 1	1	42.40	30.00	29.68	Replace	Check	No
16261-37070			RADIATOR HOSE, BYPASS NO.1	1	37.20	30.00	26.04	Replace	Check	No
16264-37080			RADIATOR HOSE, BYPASS NO.2	1	29.00	30.00	20.30	Replace	Check	No
16267-37030			RADIATOR HOSE, BYPASS NO.3	1	37.20	30.00	26.04	Replace	Check	No
16281-37030			RADIATOR HOSE, BYPASS NO.4	1	37.20	30.00	26.04	Replace	Check	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMO N		COOLANT	1	12.32	0.00	12.32	Replace	Replace <i>neu</i>	No ☒
16711-37040			FAN SHROUD	1	244.50	30.00	171.15	Replace	Replace <i>S</i>	No ☒ <i>CR</i>
16712-37030			FAN SHROUD TOP	1	99.60	30.00	69.72	Replace	Replace <i>S</i>	No ☒ <i>CR</i>
16361-37010			FAN BLADE	1	158.60	30.00	111.02	Replace	Replace <i>S</i>	No ☒ <i>cut</i>
16361-28360			FAN BLADE NO 2	1	204.20	30.00	142.94	Replace	Replace <i>S</i>	No ☒ <i>cut</i>
16363-37010			FAN MOTOR NO 1	1	538.30	30.00	376.81	Replace	Replace <i>S</i>	No ☒ <i>short</i>
16363-37020			FAN MOTOR NO 2	1	538.30	30.00	376.81	Replace	Replace <i>S</i>	No ☒ <i>short</i>
53801-47050		6505557	FENDER FRT/RH	1	723.40	100.00	0.00	Replace	Repair	No ☒
75374-47051			NAME PLATE (HYBRID)	1	51.90	30.00	36.33	Replace	Replace	No ☒ <i>neu</i>
53875-47030		6505553	FENDER LINER FRT/RH	0	171.70	30.00	0.00	Replace	Not given	No ☒ <i>S</i>
53851-47040			FENDER LINER PAD, FR WHEEL RH	0	49.30	30.00	0.00	Replace	Not given	No ☒ <i>S</i>
53802-47050		6505558	FENDER FRT/LH	1	723.40	100.00	0.00	Replace	Repair	No ☒
75374-47051			NAME PLATE (HYBRID)	1	51.90	30.00	36.33	Replace	Replace	No ☒ <i>neu</i>
53876-47030		6505554	FENDER LINER FRT/LH	0	171.70	30.00	0.00	Replace	Not given	No ☒ <i>S</i>
53852-47020			FENDER LINER PAD, FR WHEEL LH	0	49.30	30.00	0.00	Replace	Not given	No ☒ <i>S</i>
TOTAL MATERIALS							10,783.35	6,773.60		
TOTAL MATERIALS(Discounted)							8,626.68	5,418.88		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 6773.60 \\
 - 20\% \\
 \hline
 5418.88 \\
 900 \\
 + 1330 \\
 \hline
 7648.88
 \end{array}$$

4/5 - \$7650

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018		24 Jul 2018 15:36 Edit Adj Rpt	S\$7,650.00 Edit Estimates	S\$7,650.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:

FONG CHEE CHEONG, ID: S8175774G

Main Claimant:

SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K

Vehicle Reg. No.:

SHF1025X

Date of Loss:

12/07/2018 00:00 - :59
[42 Months and 25 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 564992

Policy/Cover Note No.:

29027333QMX
Coverage: 25/09/2017 - 25/09/2018

Vehicle Reg. No. (Insured):

SJH67Y

Policy No. (Claimant):

Excess:

Repairer:

SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/08/2018]

Adj Asg. Remarks:

Direct Survey done on 16/07/18.

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

*SHF1025X (564992)
 [SJH67Y]
 TP
 SMRT TAXIS PTE LTD
 Jul 12 2018 12:00AM
 [FONG CHEE CHEONG]
 SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 16:04	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/08/18 14:23	Chassis Number	Load JPG	☒
2	15/08/18 14:23	General View	Load JPG	☒
3	15/08/18 14:23	General View	Load JPG	☒
4	15/08/18 14:23	General View	Load JPG	☒
5	15/08/18 14:23	General View	Load JPG	☒
6	15/08/18 14:23	General View	Load JPG	☒
7	15/08/18 14:23	General View	Load JPG	☒
8	15/08/18 14:23	General View	Load JPG	☒
9	15/08/18 14:23	General View	Load JPG	☒
10	15/08/18 14:23	General View	Load JPG	☒
11	15/08/18 14:23	General View	Load JPG	☒
12	15/08/18 14:23	General View	Load JPG	☒
13	15/08/18 14:23	General View	Load JPG	☒
14	15/08/18 14:23	General View	Load JPG	☒
15	15/08/18 14:23	General View	Load JPG	☒
16	15/08/18 14:23	General View	Load JPG	☒
17	15/08/18 14:23	General View	Load JPG	☒
18	15/08/18 14:23	General View	Load JPG	☒
19	15/08/18 14:23	General View	Load JPG	☒
20	15/08/18 14:23	General View	Load JPG	☒
21	15/08/18 14:23	General View	Load JPG	☒
22	15/08/18 14:23	General View	Load JPG	☒
23	15/08/18 14:23	General View	Load JPG	☒
24	15/08/18 14:23	General View	Load JPG	☒
25	15/08/18 14:23	General View	Load JPG	☒
26	15/08/18 14:23	General View	Load JPG	☒
27	15/08/18 14:23	General View	Load JPG	☒
28	15/08/18 14:23	General View	Load JPG	☒
29	15/08/18 14:23	General View	Load JPG	☒
30	15/08/18 14:23	General View	Load JPG	☒
31	15/08/18 14:23	General View	Load JPG	☒
32	15/08/18 14:23	General View	Load JPG	☒
33	15/08/18 14:23	General View	Load JPG	☒
34	15/08/18 14:23	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	15/08/18 14:23	General View		☒
36	15/08/18 14:23	General View		☒
37	15/08/18 14:23	General View		☒
38	15/08/18 14:23	General View		☒
39	15/08/18 14:23	General View		☒
40	15/08/18 14:23	General View		☒
41	15/08/18 14:23	General View		☒
42	15/08/18 14:23	General View		☒
43	15/08/18 14:23	General View		☒
44	15/08/18 14:23	General View		☒
45	15/08/18 14:23	General View		☒
46	15/08/18 14:23	General View		☒
47	15/08/18 14:23	General View		☒
48	15/08/18 14:23	General View		☒
49	15/08/18 14:23	General View		☒
50	15/08/18 14:25	Reinspection Photo		☒
51	15/08/18 14:25	Reinspection Photo		☒
52	15/08/18 14:25	Reinspection Photo		☒
53	15/08/18 14:25	Reinspection Photo		☒
54	15/08/18 14:25	Reinspection Photo		☒
55	15/08/18 14:25	Reinspection Photo		☒
56	15/08/18 14:25	Reinspection Photo		☒
57	15/08/18 14:25	Reinspection Photo		☒
58	15/08/18 14:25	Reinspection Photo		☒
59	15/08/18 14:25	Reinspection Photo		☒
60	15/08/18 14:25	Reinspection Photo		☒
61	15/08/18 14:25	Reinspection Photo		☒
62	15/08/18 14:25	Reinspection Photo		☒
63	15/08/18 14:25	Reinspection Photo		☒
64	15/08/18 14:25	Reinspection Photo		☒
65	15/08/18 14:25	Reinspection Photo		☒
66	15/08/18 14:25	Reinspection Photo		☒
67	15/08/18 14:25	Reinspection Photo		☒
68	15/08/18 14:25	Reinspection Photo		☒
69	15/08/18 14:25	Reinspection Photo		☒
70	15/08/18 14:25	Reinspection Photo		☒
71	15/08/18 14:25	Reinspection Photo		☒
72	15/08/18 14:25	Reinspection Photo		☒
73	15/08/18 14:25	Reinspection Photo		☒
74	15/08/18 14:25	Reinspection Photo		☒
75	15/08/18 14:25	Reinspection Photo		☒
76	15/08/18 14:25	Reinspection Photo		☒
77	15/08/18 14:25	Reinspection Photo		☒
78	15/08/18 14:25	Reinspection Photo		☒
79	15/08/18 14:25	Reinspection Photo		☒
80	15/08/18 14:25	Reinspection Photo		☒
81	15/08/18 14:25	Reinspection Photo		☒
82	15/08/18 14:25	Reinspection Photo		☒
83	15/08/18 14:25	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	15/08/18 14:25	Reinspection Photo		☒
85	15/08/18 14:25	Reinspection Photo		☒
86	15/08/18 14:36	Photo After Spray		☒
87	15/08/18 14:36	Photo After Spray		☒
88	15/08/18 14:36	Photo After Spray		☒
89	15/08/18 14:36	Photo After Spray		☒
90	15/08/18 14:36	Photo After Spray		☒
91	15/08/18 14:36	Photo After Spray		☒
92	15/08/18 14:36	Photo After Spray		☒
93	15/08/18 14:36	Photo After Spray		☒
94	15/08/18 14:36	Photo After Spray		☒
95	15/08/18 14:36	Photo After Spray		☒
96	15/08/18 14:36	Photo After Spray		☒
97	15/08/18 14:36	Photo After Spray		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 15:55	TP GIA REPORT		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18012911/R1SBE2

Date: 27/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29027333QMX

Claimant Vehicle No: SHF1025X

Insured Vehicle No: SJH67Y

Date of Loss: 12/07/2018

Nature of Claim: TP

Claim No: 564992

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF1025X

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR1472577

Reg. Date: 17/12/2014 (Man. Year: 2014)

Chassis No: JTDKN36U305754566

Colour: Maroon

Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	19,708.62	6,773.60	12,935.02	65.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,273.00	2,230.00	2,043.00	47.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,981.62	9,003.60	14,978.02	62.46
Approved Total (Overridden) (S\$)		7,650.00		
Nett Amount (S\$)	23,981.62	7,650.00	16,331.62	68.10

INSPECTION

Date of Assignment: 24/07/2018

Date Inspected: 16/07/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHF1025X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 30%)	Deformed	482.00 F	*337.40 F
2	10		*BUMPER CLIPS (DISC 30%)	Necessary	21.00 F	*14.70 F
3	1		*BUMPER SUPPORT F/LH (DISC 30%)	Necessary	76.40 F	*53.48 F
4	1		*BUMPER SUPPORT F/RH (DISC 30%)	Necessary	76.40 F	*53.48 F
5	1		*BUMPER ENERGY ABSORBER FRT (DISC 30%)	Deformed	78.80 F	*55.16 F
6	1		*BUMPER REINFORCEMENT FRT (DISC 30%)	Bent	498.40 F	*348.88 F
7	1		*ARM SUB-ASSY, FR BUMPER LH (DISC 30%)	Bent	250.40 F	*175.28 F
8	1		*ARM SUB-ASSY, FR BUMPER RH (DISC 30%)	Bent	250.40 F	*175.28 F
9	1		*BRACKET, FR BUMPER (DISC 30%)	Necessary	110.40 F	*77.28 F
10	1		*BUMPER GRILLE SUB-ASSY, LOWER (DISC 30%)	Cracked	311.10 F	*217.77 F
11	1		*EMBLEM FRONT (DISC 30%)	Necessary	86.50 F	*60.55 F
12	1		*GRILLE RADIATOR (DISC 30%)	Deformed	310.60 F	*217.42 F
13	1		*GRILLE RADIATOR LOWER NO.2 (DISC 30%)	Deformed	94.60 F	*66.22 F
14	1		*BUMPER LIP FRT (DISC 30%)	Cracked	139.60 F	*97.72 F
15	1		*BUMPER FRT ABSORBER LOWER (DISC 30%)	Cracked	127.70 F	*89.39 F
16	1		*SUPPORT SUB-ASSY (DISC 30%)	Bent	1,460.40 F	*1,022.28 F
17	1		*A/C CONDENSER (DISC 30%)	Bent	1,181.90 F	*827.33 F
18	1		*RADIATOR ASSY, UPPER (DISC 30%)	Bent	679.60 F	*475.72 F
19	1		*RADIATOR ASSY (DISC 30%)	Bent	1,496.90 F	*1,047.83 F
20	1		*FAN SHROUD (DISC 30%)	Cracked	244.50 F	*171.15 F
21	1		*FAN SHROUD TOP (DISC 30%)	Cracked	99.60 F	*69.72 F
22	1		*FAN BLADE (DISC 30%)	Cut	158.60 F	*111.02 F
23	1		*FAN BLADE NO 2 (DISC 30%)	Cut	204.20 F	*142.94 F
24	1		*FAN MOTOR NO 1 (DISC 30%)	Shorted	538.30 F	*376.81 F
25	1		*FAN MOTOR NO 2 (DISC 30%)	Shorted	538.30 F	*376.81 F
26	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
27	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
28	1		*NUMBER PLATE (SN)	Bent	15.00 F	*15.00 F
29	1		*NUMBER PLATE FRAME (SN)	Cracked	12.00 F	*12.00 F
30	1		*COOLANT (SN)	Necessary	12.32 F	*12.32 F
31	1		*DEFLECTOR, RADIATOR LH	Serviceable	77.00 F	*- F
32	1		*DEFLECTOR, RADIATOR RH	Serviceable	83.50 F	*- F
33	1		*HOOD END PANEL SEAL	Serviceable	35.50 F	*- F
34	1		*COVER, RADIATOR	Serviceable	122.80 F	*- F
35	1		*UNDER COVER CENTER	Serviceable	448.30 F	*- F
36	1		*RADIATOR LOWER SUPPORT	Serviceable	876.30 F	*- F
37	1		*HOOD PANEL INSULATOR	Serviceable	390.50 F	*- F
38	1		*HOOD HINGE RH	Serviceable	55.90 F	*- F
39	1		*HOOD HINGE LH	Serviceable	55.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*WIPER GARNISH	Serviceable	614.00 F	*- F
41	1		*WIPER GARNISH COVER, LH	Serviceable	23.80 F	*- F
42	1		*WIPER GARNISH COVER, RH	Serviceable	23.80 F	*- F
43	1		*HOOD LOCK	Serviceable	128.90 F	*- F
44	1		*CABLE ASSY, HOOD	Serviceable	52.20 F	*- F
45	1		*HOOD AUXILIARY CATCH	Serviceable	8.60 F	*- F
46	1		*CLAMP, HOOD LOCK	Serviceable	5.90 F	*- F
47	1		*HORN ASSY, HIGH	Serviceable	110.40 F	*- F
48	1		*HORN ASSY, LOW	Serviceable	110.40 F	*- F
49	1		*HEAD LAMP LH	Serviceable	945.20 F	*- F
50	1		*HEAD LAMP RH	Serviceable	945.20 F	*- F
51	1		*TUBE & ACCESSORY	Serviceable	631.90 F	*- F
52	1		*HOSE SUB-ASSY, DISCHARGE	Serviceable	386.90 F	*- F
53	1		*HOSE, INVERTER NO.1	Serviceable	80.00 F	*- F
54	1		*HOSE, INVERTER COOLING NO.5	Serviceable	125.30 F	*- F
55	2		*CUSHION, RADIATOR	Serviceable	22.60 F	*- F
56	1		*SUPPORT, RADIATOR, LH	Serviceable	17.70 F	*- F
57	1		*SUPPORT, RADIATOR, RH	Serviceable	54.50 F	*- F
58	2		*SUPPORT, RADIATOR	Serviceable	37.00 F	*- F
59	1		*RADIATOR HOSE LOWER	Serviceable	42.40 F	*- F
60	1		*RADIATOR ASSY, UPPER	Serviceable	679.60 F	*- F
61	1		*RADIATOR TOP HOSE NO 1	Serviceable	42.40 F	*- F
62	1		*RADIATOR HOSE, BYPASS NO.1	Serviceable	37.20 F	*- F
63	1		*RADIATOR HOSE, BYPASS NO.2	Serviceable	29.00 F	*- F
64	1		*RADIATOR HOSE, BYPASS NO.3	Serviceable	37.20 F	*- F
65	1		*RADIATOR HOSE, BYPASS NO.4	Serviceable	37.20 F	*- F
66	1		*FENDER LINER FRT / RH	Serviceable	171.70 F	*- F
67	1		*FENDER LINER PAD, FR WHEEL, RH	Serviceable	49.30 F	*- F
68	1		*FENDER LINER FRT / LH	Serviceable	171.70 F	*- F
69	1		*FENDER LINER PAD, FR WHEEL, LH	Serviceable	49.30 F	*- F
70	1		*COVER, FR BUMPER HOLE LH	Repair	18.50 F	*- F
71	1		*COVER, FR BUMPER HOLE RH	Repair	18.50 F	*- F
72	1		*HOOD PANEL	Repair	748.10 F	*- F
73	1		*FENDER FRT / RH	Repair	723.40 F	*- F
74	1		*FENDER FRT / LH	Repair	723.40 F	*- F

F=Franchise part.

Total Parts (\$\$) **19,708.62** **6,773.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,521.00	900.00
2	SPRAY PAINT	New	2,052.00	1,100.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	60.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	60.00
5	TO TOP UP A/C GAS	New	120.00	80.00
6	TO REMOVE & REFIT RADIATOR LOWER SUPPORT	New	120.00	0.00
7	TO CONDUCT RADIATOR PRESSURE CHECK	New	120.00	30.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			4,273.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >