

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)
 Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLG4419X)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHF HEADLAMP HID BULB <i>incl</i>	0.00	0.00	*240.00 F
2	1		*LHF HEADLAMP HID CONTROL UNIT <i>incl</i>	0.00	0.00	*500.00 F
3	1		*LHF HEADLAMP HID MODULE <i>incl</i>	0.00	0.00	*250.00 F
4	1		*LHF FENDER BRACKET, TOP <i>incl</i>	0.00	0.00	*20.00 F
5	1		*LHF FENDER BRACKET, SIDE <i>incl</i>	0.00	0.00	*20.00 F
6	1		*HORN <i>incl</i>	0.00	0.00	*80.00 F
7	1		*WIPER TANK MOTOR <i>incl</i>	0.00	0.00	*65.00 F
Total Parts (S\$)						1,175.00 <i>1190</i>

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

SUPP 1190.00
 PARTS 420.00
 SAL 45.00
 LAB 1820.00
 7175.00

Adrian Lij
 20/07/18.
 H.L.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)
 Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

00 6980

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BONNET <i>Washed</i>	0.00	0.00	*1,100.00 F ✓
2	1	NA	*FRONT BONNET HINGE - LH <i>Best</i>	0.00	0.00	*25.00 F ✓
3	1	NA	*FRONT BONNET HINGE - RH <i>Not in</i>	0.00	0.00	*25.00 F ✓
4	1	NA	*FRONT BONNET ABSORBER - RH <i>Not in</i>	0.00	0.00	*50.00 F ✓
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE <i>Not in</i>	0.00	0.00	*35.00 F ✓
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH <i>Not in</i>	0.00	0.00	*80.00 F ✓
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE <i>Not in</i>	0.00	0.00	*25.00 F ✓
8	1	NA	*FRONT BONNET INSULATOR <i>Not in</i>	0.00	0.00	*80.00 F ✓
9	5	NA	*FRONT BONNET INSULATOR CLIP <i>Not in</i>	0.00	0.00	*7.50 F ✓
10	1	NA	*FRONT BONNET RUBBER <i>Not in</i>	0.00	0.00	*10.00 F ✓
11	1	NA	*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*700.00 F ✓
12	1	NA	*FRONT BUMPER CLIPS <i>in</i>	0.00	0.00	*50.00 F ✓
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>Not in</i>	0.00	0.00	*15.00 F ✓
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>Not in</i>	0.00	0.00	*15.00 F ✓
15	1	NA	*FRONT BUMPER FOAM <i>Crushed</i>	0.00	0.00	*50.00 F ✓
16	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*265.00 F ✓
17	1	NA	*FRONT BUMPER TOWING COVER - RH <i>Not in</i>	0.00	0.00	*15.00 F ✓
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - LH <i>Missing</i>	0.00	0.00	*45.00 F ✓
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - RH <i>Not in</i>	0.00	0.00	*45.00 F ✓
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH <i>Not in</i>	0.00	0.00	*20.00 F ✓
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH <i>Not in</i>	0.00	0.00	*20.00 F ✓
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH <i>Not in</i>	0.00	0.00	*100.00 F ✓
23	1	NA	*FRONT BUMPER NOZZLE - LH <i>Crushed</i>	0.00	0.00	*80.00 F ✓
24	1	NA	*FRONT BUMPER NOZZLE - RH <i>Not in</i>	0.00	0.00	*80.00 F ✓
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE <i>Not in</i>	0.00	0.00	*60.00 F ✓
26	1	NA	*GRILLE ASSY <i>Crushed</i>	0.00	0.00	*250.00 F ✓
27	1	NA	*GRILLE LOGO <i>in</i>	0.00	0.00	*40.00 F ✓
28	1	NA	*SUPPORT PANEL <i>Crushed</i>	0.00	0.00	*265.00 F ✓
29	1	NA	*RADIATOR - OUTER <i>Not in</i>	0.00	0.00	*250.00 F ✓
30	1	NA	*RADIATOR - INNER <i>Not in</i>	0.00	0.00	*250.00 F ✓
31	1	NA	*CONDENSER <i>Not in</i>	0.00	0.00	*280.00 F ✓
32	1	NA	*AUTO COOLER <i>Not in</i>	0.00	0.00	*200.00 F ✓
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH <i>Not in</i>	0.00	0.00	*12.00 F ✓
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>Not in</i>	0.00	0.00	*12.00 F ✓
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE <i>Not in</i>	0.00	0.00	*625.00 F ✓
36	1	NA	*HEAD LAMP - RH <i>Not in</i>	0.00	0.00	*715.00 F ✓
37	1	NA	*HEAD LAMP - LH <i>Crushed</i>	0.00	0.00	*715.00 F ✓
38	1	NA	*RADIATOR TOP HOSE <i>Not in</i>	0.00	0.00	*110.00 F ✓
39	1	NA	*RADIATOR BOTTOM HOSE <i>Not in</i>	0.00	0.00	*75.00 F ✓
40	1	NA	*FRONT FENDER - LH <i>Distorted</i>	0.00	0.00	*300.00 F ✓
41	1	NA	*FRONT FENDER COWLING - LH <i>Torn</i>	0.00	0.00	*60.00 F ✓
42	1	NA	*FRONT FENDER COWLING CLIPS - LH <i>Not in</i>	0.00	0.00	*25.00 F ✓
43	1	NA	*WIPER TANK ASSY <i>Distorted</i>	0.00	0.00	*80.00 F ✓
44	1	NA	*WIPER TANK MOTOR <i>Qty 2</i>	0.00	0.00	*65.00 F ✓

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

4420

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>New</i>	20.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>New</i>	35.00 ✓ 25
Sub Total (S\$)			55.00 ✓ 45

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900 ✓ 1,100.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; LH FRONT WHEEL HOUSE; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	900 ✓ 1,100.00
3	TO CHECK WIRING	New	20.00 ✓
4	TO RESET CHECK LIGHT	New	60.00 ✗
5	TO 4 WHEEL ALIGNMENT	New	70.00 ✗
Gross Labour Cost (S\$)			2,350.00 ✓ 1820

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Adrian Ling.
P/P 17/07/18
Not Authorised.
OT Days.
Excess \$600.