



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0718-6580
Policy No:	PNPV2017-00006429	Date of Loss:	16/07/2018
Vehicle Reg. No.:	SLG4419X	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOW CHEN HOW	Contact No:	+6593691843
Driver:	CHOW CHEN HOW		
Make/Model:	AUDI A3, 1.4 TFSI (A)	Vehicle Reg. Date:	29/09/2016
Vehicle Colour:	GREY		
Engine No:	CZC564564	Chassis No:	WAUZZZ8V4G1105109
Odometer:	33660 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	7,326.50
Miscellaneous Items	55.00
Labour	1,250.00
Paintwork Labour	1,100.00
Towing	0.00
Gross Total (\$)	9,731.50
+ GST 7.00% (\$)	681.21
Nett Amount (\$)	10,412.71

This claim is handled by: **NG PEI WEN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)**Parts:** 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BONNET <i>Washed</i>	0.00	0.00	*1,100.00 F ✓
2	1	NA	*FRONT BONNET HINGE - LH <i>Best</i>	0.00	0.00	*25.00 F ✓
3	1	NA	*FRONT BONNET HINGE - RH ?	0.00	0.00	*25.00 F ?
4	1	NA	*FRONT BONNET ABSORBER - RH <i>new</i>	0.00	0.00	*50.00 F +
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE <i>new</i>	0.00	0.00	*35.00 F +
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH <i>new</i>	0.00	0.00	*80.00 F +
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE <i>new new</i>	0.00	0.00	*25.00 F +
8	1	NA	*FRONT BONNET INSULATOR <i>new new</i>	0.00	0.00	*80.00 F +
9	5	NA	*FRONT BONNET INSULATOR CLIP <i>new</i>	0.00	0.00	*7.50 F +
10	1	NA	*FRONT BONNET RUBBER <i>new</i>	0.00	0.00	*10.00 F ✓
11	1	NA	*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*700.00 F ✓
12	1	NA	*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*50.00 F ✓
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>Replaced</i>	0.00	0.00	*15.00 F ✓
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>new new</i>	0.00	0.00	*15.00 F +
15	1	NA	*FRONT BUMPER FOAM <i>Crushed</i>	0.00	0.00	*50.00 F ✓
16	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*265.00 F ✓
17	1	NA	*FRONT BUMPER TOWING COVER - RH <i>new new</i>	0.00	0.00	*15.00 F +
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - LH <i>Missing</i>	0.00	0.00	*45.00 F ✓
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - RH <i>new new</i>	0.00	0.00	*45.00 F +
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH <i>Replaced</i>	0.00	0.00	*20.00 F ✓
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH <i>new</i>	0.00	0.00	*20.00 F +
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH <i>cut & new new</i>	0.00	0.00	*100.00 F +
23	1	NA	*FRONT BUMPER NOZZLE - LH <i>Crushed</i>	0.00	0.00	*80.00 F ✓
24	1	NA	*FRONT BUMPER NOZZLE - RH <i>new new</i>	0.00	0.00	*80.00 F ✓
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE <i>new new</i>	0.00	0.00	*60.00 F +
26	1	NA	*GRILLE ASSY <i>Crushed</i>	0.00	0.00	*250.00 F ✓
27	1	NA	*GRILLE LOGO <i>new</i>	0.00	0.00	*40.00 F ✓
28	1	NA	*SUPPORT PANEL <i>Crushed</i>	0.00	0.00	*265.00 F ✓
29	1	NA	*RADIATOR - OUTER } <i>new new</i>	0.00	0.00	*250.00 F +
30	1	NA	*RADIATOR - INNER }	0.00	0.00	*250.00 F +
31	1	NA	*CONDENSER	0.00	0.00	*280.00 F +
32	1	NA	*AUTO COOLER	0.00	0.00	*200.00 F +
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH ?	0.00	0.00	*12.00 F ?
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>new new</i>	0.00	0.00	*12.00 F +
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE <i>new new</i>	0.00	0.00	*625.00 F +
36	1	NA	*HEAD LAMP - RH <i>new new</i>	0.00	0.00	*715.00 F +
37	1	NA	*HEAD LAMP - LH <i>smashed</i>	0.00	0.00	*715.00 F ✓
38	1	NA	*RADIATOR TOP HOSE <i>new new</i>	0.00	0.00	*110.00 F +
39	1	NA	*RADIATOR BOTTOM HOSE <i>new new</i>	0.00	0.00	*75.00 F +
40	1	NA	*FRONT FENDER - LH <i>Distorted</i>	0.00	0.00	*300.00 F ✓
41	1	NA	*FRONT FENDER COWLING - LH <i>torn</i>	0.00	0.00	*60.00 F ✓
42	1	NA	*FRONT FENDER COWLING CLIPS - LH <i>new</i>	0.00	0.00	*25.00 F ✓
43	1	NA	*WIPER TANK ASSY <i>Distorted</i>	0.00	0.00	*80.00 F ✓
44	1	NA	*WIPER TANK MOTOR ?	0.00	0.00	*65.00 F ?

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
F=Franchise part.						
Total Parts (S\$)						7,326.50

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>New</i>	20.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>New</i>	35.00 25
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS.	New	1,100.00 900
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; LH FRONT WHEEL HOUSE; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 900
3	TO CHECK WIRING	New	20.00 ✓
4	TO RESET CHECK LIGHT	New	60.00 ✗
5	TO 4 WHEEL ALIGNMENT	New	70.00 ✗
Gross Labour Cost (S\$)			2,350.00

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling.
P/P 17/07/18.
Not Authorised.
07 Days.
Excess \$600.