

15/5/2010

INS. CASE OWNER:

Finchuan

CC 4 ASM
AXA1801

2455, R1 e6h32

LKK:

IDAC:

Surveyor:

Rasm

DOI:

ASSIGNMENT

Date / Time:

17/7/18

Registered in Merimen:

Pre-assign / CCU / FTE

SFW 1927T



Insured Vehicle No.:

Claim No.:

S8MOD00W/51828

Name of Insured:

YAP FEN SIA FRANCIS

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

15/7/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Sjm 88795

INSRS:
WSP:
Tel:
Liability:
RMKS:Sng
Ah
LeeINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

18/7/18

Ashw

Sjm 88795-7

SFW 1927T-7

STAGE

DATE / PIC

Non-Reporting ltr (1st): 18.7.18

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 12.9.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MEB

Repair Cost:

SS 4,000

(15 days) Reduction:

50 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: JAMES

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 4,280.00

DID REPAIR ENDORSE TP

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 840.00

(S 60 x 14 days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS 44.99

(AUDATEX)

(e.g. Tow/ Independent)

2) Report Format:

TP

Legal Cost

SS

3) Survey fee:

+350

Total:

SS 5,166.99

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with: JANICE

Email

Call

Payee 1:

SS 5,166.99

Name 1:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

(08/11/13)

REF:

Surveyor: *Jan*

ASSIGNMENT

00143
06 APR 2019 / Jan

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *11k*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *12* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SJM 88793* Yr Regn: *2009 / Jan*Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *TOYOTA AXIO 1.5 XA* c.c *1496*Colour: *Blue* A/C: Insured / Std / NI / NASp. Reading: *306 703* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *N2E1416095618*Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: *215/16R15*R: *215/16R15*BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *15/07/18* D.O.I. *18/07/18*Survey held at *SP4 44 TCC*Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>refer to email. repair limit 3k. repair K1V</i>
	<i>4/3: 4,000 (RED: 43,997.39 50%)</i>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Report Format: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS, SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

TOTAL

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012955/eb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 17-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 1927T	Veh. Inspected	SJM 8879S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/07/2018	Inspection Date		
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000521
Version: SNGAHTEE/1
Date Calculated: 18/07/2018 03:35

Full Report - V1
Registration: SJM8879S
Printed: 18/07/2018 10:35

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	DARREN SNG	Date of Incident:	15/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla
Sub Model:	BASE MODEL
Model Sheet Number:	YAC 01
Registration:	SJM8879S
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 12/2008	AIR CONDITIONING
PARKING HELP SYSTEM	1.6 LTR 91 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	17/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000521



Version: SNGAHTEE/1

Date Calculated: 18/07/2018 03:35

Full Report - V1

Registration: SJM8879S

Printed: 18/07/2018 10:35



Addresses

Cost Summary

Total Labour	\$2,128.50
Total Paint/Material	\$295.14
Total Parts	\$5,088.75
Total of Additional Costs	\$435.00
Excess:	TBA
Grand Total Exc GST:	\$7,947.39
7 % GST:	\$556.32
Grand Total Inc GST:	\$8,503.71

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
M250	R + R REAR AXLE INCLUDES: R + R BOOT TRIMS AND WHEELS, BLEED BRAKE SYSTEM	27.0	121.50
NO NUMBER	ADD/WORK FOR PARKING AID SENSOR DRILLING	2.0	9.00
B310)	RENEW R/RR WING INCLUDES: TAILLAMP, LUGG COMP CARPET AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT NOT INCLUDED: SEAT BENCH, SIDE WINDOW RR	60.0	270.00
B290	RIGHT AND BUMPER R + R RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT	37.0	166.50
NO NUMBER	RENEW R/TAILLAMP ATTACHMENT	5.0	22.50
B350	R + R BOOTLID	6.0	27.00
B360)	RENEW BOOTLID (REMOVED) INCLUDES: CONVERT ATTACHED PARTS, RENEW IF NECESSARY	3.0	13.50
B370	R + R BOOTLID HINGES	2.0	9.00
G020	R + R REAR PANEL WINDOW	28.0	126.00
NO NUMBER	R + R L/R OUTER PARKING AID SENSOR	1.0	4.50
NO NUMBER	R + R R/R OUTER PARKING AID SENSOR	1.0	4.50
NO NUMBER	R + R L/R CENTRE PARKING HELP SENSOR	1.0	4.50

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: DS000521

Registration: SJM8879S

Version: SNGAHTEE/1

Printed: 18/07/2018 10:35

Date Calculated: 18/07/2018 03:35

NO NUMBER	R + R R/R CENTRE PARKING HELP SENSOR	1.0	4.50
NO NUMBER	R + R REAR PARKING AID SENSORS ADD/WORK	2.0	9.00
B410	R + R REAR BUMPER	4.0	18.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.50
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT NOT INCLUDED: PARKING HELP SENSOR REMOVE AND REFIT		
M260	R + R FUEL TANK	11.0	49.50
B326	RENEW BOOT FLOOR (COMPOSITE WORK) (ASSEMBLIES AND REAR END PANEL REMOVED)	77.0	346.50
NO NUMBER	RENEW L/R SIDEMEMBER END	5.0	22.50
NO NUMBER	RENEW R/R SIDEMEMBER END	5.0	22.50
B450)	R + R REAR SEAT CUSHION	1.0	4.50
B450)	R + R LEFT REAR SEAT BACK REST	1.0	4.50
B450)	R + R RIGHT REAR SEAT BACK REST	1.0	4.50
M240)	DETACH + REFIT EXHAUST SYSTEM	2.0	9.00
M240)	R + R FRONT EXHAUST PIPE	2.0	9.00
NO NUMBER	R + R FRONT CENTRE PROTECTION SHIELD	3.0	13.50
420091A	R + R SPARE WHEEL AND SPARE TYRE	3.0	13.50
3571	REPAIR L/R LAMP PANEL	5.0*	22.50

LABOUR COST

Total Work Units	297.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	29.7HRS	\$1,336.50
Paint Labour	17.6HRS	\$792.00
Total Labour	47.3HRS	\$2,128.50

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC - PREPARE OFF VEHICLE		
2711	REAR SKIRT CPL NEW PART PAINTING	16.0	
2931	BOOTLID NEW PART PAINTING	18.0	
3482	R/R WING NEW PART PAINTING	28.0	
3572	R/R LAMP PANEL NEW PART PAINTING	9.0	
3901	REAR FLOOR PANEL SURFACE PAINT	11.0	
4001	L/S-MEMBER END PANELSURFACE PAINT	4.0	
4002	R/S-MEMBER END PANELSURFACE PAINT	4.0	
2581	REAR BUMPER NEW PART PAINT K1R	15.0	
2671	L/R CTR PARK SENSOR NEW PART PAINT K1R	3.0	
2672	R/R CTR PARK SENSOR NEW PART PAINT K1R	3.0	
2673	L/R OUT PARKING SENSNEW PART PAINT K1R	3.0	
2674	R/R OUT PARKING SENSNEW PART PAINT K1R	3.0	
2675	L/R INN SENSOR COVERNEW PART PAINT K1R	3.0	
2676	R/R INN SENSOR COVERNEW PART PAINT K1R	3.0	
2677	L/R OUT SENSOR COVERNEW PART PAINT K1R	3.0	
2678	R/R OUT SENSOR COVERNEW PART PAINT K1R	3.0	
2983	TAILGATE TRIM NEW PART PAINT K1R	3.0	
3571	L/R LAMP PANEL REPAIR PAINTING <50%	7.0	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000521

Version: SNGAHTEE/1

Date Calculated: 18/07/2018 03:35

Full Report - V1

Registration: SJM8879S

Printed: 18/07/2018 10:35

1782	R/R DOOR SURFACE PAINT	7.0	
LABOUR COST - PAINT			
	TIME(PAINT)	146.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	176.0	
	Total Paintwork Labour	17.6HRS	\$792.00
MATERIAL COST - PAINT			
	New Part Painting		Cost Price \$111.96
	New Part Painting - Plastic K1R		\$83.63
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$60.01
	Repair Painting		\$1.94
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$295.14
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$295.14

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2581	1	REAR BUMPER	52159 12934		0%	DE 170.00*
2619	1	L/R CTR BUMPER BRKT	52158 12090		0%	ne 35.00*
2620	1	R/R CTR BUMPER BRKT	52157 12160		0%	ne 35.00*
2621	1	L/R BUMPER RR BRKT	52156 12290		0%	ne 35.00*
2622	1	R/F BUMPER RR BRKT	52155 12320		0%	ne 35.00*
2623	1	L/R LOWER PROTECTOR	52592 12120		0%	ne X 35.00*
2624	1	R/R LOWER PROTECTOR	52591 12200		0%	ne X 35.00* x m
2625	1	L/R IMPACT DAMPER	52016 02060		0%	ne X 35.00*
2626	1	R/R IMPACT DAMPER	52015 02070		0%	ne 35.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0%	ne 25.00*
2671	1	L/R CTR PARK SENSOR	89341 33130C0		0%	0.00F
2672	1	R/R CTR PARK SENSOR	89341 33130C0		0%	0.00F
2673	1	L/R OUT PARKING SENS	89341 33180C0		0%	0.00F
2674	1	R/R OUT PARKING SENS	89341 33180C0		0%	0.00F
2675	1	L/R INN SENSOR COVER	89348 33030C0		0%	0.00F
2676	1	R/R INN SENSOR COVER	89348 33030C0		0%	0.00F
2677	1	L/R OUT SENSOR COVER	89348 33080C0		0%	0.00F
2678	1	R/R OUT SENSOR COVER	89348 33080C0		0%	0.00F
2702	1	REAR NUMBER PLATE	KNPL6		0%	0.00F
2711	1	REAR SKIRT CPL	58307 12A40		0%	ne X 150.00*
2931	1	BOOTLID	64401 02290		0%	ne 280.00*
2944	1	BOOTLID SEAL	64461 02110		0%	ne 10.00*
2953	1	L/R HINGE	64503 02090		0%	ne X 45.00*
2954	1	R/R HINGE	64503 02090		0%	ne X 45.00*
2977	1	BOOT/TAILGATE LOCK	64610 12440		0%	ne 45.00*
2983	1	TAILGATE TRIM	76811 02915		0%	ne 75.00*
3015	1	REAR BADGE	90975 02071		0%	ne 25.00*
3160	1	REAR SCREEN BOND KIT	PZ49I 00C1131		0%	ne 0.00F
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS		0%	ne 0.00
3164	2	SPACER	56115 30120		0%	ne 0.00F
3165	2	SPACER	56116 22050		0%	ne 0.00F

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000521

Version: SNGAHTEE/1

Date Calculated: 18/07/2018 03:35

Full Report - V1

Registration: SJM8879S

Printed: 18/07/2018 10:35

3169	1	LWR REAR WINDOW MLDG	64813 12180	0%		0.00FNN
3175	1	REAR WINDOW MOULDING	75571 12A10	0%	mu	55.00*
3281	1	L/R OUTER LAMP	81561 02410	0%	CRA	95.00*
3282	1	R/R OUTER LAMP	81551 02410	0%	CRA	95.00*
3361	1	L/NUMBER PLATE LAMP	81270 02131	0%	W/X	25.00*
3362	1	R/NUMBER PLATE LAMP	81270 02131	0%	W/X	25.00*
3482	1	R/R WING	61601 12A40	0%	mu	350.00*
3572	1	R/R LAMP PANEL	61697 02908	0%	RA	70.00*
3786	1	R/R VENT INSERT	62940 02090	0%	DE	45.00*
3901	1	REAR FLOOR PANEL	58311 12310	0%	mu	280.00*
4001	1	L/S-MEMBER END PANEL	57604 12080	0%	Expain	150.00*
4002	1	R/S-MEMBER END PANEL	57603 12080	0%	mu	150.00*
4907	1	TAILGATE TRIM	64719 12150C0	0%	CRA	150.00*
4959	1	SPARE WHEEL TRIM	58398 12040	0%	DE	150.00*
4960	1	RR SPARE WHEEL TRIM	58399 12020	0%	CRA	140.00*
4978	1	LUGG COMPART CARPET	64771 12250C0	0%	W/X	150.00*
4985	1	END PANEL TRIM	58387 12070	0%	DE	75.00*
5001	1	L/LWR C-PILLAR TRIM	62474 12020B0	0%	DE	150.00*
5002	1	R/LWR C-PILLAR TRIM	62473 02020B0	0%	DE	150.00*
8845	1	CENTRE COVER PANEL	58153 12181	0%	W/X	75.00*
9696	1	SPARE TYRE	195/65 R 15 .. V	0%	W/X	280.00*
1000	1	END PNL T/GRNS CLIPS	Renew	0%	mu	15.00*
1000	1	TAILLAMP CLIPS	Renew	0%	mu	5.00*
1000	1	REAR INSULATOR CLIPS	Renew	0%	mu	20.00*
1000	1	R/R BOOT STOPPER	X 2PCS	0%	mu	90.00*
1000	1	REAR 'X' LOGO	Renew	0%	mu	25.00*
1000	1	REAR 'AXIO' LOGO	Renew	0%	mu	20.00*
1000	1	REVERSE CAMERA	Renew	0%	W/X	380.00*
f: OEM Parts				Saving		\$476.25
g: Original				Sub Total		\$4,425.00
h: Secondhand				Mark Up From Cost (15 %)		\$663.75
p: Parallel				Total Parts		\$5,088.75
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REAR NUMBER PLATE SPECIALIST	0%	\$35.00
REAR PARKING SPECIALIST		\$180.00
SENSOR		
REAR SCREEN GUM SPECIALIST	0%	\$40.00
ANTI RUST COAT SPECIALIST		\$180.00
Total Extras		\$435.00

Final Calculation

Total Parts		\$5,088.75
Labour		
Total Panel/Mechanical	\$1,336.50	
Total Paintwork	\$792.00	
Total Labour		\$2,128.50
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000521

Version: SNGAHTEE/1

Date Calculated: 18/07/2018 03:35

Full Report - V1

Registration: SJM8879S

Printed: 18/07/2018 10:35

Cost of Specialist	\$435.00	
Total of Additional Costs		\$435.00
Total Paint/Material Costs		\$295.14
Grand Total Excludes GST		\$7,947.39
GST @ 7 %		\$556.32
Grand Total Includes GST		\$8,503.71

1661-25

Assessment Notes

Panel
Hp 90010068
12 days
4s
18/07/18 @ 1815
Ready after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000521
Version: SNGAHTEE/2
Date Calculated: 13/11/2018 08:37

Full Report - V1
Registration: SJM8879S
Printed: 13/11/2018 16:38

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	15/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla
Sub Model:	BASE MODEL
Model Sheet Number:	YAC 01
Registration:	SJM8879S
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 12/2008	AIR CONDITIONING
PARKING HELP SYSTEM	1.6 LTR 91 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	17/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD**Claim Reference:****Assessment Number: DS000521****Version: SNGAHTEE/2****Date Calculated: 13/11/2018 08:37****Full Report - V1****Registration: SJM8879S****Printed: 13/11/2018 16:38****Addresses****Cost Summary**

Total Labour	\$2,088.00
Total Paint/Material	\$286.11
Total Parts	\$3,616.75
Total of Additional Costs	\$435.00
Repair Cost Exc GST:	\$6,425.86
Overall Discount (20%):	-\$1,285.17
Excess:	TBA
After Deduction -	
Grand Total Exc GST:	\$5,140.69
7 % GST:	\$359.85
Grand Total Inc GST:	\$5,500.54

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
M250	R + R REAR AXLE	27.0	121.50
	INCLUDES: R + R BOOT TRIMS AND WHEELS, BLEED BRAKE SYSTEM		
NO NUMBER	ADD/WORK FOR PARKING AID SENSOR DRILLING	2.0	9.00
B270	RENEW R/R SIDE PANEL	72.0	324.00
	INCLUDES: R + R TAILLAMP, BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R SEAT CUSHION, R/R SIDE WINDOW AND REAR BUMPER		
B290	RENEW REAR END PANEL (BUMPER REMOVED)	37.0	166.50
	INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT		
B350	R + R BOOTLID	6.0	27.00
B360)	RENEW BOOTLID (REMOVED)	3.0	13.50
	INCLUDES: CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
G020	R + R REAR PANEL WINDOW	28.0	126.00
NO NUMBER	R + R L/R OUTER PARKING AID SENSOR	1.0	4.50
NO NUMBER	R + R R/R OUTER PARKING AID SENSOR	1.0	4.50
NO NUMBER	R + R L/R CENTRE PARKING HELP SENSOR	1.0	4.50

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: DS000521

Registration: SJM8879S

Version: SNGAHTTE/2

Printed: 13/11/2018 16:38

Date Calculated: 13/11/2018 08:37

NO NUMBER	R + R R/R CENTRE PARKING HELP SENSOR	1.0	4.50
NO NUMBER	R + R REAR PARKING AID SENSORS ADD/WORK	2.0	9.00
B410	R + R REAR BUMPER	4.0	18.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.50
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		
	NOT INCLUDED: PARKING HELP SENSOR REMOVE AND REFIT		
M260	R + R FUEL TANK	11.0	49.50
B326	RENEW BOOT FLOOR (COMPOSITE WORK) (ASSEMBLIES AND REAR END PANEL REMOVED)	77.0	346.50
NO NUMBER	RENEW L/R SIDEMEMBER END	5.0	22.50
NO NUMBER	RENEW R/R SIDEMEMBER END	5.0	22.50
B450)	R + R REAR SEAT CUSHION	1.0	4.50
B450)	R + R LEFT REAR SEAT BACK REST	1.0	4.50
B450)	R + R RIGHT REAR SEAT BACK REST	1.0	4.50
M240)	DETACH + REFIT EXHAUST SYSTEM	2.0	9.00
M240)	R + R FRONT EXHAUST PIPE	2.0	9.00
420091A	R + R SPARE WHEEL AND SPARE TYRE	3.0	13.50
3571	REPAIR L/R LAMP PANEL	5.0*	22.50

LABOUR COST

Total Work Units	299.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	29.9HRS	\$1,345.50
Paint Labour	16.5HRS	\$742.50
Total Labour	46.4HRS	\$2,088.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2931	BOOTLID NEW PART PAINTING	18.0	
3482	R/R WING NEW PART PAINTING	28.0	
3572	R/R LAMP PANEL NEW PART PAINTING	9.0	
3901	REAR FLOOR PANEL SURFACE PAINT	11.0	
4001	L/S-MEMBER END PANELSURFACE PAINT	4.0	
4002	R/S-MEMBER END PANELSURFACE PAINT	4.0	
2581	REAR BUMPER NEW PART PAINT K1R	15.0	
2671	L/R CTR PARK SENSOR NEW PART PAINT K1R	3.0	
2672	R/R CTR PARK SENSOR NEW PART PAINT K1R	3.0	
2673	L/R OUT PARKING SENSNEW PART PAINT K1R	3.0	
2674	R/R OUT PARKING SENSNEW PART PAINT K1R	3.0	
2675	L/R INN SENSOR COVERNEW PART PAINT K1R	3.0	
2676	R/R INN SENSOR COVERNEW PART PAINT K1R	3.0	
2677	L/R OUT SENSOR COVERNEW PART PAINT K1R	3.0	
2678	R/R OUT SENSOR COVERNEW PART PAINT K1R	3.0	
2983	TAILGATE TRIM NEW PART PAINT K1R	3.0	
3571	L/R LAMP PANEL REPAIR PAINTING <50%	7.0	
1782	R/R DOOR SURFACE PAINT	7.0	
2711	REAR SKIRT CPL SURFACE PAINT	5.0	

LABOUR COST - PAINT

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000521

Version: SNGAHTEE/2

Date Calculated: 13/11/2018 08:37

Full Report - V1

Registration: SJM8879S

Printed: 13/11/2018 16:38

TIME(PAINT)	135.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	165.0	
Total Paintwork Labour	16.5HRS	\$742.50
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$95.46
New Part Painting - Plastic K1R		\$83.63
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$67.48
Repair Painting		\$1.94
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$286.11
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$286.11

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
2581	1	REAR BUMPER	52159 12934		0% 170.00*
2619	1	L/R CTR BUMPER BRKT	52158 12090		0% 35.00*
2620	1	R/R CTR BUMPER BRKT	52157 12160		0% 35.00*
2621	1	L/R BUMPER RR BRKT	52156 12290		0% 35.00*
2622	1	R/F BUMPER RR BRKT	52155 12320		0% 35.00*
2626	1	R/R IMPACT DAMPER	52015 02070		0% 35.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% 25.00*
2671	1	L/R CTR PARK SENSOR	89341 33130C0		0% 0.00F
2672	1	R/R CTR PARK SENSOR	89341 33130C0		0% 0.00F
2673	1	L/R OUT PARKING SENS	89341 33180C0		0% 0.00F
2674	1	R/R OUT PARKING SENS	89341 33180C0		0% 0.00F
2675	1	L/R INN SENSOR COVER	89348 33030C0		0% 0.00F
2676	1	R/R INN SENSOR COVER	89348 33030C0		0% 0.00F
2677	1	L/R OUT SENSOR COVER	89348 33080C0		0% 0.00F
2678	1	R/R OUT SENSOR COVER	89348 33080C0		0% 0.00F
2702	1	REAR NUMBER PLATE	KNPL6		0% 0.00F
2931	1	BOOTLID	64401 02290		0% 280.00*
2944	1	BOOTLID SEAL	64461 02110		0% 70.00*
2977	1	BOOT/TAILGATE LOCK	64610 12440		0% 45.00*
2983	1	TAILGATE TRIM	76811 02915		0% 75.00*
3015	1	REAR BADGE	90975 02071		0% 25.00*
3160	1	REAR SCREEN BOND KIT	PZ49I 00C1131		0% 0.00F
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS		0% 0.00
3164	2	SPACER	56115 30120		0% 0.00F
3165	2	SPACER	56116 22050		0% 0.00F
3169	1	LWR REAR WINDOW MLDG	64813 12180		0% 0.00F
3175	1	REAR WINDOW MOULDING	75571 12A10		0% 55.00*
3281	1	L/R OUTER LAMP	81561 02410		0% 95.00*
3282	1	R/R OUTER LAMP	81551 02410		0% 95.00*
3482	1	R/R WING	61601 12A40		0% 350.00*
3572	1	R/R LAMP PANEL	61697 02908		0% 70.00*
3786	1	R/R VENT INSERT	62940 02090		0% 45.00*
3901	1	REAR FLOOR PANEL	58311 12310		0% 280.00*
4001	1	L/S-MEMBER END PANEL	57604 12080		0% 150.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000521

Version: SNGAHT/2

Date Calculated: 13/11/2018 08:37

Full Report - V1

Registration: SJM8879S

Printed: 13/11/2018 16:38

4002	1	R/S-MEMBER END PANEL	57603 12080	0%	150.00*
4907	1	TAILGATE TRIM	64719 12150C0	0%	150.00*
4959	1	SPARE WHEEL TRIM	58398 12040	0%	150.00*
4960	1	RR SPARE WHEEL TRIM	58399 12020	0%	140.00*
4985	1	END PANEL TRIM	58387 12070	0%	75.00*
5001	1	L/LWR C-PILLAR TRIM	62474 12020B0	0%	150.00*
5002	1	R/LWR C-PILLAR TRIM	62473 02020B0	0%	150.00*
1000	1	END PNL T/GRNS CLIPS	Renew	0%	15.00*
1000	1	TAILLAMP CLIPS	Renew	0%	5.00*
1000	1	REAR INSULATOR CLIPS	Renew	0%	20.00*
1000	1	R/R BOOT STOPPER	X 2PCS	0%	90.00*
1000	1	REAR 'X' LOGO	Renew	0%	25.00*
1000	1	REAR 'AXIO' LOGO	Renew	0%	20.00*
f: OEM Parts				Saving	\$476.25
g: Original				Sub Total	\$3,145.00
h: Secondhand				Mark Up From Cost (15 %)	\$471.75
p: Parallel				Total Parts	\$3,616.75
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REAR NUMBER PLATE SPECIALIST	0%	\$35.00
REAR PARKING SPECIALIST		\$180.00
SENSOR		
REAR SCREEN GUM SPECIALIST	0%	\$40.00
ANTI RUST COAT SPECIALIST		\$180.00
Total Extras		\$435.00

Final Calculation

Total Parts	\$3,616.75
Labour	
Total Panel/Mechanical	\$1,345.50
Total Paintwork	\$742.50
Total Labour	\$2,088.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$435.00
Total of Additional Costs	\$435.00
Total Paint/Material Costs	\$286.11
Repair Costs Excludes GST	\$6,425.86
Deductions	
Deduction (20.00 %) Before GST	-\$1,285.17
Deduction for Excess	TBA
Total Deductions	-\$1,285.17
Grand Total Excludes GST (After Deduction)	\$5,140.69
GST @ 7 %	\$359.85
Grand Total Includes GST (After Deduction)	\$5,500.54

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: DS000521

Registration: SJM8879S

Version: SNGAHTEE/2

Printed: 13/11/2018 16:38

Date Calculated: 13/11/2018 08:37

Assessment Notes



Service Request Details

Claim

S8M00OLL

Reference

None

Loss Date

July 15, 2018

Request Date

July 16, 2018

Due Date

July 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJM8879S

Make

TPVD TOYOTA

16/7/2018 @ 4:22pm

Joyce veh in

estimate not yet done.. will arrange survey when estimate done.

Model

AXIO-1.5 (A)

Service Address

...

Primary Contact/Insured

YAP FEN SIN FRANCIS

BLK 542 BUKIT BATOK STREET 52, #06-541, 650542, Singapore

MOTOR@INSUREHUB.COM.SG

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

NON REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

18 JULY 2018

**YAP FEN SIN FRANCIS
BLK 542 BUKIT BATOK STREET 52, #06-541
Singapore 650542**

Dear Sir,

**OUR REF : CC4/ASM18012955/eb3
YOUR REF : SKW 1927T**

**ACCIDENT INVOLVING SKW 1927T & SJM 8879S ALONG CLEMENTI AVE 6
TOWARD AYE ON 15/07/2018**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to AsherSng@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 6051 if you have any further enquiries.

Yours sincerely,
Claim department

This is a computer generated letter and no signature is required.

CC: AXA INSURANCE PTE LTD

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Thursday, 19 July, 2018 12:27 PM
To: 'Sharon Sng'
Subject: SJM 8879S doa : 15/07/18

Hi Sharon,

Kindly take note, the repair limit to repair this vehicle is 3K only


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



MANDATE REQUEST FOR S8M00OLL

Type

🔗 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,280.00 Loss of Use: \$840.00 (14days x \$60) LTA Search: \$2.00 AUDATEX Fee: \$44.94 Total: \$5,166.94 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (28/01/2019)

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKW 1927T (Insd veh)	Model:	TOYOTA AXIO 1.5X A
	SJM 8879S (TP veh)		
Date of Accident:	15/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	8,197.54	
Final Repair Cost	:	\$	4,280.00	
Loss of Use	:	\$	840.00	14 days at \$60.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$	2.00	

Audatex	:	\$	44.94	
---------	---	----	-------	--

	:	\$		
Final Settlement Sum	:	\$	5,166.94	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	:	\$ 5,166.94

NUR SHAQILAH BTE ABDOL
WAHAB

04/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012955/R1eb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: KIAN CHUAN

Date : 04-03-2019

Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 1927T	Veh. Inspected	SJM 8879S
Policy No.	GA173654	Coverage (\$)	0.00
Claim No.	S8M00OLL	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO 1.5X A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZE1416095618	Colour	BLUE
Odometer	306703	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/16R15	MICHELIN	6 mm
L/H Front Tyre	215/16R15	MICHELIN	6 mm
R/H Rear Tyre	215/16R15	MICHELIN	6 mm
L/H Rear Tyre	215/16R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/07/2018	Inspection Date	18/07/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 8879S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP) (CONSISTENT)	DEFORMED	170.00	170.00
1	L/R CTR BUMPER BRKT (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	R/R CTR BUMPER BRKT (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	L/R BUMPER RR BRKT (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	R/F BUMPER RR BRKT (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	L/R LOWER PROTECTOR (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	R/R LOWER PROTECTOR (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	L/R IMPACT DAMPER (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	R/R IMPACT DAMPER (WCP) (CONSISTENT)	BENT	35.00	35.00
1	RR BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	25.00	25.00
1	L/R CTR PARK SENSOR (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R CTR PARK SENSOR (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R OUT PARKING SENS (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R OUT PARKING SENS (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R INN SENSOR COVER (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R INN SENSOR COVER (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R OUT SENSOR COVER (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R OUT SENSOR COVER (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR NUMBER PLATE (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR SKIRT CPL (WCP) (CONSISTENT)	NOT NECESSARY	150.00	-
1	BOOTLID (WCP) (CONSISTENT)	BUCKLED	280.00	280.00
1	BOOTLID SEAL (WCP) (CONSISTENT)	NECESSARY	70.00	70.00
1	L/R HINGE (WCP) (CONSISTENT)	NOT NECESSARY	45.00	-
1	R/R HINGE (WCP) (CONSISTENT)	NOT NECESSARY	45.00	-
1	BOOT/TAILGATE LOCK (WCP) (CONSISTENT)	BENT	45.00	45.00
1	TAILGATE TRIM (WCP) (CONSISTENT)	DEFORMED	75.00	75.00
1	REAR BADGE (WCP) (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR SCREEN BOND KIT (NPA) (WCP) (CONSISTENT)	NECESSARY	-	-
1	SET REAR SCREEN FIX (NPA) (WCP) (CONSISTENT)	NECESSARY	-	-
2	SPACER (NPA) (WCP) (CONSISTENT)	NECESSARY	-	-
2	SPACER (NPA) (WCP) (CONSISTENT)	NECESSARY	-	-

Report Ref No. CC4/ASM18012955/R1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LWR REAR WINDOW MLDG (NPA) (WCP) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR WINDOW MOULDING (WCP) (CONSISTENT)	NECESSARY	55.00	55.00
1	L/R OUTER LAMP (WCP) (CONSISTENT)	CRACKED	95.00	95.00
1	R/R OUTER LAMP (WCP) (CONSISTENT)	CRACKED	95.00	95.00
1	L/NUMBER PLATE LAMP (WCP) (CONSISTENT)	NOT NECESSARY	25.00	-
1	R/NUMBER PLATE LAMP (WCP) (CONSISTENT)	NOT NECESSARY	25.00	-
1	R/R WING (WCP) (CONSISTENT)	BUCKLED	350.00	350.00
1	R/R LAMP PANEL (WCP) (CONSISTENT)	BENT	70.00	70.00
1	R/R VENT INSERT (WCP) (CONSISTENT)	DEFORMED	45.00	45.00
1	REAR FLOOR PANEL (WCP) (CONSISTENT)	BUCKLED	280.00	280.00
1	L/S - MEMBER END PANEL (WCP) (CONSISTENT)	PUNCTURE	150.00	150.00
1	R/S - MEMBER END PANEL (WCP) (CONSISTENT)	BUCKLED	150.00	150.00
1	TAILGATE TRIM (WCP) (CONSISTENT)	CRACKED	150.00	150.00
1	SPARE WHEEL TRIM (WCP) (CONSISTENT)	DEFORMED	150.00	150.00
1	RR SPARE WHEEL TRIM (WCP) (CONSISTENT)	CUT	140.00	140.00
1	LUGG COMPARTMENT CARPET (WCP) (CONSISTENT)	NOT NECESSARY	150.00	-
1	END PANEL TRIM (WCP) (CONSISTENT)	DEFORMED	75.00	75.00
1	L/LWR C-PILLAR TRIM (WCP) (CONSISTENT)	DEFORMED	150.00	150.00
1	R/LWR C-PILLAR TRIM (WCP) (CONSISTENT)	DEFORMED	150.00	150.00
1	CENTRE COVER PANEL (WCP) (CONSISTENT)	NOT NECESSARY	75.00	-
1	SPARE TYRE (WCP) (CONSISTENT)	NOT NECESSARY	280.00	-
1	END PNL T/GRNS CLIPS (WCP) (CONSISTENT)	NECESSARY	15.00	15.00
1	TAILLAMPS CLIPS (WCP) (CONSISTENT)	NECESSARY	5.00	5.00
1	REAR INSULATOR CLIPS (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	R/R BOOT STOPPER (WCP) (CONSISTENT)	NECESSARY	90.00	90.00
1	REAR 'X' LOGO (WCP) (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR 'AXIO' LOGO (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	REVERSE CAMERA (WCP) (CONSISTENT)	NOT NECESSARY	380.00	-
	COST PLUS 15%		663.75	471.75
			5,088.75	3,616.75
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR PARKING SENSOR (SN) (CONSISTENT)	SHORTED	180.00	180.00

Report Ref No. CC4/ASM18012955/R1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SCREEN GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			255.00	255.00
	LABOUR			
	ANTI RUST COAT.		180.00	180.00
	TOTAL PANEL / MECHANICAL.		1,345.50	1,345.50
	TOTAL PAINTWORK.		792.00	742.50
			2,317.50	2,268.00
GRAND TOTAL			7,661.25	6,139.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CC4/ASM18012955/R1eb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.