| INS. CASE OWN | Clava | CC 4 / FWD 180 | 11956, K | e a 3 9 2 LKX | | |
|---|---------------------|--|---|---|--|----|
| Surveyor: | | enneth DOI: ASSIGN | | tte / Time : | 18/18/18 | 51 |
| Pre-ussign / CC | Y2 | Q 60646 | Claim No. : | gistered in Merimen: | | 6 |
| Name of Insured | clife owe | KAH WAY - 98 55 75 98 | Policy No. : | M-8ENZ | 5- 0100 FD 9 | |
| Insured Tel No. Excess See II :S Is driver the own | | DOA: 14/2/2018 Nature of Accident: | Make / Model : Place of Accident : | kpt 7 | ECP | _ |
| If NO. Driver N | iume / Age : | (V/L-YES/NO) | OI GIA REPORT: | YES / NO ; TP GIA % Fin | REPORT: YES/NO | |
| Slop 212 | 1 | |) | | | |
| INSRS: WSP: ESTU Tel: Liability: RMKS: | IN- PINL TE | SRS: SP: I: ability: MKS; | INSRS: WSP: Tel: Linbility: RMKS: | | INSRS: WSP: Tel: Liability: RMKS: | |
| Date/Time | | | | | | |
| clar | C184-691 - X | : Statebules | | AGE | DATE / PIC | |
| 06~ | 3L3 1088 L | or stated was | No No | m-Reporting ltr (1at) m-Reporting ltr (2nd) m-Reporting ltr (Final) | | |
| No. 17 15 | Erren Typ 146117 | 1 August | | tification ltr (if non-pic II OI: | kup): | - |
| 8/-1:06 | parame data parame | 4 CIRPIC. | | ter call itr to Oil: | | |
| 25.1.19 | THE PRES TO TY | PIST TO PREPARE REPUBL. | | comentation Check L | ist: Handler Typist | |
| | | | No. | tification ltr (if non-pic | kup) | |
| | | | Af | ter call ltr to OI: | | |
| | | | 110 | thorisation To Act | / | |
| | | | 100 | lease Voucher: | | |
| | | | Est | al Repair Bill: | / | |
| | | | Ca | r Rental Invoice: | V. | |
| | | | To | wing Invoice | | |
| | | | LT | A / GIA : | |] |
| | | | Me | dical Bill: | | |
| | | | PD | t | | |
| | | | M | andate/Reject Instruct | ion: | |
| | | | LC | D | | |
| | | | Pa | yment Breakdown Fo | rm: | |
| PRELIMINARY ADVIC | E Date/Time: | Sent By: \ | Po | st-Repair Photos: | | |
| | | | | hers: | | _ |
| FINALIZATION | Date/Time: | Confirm with: | | onfirm by: ICSE | | |
| | P SS 10,915.53 (| 1□ days) Reduction: | 61 % | | I Call | |
| FINAL SETTLEMENT | Ditte/Time: 37-3-19 | Confirm with CHEMEN | | nail Call | | |
| Final Liability: | | eed / Assessed) BOLA S/N No.: | | NO or B 28, Ass. Lin | 100% | |
| Repair Cost: # 401 : | S\$ 11,679,63 | | PER DI DIEST | | 2005 | |
| ons of Rental (LOR): | SS 1,105-44 (| 14 days) K + 18 AL | | (Dinie) | r 1 | |
| Loss of Use (LOU): | SS - (S | x days) | | TO O | 12/100 | |
| oss of Income (LOI) | SS (S | x days) | | X | 13 10 | |
| OR only LOU on | | LOR+LOI [Tick only or | ne] | | N I | |
| GIA/LTA Search | SSTA | | | | | |
| Medical: | S\$ - | PA IN MERCHANISM TO THE PARTY OF THE PARTY O | | Claim status: Normal | | _ |
| Disbursement: Legal Cost | SS - SS - | (e.g. Tow/ Independ | | | 500 | |
| Legal Cost | SS (2,793.5) | Global Sum SS: | [3] | Survey fee: | and the same of th | |
| FINAL PAYMENT | Date/Time: 31-3-19 | Confirm with: (ARME) | 90 | 100 | | _ |
| | | | | nail Cail | | |
| Payee 1 | 55 13, 793.51 | Name 1: ESTERM PROFES | MANUE PIE UD | | | |
| Payee 2: (Strike if N.A.): Payee 3: (Strike if N.A.) | SS | Name 2: | | | | |
| | S\$ | Nume 3: | | | | |

| E | |
|---|---|
| ignification well REF: FWD | |
| ASS REC BY: | COLONDATINE |
| 0.00 | SSIGNMENT O. O. C. LO. |
| From Date: 17107118 | Veh No. SZS 40682 Yr Regn. 08, 17 |
| Estimated Cost: | Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / |
| OF TP WS I TP RES / OD RES / EVA / INV / MV | Truck / Trailer or |
| To Inspect Vehicle No. SLS 4068 L | Make: Tay Privis as 1798 |
| at Workshap m/a Esteem Performance | Colour B. P. White A/C: Insured / Std / NI / NA |
| of 385 Sin Ming Drive | Sp.Reading 75869 T/Radio: Insured / Std / NI / NA |
| Insured: | Eng/No: |
| | CNO: JTDKB3FU60357028 |
| Policy No. | Gen. Cond: 800d) Fair / Poor / Burnt |
| Claims No. | |
| Sum Insured: Excess: | Steering: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Ingreder / Jammed / Leaked / Burnt or |
| Make of Veh: | Modi: Nil / S/Rim / STB A/Rim or |
| 7 | Tyre Size: F: 195/65R15 |
| (Policy Condition) | R: - |
| Remark: The veh had commenced its N/S O | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / |
| repair at the time of inspection. | TOYO/YOKO OF WOMIGH |
| Bal. or Market Value | Front 0 Rear |
| IDAC Accident Rport: Consistent? Yes or No | R/Bal. 7 mm R/Bal. 3 mm |
| GIA / PR Seen: Consistent? : Yes or No | 2 |
| 10-04 | D.O.A. 14/7/18 D.O.I. 17/7/18 |
| 47 C C C C C C C C C C C C C C C C C C C | |
| Lum Sum: /-B-, % 3 Val. Yes or No | Survey held at |
| CA / REV / REP. / 24 HRS | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or |
| Vehicle: IN / C | |
| | The U/C / Chassis frame / Body Structure affected due to collision. |
| 18/7 Ble pass to Corhere | · · · · · · · · · · · · · · · · · · · |
| 10 / + 1- HE PETT TO COTTON | |
| the contraction of the contraction of the | |
| PP:+10,915.53 (RED:+16,1842-37 61%) | |
| | |
| | |
| | |
| | |
| | |
| Calleffine File Pass to? : Preli, Report | Days Of Repair: |
| : Final Report | Resurvey No. of Trip: Survey Fee: |
| Cate/Time, File Return to? | Transportation: |
| Z) Add F | Fee: Site Insp (\$)s+Rssi |
| | Interview (\$) Photos |
| Report Format : | Tech Invs (\$) Others |
| Lump Sum / I.B.I: (\$ | Weekend (\$ |

TOTAL



Blk 5033 Ang Mo Klo, Ind Park 2 #01-261/ 259, 589538. Tel: +85-6484 1221 Fax: +65-6484 7829 Webbile: www.esteempart.com.eg

₽ No. & Model:

als No

SLS 4068 L TOYOTA PRIUS

JTDKB3FU603570288

Submit By

Year Manufacture

Engine No.

Carmen Lim

2017

Cost / List

| | Part Description | | Qty | Unit Price | Price | Disposition by Surveyor |
|-------------|---|----------------|-------|-----------------|--------|----------------------------|
| - | Reverse sensor | Shar | 1 | \$200.00 | S.N | |
| | Rear bumper | Del | 1 | \$497.50 | + | 1 |
| | Rear bumper clip | M | 10 | \$40.00 | 1 | - |
| T) | Rear bumper side retainer LH | Pan | 1 | \$112.70 | | X |
| | Rear bumper side retainer RH | 52 | 1 | \$112.70 | 3 | A |
| 7 | Rear bumper reinforcement | By | 1 | \$398.90 | 1 | (2) |
| 5 | Rear bumper lower garnish centre | 04 | 1 | \$582.60 | | |
| - | Rear bumper lower garnish LH | Jn | 1 | \$149.70 | | · X |
| - | Tail door emblem | M | 1 | \$61.70 | - | |
| | Wording "PRIUS" | M | 1 | \$51.90 | 4 | |
| | Wording "HYBRID" | M | 1 | \$55.47 | / | |
| _ | Tail door plate garnish | n | 1 | \$782.50 | | X |
| 2 | Tail end panel | n | 1 | \$596.60 | | X |
| 4 | Tail end panel garnish | Si | 1 | \$151.60 | | 7 |
| 5 | Tail end panel garnish clip | m | 10 | \$35.00 | | X |
| - | Boot weatherstrip | 5m | 1 | \$353.10 | | X |
| 6 | Bonnet | Ry | 1 | \$812.40 | 1 | |
| 8 | Bonnet lock | 1 | 1 | \$130.00 | | X |
| _ | Bonnet hinge LH | n | 1 | \$57.80 | | 1 |
| 9 | Bonnet hinge RH | n | 1 | \$57.80 | | 1 |
| 20 | Front support panel centre | n | 1 | \$338.50 | | X |
| 21 | Front support panel LH | 134 | 1 | \$213.50 | 1 | |
| 22 | Headless panel H | By 68 | | \$89,20 | 4 | |
| 23 :: If | any of the quoted parts are recommended to be charged accordingly under supplementary. | repaired, ther | an ad | ditional labour | charge | |

65733 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 any Reg No. 200005485N / GST No. 20-0005485-N

2803-17-

are Parts

& Model:

SLS 4068 L ·

TOYOTA PRIUS JTDKB3FU603570288

Submit By

Year Manufacture : Engine No.

Carmen Lim 2017

Cost/List

| 0. | Part Description | | Qty | Unit Price | Price | Disposition by Surveyor |
|------|--------------------------------------|------|-----|---------------|-------|----------------------------|
| 24 | Support panel lower | N | 1 | \$387.95 | | 7 |
| 25 | Front support panel top garnish | 14 | 1 | \$285.40 | | 1 |
| 26 | Front support panel top garnish clip | Ar | 10 | \$35.00 | | 1 |
| 27 | Brace panel | 13 | 1 | \$105.20 | | X |
| 28 | Condenser | 15 | 1 | \$1,544.70 | | 3 |
| 29 | Radiator | 12 | 1 | \$1,841.80 | | 17 |
| 30 | Radiator fan motor RH | SL | 1 | \$455.70 | | X |
| 31 | Radiator fan motor LH | In | 1 | \$491.79 | | X |
| 32 | Radiator fan blade LH | 54 | 1 | \$197.80 | | × |
| 33 | Radiator fan blade RH | A | 1 | \$219.80 | | 1 |
| 34 | Radiator fan cowling | 1/Em | 1 | \$287.67 | | 1 |
| 35 | Radiator top hose | 54 | 1 | \$49.80 | | Χ. |
| 36 | Radiator bottom hose | 5- | 1 | \$46.95 | | × |
| 37 | Radiator spare tank | 2 | 1 | \$186.70 | | X |
| 38 | Headlamp LH | cm | 1 | \$2,531.60 | + | |
| 39 | Front bumper | 70 | 1 | \$450.80 | 4 | |
| 4 | Front bumper clip | M | 10 | \$40.00 | + | |
| 41 | Front bumper reinforcement - upper | ·N | 1 | \$711.50 | | X |
| 42 | Front bumper reinforcement - lower | n | 1 | \$245,30 | | * |
| 43 | Front bumper side retainer RH | Ph. | 1 | \$107.20 | | X |
| (44) | Front bumper side retainer LH | cn | 1 1 | \$107.20 | - | |
| 45 | Front bumper upper grille | n, | | \$321,90 | 4 | |
| 18 | Front bumper lower grille | D, | 1 1 | \$148.60 | 1 | |

ite; if any of the quoted parts are recommended to be repaired, then an additional labour charge I be charged accordingly under supplementary.

333 Ang Mo Kio Industrial Perk 2 #01-259 Singupore 569536 Tel: 64841221 Fex: 64847829 enry Reg No. 200005485N / GST No. 20-0005485-N

e Parts

ficie No. :

sis No

SLS 4068 L TOYOTA PRIUS JTDKB3FU603570288

Submit By : Year Manufacture : Carmen Lim 2017

Engine No.

Cost / List

| lo. | Part Description | | Qty | Unit Price | Price | Disposition by Surveyor |
|------|-------------------------------------|-----|-----|---------------|-------|----------------------------|
| 47 | Front bumper emblem | nex | 1 | \$87.10 | | |
| 48 | Front bumper tow cover LH | nio | - 1 | \$25.70 | - | |
| 49 | Front bumper sponge - upper | cm | 1 | \$89.81 | | |
| 50 | Front bumper sponge - lower | Sa | 1 | \$135.70 | | 8 |
| 51 | Fog lamp LH | cm | 1 | \$910.70 | 1 | - |
| (5°) | Engine under cover Ut Luss | In | 1 | \$198.30 | | 7 |
| 53 | Engine under cover clip | m | 10 | \$35.00 | | * |
| (54) | LH front fender | Ry | 1 | \$868.70 | + | |
| 55 | LH front fender undershield | 70 | - 1 | \$195.60 | | _ |
| 56 | LH front fender undershield clip | n | 10 | \$25.00 | | _ |
| 57 | LHF fender wording "HYBRID" | ne | 1 | \$44.17 | | |
| 58 | LH front fender quarter garnish | mi | 1 | \$122.70 | | |
| 59 | LH front door | n | - 1 | \$1,121.75 | | × |
| 60 | LH front door hinge top | n | 1 | \$78.30 | | × |
| 61 | LH front door hinge bottom | N | 1 | \$78.30 | | × |
| 62 | LH front door weatherstip | SL | 1 | \$211,69 | | * |
| 63 | LHF door glass outer moulding | 54 | 1 | \$121.75 | | X |
| 6 | LH front lower arm | | 1 | \$492.65 | | 7 |
| 65 | LH front shock absorber | | 1 | \$386.70 | | 7 |
| 66 | LH front shock absorber top mouting | · . | 1 | \$186.73 | | 7/50 |
| 67 | LH front shock absorber stopper | | 1 | \$29.97 | | 7 |
| 68 | LH front knuckle arm | | 1 | \$578.60 | | 7 |
| 69 | LH front knuckle bearing | | 1 | \$556.70 | | Ŋ |

te: If any of the quoted parts are recommended to be repaired, then an additional labour charge

7369.48 V

be charged accordingly under supplementary.

³³ Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel; 64841221 Fax: 64847829 — ny Reg No. 200005485N / GST No. 20-0005485-N

| σ. | r | | | |
|----|---|----|-----|--|
| 1 | _ | | | |
| à | Р | al | rts | |

icle No. '→ & Model: - is No : **SLS 4068 L**

TOYOTA PRIUS JTDK83FU603570288

Submit By Year Manufacture

Engine No. Cost / List Carmen Lim

2017

| - 003 | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-----------|-----------------------------|------|---------------|-------|----------------------------|
| ģ — 70 | LH front wheel hub lock nut | 1 | \$121.17 | | χ, |
| 71 | LH front tie rod | 1 | \$1,621.47 | | Z |
| 72 | LH front tie rod end | 1 | \$133.75 | | Z |
| 73 | LH front drive shaft | 1 | \$1,727.80 | | X |
| 74 | LH front wheel housing | 1 | \$935.99 | + | |
| 75 | LH front rim | 1- 1 | \$1,575.10 | | χ |
| 76 | The second second | | d v | | |
| 77 | ga , , , , , | | | | |
| 78 | | | | | |
| 79 | | | | 1 | |
| 80 | | | | | |
| 81 | | | | | |
| 82 | | | | | |
| 83 | | | | | |
| 84 | | | | | |
| 85 | Ø | | | | |
| 86 | | | | | |
| 87 | | | 1 | | |
| 88 | | | | | |
| 89 | | | | | |
| 90 | | | | | |
| 91 | 1.0 | | | | |
| 92 | | | | | |



Bik 5033 Ang Mo. Kio, Ind Park 2 #01-251/ 259, 589536. Tel: +85-6484 1221 Fax: +85-6484 7829 Websile: www.ostoemperf.com.ag

Labour

| Vehicle No. | : | SLS 4068 L Submit By | | | _ | Carmen Lim | |
|--------------|---|----------------------|---------------------|---|---|------------|--|
| Make & Model | : | TOYOTA PRIUS | Year of Manufacture | : | | 2017 | |

| S/No | Labour Description | Esimated Price | Adjusted Price |
|------|---|-------------------|-------------------|
| 1 | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT | | |
| | REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, | | |
| | FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, LHF | | |
| | DOOR) | \$1,800.00 | 1204 |
| 2 | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT | | |
| | REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, | | |
| | FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, LHF | | |
| | DOOR) | \$1,800.00 | 1400 |
| 3 | To check wiring | \$50.00 | 401 |
| 4 | To remove & refit reverse sensor | \$120.00 | 501 |
| 5 | To tuff coat | \$250.00 | 801 |
| 6 | To remove & refit spare tyre, spare tyre board, carpet trim | | |
| | to assist work load. | \$150.00 | X |
| 7 | To remove & refit radiator, condenser to assist work load, | | |
| | to top up A/C gas. | \$120,00 | 104 |
| 8 | To remove & refit undercarriage to assist work load. | \$250.00 | * |
| 9 | To wheel alignment | \$120.00 | 601 |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : SLS 4068 L · Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Adjusted Esimated S/No Labour Description Price Price To remove & refit Door trim, door glass, window regulator, 10 X wn \$120.00 door lock to assist work load. To conduct water leakage tests to ensure proper air and 11 301 \$120.00 sealing NA To Re-align chassic \$300.00 12 501 \$60.00 13 Towing

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536

Spare Parts Tel:64841221 Fax:64847829

Vehicle No.

Make & Model:

Chassis No :

SLS 4068 L Submit By TOYOTA PRIUS Year Manut

Year Manufacture : 2017 Engine No. :

CARMEN LIM

Cost / List

Supplementary

JTDKB3FU603570288

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|------------------------|-----|---------------|-------|----------------------------|
| 1 | Headlamp ballast LH nd | -1 | \$551.97 | | |
| 2 | | 1 | | | |
| 3 | | 1 | | | |
| 4 | | 1 | | | |
| 5 | | 1 | | | |
| 6 | | 1 | | | |
| 7 | | -1 | | | |
| 8 | | 1 | | | |
| 9 | | 1 | | | |
| 10 | | 1 | | | |
| 11 | | 1 | | | |
| 12 | | 1 | | | |
| 13 | | 1 | | | |
| 14 | | 1 | | | |
| 15 | | 1 | | | |
| 16 | | -1 | | | |
| 17 | | 1 | | | |
| 18 | | 1 | | | |
| 19 | | 1 | | | |
| 20 | | 4 | | | |
| 21 | | 1 | | | |
| 22 | | 1 | | | |
| 23 | | 1 | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

Ke



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6464 1221 Fax: +65-6464 7829 Website: www.esteemperf.com.sg

| No. 0099 | | | Nos Norhark | 1 |
|--|--------------|------------------------------------|----------------------------------|------|
| Repair Estimates | SLS | 4068 L | Finalised Renny Bepains | 2 |
| Plus/Less25% Total of Cost / List | \$ \$ | 29,178.43 7,294.61 21,883.82 | 15-000-71 7565,18 7695,293 | . 1 |
| (b) Nett Price Items Less Total of Nett Item | | | | |
| (c) Special Nett Items | \$ | 200.00 | 700 | - |
| _abour | \$ | 5,260.00 | 10915.53 ~ OK | 1.50 |
| The above total will be subjected to | 7% G.S.T. | | | |
| ne of Surveyor | | | Kennerh | |
| Company | | | LICK | |
| Survey conducted on | : | Ä, | 1717/18 at 11:40 | |
| Remarks By Surveyor | | | | |
| (a) The repair of this vehicle is | authorized / | | | |
| (b) Recommended Days of R | epair : | | day(s) | |
| (c) Resurvey | in (F | Required / Net R | equired | |
| (d) Excess | :\$ | | - p | |
| R (e) Signature of surveyor | *: | | Le Date: 17/7/10 | |



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

| Repair Estimates | S | LS 4068 L | Nor Norhark |
|--------------------------------------|-----------|-----------|--|
| Parts (a) Cost / List Price Items | \$ | 29,178.43 | |
| Plus/Less25% | \$ | 7,294.61 | LKK Auto Consultants hence notify the Repairer of the fell the fell |
| Total of Cost / List | \$ | 21,883.82 | * To resummy before the following: |
| (b) Nett Price Items | | | To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" benis No illegal modification(s) is allowed. |
| Less | · | | Surjetunianianiani |
| Total of Nett Item | | | Acknowledged by Renairer |
| (c) Special Nett Items | \$ | 200.00 | Signature: Date: |
| Total Parts Cost | \$ | 22,083.82 | |
| Labour | \$ | 5,260.00 | |
| Total | \$ | 27,343.82 | |
| The above total will be subjected to | 7% G.S.T. | | |
| Name of Surveyor | | | Kennery |



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No.

SLS 4068 L

Make & Model : Chassis No : TOYOTA PRIUS

JTDKB3FU603570288

Submit By

Year Manufacture

Engine No.

Carmen Lim

2017

Cost / List

| S/No. | Part Description | | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|----------------------------------|--------|-----|---------------|-------|----------------------------|
| 1 | Reverse sensor | Shar | 1 | \$200.00 | S.N | |
| 2 | Rear bumper | Pul | 1 | \$497.50 | | |
| 3 | Rear bumper clip | M | 10 | \$40.00 | | |
| 4 | Rear bumper side retainer LH | Sen | 1 | \$112.70 | | X |
| 5 | Rear bumper side retainer RH | Su | 1 | \$112.70 | | X ? |
| 6 | Rear bumper reinforcement | | 1 | \$398.90 | | ? |
| 7 | Rear bumper lower garnish centre | Del | 1 | \$582.60 | | _ |
| 8 | Rear bumper lower garnish LH | Jn | 1 | \$149.70 | | X |
| 9 | Tail door emblem | 14 | 1 | \$61.70 | | _ |
| 10 | Wording "PRIUS" | M | 1 | \$51.90 | | |
| 11 | Wording "HYBRID" | M | 1 | \$55.47 | | |
| 12 | Tail door plate garnish | n | 1 | \$782.50 | | * |
| 13 | Tail end panel | n | 1 | \$596.60 | | X |
| 14 | Tail end panel garnish | | 1 | \$151.60 | | ? |
| 15 | Tail end panel garnish clip | | 10 | \$35.00 | | - |
| 16 | Boot weatherstrip | 5h | 1 | \$353.10 | | X |
| 17 | Bonnet | Ry | 1 | \$812.40 | | ~ |
| 18 | Bonnet lock | 1 | 1 | \$130.00 | | X |
| 19 | Bonnet hinge LH | | 1 | \$57.80 | | 7 |
| 20 | Bonnet hinge RH | n | 1 | \$57.80 | | 1 |
| 21 | Front support panel centre | | 1 | \$338.50 | | 7 |
| 22 | Front support panel LH | 131 | 1 | \$213.50 | | - |
| 23 | Headlamp panel LH | By 644 | 1 | \$89.20 | | _ |

Spare Parts

| Vehicle No. | |
|-------------|--|
|-------------|--|

Make & Model : Chassis No : SLS 4068 L TOYOTA PRIUS JTDKB3FU603570288 Submit By : Year Manufacture : Engine No. :

Carmen Lim 2017

Cost / List

| S/No. | Part Description | | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|--------------------------------------|----|-----|---------------|-------|----------------------------|
| 24 | Support panel lower | | 1 | \$387.95 | | 7 |
| 25 | Front support panel top garnish | | 1 | \$285.40 | | 7 |
| 26 | Front support panel top garnish clip | | 10 | \$35.00 | | 7 |
| 27 | Brace panel | 1 | 1 | \$105.20 | | X |
| 28 | Condenser | | 1 | \$1,544.70 | | 7 |
| 29 | Radiator | | 1 | \$1,841.80 | | 1 |
| 30 | Radiator fan motor RH | SL | 1 | \$455.70 | | × |
| 31 | Radiator fan motor LH | In | 1 | \$491.79 | | × |
| 32 | Radiator fan blade LH | 54 | 1 | \$197.80 | | × |
| 33 | Radiator fan blade RH | 1 | 1 | \$219.80 | | < |
| 34 | Radiator fan cowling | 1º | 1 | \$287.67 | | 1 |
| 35 | Radiator top hose | Sh | 1 | \$49.80 | | * |
| 36 | Radiator bottom hose | Sm | 1 | \$46.95 | | × |
| 37 | Radiator spare tank | 2 | 1 | \$186.70 | | X |
| 38 | Headlamp LH | cm | 1 | \$2,531.60 | | |
| 39 | Front bumper | 7, | 1 | \$450.80 | | _ |
| 40 | Front bumper clip | Ne | 10 | \$40.00 | | |
| 41 | Front bumper reinforcement - upper | | 1 | \$711.50 | | 7 |
| 42 | Front bumper reinforcement - lower | | 1 | \$245.30 | | 7 |
| 43 | Front bumper side retainer RH | Sh | 1 | \$107.20 | | X |
| 44 | Front bumper side retainer LH | Ch | 1 1 | \$107.20 | | |
| 45 | Front bumper upper grille | n, | | \$321.90 | | - |
| 46 | Front bumper lower grille | D, | 1 1 | \$148.60 | | |

Spare Parts

Vehicle No. : Make & Model : Chassis No : SLS 4068 L

TOYOTA PRIUS JTDKB3FU603570288 Submit By : Year Manufacture : Carmen Lim

2017

Engine No.
Cost / List

| S/No. | Part Description | | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|-------------------------------------|-----|-----|---------------|-------|----------------------------|
| 47 | Front bumper emblem | nes | 1 | \$87.10 | | |
| 48 | Front bumper tow cover LH | nis | 1 | \$25.70 | | |
| 49 | Front bumper sponge - upper | cm | 1 | \$89.81 | | |
| 50 | Front bumper sponge - lower | | 1 | \$135.70 | | 7 |
| 51 | Fog lamp LH | cm | 1 | \$910.70 | | _ |
| 52 | Engine under cover | | 1 | \$198.30 | | 7 |
| 53 | Engine under cover clip | | 10 | \$35.00 | | 7 |
| 54 | LH front fender | Ry | 1 | \$868.70 | | |
| 55 | LH front fender undershield | 70 | 1 | \$195.60 | | |
| 56 | LH front fender undershield clip | na | 10 | \$25.00 | | _ |
| 57 | LHF fender wording "HYBRID" | ne | 1 | \$44.17 | | |
| 58 | LH front fender quarter garnish | min | 1 | \$122.70 | | _ |
| 59 | LH front door | n | 1 | \$1,121.75 | | × |
| 60 | LH front door hinge top | n | 1 | \$78.30 | | × |
| 61 | LH front door hinge bottom | 1 | 1 | \$78.30 | | × |
| 62 | LH front door weatherstip | Sh | 1 | \$211.69 | | × |
| 63 | LHF door glass outer moulding | 54 | 1 | \$121.75 | | X |
| 64 | LH front lower arm | | 1 | \$492.65 | | 7 |
| 65 | LH front shock absorber | | 1 | \$386.70 | | 7 |
| 66 | LH front shock absorber top mouting | | 1 | \$186.73 | | 1 |
| 67 | LH front shock absorber stopper | | 1 | \$29.97 | | 7 |
| 68 | LH front knuckle arm | | 1 | \$578.60 | | 7 |
| 69 | LH front knuckle bearing | | 1 | \$556.70 | | ? |

| _ | | - | - | |
|---|----|----|--------------|-----|
| | - | | \mathbf{u} | |
| | ua | 16 | Pa | 113 |
| | | | | |

| Vehic | e | No. | 1 |
|-------|---|-------|---|
| Make | & | Model | |

Chassis No

SLS 4068 L

TOYOTA PRIUS JTDKB3FU603570288 Submit By : Year Manufacture :

Carmen Lim 2017

Engine No. Cost / List

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|-----------------------------|-----|---------------|-------|----------------------------|
| 70 | LH front wheel hub lock nut | 1 | \$121.17 | | X |
| 71 | LH front tie rod | 1 | \$1,621.47 | | 7 |
| 72 | LH front tie rod end | 1 | \$133.75 | | ? |
| 73 | LH front drive shaft | 1 | \$1,727.80 | | 7 |
| 74 | LH front wheel housing | 1 | \$935.99 | | |
| 75 | LH front rim | 1 | \$1,575.10 | | X |
| 76 | | | | | |
| 77 | | | | | |
| 78 | | | | | |
| 79 | | | | | |
| 80 | | | | | |
| 81 | | | | | |
| 82 | | | | | |
| 83 | | | | | |
| 84 | | | | | |
| 85 | | | | | |
| 86 | | | | | |
| 87 | | | | | |
| 88 | | | | | |
| 89 | | | | | |
| 90 | | | | | |
| 91 | | | | | |
| | | | | | |



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

| Vehicle No. | 2 | SLS 4068 L | Submit By : | Carmen Lim |
|--------------|---|--------------|-----------------------|------------|
| Make & Model | : | TOYOTA PRIUS | Year of Manufacture : | 2017 |

| S/No | Labour Description | Esimated Price | Adjusted Price |
|------|---|-------------------|-------------------|
| 1 | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT | | |
| | REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, | | |
| | FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, LHF | | |
| | DOOR) | \$1,800.00 | 1204 |
| 2 | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT | | |
| | REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, | | |
| | FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, LHF | | |
| | DOOR) | \$1,800.00 | 14000 |
| 3 | To check wiring | \$50.00 | 401 |
| 4 | To remove & refit reverse sensor | \$120.00 | 501 |
| 5 | To tuff coat | \$250.00 | 901 |
| 6 | To remove & refit spare tyre, spare tyre board, carpet trim | | |
| | to assist work load. | \$150.00 | Х |
| 7 | To remove & refit radiator, condenser to assist work load, | | |
| | to top up A/C gas. | \$120.00 | 1001 |
| 8 | To remove & refit undercarriage to assist work load. | \$250.00 | ? |
| 9 | To wheel alignment | \$120.00 | 601 |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

| Vehicle No. | : | SLS 4068 L | Submit By : | Carmen Lim |
|--------------|---|--------------|-----------------------|------------|
| Make & Model | • | TOYOTA PRIUS | Year of Manufacture : | 2017 |

| S/No | Labour Description | Esimated Price | Adjusted Price |
|------|--|-------------------|-------------------|
| 10 | To remove & refit Door trim, door glass, window regulator, | | |
| | door lock to assist work load. | \$120.00 | Х |
| 11 | To conduct water leakage tests to ensure proper air and | | 195 |
| | sealing | \$120.00 | 301 |
| 12 | To Re-align chassic | \$300.00 | ? |
| 13 | Towing | \$60.00 | 501 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| _ | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Josey Lah

Date: 18 Jul 2018

Preliminary Advice

Insured Vehicle No : SKQ6064G

TP Vehicle No

: SLS4068L

Accident Date

: 14/07/2018

Make

TOYOTA PRIUS HYBRID

Assignment Date

: 17/07/2018

Date of Inspection 17/07/2018

Est. Duration of Repair

: 10-14 days

Inspection At

Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259

Singapore 569536

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear N/S and front N/S... portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 27,343.82 |
|-----------------------------|------|-----------|
| Revised Amount | :5\$ | 10,202.38 |
| Check Items (Estimated) | :S\$ | 9,637.62 |
| Total | :S\$ | 19,840.00 |

Lump Sum Repair

:S\$

Total Loss Consideration

| New for Old Value | SS |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

|) |) The vehicle is repairable at our adjusted amount. We have also confirmed | excess | and policy | coverage |
|---|--|--------|------------|----------|
| | Kindly let us have your authorisation. | | | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.

Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Friday, 20 July 2018 10:53 AM

To:

'Carmen Lim'

Subject:

RE: REQUEST FOR PRI SURVEY SLS4068L (FWD Ref: PNPV2018-00005709)

WTHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards.

Asher Sng | Case Handler LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkauto.com</u> | fax: 6741-4108 8lk 51. Paya Ubi Industrial Park. Ubi Avenue 1, #02-25 | \$(408933)

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]

Sent: Monday, 16 July, 2018 4:04 PM To: Motor Claims SG - SG Common

Subject: REQUEST FOR PRI SURVEY SLS4068L

Dear Sir / Madam.

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCICDENT CASES (NIMA)

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SLS 4068 L

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address 385 Sin Ming Drive (Inside VICOM) Singapore 575718
Tel: 8799 0066

Tel: 8799 0066 Fax: 6451 0394

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Thank you

Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066 P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

| | AUDIT TRAIL | | | Phil |
|-----|----------------------|------------------------------|--|-------------------------|
| lo. | On | Audit | Remarks | By [A] |
| 1 | 17 Jul 2018 15:09 | Clm Veh Model Changed | (205436) TOYOTA PRIUS HYBRID 1.8 CVT (A). | HOV |
| 2 | 17 Jul 2018 15:09 | Clm Created | Reg No: SLS4068L. Acct Date: 2018/07/14, Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Esteem Performance Pte Ltd (HQ) | (A) HO! ME KWA |
| 3 | 17 Jul 2018 15:09 | Adj Co Assigned | LKK Auto Consultants Pte Ltd (HQ):; RR Region: FWD - Ext Auto Adj Assignment. Sugges ted Adj. : VICOM Ltd. | HO! |
| 4 | 17 Jul 2018 15:09 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2018/07/26 | HO! |
| 5 | 17 Jul 2018 15:09 | Adj Mandate Set | Approved:0.00.Reinsp:Adj decides. | HO' |
| 5 | 17 Jul 2018 15:09 | Adj Adjuster Assigned | [None] -> KENNETH KONG | HO ME |
| 7 | 18 Jul 2018 11:33 | Clm Registration Modified | Pol No:->PNPV2018-00005709. | Jose Lo |
| 8 | 18 Jul 2018 14:14 | Adj Im. Advice Submitted | Next Rpt: Final Rpt. Due Date: 2018/07/26 | HO ME KW |
| 9 | 25 Jan 2019 17:37 | Adj Rpt Initiated | | A] HUH OY |
| 0 | 25 Jan 2019 17:37 | Clm Dtl Modified | JPJ Reg. Date: -> 2017/09/21. | (A HUE YO |
| 1 | 25 Jan 2019 17:37 | Clm Details Notified | | A] HUH YO |
| 2 | 14 Feb 2019 09:07 | Adj Mandate Request | Cur.Req:12792.51:LIABILITY: 100% B:28 3VEH CC OI LAST QUANTUM: (a) COR w/GST: \$11,679,62 + (b) LOR: \$1,105.44 (14day x \$78.96) Total: a+b = \$12,792.51 PLEASE RE VERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY. | Ash Sn Ron |

Date From Date To Audit Type None T Go

| ACTIVITY | | |
|-----------|--|--|
| No record | | |

| terimen Billin | g for this case - | Transaction H | istory | | | | |
|----------------|---------------------|---------------|------------------------------------|---|----------|----------|--------|
| Bill Ref No | Bill Date | Acc Type | Acc Name | Co Name (Branch) | Ref 1 | Ref 2 | Amount |
| 1863245 | 18/07/2018 14:14 | Motor | LKK Auto Consultants Pte Ltd | LKK Auto Consultants Pte Ltd (HQ) | SL54068L | SKQ6064G | 10,70 |

Print Received Message

This mail is associated with:

*SLS4068L (1201800009066) [SKQ6064G] TP GRAB RENTALS PTE LTD Jul 14 2018 11:00AM [CHEONG KAH WAI] Esteem Performance Pte Ltd

From

FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 18/02/2019 14:24 PM.

To

LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12792.51) - SLS4068L - Claim Handler: Clara Li Zi Rong

| Approved:12792.51. | |
|--------------------|--|
| | |
| | |
| | |



Bix 5033 Ang Mo Klo, Ind Park 2 #01-261/ 259, 589635. Tol: +65-5484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Your Ref: PNPV2018-00005709

Our Ref: SLT 1287 K

Date: 21-11-18

FWD SINGAPORE PTE LTD

6 Temasek Boulevard #18-01 Suntec Tower Four Singapore 038986

RE

: ACCIDENT INVOLVING

SLS 4068 L & SKQ 6064 G

ACCIDENT DATE

14-07-2018

ACCIDENT ALONG

KPE TOWARD CITY

We are the workshop for the owner of motor vehicle no: SLS 4068 L which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured SKQ 6064 G we are submitting these claims for your consideration.

1 Cost of repair S\$ 11,679.62

2 Loss of rental 14 days @ \$ 78.96 / day 8\$ 1,105.44 3 Surveyor Fee SS 0.00 4 GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 SS 0.00 for each report fee) 5 LTA Fee SS 7.45 5 \$ 12,792.51

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate,etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Casmen Lim Claims Executive

Email: carmen@esteemperf.com.sg

LETTER OF AUTHORITY

| ACCIDEN | VII INV | OLVING | SLS 4068L | 8. | SKQ 6064 6 | | | |
|---------|---------|--------|-----------|----|------------|---|-------|--|
| Alona | KPE | Tavard | Gty | On | 14/07/2018 | @ | 11:45 | |
| J | | | | | | | | |

| I, | Grab Rentals Pte I | .td Nric No | 201617200G | _ |
|-----------|----------------------|-----------------------|---|-----|
| of | 18 Sin Ming Lane | #01-08 Midview City S | Singapore 573960 | |
| Owner of | motor vehicle no. | SLS 4068L | do hereby appoint | M/S |
| | | | authorized representation egotiate and settle my claim ag | |
| the other | party/parties involv | ed in the above me | entioned accident. M/S EST | EEM |

I also confirm and instruct that any agreed settlement sum in respect of my claim be paid to M/S ESTEEM PERFORMANCE PTE LTD and such payment will constitute a full and final discharge of my claims.

I further authorize M/S ESTEEM PERFORMANCE PTE LTD to execute the discharge voucher on my behalf.

Signature of Owner

To Whom It May Concern:



RELEASE

| Claim Reference: | 1201800009066 | |
|-----------------------|----------------------|--|
| Surveyor's Reference: | CC4/FWD18012956/Kea3 | |
| TP Reference: | SLS 4068L | |

We, ESTEEM PERFORMANCE PTE LTD ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SLS 4068L ("Vehicle") to accept the sum of \$12,792.51, being the amount claimed for \$11,679.62 (repair costs), \$1,105.44 (loss of rental/ use), \$ - (loss of income), \$7.45 (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 14/07/2018 (date of accident) at / along KPE TOWARD CITY (location) involving vehicle no/s. SLS 4068L and SKQ 6064G.

This is pursuant to the inspection conducted on 17/07/2018 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of <u>SKQ 6064G</u> be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 6 day of March 2019

CLAIMANT

[Signed by the

"Workshop" with Co. Stamp]

For and on behalf of the "Claimant"

KSC

[FWD's appointed surveyor with Co. Stamp]
For and on behalf of FWD Singapore Pte. Ltd.



PERFORMANCE Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg GST Registration No: 20-0005485-N CO Registration: 200005485N

FWD Singapore Pte Ltd M/S:

6 Temasek Boulevard

#18-01 Suntec Tower Four

Singapore 038986

TEL: 6820 8888

ATTN: Motor Claim Department

Your Ref No:

SKQ6064G

Claim Type:

Third Party 14/07/2018

Accident Date: TP Veh Reg No:

SKQ6064G

Claim No:

CER1301165

Final No:

CIV1301488

Date:

20 Nov 2018

Policy No:

A29069766MKF

Veh Reg No:

SLS4068L

Make/Model:

TOYOTA PRIUS

HYBRID 1.8 CVT

Chassis No:

JTDKB3FU603570288

Engine No:

Reg. Date:

Tax Invoice to Vehicle No :SLS4068L

| | Description | Quantity List Pri | ce Amount |
|---|----------------|----------------------|---------------|
| | Others | | SS SS |
| 1 | COST OF REPAIR | 1 PCS 10,915. | 53 |
| | | 10,915. | 53 10,915.53 |
| | | Total | S\$ 10,915.53 |
| | | Add GST @ 7% | 764.09 |
| | | Total Amount Payable | S\$ 11,679.62 |

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND SIX HUNDRED SEVENTY NINE AND CENTS SIXTY TWO ONLY

The above vehicle was surveyed by KENNETH on 17/07/2018

For Esteem Performance Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

CONFIDENTIAL SCHEDULE TO VEHICLE RENTAL AGREEMENT

| Dat | to: | 01/27/2018 | Vehicle Rental Agreement No. | 6291 |
|-----|--|--|--|---------------|
| Re | nter Details | IX DAMES | Additional Driver (if any) | |
| 8 | Name | Ah Tee Chriq | 29 Name | |
| 12 | Address | 58 Geylang Bahru #15-3353 | 24 Address | |
| 13 | Date of Birth | 12/12/1963 | Date of Birth | |
| 日 | NRIC/Passport No. | S1617320G | S NRIC No. | |
| M | Driving License No. | S1617320G | Driving License No. | |
| 8 | Telephone No. | 6591271890 | Telephone No. | |
| H | Mobile No. | 6591271890 | Mobile No Mobile | |
| Ve | nicle Description | | Additional Driver (if any) | |
| 8 | Vehicle No | SLS4068L | ⊗ Name | |
| 8 | Make/Model | TOYOTA Prius | ☑ Address | |
| Re | ntal Period | | | |
| 100 | Minimum Rental Period | 418 | ☑ NRIC No. | |
| 55 | Date Checked Out | 01/27/2018 | Driving License No. | |
| 50 | No. of Days | | ▼ Telephone No. | |
| Ø | Expected Date of Return | 03/21/2019 | M Mobile No | |
| 10 | Actual Date of Return | | TO SEE MANAGEMENT OF | |
| Re | ntal Charges* & Deposit | p state of | | |
| Ø | () RR Rental Charges/Day | Per day @ \$ \$85,00 Per week @ \$ \$595,00 | Deposit Received | S \$1,500.00 |
| 63 | (X) ER Promotion Rental Charges/Day | Per day @ S \$78.96 Per week @ S \$552.66 | Total Amount Received* | S \$0.00 |
| 33 | () DO Promotion Rental Charges/Day | Per day @ S Per week @ S | * Inclusive GST | |
| Re | ntal Period | 418 days/59 weeks | Total Rental Charges | S \$33.040.90 |

| Liability Assessment / Nature | Non-Refundable Excess Payable | e by Renter | Rental Charge / Replacement |
|--|--|---|---|
| of incident | Renter or authorised driver(s) is 26 years of age or older | Renter or authorised driver(s) is below 26 years of age | Vehicle |
| 3 rd Party Fault | S\$2140 | S\$5350 | Rental Charges waived or replacement vehicle provided (subject to availability) |
| High Liability | S\$2140 | S\$5350 | No walver of Rental Charges & no replacement vehicle provided |
| Own Damage (inclusive of Act of God incidents & accidents in Malaysia) | S\$2140 | S\$5350 | No waiver of Rental Charges & no replacement vehicle provided |
| Stolen Vehicle | S\$2140 | \$\$5350 | Rental Charges waived or replacement vehicle provided (subject to availability) |
| Damage to Windscreen | S\$107 | S\$107 | No waiver of Rental Charges & no replacement vehicle provided |

| Payment Method | Francisco Indiana | |
|-------------------|-------------------|------|
| (X) Driver Wallet | () Cash | SG\$ |
| () Credit Card | () Debit Account | |
| Type Card No. | Bank Name | |
| Card No. | Account No. | |

CONFIDENTIAL

- I, the Renter, agree that the Lessor may collect, use & disclose my personal data, as provided in this Schedule &/or pursuant to the Agreement from time to time, for the following purposes in accordance with the Personal Data Protection Act 2012 & the Lessor's group Privacy Policy (available at www.grab.com/sg/privacy/):
- (a) administration of the vehicle rental under the Agreement;
- (b) for internal administrative purposes;
- (c) to communicate with me; &
- (d) for the Lessor to comply with its obligations under law.

| ,- | _ | - | - | - | _ |
|----|-----|---|----|---|---|
| | | | | | |
| | | ٠ | ٠ | | |
| | | 2 | c | | |
| | - 4 | ø | ٠, | | |
| | | | | | |

Further, I understand that my personal data may be used for marketing purposes by the Lessor, its affiliated companies or their partners; & I hereby consent to receive marketing & promotional materials by telephone, SMS or e-mail.

Agreement

The Renter has read, understood & agrees with all terms & conditions of this Agreement.

chythee

Renter's Signature/Stamp Date: SENTALS OF THE SENTENCES OF THE SENTENCE

Authorised Signatory/Stamp Grab Rentals Pte Ltd

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

16 Jul 2018 / 15:57:33

Receipt Date/Time: 16 Jul 2018 / 15:57:33

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180716-001718

Previous Receipt No.:

| S/N | Item Description/ | | Amount | GST | Amount |
|-------|-------------------------------------|--------------------------|--|--------|-----------|
| | Business Transaction Reference | | Before | Amount | After GST |
| | No. | | GST (S\$) | (8\$) | (S\$) |
| Resu | It of Insurance Enquiry - SHD200Z | | 50 65 65 | 17 55 | 7,007 |
| As at | 14 Jul 2018/06:45:00 | | | | |
| Însur | ance Co: AXA INSURANCE PTE LTD | | | | |
| 1 | insurance Enquiry - SHD200Z | | | | |
| | Enquiry Fee 20180718155849758702 | | 7.00 | 0.49 | 7.49 |
| | | Sub-Total | 7.00 | 0.49 | 7.49 |
| Resu | t of Insurance Enquiry - SKQ6064G V | | | | |
| | 14 Jul 2018/11:45:00 | | | | |
| | ance Co: FWD SINGAPORE PTE, LTD | . V | | | |
| | Insurance Enquiry - SKQ6064G | | | | |
| | Enquiry Fee 20180716155649787754 | | 7.00 | 0.49 | 7.49 |
| | EU TOUT TO TOUGHT OF TOTAL | Sub-Total | 7.00 | 0.49 | 7.49 |
| | | Total Before Rounding | 14.00 | 0.98 | 14.98 |
| | | Rounding Difference | | | 0.03 |
| | | Total Amount Payable | | | 14,95 |
| | | Paid By | | | |
| | | 20180716155700939 | Direct Debit: eNE (Internet Banking | A | 14.95 |
| | | Total | Sentores and Harry | en . | 14.95 |
| | | Cash Change | | | 0.00 |
| | | Tendered Amount | | | 14.95 |
| | | Excess Refundable Amount | | | 0.00 |
| | | | | | |

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Page 1 of 1 Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

| LAIM SUB | FOLDER TRA | CKING | | | | | | | | | |
|----------------------------------|--|-------------------|----------------------------|----------------|--|--------|--|------------------|-----------|----------|-------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | | Ad) 5 | ubmitted | Ins Auth'ed | Stat | N/W | |
| Main | 18 Jul 2018 16 Jul 2018 00:00 S\$10,915.53 S\$10,915.53 View Rpt | | 3 | | Pending for Surve Report Cancel Case | | | | | | |
| | Main | ∏ R | eference | Cla | im Det | ails | \neg | Documen | ts | ٦. | Show Alf |
| CLAIM SU | BFOLDER D | ETAILS | | | | | [Created | by adjuster] | | | |
| Insured: | CHEONG | KAH WAI, ID: 5 | 6807007D | | | | | | | | |
| Main Claimant: | GRAB RE | NTALS PTE LTD, | Co. Reg. No.: 20 | 1617200G | | | | | | | |
| Vehicle Reg No.: | SLS406 | 8L | | | Date of | Loss: | DSS: 14/07/2018 11:00 - :59 [9 Months and 23 Days From LTA Reg Date (Man Yr)] | | | | tan Yr)] |
| Claim Type: | TP / 120 | 1800009066 | | | olicy/C Note No | | PNPV2018-00005709 (Comprehensive) | | | | |
| Vehicle Reg No. (Insured): | SKQ6064 | G | | | olicy N | | A29069766MKF | | | | |
| | | | | E | xcess | | | | | | |
| Repairer: | Esteem P | erformance Pte | Ltd (HQ) Blk 5033 | Ang Ma Kie Ir | nd Park | 2, #0 | 1-259, 5695 | 36 Ang Ma Kia | Tel: | | |
| Handling Insurer: | FWD Sing | apore Pte. Ltd. (| (HQ) - Tel: 6727 5 | 700 [Handle | ed by C | lara L | i Zi Rong] | | | | |
| Claimant's Insurer: | MSIG Ins | urance (Singapo | re) Pte. Ltd. (HQ) |) - Tel: +65 6 | 827.78 | 88 | | | | | |
| Adjuster: | LKK Auto | Consultants Pte | Ltd (HQ) - Tel: 62 | 256-3561 [| Handled | by K | ENNETH K | ong] [Final | Rpt du | e 26/07 | 2018] |
| ASSOCIAT | ED MAIL RE | CEIVED | | | | | | v | iew Ali | Compos | e Case Mail |
| FWD_5G | (18/02/2019 |): Alert - Adj Ma | ndate Approved (| 5\$12792.51 | - SLS | 40681 | Claim H | andler: Clara Li | Z | | |
| ALL ASSO | CIATED TAS | KS ⁼ | | | | | new All | Search Tasks | Create Ne | w Task I | Complete |
| Due Date No results. | Priority | Type Task | Group Subject | ct Handle | r A | _ | ed By | Completed On | | eated On | 1712/21/21 |

Claim Documents

| Letters/Correspondences | | | 1 per pa | ige V | |
|-------------------------|-----------------|--|----------------|-----------|----------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Total contract | Thumbnail | |
| 1 | (Draft) | Third Party Express Settlement - Payment Breakdown | 0 | Edit | |
| Ass | essment Reports | | T ner ne | ige 🔽 | V |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | 1 per pa | Thumbnail | |
| 1 | 18/07/18 14:14 | Adjuster Immediate Advice | Ð | Load HTM | - |
| Pho | otos/Images | | 7 | no Fall | V |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | 3 per pa | Thumbnail | - |
| 1 | 01/02/19 16:57 | General View | 0 | Load JPG | 1 |
| 2 | 01/02/19 16:57 | General View | ő | Load JPG | 12 |
| 3 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 4 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 5 | 01/02/19 16:57 | General View | ő | Load JPG | V |
| 6 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| , | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 8 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 9 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 10 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 11 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 12 | 01/02/19 16:57 | General View | 0 | Load JPG | ₹ |
| 13 | 01/02/19 16:57 | General View | 0 | Load 3PG | N/ |
| 14 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 15 | 01/02/19 16:57 | General View | 0 | Load 3PG | 12 |
| 16 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 17 | 01/02/19 16:57 | Odometer Reading | 0 | Load JPG | V |
| 18 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 19 | 01/02/19 16:57 | General View | 0 | Load 3PG | V |
| 20 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 21 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 22 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 23 | 01/02/19 16:57 | General View | 0 | Load JPG | 1 |
| 24 | 01/02/19 16:57 | General View | 0 | Load JPG | V |
| 25 | 01/02/19 16:57 | General View | 0 | Load JPG | Ø |
| 26 | 01/02/19 16:57 | Chassis Number | 0 | Load JPG | V |
| 27 | 01/02/19 16:57 | General View | 0 | Load JPG | 120 |
| 8 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | V |
| 29 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | V |
| 30 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | N |

Page 2 of 2

| Let | ters/Corresponder | nces | 1 per | page 🗸 | V |
|-----|-------------------|--|-------|-----------|-------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 31 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | V |
| 32 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | Z |
| 33 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | V |
| 34 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | V |
| 35 | 14/02/19 09:06 | Reinspection Photo | 0 | Load JPG | V |
| Doc | cumentation | | 1 per | page 🔻 | 7 |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 17/07/18 15:10 | TP ESTIMATE + TP GIA REPORT | 0 | Load PDF | |
| 2 | 17/07/18 15:10 | ACKNOWLEDGEMENT EMAIL TO FWD DD 16.07.2018 | 0 | Load PDF | |
| 3 | 18/07/18 11:58 | EMAIL - FWD TO OI DD 18.07.2018 | 0 | Load PDF | |
| 4 | 19/07/18 11:27 | TP ESTIMATE - MARKED | 0 | Load PDF | |
| 5 | 28/01/19 10:05 | WORKSHOP INVOICE | 0 | Load PDF | |
| 6 | 28/01/19 10:05 | RENTAL RECEIPT | 0 | Load PDF | |
| 7 | 28/01/19 10:05 | LOD | 0 | Load PDF | |
| 8 | 11/03/19 14:26 | Release Voucher | 0 | Load PDF | |
| 9 | 11/03/19 14:26 | AUTHORISATION TO ACT FORM | 0 | Load PDF | |
| 10 | 11/03/19 14:26 | LTA SEARCH | 0 | Load PDF | |
| No | Finalized On | FWD Singapore Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 18/07/18 11:34 | Insured GIA Report | 0 | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset Save 7 | rint |
|---|--------------|------|
| There are no document checklists configured. | - | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | |
| | | 0 |
| | | ~ |
| Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other perties. | | |

| ALCOHOL: | THE THE | COLUMN | prompt program | nv | CHIDA | myon |
|----------|---------|--------|----------------|-----|-------|-------|
| NUIE: | IU DE | COMPL | EIEU | 0.1 | SUR | VETUR |

| TEAN | |
|-------------------------|--|
| $I \succ \Delta I \lor$ | |
| | |

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| Vehi | cle No: | SKQ60 | 64G (Insd vel | 1) | Model: | | TOYOTA PRIUS HYBRID 1.8 |
|-------|--|-------------|-------------------|-------|----------------------|---------|----------------------------|
| | | SLS40 | 68L (TP veh) | | | - 1 | CVT (A) |
| Date | of Accident: | 14/07/2018 | | | | 20 20 | |
| _ | | | | | | _ | |
| Glob | al Sum Settlem | nent : | [] Yes | | [X] No | | |
| Repa | air Estimate | | | : \$ | 29,700.85 | | |
| Final | Repair Cost | | | : \$ | 11,679.62 | | |
| Loss | of Use | | | : \$ | | | days at \$0.00 per day |
| Rent | al (if any) | | | : \$ | 1,105.44 | 14 | days |
| LTA | / GIA Search F | ee | | : \$ | 7.45 | | |
| Othe | rs: | | | : \$ | 0.00 | | |
| | | | | : 8 | | | |
| Final | Settlement Su | m | | : \$ | 12,792.51 | | |
| B) | For Non GIA R For GIA Regist BOLA Liability: | tered Wo | orkshop: (%) | | Assessed Liabil | le: Yes | No BOLA Scenario No: |
| Rem | | bility to b | e filled only for | chair | collisions and for c | ases w | vhere BOLA does not apply. |
| Payn | nent Instruction | n: Paye | e's Breakdow | n | | | |
| 1) | Esteem Perfor | mance P | te Ltd | | : \$ | | 12,792.5 |
| 2) | | | | | : \$ | | |
| 3) | | | | | : \$ | | |
| 4) | | | | | : \$ | | |
| | | | | | | | |

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/FWD18012956/KEA3Q2

Date:

11/03/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.

Policy No:

PNPV2018-00005709

Claimant Vehicle SLS4068L

Insured Vehicle No :

SKQ6064G

Date of Loss:

14/07/2018

Nature of Claim:

TP

Claim No: 1201800009066

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SLS4068L

Make & Model:

TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No:

2ZRS086193

Reg. Date:

21/09/2017 (Man. Year: 2017)

Chassis No:

JTDKB3FU603570288

Colour:

Metallic Pearl White

Odometer:

75864 km

Engine Capacity:

1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Front Right Side: West Lake 8 mm West Lake 8 mm Rear Left Side: Rear Right Side:

West Lake 3 mm West Lake 3 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------|----------------------|------------|------------|--------|
| Parts | | 22,497.80 | 7,895.53 | 14,602.27 | 64.91 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 5,260.00 | 3,020.00 | 2,240.00 | 42.59 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Gross Total (S\$) | 27,757.80 | 10,915.53 | 16,842.27 | 60.68 |
| | + GST 7.00/7.00% (S\$) | 1,943.05 | 764.09 | 1,178.96 | 60.68 |
| | Nett Amount (S\$) | 29,700.85 | 11,679.62 | 18,021.23 | 60.68 |
| | + Car Rental (14.0 x S | \$\$78.96/day) (S\$) | 1,105.44 | | |
| | + Doo | /Search Fee (S\$) | 7.45 | | |
| | , | Nett Liability (S\$) | 12,792.51 | | |

INSPECTION

Date of Assignment:

16/07/2018

Date Inspected:

17/07/2018 Inspected At:

385 SIN MING DRIVE

Repairer: Esteem Performance Pte Ltd

(HQ)

Estimated Period of Repair:

10.0 days

Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2019)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS4068L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Dented | 497.50 FL | *497.50 FL |
| 2 | 10 | | *REAR BUMPER CLIP | Necessary | 40.00 FL | *40.00 FL |
| 3 | 1 | | *REAR BUMPER SIDE RETAINER LH | Serviceable | 112.70 FL | *-FL |
| 4 | 1 | | *REAR BUMPER SIDE RETAINER RH | Serviceable | 112.70 FL | *-FL |
| 5 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 398.90 FL | *398.90 FL |
| 6 | 1 | | *REAR BUMPER LOWER GARNISH CENTRE | Dented | 582.60 FL | *582.60 FL |
| 7 | 1 | | *REAR BUMPER LOWER GARNISH LH | Serviceable | 149.70 FL | *-FL |
| 8 | 1 | | *TAIL DOOR EMBLEM | Necessary | 61.70 FL | *61.70 FL |
| 9 | 1 | | *WORDING PRIUS | Necessary | 51.90 FL | *51,90 FL |
| 10 | 1 | | *WORDING HYBRID | Necessary | 55.47 FL | *55.47 FL |
| 11 | 1 | | *TAIL DOOR PLATE GARNISH | Repair | 782.50 FL | *-FL |
| 12 | 1 | | *TAIL END PANEL | Repair | 596.60 FL | *-FL |
| 13 | 1 | | *TAIL END PANEL GARNISH | Serviceable | 151.60 FL | *-FL |
| 14 | 10 | | *TAIL END PANEL GARNISH CLIP | Not Necessary | 35.00 FL | *-FL |
| 15 | 1 | | *BOOT WEATHERSTRIP | Serviceable | 353.10 FL | *-FL |
| 16 | 1 | | *BONNET | Bent | 812.40 FL | *812.40 FL |
| 17 | 1. | | *BONNET LOCK | Repair | 130.00 FL | *-FL |
| 18 | 1 | | *BONNET HINGE LH | Repair | 57.80 FL | *-FL |
| 19 | 1 | | *BONNET HINGE RH | Repair | 57.80 FL | *-FL |
| 20 | 1 | | *FRONT SUPPORT PANEL CENTRE | Repair | 338.50 FL | *-FL |
| 21 | 1 | | *FRONT SUPPORT PANEL LH | Bent | 213.50 FL | *213.50FL |
| 22 | 1 | | "HEADLAMP PANEL LH | Bent | 89.20 FL | *89.20 FL |
| 23 | 1 | | *SUPPORT PANEL LOWER | Repair | 387.95 FL | *-FL |
| 24 | 1 | | *FRONT SUPPORT PANEL TOP GARNISH | Serviceable | 285.40 FL | *-FL |
| 25 | 10 | | *FRONT SUPPORT PANEL TOP GARNISH CLIP | Not Necessary | 35.00 FL | *-FL |
| 26 | 1 | | *BRACE PANEL | Repair | 105.20 FL | *-FL |
| 27 | 1 | | *CONDENSER | Serviceable | 1,544.70 FL | *-FL |
| 28 | 1 | | *RADIATOR | Serviceable | 1,841.80 FL | *-FL |
| 29 | 1 | | *RADIATOR FAN MOTOR RH | Serviceable | 455.70 FL | *-FL |
| 30 | 1 | | *RADIATOR FAN MOTOR LH | Serviceable | 491.79 FL | *-FL |
| 31 | 1 | | *RADIATOR FAN BLADE LH | Serviceable | 197.80 FL | *-FL |
| 32 | 1 | | *RADIATOR FAN BLADE RH | Serviceable | 219.80 FL | *-FL |
| 33 | 1 | | *RADIATOR FAN COWLING | Serviceable | 287.67 FL | *-FL |
| 34 | 1 | | *RADIATOR TOP HOSE | Serviceable | 49.80 FL | *-FL |
| 35 | 1 | | *RADIATOR BOTTOM HOSE | Serviceable | 46.95 FL | *-FL |
| 36 | 1 | | *RADIATOR SPARE TANK | Serviceable | 186.70 FL | *-FL |
| 37 | 1 | | *HEADLAMP LH | Cracked | 2,531.60 FL | *2,531.60 FL |
| 38 | 1 | | *FRONT BUMPER | Torn | 450.80 FL | *450.80 FL |
| 39 | 10 | | *FRONT BUMPER CLIP | Necessary | 40.00 FL | *40.00 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--------|--------------|---------------------------------------|--------------------|-------------|------------|
| 40 | 1 | | *FRONT BUMPER REINFORCEMENT-UPPER | Repair | 711.50 FL | *- FL |
| 41 | 1 | | *FRONT BUMPER REINFORCEMENT-LOWER | Repair | 245:30 FL | *-FL |
| 42 | 1 | | *FRONT BUMPER SIDE RETAINER RH | Serviceable | 107.20 FL | *-FL |
| 43 | 1 | | *FRONT BUMPER SIDE RETAINER LH | Cracked | 107.20 FL | *107.20 FL |
| 44 | 1 | | *FRONT BUMPER UPPER GRILLE | Distorted | 321.90 FL | *321.90 FL |
| 45 | 1 | | *FRONT BUMPER LOWER GRILLE | Distorted | 148.60 FL | *148.60 FL |
| 46 | 1 | | *FRONT BUMPER EMBLEM | Necessary | 87.10FL | *87.10 FL |
| 47 | 1 | | *FRONT BUMPER TOW COVER LH | Missing | 25.70 FL | *25.70 FL |
| 48 | 1 | | *FRONT BUMPER SPONGE-UPPER | Cracked | 89.81 FL | *89.81 FL |
| 49 | 1 | | *FRONT BUMPER SPONGE-LOWER | Serviceable | 135.70 FL | *-FL |
| 50 | 1 | | *FOG LAMP LH | Cracked | 910.70 FL | *910.70 FL |
| 51 | 1 | | *ENGINE UNDER COVER | Serviceable | 198.30 FL | *-FL |
| 52 | 10 | | *ENGINE UNDER COVER CLIP | Not Necessary | 35.00 FL | *-FL |
| 53 | 1 | | *LH FRONT FENDER | Bent | 868.70 FL | *868.70 FL |
| 54 | 1 | | *LH FRONT FENDER UNDERSHIELD | Torn | 195.60 FL | *195.60 FL |
| 55 | 10 | | *LH FRONT FENDER UNDERSHIELD CLIP | Necessary | 25.00 FL | *25.00 FL |
| 56 | 1 | | *LHF FENDER WORDING HYBRID | Necessary | 44.17 FL | *44.17 FL |
| 57 | 1 | | *LH FRONT FENDER QUARTER GARNISH | Missing | 122.70 FL | *122.70 FL |
| 58 | 1 | | *LH FRONT DOOR | Repair | 1,121.75FL | *-FL |
| 59 | 1 | | *LH FRONT DOOR HINGE TOP | Repair | 78.30 FL | *-FL |
| 60 | 1 | | *LH FRONT DOOR HINGE BOTTOM | Repair | 78.30 FL | *-FL |
| 61 | 1 | | *LH FRONT DOOR WEATHERSTRIP | Serviceable | 211.69 FL | *-FL |
| 62 | 1 | | *LHF DOOR GLASS OUTER MOULDING | Serviceable | 121.75 FL | *-FL |
| 63 | 1 | | *LH FRONT LOWER ARM | Serviceable | 492.65 FL | *-FL |
| 64 | 1 | | *LH FRONT SHOCK ABSORBER | Serviceable | 386.70 FL | *-FL |
| 65 | 1 | | *LH FRONT SHOCK ABSORBER TOP MOUNTING | Serviceable | 186.73 FL | *-FL |
| 66 | 1 | | *LH FRONT SHOCK ABSORBER STOPPER | Serviceable | 29.97 FL | *-FL |
| 67 | 1 | | *LH FRONT KNUCKLE ARM | Serviceable | 578.60 FL | *-FL |
| 68 | 1 | | *LH FRONT KNUCKLE BEARING | Serviceable | 556.70 FL | *-FL |
| 69 | 1 | | *LH FRONT WHEEL HUB LOCK NUT | Serviceable | 121.17 FL | *-FL |
| 70 | 1 | | *LH FRONT TIE ROD | Serviceable | 1,621.47 FL | *-FL |
| 71 | 1 | | *LH FRONT TIE ROD END | Serviceable | 133.75 FL | *- FL |
| 72 | 1 | | *LH FRONT DRIVE SHAFT | Repair | 1,727.80 FL | *-FL |
| 73 | 1 | | *LH FRONT WHEEL HOUSING | Bent | 935.99 FL | *935.99 FL |
| 74 | 1 | | *LH FRONT RIM | Repair | 1,575.10 FL | *-FL |
| 75 | 1 | | *HEADLAMP BALLAST LH | Dented | 551.97 FL | *551.97 FL |
| 76 | 1 | | *REVERSE SENSOR | Shorted | 200.00 FS | *200.00 FS |
| F=Fra | nchise | part. S=Spch | Nett. L=ListItemDisc. | | | |
| | | | | Sub Total (S\$) | 29,930.40 | 10,460.71 |
| | | | - List Item Discount on L Items | 25.00/25.00% (S\$) | 7,432.60 | 2,565.18 |
| | | | | Total Parts (S\$) | 22,497.80 | 7,895.53 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| W DAMAGED PARTS & KNOCK OUT ACCIDENT AREA (REAR BUMPER,TAILDOOR,END RONT BUMPER,BONNET,SUPPORT PANEL,LHF LHF DOOR) Y,RESPRAY PAINT FOR AFFECTED ACCIDENT AREA (REAR BUMPER,TAILDOOR,END RONT BUMPER,BONNET,SUPPORT PANEL,LHF LHF DOOR) EK WIRING EVE & REFIT REVERSE SENSOR COAT EVE & REFIT SPARE TYRE,SPARE TYRE CARPET TRIM TO ASSIST WORK LOAD | New New New New New New | 1,800.00 1,800.00 50.00 120.00 250.00 | 1,400.00 40.00 50.00 |
|--|--|---|--|
| AREA (REAR BUMPER, TAILDOOR, END RONT BUMPER, BONNET, SUPPORT PANEL, LHF LHF DOOR) Y, RESPRAY PAINT FOR AFFECTED ACCIDENT AREA (REAR BUMPER, TAILDOOR, END RONT BUMPER, BONNET, SUPPORT PANEL, LHF LHF DOOR) K WIRING OVE & REFIT REVERSE SENSOR COAT | New New New | 1,800.00 50.00 120.00 250.00 | 1,200.00 1,400.00 40.00 50.00 90.00 |
| AREA (REAR BUMPER,TAILDOOR,END RONT BUMPER,BONNET,SUPPORT PANEL,LHF LHF DOOR) K WIRING OVE & REFIT REVERSE SENSOR COAT OVE & REFIT SPARE TYRE,SPARE TYRE | New New New | 50.00 120.00 250.00 | 40.00 50.00 |
| OVE & REFIT REVERSE SENSOR COAT OVE & REFIT SPARE TYRE,SPARE TYRE | New New | 120.00 250.00 | 50.00 |
| COAT DVE & REFIT SPARE TYRE,SPARE TYRE | New | 250.00 | |
| OVE & REFIT SPARE TYRE, SPARE TYRE | 2072 | T-21 (10 th) | 90.00 |
| | New | 150.00 | |
| | | 100,00 | |
| OVE & REFIT RADIATOR, CONDENSER TO ASSIST DAD, TO TOP UP AC GAS | New | 120.00 | 100.00 |
| OVE & REFIT UNDERCARRIAGE TO ASSIST WORK | New | 250.00 | - |
| EL ALIGNMENT | New | 120.00 | 60.00 |
| TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD | | 120.00 | i.e |
| OUCT WATER LEAKAGE TESTS TO ENSURE AIR AND SEALING | New | 120.00 | 30.00 |
| LIGN CJASSIC | New | 300.00 | |
| | New | 60.00 | 50.00 |
| Gross Labor | ur Cost (S\$) | 5,260.00 | 3,020.00 |
| | OUCT WATER LEAKAGE TESTS TO ENSURE AIR AND SEALING LIGN CJASSIC Gross Labor | OUCT WATER LEAKAGE TESTS TO ENSURE New AIR AND SEALING LIGN CJASSIC New New Gross Labour Cost (S\$) | AIR AND SEALING LIGN CJASSIC New 300.00 New 60.00 |

< END OF ESTIMATES >