



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|--|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN | | | Ref: CC4/ASM18012957/Aes3q2 Date: 28/03/2021 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SKG 6682A | Veh. Inspected | SGK 6873S | |
| Policy No. | GA111751 / 1 | Coverage (\$) | 0.00 | |
| Claim No. | S8M00OKC | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 17/07/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA JAZZ | c.c | 1498 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JHMGK5850GX203117 | Colour | PURPLE | |
| Odometer | 167773 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 185/55 R16 | DUNLOP | 6 mm | |
| L/H Front Tyre | 185/55 R16 | DUNLOP | 6 mm | |
| R/H Rear Tyre | 185/55 R16 | DUNLOP | 6 mm | |
| L/H Rear Tyre | 185/55 R16 | DUNLOP | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 14/07/2018 | Inspection Date | 20/07/2018 | |
| Survey held at | RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |