



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
151 POWER EARTH MODULE WIRE - CHECK PRICE	1 PC	0.00	?
152 FRONT GRILLE STICKER - CHECK PRICE	1 PC	na	0.00 ✓
153 REAR WINDSCREEN SEALANT	1 PC	na	60.00 80.00
154 REAR WINDSCREEN INNER SEAL	1 PC	na	60.00 30.00
155 REAR FENDER GLASS SEALANT	2 PC	na	80.00 X
156 REAR FENDER GLASS INNER SEAL	2 PC	na	80.00 X
157 NUMBER PLATE REAR	1 PC	na	35.00 ✓
158 REAR CAMERA RECORDER - CHECK PRICE	1 PC	0.00	?
159 TAILGATE LAMP STICKER - CHECK PRICE	2 PC	0.00	?
160 TAILAMP STICKER - CHECK PRICE	2 PC	0.00	?
161 TAILGATE CTR REFLECTOR LAMP STICKER - CHECK PRICE	1 PC	na	0.00 ✓
162 TAILGATE TOP CTR PLATE WITH STICKER - CHECK PRICE	1 PC	0.00	?
163 REAR BUMPER REFLECTOR LAMP WHITE - CHECK PRICE	2 PC	0.00	?
164 TAILGATE INNER TRIMBOARD SIDE LAMP - CHECK PRICE	2 PC	0.00	?
165 REVERSE SENSOR	1 SET	shen 200.00	✓
166 REVERSE SENSOR MODULE & WIRE HARNESS - CHECK PRICE	1 SET	0.00	?
		835.00	835.00

LABOUR

167 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
168 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	150.00
169 TO REMOVE & REPLACE ALTERNATOR BELTING A/C COMPRESSOR	1 PC	200.00	?
170 TO RESET ENGINE LIGHT, HEADLAMP ECU AIRBAG	1 PC	280.00	120.00
171 TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX, ENGINE ECU MODULE, POWER EARTH MODULE & WIRE	1 PC	200.00	?
172 TO REMOVE & REINSTALL, REPLACE ENGINE MOUNTING FRONT, REAR, GEARBOX MOUNTING	1 PC	180.00	?
173 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	180.00	60.00
174 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT, TO KNOCK & REPAIR FRONT DOOR LH, & RH, FRONT WHEELHOUSE, FRONT CHASSIS FRAME INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,400.00	700.00
175 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT WHEELHOUSE, FRONT CHASSIS FRAME.	1 PC	1,200.00	1000.00
176 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
177 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	100
178 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	?
179 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	150.00	120
180 TO REMOVE & REINSTALL/REPLACE TAILGATE MOTOR	1 PC	150.00	60
181 TO REMOVE & REINSTALL/REPLACE REAR A/C BLOWER & COOLING COIL ASSY	1 PC	250.00	?
182 TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS WITH MOULDING LH & RH	1 PC	na 240.00	X
183 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	380.00	150
184 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	380.00	?
185 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	180.00	60
186 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	100.00	60
187 TO DISMANTLE & INSTALL/REPLACE REAR THIRD SEATBELT	1 PC	200.00	?
188 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	✓
189 TO RESET TAILGATE MOTOR,SRS LIGHT,ENGINE LIGHT	1 PC	380.00	?
190 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	280.00	120
191 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	180.00	80
192 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD TAILAMP PANEL,END PANEL,SPARE TYRE PANEL,RR FENDER,RR CHASSIS FRAME & SIDE PANEL & OUTER PANEL.TO KNOCK & REPAIR FLOOR PANEL,REAR WHEELHOUSE,RR FENDER INNER.TO REFIT LISTED PARTS BACK SAME.	1 PC	3,000.00	2200
193 TO SPRAY TAILGATE,RR BUMPER,END PANEL,SPARE TYRE PANEL,TAILAMP PANEL,RR FENDER,RR FENDER INNER,RR CHASSIS FRAME,RR CHASSIS SIDE PANEL OUTER,RR CHASSIS SIDE PANEL,FLOOR PANEL,RR WHEELHOUSE	1 PC	2,300.00	1600
		12,320.00	12,320.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 56,695.10
		Add GST @ 7%	3,968.66
		Total Amount Payable	S\$ 60,663.76

TOTAL: SINGAPORE DOLLAR SIXTY THOUSAND SIX HUNDRED SIXTY THREE AND CENTS SEVENTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: VC011649
Our ref: CC4/QBE18012958/Kwa3

Date: 18.07.2018

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLH 5358B


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.07.2018 at the premises of M/s Ah Lim Motor Company (AMK) - Ang Mo Kio have the following to report:-

Workshop Estimate Amount	: S\$	56,695.10	(est.)
Revised Estimate Amount	: S\$	18,724.68	(est.)
"Check" Items Amount	: S\$	28,161.06	(est.)
Total (Including Check Items)	: S\$	46,885.74	(est.)
Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 28 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Monday, 16 July 2018 2:08 PM
To: assignments
Subject: FW: TP / OUR CLIENT SLH5358B DOA: 10/07/2018 POLICY NO. D17MTPV01016659 YOUR INSURED SJX8053A
Attachments: 5358 - SOMPO.pdf; 5358.pdf; SJX8053A.pdf

2.37pm @ 16/07/2018

person @ zila

vehicle in

arrange on 17/07/2018

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Joyce Foo [mailto:joyce.foo@qbe.com]

Sent: Monday, 16 July 2018 2:06 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: TP / OUR CLIENT SLH5358B DOA: 10/07/2018 POLICY NO. D17MTPV01016659 YOUR INSURED SJX8053A

Our Ref. VC011649

Hi

Please assist to arrange for TP survey - Direct settlement.

Thank You & Best Regards

Joyce Foo

Senior Assistant - Claims

QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd

Phone: +65 6477 1184

Email: joyce.foo@qbe.com

Visit us on the web at www.qbe.com.sg

-----Original Message-----

From: zila [mailto:zila@ahlimmotor.com.sg]

Sent: Monday, 16 July, 2018 9:16 AM

To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>

Subject: TP / OUR CLIENT SLH5358B DOA: 10/07/2018 POLICY NO. D17MTPV01016659 YOUR INSURED SJX8053A

Hi Claims Dept,

Kindly arrange for survey.

Note: Vehicle is in @ ALM AMK Autopoint workshop.

Pls advise on liability & OIC as we have video footage.

Thanks.

--

Best Regards, Zila Ah Lim Motor Tel: 64831244 Fax: 64836170

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Thursday, 19 July, 2018 11:16 AM
To: 'Joyce Foo'
Cc: Admin A; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO)
Subject: RE: TP / OUR CLIENT SLH5358B DOA: 10/07/2018 POLICY NO. D17MTPV01016659 YOUR INSURED SJX8053A
Attachments: Preliminary Advice.pdf, LKK SURVEY PHOTO.pdf, TP ESTIMATE - MARKED.pdf
Categories: HMK

WITHOUT PREJUDICE

QBE ref: VC011649
LKK REF: CC4/QBE18012958/Kwa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SLH 5358B

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Please take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)

Sent: Monday, 16 July, 2018 2:41 PM

To: 'Joyce Foo' <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: TP / OUR CLIENT SLH5358B DOA: 10/07/2018 POLICY NO. D17MTPV01016659 YOUR INSURED SJX8053A

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

This email has been checked for viruses by AVG.

<https://www.avg.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE18012958/Kea3s2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 20-03-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 8053A	Veh. Inspected	SLH 5358B
Policy No.	8-V0006680-MVA	Coverage (\$)	0.00
Claim No.	VC011649	Excess (\$)	0.00
Assign From	JOYCE FOO	Assign Date	16/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ACR507006809	Colour	METALLIC SILVER
Odometer	59762	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R18	YOKOHAMA	8 mm
L/H Front Tyre	225/50R18	YOKOHAMA	8 mm
R/H Rear Tyre	225/50R18	YOKOHAMA	8 mm
L/H Rear Tyre	225/50R18	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2018	Inspection Date	17/07/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	28 Working Days
-------------------------------------	-----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5358B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BUCKLED	693.40	693.40
2	FRONT BONNET HINGE	DISTORTED	134.40	134.40
12	FRONT BONNET INSULATOR CLIPS	NOT NECESSARY	38.52	-
1	FRONT BONNET RUBBER CTR	SERVICEABLE	45.90	-
1	FRONT BONNET INNER LOCK	BENT	149.70	149.70
1	FRONT BONNET INNER LOCK CABLE	JAMMED	67.92	67.92
1	FRONT BONNET STAND	MISSING	57.40	57.40
1	FRONT BONNET STAND HOLDER	CRACKED	18.75	18.75
1	FRONT BONNET STAND CLIPS (AT SUPPORT)	NECESSARY	17.92	17.92
1	FRONT GRILLE WITH CHROME ASSY	CRACKED	389.81	389.81
1	FRONT GRILLE EMBLEM CHROME	NECESSARY	85.90	85.90
1	FRONT GRILLE TOP RUBBER	NECESSARY	85.90	85.90
8	FRONT GRILLE CLIPS	NECESSARY	25.68	25.68
2	HEADLAMP (NOT HID)	MTG CRACKED	1,811.22	1,811.22
2	HEADLAMP TOP RUBBER (NPA)	SERVICEABLE	-	-
2	HEADLAMP HIGH BEAM BULB	NECESSARY	123.40	123.40
2	HEADLAMP SIGNAL BULB	SERVICEABLE	36.04	-
2	HEADLAMP LOWER BEAM (NPA)	SERVICEABLE	-	-
4	HEADLAMP CLIPS	NECESSARY	12.84	12.84
1	FRONT BUMPER	BENT	493.35	493.35
2	FRONT BUMPER SIDE RETAINER	DISTORTED	162.50	162.50
12	FRONT BUMPER CLIPS	NECESSARY	46.68	46.68
2	FRONT BUMPER TOW COVER	SERVICEABLE	48.04	-
1	FRONT BUMPER LOWER GRILLE CTR	CRACKED	107.20	107.20
1	FRONT BUMPER TOP CTR BEAM	BENT	149.80	149.80
1	FRONT BUMPER REINFORCEMENT	BENT	425.90	425.90
1	FRONT BUMPER REINFORCEMENT BRACKET	TO REPAIR SEE LABOUR	217.60	-
1	FRONT BUMPER SPONGE	CRACKED	68.80	68.80
1	FRONT BUMPER LOWER RUBBER CTR	SERVICEABLE	135.60	-
1	ENGINE UNDER COVER CTR	SERVICEABLE	225.90	-

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	ENGINE UNDER COVER CLIPS	NOT NECESSARY	31.10	-
2	FOGLAMP	SERVICEABLE	472.80	-
2	FOGLAMP OUTER SIDE COVER	SERVICEABLE	249.40	-
2	FRONT FENDER	TO REPAIR SEE LABOUR	1,164.80	-
1	FRONT FENDER COWLING	CRACKED	423.34	423.34
20	FRONT FENDER COWLING CLIPS	NECESSARY	42.20	42.20
10	FRONT FENDER RIVET CLIPS (NPA)	NOT NECESSARY	-	-
1	A/C COMPRESSOR ASSY	TO REPAIR SEE LABOUR	2,512.60	-
1	AIR CON CONDENSER ASSY	PUNCTURE	1,751.60	1,751.60
1	AIR CON CONDENSER PIPE (COND VALVE)	SERVICEABLE	711.64	-
1	AIR CON CONDENSER PIPE (COND COMP)	SERVICEABLE	375.60	-
1	AIR CON CONDENSER PIPE (COMP VALVE)	SERVICEABLE	566.40	-
1	AIR CON CONDENSER FAN BLADE	DISTORTED	156.30	156.30
1	AIR CON CONDENSER FAN MOTOR	JAMMED	511.67	511.67
1	AIR CON CONDENSER FAN COWLING	CRACKED	274.63	274.63
1	RADIATOR ASSY	PUNCTURE	2,159.60	2,159.60
1	RADIATOR TOP CTR PLATE	CRACKED	86.01	86.01
1	RADIATOR TOP HOSE	SERVICEABLE	69.70	-
1	RADIATOR BOTTOM HOSE	SERVICEABLE	61.20	-
2	RADIATOR TOP BRACKET	TO REPAIR SEE LABOUR	134.80	-
2	RADIATOR TOP BRACKET BUSH	CUT	49.40	49.40
2	RADIATOR LOWER BUSH	SERVICEABLE	45.40	-
1	RADIATOR FAN MOTOR	JAMMED	511.67	511.67
1	RADIATOR FAN BLADE	DISTORTED	126.70	126.70
1	RADIATOR SPARE TANK	SERVICEABLE	430.40	-
2	RADIATOR SPARE TANK HOSE	SERVICEABLE	95.60	-
1	RADIATOR SPARE TANK CTR PIPE	SERVICEABLE	86.90	-
1	RADIATOR SUPPORT PANEL	BUCKLED	1,021.70	1,021.70
2	RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE	CRACKED	88.54	88.54
1	RADIATOR SUPPORT PANEL TOP GARNISH	CRACKED	197.60	197.60
12	RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	50.52	50.52

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	HORN	SERVICEABLE	285.40	-
1	ALTERNATOR ASSY	SERVICEABLE	2,370.50	-
1	ALTERNATOR BELTING	SERVICEABLE	196.70	-
1	ALTERNATOR WIRE SOCKET (NPA)	SERVICEABLE	-	-
1	RESONATOR TANK LH	SERVICEABLE	109.55	-
1	RESONATOR TANK UPPER HOSE LH	SERVICEABLE	95.70	-
1	WIPER WASHER TANK RH	SERVICEABLE	141.70	-
1	WIPER WASHER TANK NECK RH	SERVICEABLE	57.80	-
1	HEADLAMP BULB LOWER	SERVICEABLE	123.40	-
1	WIPER WASHER TANK MOTOR	SERVICEABLE	393.92	-
1	BATTERY TRAY	SERVICEABLE	87.90	-
1	BATTERY TRAY TOP BRACKET	TO REPAIR SEE LABOUR	47.90	-
1	AIR CLEANER BOX COMPLETE	SERVICEABLE	919.60	-
1	AIR DUCT OUTER	DENTED	100.70	100.70
2	AIR DUCT OUTER CLIPS	NOT NECESSARY	6.42	-
1	ENGINE ECU UNIT LH	SERVICEABLE	2,768.70	-
1	ENGINE MOUNTING RH	SERVICEABLE	298.70	-
1	ENGINE MOUNTING FRONT	SERVICEABLE	141.70	-
1	ENGINE MOUNTING REAR	SERVICEABLE	207.80	-
1	GEARBOX MOUNTING LH	SERVICEABLE	244.67	-
1	REAR WINDSCREEN MOULDING	NECESSARY	137.30	137.30
1	TAILGATE	BENT	1,592.70	1,592.70
2	TAILGATE HINGE	TO REPAIR SEE LABOUR	137.40	-
1	TAILGATE EMBLEM	NECESSARY	65.70	65.70
1	TAILGATE LOGO (ESTIMA) LH	NECESSARY	56.95	56.95
1	TAILGATE LOGO (X) RH	NECESSARY	41.75	41.75
1	TAILGATE NO PLATE CHROME MOULDING	SERVICEABLE	245.60	-
2	TAILGATE NO PLATE LAMP	SERVICEABLE	119.40	-
1	TAILGATE INNER LOCK	JAMMED	391.60	391.60
1	TAILGATE INNER LOCK COVER	MISSING	41.25	41.25
1	TAILGATE INNER LOCK CATCH	DISTORTED	39.67	39.67
1	TAILGATE OUTER SWITCH OPENING (NPA)	SERVICEABLE	-	-

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE OUTER SWITCH OPENING COVER (NPA)	SERVICEABLE	-	-
1	TAILGATE CTR REFLECTOR WHITE	SERVICEABLE	345.20	-
2	TAILGATE CTR REFLECTOR CLIPS	NOT NECESSARY	15.60	-
2	TAILGATE LAMP WHITE	SERVICEABLE	843.40	-
6	TAILGATE LAMP CLIPS	NECESSARY	40.20	40.20
1	TAILGATE WIPER MOTOR	SERVICEABLE	720.85	-
2	TAILGATE SIDE STOPPER RUBBER ADJUSTER	MISSING	15.68	15.68
1	TAILGATE OUTER SIDE HOLDER COVER RH	SERVICEABLE	45.90	-
1	TAILGATE INNER TRIMBOARD	BUCKLED	481.74	481.74
2	TAILGATE INNER TRIMBOARD SIDE COVER LAMP LED (NPA)	SERVICEABLE	-	-
2	TAILGATE INNER UPPER SIDE GARNISH	SERVICEABLE	309.40	-
1	REAR BUMPER	BENT	686.20	686.20
2	REAR BUMPER SIDE RETAINERS	DISTORTED	119.20	119.20
2	REAR BUMPER CTR RETAINERS	CRACKED	123.40	123.40
12	REAR BUMPER CLIPS	NECESSARY	46.68	46.68
1	REAR BUMPER SPONGE LH	TORN	75.30	75.30
2	REAR BUMPER TOW COVER	MISSING	55.20	55.20
1	REAR END PANEL	BENT	691.70	691.70
1	REAR END PANEL TOP GARNISH	DISTORTED	298.90	298.90
12	REAR END PANEL TOP GARNISH CLIPS	NECESSARY	87.00	87.00
1	REAR END PANEL TOP GARNISH CTR COVER	SERVICEABLE	41.70	-
1	REAR END PANEL INNER LOWER GARNISH	BUCKLED	201.70	201.70
1	SPARE TYRE PANEL	BENT	380.90	380.90
6	SPARE TYRE PANEL LOWER SIDE RUBBER	MISSING	247.00	123.00
2	SPARE TYRE PANEL LOWER SIDE BRACKET	TO REPAIR SEE LABOUR	149.70	-
1	SPARE TYRE PANEL BRACKET	TO REPAIR SEE LABOUR	100.70	-
1	SPARE TYRE PANEL CTR BRACKET	TO REPAIR SEE LABOUR	244.89	-
1	SPARE TYRE PANEL TOP TRIMBOARD	SERVICEABLE	1,048.40	-
2	REAR CHASSIS SIDE PANEL LH & RH	TO REPAIR SEE LABOUR	2,497.40	-

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR CHASSIS SIDE PANEL OUTER LH & RH	TO REPAIR SEE LABOUR	1,137.80	-
2	REAR CHASSIS FRAME LH & RH	TO REPAIR SEE LABOUR	1,855.60	-
2	REAR FENDER OUTER LH & RH	TO REPAIR SEE LABOUR	2,095.40	-
2	REAR FENDER LOWER AIR VENT	SERVICEABLE	259.48	-
2	REAR FENDER INNER TRIMBOARD LH & RH	DEFORMED	1,440.30	1,440.30
1	REAR FENDER INNER SIDE TOOL JACK COVER	SERVICEABLE	206.70	-
1	REAR A/C BLOWER & COOLING COIL ASSY	HOUSING CRACKED	2,111.70	2,111.70
2	REAR FENDER GLASS WITH MOULDING LH & RH	SERVICEABLE	1,392.60	-
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	1,202.70	-
1	REAR EXHAUST BOX TOP HEAT PLATE	TO REPAIR SEE LABOUR	126.70	-
4	REAR EXHAUST BOX MOUNTING	SERVICEABLE	309.96	-
1	REAR EXHAUST CTR PIPE	TO REPAIR SEE LABOUR	1,916.74	-
3	REAR EXHAUST CTR PIPE MOUNTING	SERVICEABLE	232.47	-
2	TAILLAMP WHITE	CRACKED	799.40	799.40
6	TAILLAMP CLIPS	NECESSARY	33.00	33.00
2	TAILLAMP PANEL	TO REPAIR SEE LABOUR	505.40	-
1	FLOOR PANEL CARPET (NPA)	SERVICEABLE	-	-
1	SPARE TYRE PANEL CARPET (NPA)	SERVICEABLE	-	-
2	REAR THIRD SEATBELT (NPA)	SERVICEABLE	-	-
2	HEADLAMP SMALL BULB SOCKET (ADDITIONAL)	CRACKED	51.48	51.48
2	HEADLAMP SIGNAL LAMP SOCKET LH & RH (ADDITIONAL)	CRACKED	77.40	77.40
1	END PANEL SIDE OUTER LH (ADDITIONAL)	BENT	165.67	165.67
1	END PANEL SIDE OUTER RH (ADDITIONAL)	BENT	165.67	165.67
1	REAR A/C BROWER LIQUID PIPE NO1 (ADDITIONAL)	BENT	201.30	201.30
1	REAR A/C BROWER SUCTION PIPE NO2 (ADDITIONAL)	BENT	274.80	274.80
5	TAILGATE TOP SPOILER CLIP BIG (ADDITIONAL)	NECESSARY	27.50	27.50
2	REAR FENDER COWLING LH & RH (ADDITIONAL)	NECESSARY	241.50	241.50

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	HEADLAMP COVER CIRCLE (ADDITIONAL)	MISSING	77.40	77.40
6	REAR FENDER INNER TRIMBOARD SIDE CLIPS (ADDITIONAL)	NECESSARY	24.00	24.00
	REAR BUMPER SPONGE RH (ADDITIONAL)	MISSING	75.30	75.30
	LESS 25% DISCOUNT		-14,681.47	-6,060.19
			44,044.41	18,180.60
1	FRONT BONNET INSULATOR (SN)	NECESSARY	356.20	120.00
1	SET TAILGATE ABSORBER MOTOR ASSY (SN)	JAMMED	880.00	880.00
1	TAILGATE RUBBER (AT BODY) (50%) (SN)	DENTED / CUT	386.40	193.20
2	REAR BUMPER SIDE REFLECTOR LAMP LED WHITE (SN)	CRACKED	120.00	120.00
	LESS 25% DISCOUNT		-435.65	-
			1,306.95	1,313.20
SPECIAL NETT ITEMS				
1	TAILGATE REVERSE CAMERA (NPA) (SN)	SERVICEABLE	-	-
1	NUMBER PLATE FRONT (SN)	MISSING	35.00	35.00
1	RADIATOR COOLANT (SN)	NECESSARY	35.00	20.00
1	BATTERY ASSY (SN)	SERVICEABLE	250.00	-
1	POWER EARTH MODULE (NPA) (SN)	SERVICEABLE	-	-
1	POWER EARTH MODULE WIRE (NPA) (SN)	SERVICEABLE	-	-
1	FRONT GRILLE STICKER (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	30.00
2	REAR FENDER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
2	REAR FENDER GLASS INNER SEAL (SN)	NOT NECESSARY	80.00	-
1	NUMBER PLATE REAR (SN)	MISSING	35.00	35.00
1	REAR CAMERA RECORDER (NPA) (SN)	SERVICEABLE	-	-
2	TAILGATE LAMP STICKER (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
2	TAILLAMP STICKER (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE CTR REFLECTOR LAMP STICKER (SN)	NECESSARY	20.00	20.00
1	TAILGATE TOP CTR PLATE WITH STICKER (NPA) (SN)	SERVICEABLE	-	-

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER REFLECTOR LAMP WHITE (NPA) (SN)	SERVICEABLE	-	-
2	TAILGATE INNER TRIMBOARD SIDE LAMP (NPA) (SN)	SERVICEABLE	-	-
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	SET REVERSE SENSOR MODULE & WIRE HARNESS (NPA) (SN)	SERVICEABLE	-	-
			905.00	430.00
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/S GAS.		150.00	100.00
	TO REMOVE & REPLACE ALTERNATOR BELTING A/C COMPRESSOR.	NOT NECESSARY	200.00	-
	TO RESET ENGINE LIGHT, HEADLAMP ECU AIRBAG.		280.00	120.00
	TO REMOVE & REINSTALL / REPLACE AIR CLEANER BOX, ENGINE ECU MODULE, POWER EARTH MODULE & WIRE.	NOT NECESSARY	200.00	-
	TO REMOVE & REINSTALL, REPLACE ENGINE MOUNTING FRONT, REAR, GEARBOX MOUNTING	NOT NECESSARY	180.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		180.00	60.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT. TO KNOCK & REPAIR FRONT DOOR LH, & RH, FRONT WHEELHOUSE, FRONT CHASSIS FRAME INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT BRACKET, FRONT FENDER, A/C COMPRESSOR ASSY, RADIATOR TOP BRACKET AND BATTERY TRAY TOP BRACKET.		1,400.00	700.00
	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT BUMPER ENFORCEMENT, FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT WHEELHOUSE, FRONT CHASSIS FRAME.		1,200.00	1,000.00
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		120.00	100.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR WINDSCREEN.		150.00	120.00
	TO REMOVE & REINSTALL / REPLACE TAILGATE MOTOR.		150.00	60.00
	TO REMOVE & REINSTALL / REPLACE REAR A/C BLOWER & COOLING COIL ASSY.		250.00	100.00
	TO REMOVE & REINSTALL / REPLACE REAR FENDER GLASS WITH MOULDING LH & RH	NOT NECESSARY	240.00	-
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		380.00	150.00
	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO REMOVE AND REINSTALL / REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.		180.00	60.00
	TO REMOVE AND REINSTALL / REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		100.00	60.00
	TO DISMANTLE & INSTALL / REPLACE REAR THIRD SEATBELT.		200.00	80.00
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS.		80.00	80.00
	TO RESET TAILGATE MOTOR, SRS, LIGHT, ENGINE LIGHT.	NOT NECESSARY	380.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		280.00	120.00
	TO REALIGN, DISMANTLE AND REINSTALL / REPLACE EXHAUST PIPE.		180.00	80.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD TAILLAMP PANEL, END PANEL, SPARE TYRE PANEL, RR FENDER, EE CHASSIS FRAME & SIDE PANEL & OUTER PANEL. TO KNOCK & REPAIR FLOOR PANEL, REAR WHEEL HOUSE, RR FENDER INNER. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF TAILGATE HINGE, SPARE TYRE PANEL LOWER SIDE BRACKET, SPARE TYRE PANEL BRACKET, SPARE TYRE PANEL CTR BRACKET, REAR CHASSIS SIDE PANEL LH & RH, REAR CHASSIS SIDE PANEL OUTER LH & RH, REAR CHASSIS FRAME LH & RH, }		3,000.00	2,200.00

Report Ref No. CC4/QBE18012958/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REAR FENDER OUTER LH & RH, REAR EXHAUST BOX, REAR EXHAUST BOX TOP HEAT PLATE, REAR EXHAUST CTR PIPE, TAILLAMP PANEL, TAILGATE LAMP STICKER AND TAILLAMP STICKER. }		-	-
	TO SPRAY TAILGATE, RR BUMPER, END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL, RR FENDER, RR FENDER INNER, RR CHASSIS FRAME, RR CHASSIS SIDE PANEL OUTER, RR CHASSIS SIDE PANEL, FLOOR PANEL, RR WHEELHOUSE.		2,300.00	1,600.00
			12,320.00	6,830.00
GRAND TOTAL			58,576.36	26,753.80
RECOMMENDED COST OF REPAIR SUM				24,800.00

Report Ref No. CC4/QBE18012958/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.