

EDIT	SIR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RATE	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	8		TO REMOVE AND INSTALL AIR CONDENSER AND RECHARGE AIR COND GAS.	65	0	0	Reviewing		
	9		TO REMOVE AND INSTALL RADIATOR AND PERFORM LEAKAGE TEST.	50	0	0	Reviewing		
	10		TO USE HYDRAULIC PUMP AND JACK CHASSIS MEMBER.	250	0	0	Reviewing		
	11		TO SPRAY UNDERCOATING.	120	0	0	Reviewing		
	12		TO CONDUCT WHEEL ALIGNMENT.	65	0	0	Reviewing		
	13		TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS.	2600	0	0	Reviewing		
	14		SPRAY PAINTING ON AFFECTED & REPLACE PARTS.	2200	0	0	Reviewing		
	15		TO TOWING.	50	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRN%	DISCOUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	48	1			AIR CONDENSER			Serviceable	0		25		0	Reviewing	
	49	1			AIR COND PIPE - SUCTION			Serviceable	0		25		0	Reviewing	
	50	1			AIR COND PIPE - DISCHARGE			Serviceable	0		25		0	Reviewing	
	51	1			AIR COND PIPE - LIQUID			Serviceable	0		25		0	Reviewing	
	52	1			RADIATOR			Serviceable	0		25		0	Reviewing	
	53	1			RADIATOR TOP HOUSING			Serviceable	0		25		0	Reviewing	
	54	2			HORN			Serviceable	0		25		0	Reviewing	
	55	1			FAN MOTOR			Serviceable	0		25		0	Reviewing	
	56	1			FAN BLADE			Serviceable	0		25		0	Reviewing	
	57	1			FAN COWLING			Serviceable	0		25		0	Reviewing	
	58	2			REAR EXHAUST MOUNTING			Serviceable	0		25		0	Reviewing	
	59	1			REAR LH CHASSIS MEMBER			Repair	0		25		0	Reviewing	
	60	1			REAR LH FENDER			Buckled	602.95		25		452.21	Reviewing	
	61	1			REAR LH FENDER INNER TRIM			Deformed	322.1		25		241.58	Reviewing	
	62	6			REAR LH FENDER INNER TRIM CLIP			Necessary	3.89		25		17.51	Reviewing	
	63	1			REAR LH FENDER AIR DUCT			Cracked	98		25		73.5	Reviewing	
	64	1			REAR LH BUMPER SPLASH GUARD			Missing	102		25		76.5	Reviewing	
	65	1			FUEL LID COVER			Buckled	58		25		43.5	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
			13	1	REAR BOOT CYLINDER LOCK			Serviceable	0		25		0	Reviewing	
			14	4	REAR BOOT STOPPER			Serviceable	0		25		0	Reviewing	
			15	1	REAR BOOT LAMP (N/S)			Cut	253.4		25		190.05	Reviewing	
			16	1	REAR BOOT LAMP (O/S)			Cracked	253.4		25		190.05	Reviewing	
			17	2	LICENCE PLATE LAMP			Serviceable	0		25		0	Reviewing	
			18	1	REAR BUMPER			Missing	534		25		400.5	Reviewing	
			19	2	REAR BUMPER BRACKET			Bent	35.6		25		53.4	Reviewing	
			20	2	REAR BUMPER SUPPORT			Serviceable	0		25		0	Reviewing	
			21	2	REAR BUMPER RETAINER			Damaged	52.3		25		78.45	Reviewing	
			22	8	REAR BUMPER CLIP			Necessary	2		25		12	Reviewing	
			23	1	REAR BUMPER SPONGE			Broken	124.7		25		93.53	Reviewing	
			24	1	REAR BUMPER REINFORCEMENT			Missing	102.8		25		77.1	Reviewing	
			25	2	REAR BUMPER REFLECTOR			Missing	58		25		87	Reviewing	
			26	2	REAR BUMPER GROMMET			Missing	10		25		15	Reviewing	
			27	1	REAR END PANEL			Bent	580.6		25		435.45	Reviewing	
			28	1	REAR END PANEL TOP GARNISH			Cracked	44.36		25		33.27	Reviewing	
			29	2	REAR END PANEL SUPPORT			Repair	0		25		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0	0	License Type		
Market Value	0	0	License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	55 DEVANSHIRE RESIDENCE, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	G6398559M	

Claim Portal						
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	9/24/18 9:00 AM	7500	7500	Open	Share	Clone
RATAN BHOSALE Pragati	7/16/18 1:42 PM	12924.86	12924.86	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
AXA MANDATE REQUEST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
TP LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
LKK REINSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 20, 2018
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 19, 2018
SJS5884P TP GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	July 16, 2018
EMAIL RECIEVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	July 16, 2018
SLQ5556Z INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	July 16, 2018