



Service Request Details

Claim	S8M00OIZ
Reference	None 
Loss Date	12 July 2018
Request Date	19 September 2018
Due Date	17 October 2018
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step Finish the work

Complete Work

More ▾

Vehicle Information

Incident SLX4563Y
Vehicle
Registration #

Make PORSCHE

Model BOXSTER

Service Address

...

Primary Contact/Insured

BABU GOVINDASAMY NAIDU SHURENDRA
15 ANG MO KIO AVENUE 9, #08-02 FAR
HORIZON GARDEN, 569765, Singapore

spynaidu@gmail.com

Claim Handler

Additional Instructions

Wkshop: Stuttgart Auto Excess: \$4000 To survey WP due to large repair cost

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	
 Workshop Invoice - SLX 4563Y.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (OD)	3 October 2018
 Discharge Voucher - SLX 4563Y.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (OD)	3 October 2018
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	17 September 2018
 ESTIMATE MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	17 September 2018
 ESTIMATE MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	17 September 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK RESURVEY PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	17 September 2018
 Immediate Advice - SLX 4563Y.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	19 July 2018
 LKK SURVEYOR PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	19 July 2018
 ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	19 July 2018
 GA346908-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	CHEN Xinyou	17 July 2018
 ESTIMATE & GIA INS.D.pdf	Letters and Correspondence	Others	VISHNU BATHAM Shekhar	17 July 2018
 SLM8296A TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	16 July 2018



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2008 PORSCHE BOXSTER (SLX4563Y)
Date of Loss	12 July 2018
Time of Loss	20.00
Loss Description	SLX4563Y (INSD) C/W REAR OF SLM8296A (TP)
Comment	

Workshop Details

Total Rebate Amount	43594
Nett Loss Amount	\$66,406.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	98



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLX4563Y

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

28/03/2008



Mileage

37881

Age of Vehicle

10

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2008

2008

Make

PORSCHÉ

PORSCHÉ

Model

BOXSTER

987 BOXSTER TIF

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

LIM WEI YEN SHARON

Date of Birth

8 September 1968

dd/mm/yyyy



Age

50

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		▼
Type of Paint		
Chassis No	WPOZZZ98Z8U701710	WPOZZZ98Z8U7
Engine No	65806972	65806972
Engine Capacity		2687
Sum Insured	0	0
Market Value	0	110000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	▼
Driving Experience	0	
Driver License #		
License Type		▼
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	15 ANG MO KIO AVE 9, #08-02, 569765, Singapore	
Address type	Personal Correspondence	▼

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	
Marital status	Unknown	
Identification #	S6836500G	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

18/07/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

4000

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

235/40Z R18

Rear Tyre Size

235/40Z R18

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT FENDER (RH)			Repair	0	0	20	0	0	Deny	
		2	3			FENDER RIVET			Serviceable	0	0	0	0	0	Deny	
		3	1			FUEL CAP LID HINGE			Cracked	38.2		20		30.56	Reviewing	
		4	1			FRONT BUMPER			Deformed	1590.4		20		1272.32	Reviewing	
		5	1			FRONT BUMPER GRILLE FRAME RH			Cracked	155.5		20		124.4	Reviewing	
		6	1			FRONT BUMPER GUIDE PLATE - 2PCS			Bent	12.2		20		9.76	Reviewing	
		7	1			FRONT BUMPER FIXING CLIP			Necessary	20.3		20		16.24	Reviewing	
		8	1			TOW COVER			Cracked	32.7		20		26.16	Reviewing	
		9	1			LICENSE PLATE BRACKET			Cut	31.8		20		25.44	Reviewing	
		10	1			FRONT BUMPER REINFORCEMENT			Bent	362.2		20		289.76	Reviewing	
		11	2			REINFORCEMENT BOLT			Necessary	11.4		20		18.24	Reviewing	
		12	2			IMPACT ABSORBER-FRT			Bent	249.2		20		398.72	Reviewing	
		13	6			SCREW			Necessary	4.2		20		20.16	Reviewing	
		14	2			SEAL-IMPACT ABSORBER FRT			Necessary	7.6		20		12.16	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		15	1			FRONT BUMPER RETAINING STRIP CENTER			Necessary	101.9		20		81.52	Reviewing	
		16	1			BONNET			Bent	1910.6		20		1528.48	Reviewing	
		17	2			BONNET DAMPER			Serviceable	0	0	0	0	0	Deny	
		18	1			BONNET HINGE LH			Serviceable	0	0	0	0	0	Deny	
		19	1			BONNET HINGE RH			Serviceable	0	0	0	0	0	Deny	
		20	1			FENDER TOP GARNISH RH			Serviceable	0	0	0	0	0	Deny	
		21	1			FRONT BUMPER TOP GARNISH CENTER			Cut	57.1		20		45.68	Reviewing	
		22	1			BONNET WEATHERSTRIP			Serviceable	0	0	0	0	0	Deny	
		23	3			TOP GARNISH VELCRO FASTENER-4PCS			Necessary	20.4		20		48.96	Reviewing	
		24	1			FRONT BONNET LOCK PLATE			Bent	25.4		20		20.32	Reviewing	
		25	2			SCREW			Necessary	2.1		20		3.36	Reviewing	
		26	1			BONNET LOCK			Bent	265.1		20		212.08	Reviewing	
		27	1			BONNET LOCK ACTUATOR			Cut	105		20		84	Reviewing	
		28	1			HEADLAMP NOZZLE RH			Serviceable	0	0	0	0	0	Deny	
		29	1			HEADLAMP (RH). HALOGEN			Damaged	2031.2		20		1624.96	Reviewing	
		30	1			FOG LAMP LH			Cracked	390		20		312	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		31	1		FOG LAMP RH			Cracked	390		20		312	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO REMOVE / REPLACE FRONT BUMPER, BONNET, RH FRONT FENDER & TO REPAIR FRONT END PANEL AREAS AFFECTED BY THE ACCIDENT	5460	0	0	Reviewing	
		2		TO RESPRAY FRONT BUMPER, BONNET, RH FRONT FENDER & FRONT END PANEL	4600	0	0	Reviewing	
		3		TO CARRY-OUT BODY CAVITY PRESERVATION	100	0	0	Reviewing	
		4		TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT COMPARTMENT TO GIVE WAY TO THE REPAIR ON THE FRONT END PANEL	0	0	0	Deny	
		5		TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	150	0	0	Reviewing	
		6		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	480	0	0	Reviewing	
		7		TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	0	0	0	Deny	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	DAYS OF REPAIR : 7 DAYS	Reviewing			
☐	2	FRONT NUMBER PLATE	Reviewing	70	SCRATCHED	
☐	3	SUNDRIES	Reviewing	50	NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$13,427.28

Claim Amount

\$13,427.28

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$6,517.28	\$6,517.28
Labour	\$10,790.00	\$10,790.00
Miscellaneous	\$120.00	\$120.00
Excess	-\$4,000.00	-\$4,000.00

Submit for Review