

ASS. REC. BY:

REF: CS/FCI18012941/Dsd3n2

Special Instructions:

Surveyor:
CWS

Bykin

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time: 17/7/18 @ 4:34pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 5683Y

Insured:

SHA 78572

at Workshop no/s:

Teamwork Garage

Tel:

6844 2475

of

Blk 53 Ubi Ave 1 # 01-24

Policy No:

Claim No:

D18005445MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/07/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

4:15pm @ 17/7/18

Person Contacted:

Daren

Vehicle

(IN) OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKM 5683Y - NA/EQI18012794/24	DOA: 13/7/18
	SHA 78572 - NA/EQI18012794/24	DOA: 13/7/18

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Item Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

NIS	OC

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report Consistent? : Yes or No
 G/A / PR Seen: Consistent? : Yes or No
 Est. Repair: 5 days Res: Yes or No
 Loss Sum: 20 % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKM 5683Y Regn: 2014 March
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C CC: 1497
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 286444 T/Radio: Insured / Std / NI / NA
 Eng/No: 1N2R093432
 C/No: 5TDKD3B3801054100
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / SRim / STD A/Rim or
 Tyre Size: F: 185/60 R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front Hour
 R/Bol: 5 mm R/Bol: 5 mm
 L/Bol: 5 mm L/Bol: 5 mm
 D.O.A: 13/07/2018 D.O.I: 18/07/2018
 Survey hold at Teamwork Pyc Ubi
 Des. of Damages: Frl / Rear / O/S / NIS / UIC / Rooftop or
 O/S Rmt
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 11/11/2019 First Capital SHA 7857 Z
 11/11/2019 Insured 2/5 4600/- with 5 days of rep
 (\$ 5,840.26 Red - 56%)

RECEIVED 11 NOV 2019

Date/Time, File Path: 11/11/19
 Type: Typist
 Signature, Full Name: _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Weekend \$

Survey Fee:
 Transportation:
 S + RS: \$
 Note:
 Other:
 TOTAL

170
50
50
70
340

Form: _____
 Stamp: _____ \$4,600/- 4/5

MOTOR SURVEY ASSIGNMENT

Date	16-07-2018	Our Ref No. D18005445MFSH
Accident Date	13-07-2018	Claim Type. Third Party
Insured Vehicle	SHA7857Z	Third Party Vehicle. SKM5683Y
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	NA	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242408)



PRI Documents



Close



PRI Header Details

Claim No	D18005445MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TEAMWOF
Workshop Name	TEAMWORK GARAGE PTE LTD (Contact Person : NA)	Survey Location & Contact Details	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK Mobile: 0 , Phone: 68442475 , Fax: 68442474 EmailId: CLAIMS@TEAMWORKGARAGE.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7857Z	TP Vehicle No	SKM5683Y
PRI Recieved Date	16-07-2018 08:18:58 PM	Surveyor Appointed Date	17-07-2018 04:38:41 PM	Surveyor Accept Date	17-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	17-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name	Action
-----------	--------

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

M/s First Capital Insurance Limited
30 Robinson Road
#10-01/02 Robinson Towers
Singapore 048546

3RD PARTY CLAIM ESTIMATION

Vehicle number	SKM5683Y
Make / Model	TOYOTA PRIUS
Chassis number	JTDKD3B3801054100
Accident date	13/7/18
Reference	1807-12

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT RH FENDER <i>Destroyed</i>	783.15 ✓
1	FRONT RH FENDER INNER SHIELD <i>deformed / torn</i>	186.00 ✓
1	FRONT RH FENDER EMBLEM (HYBRID) <i>Nec</i>	78.00 ✓
1	FRONT RH HEADLAMP <i>mainly cracked</i>	1242.00 ✓ <i>762.80</i>
1	FRONT RH HEADLAMP LOWER BRACKET <i>NH</i>	81.60 X
1	FRONT RH FOG LAMP <i>mainly cracked</i>	336.00 ✓
1	FRONT RH FOG LAMP COVER <i>mainly cracked</i>	80.40 ✓
1	FRONT BUMPER <i>destroyed / cut</i>	615.25 ✓
1	FRONT BUMPER RETAINER <i>3V2</i>	93.60 X
1	FRONT GRILLE <i>NH</i>	354.00 X
1	FRONT BUMPER REINFORCEMENT <i>NH</i>	396.75 X
1	FRONT RH WING MIRROR <i>broken</i>	632.50 ✓
1	FRONT SUPPORT PANEL <i>fig</i>	687.70 X
1	FRONT SUPPORT PANEL TOP GARNISH <i>NH</i>	174.00 X
1	FRONT RH SHOCK ABSORBER <i>destroyed</i>	514.05 ✓ <i>441.50</i>
1	FRONT RH KNUCKLE ARM <i>destroyed</i>	594.00 ✓
1	FRONT RH KNUCKLE ARM BEARING <i>Down</i>	174.00 ✓
1	FRONT RH LOWER ARM <i>destroyed</i>	1137.35 ✓ <i>522.87</i>
		8160.35
Less 25 %		2040.09
Subtotal		6120.26
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		6120.26
1	RIM <i>cut</i>	800.00 400/-
1	TYRE <i>NH</i>	500.00 X
1 BOT	BRAKE FULID <i>NH</i>	50.00 X
1 SET	FRONT BUMPER CLIP <i>Nec</i>	50.00 30/-
1 SET	FRONT FENDER INNER SHIELD CLIP <i>Nec</i>	40.00 20/-
Subtotal		1440.00
Balance C/F		7560.26

5206.47

3904.85

450.00

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	7560.26
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00 NW
3	REMOVE, RENEW AND REFIT FRONT UNDERCARRAIGE	200.00 150/-
5	PANEL BEATING ON AFFECTED AREAS	1000.00 700/-
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 600/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	2910.00
	Grand total	10470.26

18/07/2018 e 11:00h

Not Antnd 5 days.
L/Smt

Ryan

LKK Auto



5874.85

L/S 4600/-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012991/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7857Z	Veh. Inspected	SKM 5683Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005445MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS C	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKD3B3801054100	Colour	WHITE	
Odometer	286444	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WEST LAKE	5 mm	
L/H Front Tyre	185/60 R15	WEST LAKE	5 mm	
R/H Rear Tyre	185/60 R15	WEST LAKE	5 mm	
L/H Rear Tyre	185/60 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/07/2018	Inspection Date	18/07/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 5683Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT RH FENDER	DENTED	783.15	783.15
1	FRONT RH FENDER INNER SHIELD	DEFORMED / TORN	186.00	186.00
1	FRONT RH FENDER EMBLEM (HYBRID)	NECESSARY	78.00	78.00
1	FRONT RH HEADLAMP	MOUNTING CRACKED	1,242.00	762.80
1	FRONT RH HEADLAMP LOWER BRACKET	NOT NECESSARY	81.60	-
1	FRONT RH FOG LAMP	MOUNTING CRACKED	336.00	336.00
1	FRONT RH FOG LAMP COVER	MOUNTING CRACKED	80.40	80.40
1	FRONT BUMPER	DISTORTED / CUT	615.25	615.25
1	FRONT BUMPER RETAINER	SERVICEABLE	93.60	-
1	FRONT GRILLE	NOT NECESSARY	354.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	396.75	-
1	FRONT RH WING MIRROR	BROKEN	632.50	632.50
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	687.70	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	174.00	-
1	FRONT RH SHOCK ABSORBER	DISTORTED	514.05	441.50
1	FRONT RH KNUCKLE ARM	DISTORTED	594.00	594.00
1	FRONT RH KNUCKLE ARM BEARING	DAMAGED	174.00	174.00
1	FRONT RH LOWER ARM	DISTORTED	1,137.35	522.87
	LESS 25% DISCOUNT		-2,040.09	-1,301.62
			6,120.26	3,904.85
SPECIAL NETT ITEMS				
1	RIM (SN)	CUT	800.00	400.00
1	TYRE (SN)	NOT NECESSARY	500.00	-
1	BOT BRAKE FULID (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	40.00	20.00
			1,440.00	450.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	30.00
	DIAGNOIS CHECK AND CLEAR FAULT COE.		500.00	-
	REMOVE,RENEW AND REFIT FRONT UNDERCARRIAGE.		200.00	150.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,000.00	700.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			2,910.00	1,520.00
GRAND TOTAL			10,470.26	5,874.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,600.00

Report Ref No. CS/FCI18012991/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.