

ASS. REC. BY:

REF:

02/7CL1801999 / Arbznz

Special Instruction:

Survivor

ASSIGNMENT (Office)From (Person): (WS) Lurene Jaw of FCL Date/Time: 17/07/2018 5:49pm

Estimated Cost: _____ Bill to: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SBT 797E Insured: SHC 7649Yat Workshop m/s Hua Meng Tel: 6746 5519of Blk 1 Kaki Bukit Ave 6 #01-61Policy No: _____ Claim No: D18005423MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11-07-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 17/07/2018 Person Contacted: June Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SBT 797E - (16/CL11500951) / Arbznz	DA: 300515
	SHC 7649Y - NS / INC 14024157 / Hlvbdl	DA: 241214
18/7/18	Revert pending est from insurance	

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBT797E Yr Regn: 2017, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz GLC 250 c.c. 1991

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 14053 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC2533462F163892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45R20

R: 255/45R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 17/08/18

Survey held at Hua Meng

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/9	TP 1st Cop. Confirmed LC \$11,900 and 7 days with Hua Meng by Adrian. (Red. 13,640.70, 53%)
	RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp. (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : TP

Lump Sum / L.B.I: (\$ 11,900)

Survey Fee:

Transportation:

S + RS. SI

Photos 580

Other 658

TOTAL 1238

15x15 = 225

170 + 225

50

50

139

634

MOTOR SURVEY ASSIGNMENT

Date	13-07-2018	Our Ref No. D18005423MFSH
Accident Date	11-07-2018	Claim Type. Third Party
Insured Vehicle	SHC7649Y	Third Party Vehicle. SBT797E
Survey Location	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C #01-61/01-34	
Contact Person.	JUNE	
Contact No.	67465519/ 0	Fax No. 67434896
Survey Type	WITHOUT PREJUDICE: KINDLY ASK TP TO FORWARD US THEIR VF TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA MENG SPRAY PAINTING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, July 18, 2018 10:07 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005423MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle SBT 797E on 17/07/2018.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, July 17, 2018 6:15 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005423MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 17 July, 2018 5:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005423MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1219B
Vehicle Details	
Vehicle No.:	SBT797E
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC250 4MATIC COUPE AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	27492030846310
Chassis No.:	WDC2533462F163892
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$48,086.00
Original Registration Date:	31 Jul 2017
First Registration Date:	31 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$59,321.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2027
PARF Rebate Amount:	\$44,490.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,526.00
COE Rebate Amount:	\$44,048.00
Total Rebate Amount:	\$88,538.00

The information contained herein is correct as at 15 Oct 2018

OK

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WDC2533462F163892

AJEET GOBINDRAM VASWAN
266 UPPER EAST COAST ROAD
S 466412

TP 1st Gap.
Janice

Date :26.07.2018
Vehicle no :SBT 797 E
Make/Model :MERCEDES GLC250
Accident date :11.07.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bonnet <i>dented</i>	1	\$ 2079 1950.
2	Front bonnet hinges @ \$203.50 <i>new</i>	2	\$ 407 X
3	Front bonnet top catch <i>new</i>	1	\$ 71.5 X
4	Front bonnet lower centre lock	1	\$ 60.5 X
5	Front bonnet side lock @ \$69.30	2	\$ 138.6 X
6	Front bonnet side lock catch @ \$63.80	2	\$ 127.6 X
7	Front bonnet side spring @ \$33.00	2	\$ 66 X
8	Front bonnet insulation <i>new</i>	1	\$ 305.8 X
9	Front bonnet shock absorber @ \$116.60 <i>new</i>	2	\$ 233.2 X
10	Front support panel <i>Repair</i>	1	\$ 528 X
11	Front grille assy <i>cracked</i>	1	\$ 2400 1550.
12	Front grille logo <i>new</i>	1	\$ 60.5 ✓
13	Front grille top garnish <i>cracked</i>	1	\$ 231 ✓
14	Front grille side garnish @ \$258.50 <i>cracked</i>	2	\$ 517 ✓
15	Front grille clips (1set) <i>new</i>	1	\$ 70 20.
16	Front head lamp @ \$3245.00 <i>cracked</i>	2	\$ 6490 5700
17	Front head lamp top rubber @ \$95.70 <i>new</i>	2	\$ 191.4 X
18	Front bumper <i>deformed</i>	1	\$ 1700 1450.
19	Front bumper side holder @ \$68.20 <i>new</i>	2	\$ 136.4 ✓
20	Front bumper sensor @ \$308.00 <i>2 pieces damaged</i>	6	\$ 1848 520
21	Front bumper centre lower grille <i>cracked</i>	1	\$ 460 ✓
22	Front bumper centre lower grille moulding <i>new</i>	1	\$ 295 ✓
23	Front bumper fog lamp garnish @ \$145.00 <i>cracked</i>	2	\$ 290 ✓
24	Front bumper towing hook cover <i>new</i>	1	\$ 68.2 X
25	Front bumper reinforcement <i>new</i>	1	\$ 490 ✓
26	Front bumper sponge <i>cracked</i>	1	\$ 143 ✓
27	Front bumper lower side garnish @ \$77.00 <i>new</i>	2	\$ 154 ✓
28	Front bumper lower side garnish top holder @ \$40.00 <i>new</i>	2	\$ 80 X
29	Front bumper inner top garnish <i>cracked</i>	1	\$ 203.5 ✓
30	Front bumper inner lower garnish	1	\$ 104.5 ✓
31	Front bumper clips (1set) <i>new</i>	1	\$ 70 30
32	Front fender inner shield @ \$375.00	2	\$ 750 X
33	Front fender inner shield clips @ \$65.00 set <i>new</i>	2	\$ 130 X
34	Front bumper lower side moulding @ \$181.50 <i>deformed</i>	2	\$ 363 ✓
35	Front radiator side garnish @ \$93.50 <i>cracked</i>	2	\$ 187 ✓
			21449.7

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

AJEET GOBINDRAM VASWAN
266 UPPER EAST COAST ROAD
S 466412

Date :26.07.2018
Vehicle no :SBT 797 E
Make/Model :MERCEDES GLC250
Accident date :11.07.2018

No	Description	Qty	Amount (\$\$)
36	Front radiator centre lower cover <i>new</i>	1	\$ 93.5 x
37	Front number plate garnish <i>Defend</i>	1	\$ 176 ✓
38	Front bonnet centre logo <i>new</i>	1	\$ 71.5 ✓
Total			\$ 21790.7

Special Nett Items

1	Front number plate <i>Defend</i>	1	\$ 50.30
2	Front number plate holder <i>Defend</i>	1	\$ 50.30
Total			\$ 100

Labour Cost

1	Remove & reinstall air con fill in gas	\$ 200-120
2	Remove ,replace & repair consistent to the accident	\$ 1800-600
3	Respray painting	\$ 1500-500
4	Tuff kote	\$ 150 x
Total		\$ 3650

Grand Total \$ 25540.7

total 14872.16
L/S 11.9K
07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012999/Arbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7649Y	Veh. Inspected	SBT 797E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005423MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDC2533462F163892	Colour	SILVER	
Odometer	14053	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R20	MICHELIN	6 mm	
L/H Front Tyre	255/45 R20	MICHELIN	6 mm	
R/H Rear Tyre	255/45 R20	MICHELIN	6 mm	
L/H Rear Tyre	255/45 R20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2018	Inspection Date	17/07/2018	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBT 797E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DENTED	2,079.00	1,950.00
2	FRONT BONNET HINGES @\$203.50	NOT NECESSARY	407.00	-
1	FRONT BONNET TOP CATCH	NOT NECESSARY	71.50	-
1	FRONT BONNET LOWER CENTRE LOCK	NOT NECESSARY	60.50	-
2	FRONT BONNET SIDE LOCK @\$69.30	NOT NECESSARY	138.60	-
2	FRONT BONNET SIDE LOCK CATCH @\$63.80	NOT NECESSARY	127.60	-
2	FRONT BONNET SIDE SPRING @\$33.00	NOT NECESSARY	66.00	-
1	FRONT BONNET INSULATION	NOT NECESSARY	305.80	-
2	FRONT BONNET SHOCK ABSORBER @\$116.60	NOT NECESSARY	233.20	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	528.00	-
1	FRONT GRILLE ASSY	CRACKED	2,400.00	1,550.00
1	FRONT GRILLE LOGO	NECESSARY	60.50	60.50
1	FRONT GRILLE TOP GARNISH	CRACKED	231.00	231.00
2	FRONT GRILLE SIDE GARNISH @\$258.50	CRACKED	517.00	517.00
1	SET FRONT GRILLE CLIPS	NECESSARY	70.00	20.00
2	FRONT HEAD LAMP @\$3245.00	CRACKED	6,490.00	5,700.00
2	FRONT HEAD LAMP TOP RUBBER @\$95.70	NOT NECESSARY	191.40	-
1	FRONT BUMPER	DEFORMED	1,700.00	1,450.00
2	FRONT BUMPER SIDE HOLDER @\$68.20	NECESSARY	136.40	136.40
6	FRONT BUMPER SENSOR @\$308.00	DAMAGED (2 PCS ONLY)	1,848.00	520.00
1	FRONT BUMPER CENTRE LOWER GRILLE	CRACKED	460.00	460.00
1	FRONT BUMPER CENTRE LOWER GRILLE MOULDING	CUT	295.00	295.00
2	FRONT BUMPER FOG LAMP GARNISH @\$145.00	CRACKED	290.00	290.00
1	FRONT BUMPER TOWING HOOK COVER	NOT NECESSARY	68.20	-
1	FRONT BUMPER REINFORCEMENT	BENT	490.00	490.00
1	FRONT BUMPER SPONGE	CRACKED	143.00	143.00
2	FRONT BUMPER LOWER SIDE GARNISH @\$77.00	DEFORMED	154.00	154.00
2	FRONT BUMPER LOWER SIDE GARNISH TOP HOLDER @\$40.00	NOT NECESSARY	80.00	-
1	FRONT BUMPER INNER TOP GARNISH	CRACKED	203.50	203.50

Report Ref No. CS/FCI18012999/Arbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER INNER LOWER GARNISH	CRACKED	104.50	104.50
1	SET FRONT BUMPER CLIPS	NECESSARY	70.00	30.00
2	FRONT FENDER INNER SHIELD @\$375.00	NOT NECESSARY	750.00	-
2	SET FRONT FENDER INNER SHIELD CLIPS @\$65.00	NOT NECESSARY	130.00	-
2	FRONT BUMPER LOWER SIDE MOULDING @\$181.50	DEFORMED	363.00	363.00
2	FRONT RADIATOR SIDE GARNISH @\$93.50	CRACKED	187.00	187.00
1	FRONT RADIATOR CENTRE LOWER COVER	NOT NECESSARY	93.50	-
1	FRONT NUMBER PLATE GARNISH	DEFORMED	176.00	176.00
1	FRONT BONNET CENTRE LOGO	NECESSARY	71.50	71.50
	LESS 10% DISCOUNT		-	-1,510.24
			21,790.70	13,592.16
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	50.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
			100.00	60.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL AIR CON FILL IN GAS.		200.00	120.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,800.00	600.00
	RESPRAY PAINTING.		1,500.00	500.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
			3,650.00	1,220.00
	GRAND TOTAL		25,540.70	14,872.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,900.00

Report Ref No. CS/FCI18012999/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.