

205 Braddell Road S(579701)

	ACCIDENT	REPAIR ESTIMATE	
Our Ref:			
Type of Claim:	TP	Vehicle No.	SLF4864Z
		Make & Model	HONDA VEZEL 1.5X CVT
		Year of Manufacture :	2016
		Chassis No.	RU11117392
Ins Company :A	IG VS FWD	Engine No. :	L15B4037398
Excess :	i	Policy No.	+
Date of Accident :	14.07.2018	Time of Accident :	12:15
Suggested Days of Repair :		In-house Vehicle Assesso	or
Repair Estimate		Case Owner :	WILLIAM
Parts (a) Cost / List Price Items	_\$ -	Signature :	
Plus/Less 20%	\$ -	Contact No Frt Counter Operation	
Total of Cost / List	\$	63837103 – Patrick Tia 63837730 - Brenda Ng	
(b) Nett Price Items	\$	63837466 – Rohani <u>braddell_cr@sparkcarcare.c</u>	<u>om</u>
Less	101100	Workshop Operation	
Total of Nett Item		63837656 - Ngo Toh Wee 63837362 -	
(c) Special Nett Items	\$ -	63838115 - William Wang 63838115 - Andrew Goh	
Total Parts Cost (Appendix A)	\$ -	braddell_operation@sparkcar	care.com
Labour (Appendix B)	\$ 2,710.00		
Total Repair Cost	\$ 2,710.00		
The above total will be subjected i	to 7% G.S.T.		
Name of Surveyor Company			

Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is authorized / is not authorized until further notice. (b) Recommended Days of Repair : ______day(s) (c) Resurvey : Required / Not Required (d) Excess (e) Signature of surveyor Date:

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SLF4864Z	Case Owner	:	WILLIAM
Make & Model	:	HONDA VEZEL 1.5X CVT	Year Manufacture	:	2016
Chassis No	:	RU11117392	Engine No	:	L15B4037398
Sales Order	:		Supplier	:	
Order By	: .		Type of Claim	:	<u>TP</u>

S/No			Cost	List	N. a		· · · · · · · · · · · · · · · · · · ·
5/140	Part Description	QTY	Price	Price	Nett Price	S/N	Disposition By
1	Rear number plate with casing	1		1 1100	rice	S/N	Surveyor
2	Rear number plate lamp LH	1					
3	Rear number plate lamp RH	1					
4	Rear bumper	1					
5	Rear bumper corner LH	1					
6	Rear bumper corner RH	1					
7	Rear bumper reflector LH	1					
8	Rear bumper reflector RH	1					
9	Rear bumper retainer LH	1					
10	Rear bumper retainer RH	1					
11	Rear bumper clips	1					
12	Taillamp LH	1					
13	Taillamp RH	1					
14	Tailgate	1					
15	Tailgate badge logo	1					
16	Tailgate emblem - VEZEL	1					
17	Tailgate emblem - HYBRID	1					
18	Tailgate weatherstrip	1					
19	Tailgate lamp LH	1					
20	Tailgate lamp RH	1					
21	Tailgate upper lock	1					
22	Tailgate outer garnish	1					
23	Tailgate inner lower trimboard	1					
24	Tailgate opening switch	1					
25 F	Rear windscreen moulding	1					
26 F	Rear windscreen sealant	1					
27 F	Rear windscreen inner seal	1					
28 F	Rear end panel	1					
29 F	Rear end panel inner garnish	1					
30 0		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

16/07/2018 5:14 PM

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

<u>Labour</u>

Vehicle No.	:	SLF4864Z	Case Owner	:	WILLIAM
Make & Model	:	HONDA VEZEL 1.5X CVT	Year of Manufacture	*	2016

	Labour		
S/No	Labour Description	Esimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	¢100.00	
•	To remeve teal windsdreen to facilitate repairs.	\$120.00	
2	To transfer tailgate parts and fittings to new tailgate.	\$120.00	
3	To remove/refit boot compartment trims and garnish to	\$180.00	
	facilitate repairs.		
4	Labour charges to repair and panel beat rear end panel,	\$960.00	
	bootfloor/spare tyre panel and replace damaged parts (PER DAY \$240)		
5	To replace reverse sensor set and check wiring functions.	\$180.00	
	To putty, apply primer & spray-paint the rear bumper, tailgate, rear end panel, bootfloor/spare panel and affected areas. (PER PANEL \$250)	\$1,000.00	
7	To apply rust-proofing on repaired/replaced panels.	\$150.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.