

ASS. REC. BY: Matheus REP: CS3/UOI18010693/Uda-1  
 Full Name: Jenny Lew of UOI Date/Time: 18072018  
 Estimated Cost: Bill to  
 OD ☒ / WS / TP RES / OD RES / EVA / INV / MY / CS  
 To Inspect Vehicle No: SJE-6437P Insured: YM 1857Z  
 at Workshop no: Alpha Car Services Tel: 6509 8258  
 of BLK C, Kaki Bukit Ave 6 # 01-59  
 Policy No: M11004171807 Claim No: Excess:  
 Sum Insured: 8/06/2018  
 Make of Veh: D.O.A.  
 (Client's Record)

CA / REV / REP. / REV 24 HRS wp  
 Date/Time: 10:06am 12/6/18 Person Contacted: Cui ling H.O.D. Endorsement: Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJE 6437P - X</u>
	<u>YM 1857Z - X</u>
<u>12/6/18</u>	<u>Dismantled</u>

27/7/18 Summit d/s \$4200 S dy.  
Red: \$2400, 36%.

RECEIVED 27 JUL 2018



**Catherine Chong (LKK Auto)**

---

**From:** LEW JENNY <jennylew@uoi.com.sg>  
**Sent:** Wednesday, 18 July, 2018 9:28 AM  
**To:** assignments; SUR  
**Subject:** M11D04171807 / Accident involving YM1857Z & SJE6437P on 08.06.2018  
**Attachments:** 3837\_001.zip

WITHOUT PREJUDICE

Dear Catherine,

Vehicle was conducted on Pre-Repair Survey on 12.6.2018.  
Please assist with the paper re.

Thank You.

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

**UOB EMAIL DISCLAIMER**

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Leng Services Pte Ltd  
C/o: Alpha Car Services Pte Ltd  
No.1 Kaki Bukit Ave 6 #01-59  
Kaki Bukit AutoBay, Singapore 417883

Date : 25 June 2018  
Our ref : ACS/06/1802/TP

Accident Date : 08 June 2018  
Inspection Date : 11 June 2018  
Repairer Name : Alpha Car Services Pte Ltd  
No.1 Kaki Bukit Ave 6 #01-59  
Kaki Bukit AutoBay, Singapore 417883

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SJE 6437 P  
Make / Model : Toyota Vios E  
Chassis No : MR053HY9305058114  
Engine No : 1NZX730211

Year / Capacity : 2008 / 1497 cc  
Colour : Silver  
Mileage : 96523

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Yokohama	195/55 R15	5 mm	Sport
Front Offside	: Yokohama	195/55 R15	5 mm	Sport
Rear Nearside	: Yokohama	195/55 R15	5 mm	Sport
Rear Offside	: Yokohama	195/55 R15	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 84 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 6,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

# L APPRAISER PTE LTD

Vehicle Registration No: SJE 6437 P

Our Ref No: ACS/06/1802/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear boot lid <i>DD/Bent</i>	Damage	\$ 581.70	\$ 581.70 /
1	Rear boot inner lock <i>twl</i>	Damage	\$ 145.60	\$ 145.60 /
1	Rear boot outer moulding <i>Bent/cr</i>	Necessary	\$ 139.40	\$ 139.40 /
1	Rear boot weatherstrip <i>twl</i>	Necessary	\$ 181.20	\$ 181.20 /
1	Rear boot "VIOS" emblem <i>ru</i>	Necessary	\$ 42.90	\$ 42.90 /
1	Rear boot "E" emblem <i>ru</i>	Necessary	\$ 38.90	\$ 38.90 /
2	Rear taillamps <i>one/alc</i>	Damage	\$ 671.80	\$ 671.80 X
1	Rear end panel <i>DD</i>	Damage	\$ 775.90	\$ 775.90 /
1	Rear end panel inner garnish <i>twl</i>	Damage	\$ 211.10	\$ 211.10 /
1	Rear bumper <i>ee</i>	Damage	\$ 485.50	\$ 485.50 /
2	Rear bumper side brackets <i>3rd</i>	Damage	\$ 191.80	\$ 191.80 /
2	Rear bumper side retainers <i>3rd</i>	Necessary	\$ 97.30	\$ 97.30 /
1	Rear bumper splash shield <i>1st</i>	Damage	\$ 125.00	\$ 125.00 /
1	Rear floor panel <i>n</i>	Repair	\$ 782.90	X
1	Rear floor board <i>to, n</i>	Damage	\$ 183.60	\$ 183.60 /
2	Rear floor side boards <i>to, n/alc</i>	Damage	\$ 210.20	\$ 210.20 X
1	Rear exhaust silencer <i>n</i>	Damage	\$ 654.20	\$ 654.20 X
2	Rear exhaust mountings <i>17</i>	Necessary	\$ 97.00	\$ 97.00 X
1	Rear exhaust chrome tail pipe <i>17</i>	Damage	\$ 108.05	\$ 108.05 X
1	Rear fender <i>n</i>	Repair	\$ 872.90	X
1	Rear fender inner air vent <i>17</i>	Damage	\$ 89.60	\$ 89.60 X

		\$ 6,686.55	\$ 5,030.75
	Less 25%	\$ 1,671.64	\$ 1,257.69
<b>Total Cost - List Items</b>		<b>\$ 5,014.91</b>	<b>\$ 3,773.06</b>

3191.1  
2399.52

## SPECIAL NETT ITEMS

1	Rear boot "SPORT" emblem <i>ru</i>	Necessary	\$ 50.00	\$ 50.00 /
1	Rear bumper clip (1 set) <i>ru</i>	Necessary	\$ 45.00	\$ 45.00 /
1	Rear bumper lower spoiler (1set) <i>ee</i>	Damage	\$ 950.00	\$ 950.00 600
1	Rear reverse sensor (1 set) <i>shhh</i>	Damage	\$ 350.00	\$ 350.00 200
<b>Total Cost - Special Nett items</b>			<b>\$ 1,395.00</b>	<b>\$ 1,395.00</b>

Total cost of parts

\$ 6,409.91	\$ 5,168.06
-------------	-------------

# SCL APPRAISER PTE LTD

Vehicle Registration No: SJE 6437 P

Our Ref No: ACS/06/1802/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,409.91	\$ 5,168.06

## LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 20
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 80
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 50
4	To transfer boot lid mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00 60
5	To remove, refit and replace exhaust silencer and mountings.	\$ 150.00	\$ 120.00 60
6	To apply undercoating on repaired and replaced panel.	\$ 150.00	\$ 90.00 60
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00	\$ 1,250.00 600
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00	\$ 1,320.00 1080

## **GRAND TOTAL**

<b>\$ 10,239.91</b>	<b>\$ 8,258.06</b>
---------------------	--------------------

# C L APPRAISER PTE LTD

Vehicle Registration No: SJE 6437 P

Our Ref No: ACS/06/1802/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

## Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD



Cheong K. H  
Automotive Appraiser



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD		Ref : CS3/UOI18010693/Urbs2-1		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 06-08-2018		
		Code : UOI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YM 1857Z	Veh. Inspected	SJE 6437P	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D04171807	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	18/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053HY9305058114	Colour	GREY	
Odometer	96523	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/55R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/55R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/55R15	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/06/2018	Inspection Date	12/06/2018	
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 6437P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	DENTED / BENT	581.70	581.70
1	REAR BOOT INNER LOCK	TWISTED	145.60	145.60
1	REAR BOOT OUTER MOULDING	BENT / CRACKED	139.40	139.40
1	REAR BOOT WEATHERSTRIP	TWISTED	181.20	181.20
1	REAR BOOT "VIOS" EMBLEM	NECESSARY	42.90	42.90
1	REAR BOOT "E" EMBLEM	NECESSARY	38.90	38.90
2	REAR TAILLAMPS (CRACKED)	NOT CONSISTENT WITH THE IMPACT	671.80	-
1	REAR END PANEL	DENTED	775.90	775.90
1	REAR END PANEL INNER GARNISH	TWISTED	211.10	211.10
1	REAR BUMPER	DEFORMED	485.50	485.50
2	REAR BUMPER SIDE BRACKETS	BENT	191.80	191.80
2	REAR BUMPER SIDE RETAINERS	BENT	97.30	97.30
1	REAR BUMPER SPLASH SHIELD	NECESSARY	125.00	125.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	782.90	-
1	REAR FLOOR BOARD	TORN	183.60	183.60
2	REAR FLOOR SIDE BOARDS (TORN)	NOT CONSISTENT WITH THE IMPACT	210.20	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	654.20	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	97.00	-
1	REAR EXHAUST CHROME TAIL PIPE	NOT NECESSARY	108.05	-
1	REAR FENDER	TO REPAIR SEE LABOUR	872.90	-
1	REAR FENDER INNER AIR VENT	NOT NECESSARY	89.60	-
	LESS 25% DISCOUNT		-1,671.64	-799.97
			5,014.91	2,399.93
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BOOT "SPORT" EMBLEM (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR BUMPER LOWER SPOILER (SN)	DEFORMED	950.00	600.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			1,395.00	895.00

Report Ref No. CS3/UOI18010693/Urbs2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	50.00
	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR.		80.00	60.00
	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.		150.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		150.00	60.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR EXHAUST SILENCER AND REAR FENDER.		1,600.00	600.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	1,080.00
			3,830.00	2,010.00
	<b>GRAND TOTAL</b>		<b>10,239.91</b>	<b>5,304.93</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,200.00</b>

Report Ref No. CS3/UOI18010693/Urb2-1

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.