



Your Ref : VC011671

Date: 02nd March 2020

Our Ref : CC4/QBE18013029/Gha3s2

M/s QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay #29-10

South Tower

Singapore 048583

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJH 4720T
ACCIDENT ON 16/07/2018 INSURED VEHICLE SLR 3569U**

Instruction was received to inspect the vehicle Reg. No. SJH 4720T. The inspection was conducted on 18/07/2018 at the premises of Torque 5 Pte Ltd, 8 Kaki Bukit Avenue 4 #01-50 Premier @ Kaki Bukit Singapore 415875.

The following vehicle information was recorded:

Registration Number	: SJH 4720T
Make/Model	: Honda Airwave
Year of Registration	: 2008
Body Colour	: Black
Chassis Number	: GJ11210933
Engine Capacity	: 1496 cc
Speedometer Reading	: 254348 km

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	8,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	7,147.00) (est)
Nett Liability	S\$	853.00

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.