

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16018676/UUA3S2-1
Date: 03/10/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SKT883H	Insured Vehicle No :	SHB9689Z
Date of Loss:	25/09/2016	Nature of Claim:	TP
		Claim No:	C0402365

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT883H	Engine No:	L15B31000329
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Chassis No:	JHMGK5850FX202465
Reg. Date:	06/04/2015 (Man. Year: 2015)	Odometer:	32874 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,834.64	1,897.44	937.20	33.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	1,400.00	490.00	25.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,724.64	3,297.44	1,427.20	30.21
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	4,724.64	2,600.00	2,124.64	44.97
+ GST 7.00/7.00% (S\$)	330.72	182.00	148.72	44.97
Nett Amount (S\$)	5,055.36	2,782.00	2,273.36	44.97
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
(S\$)		3,082.00		
Liabe Amount (50.00%) (S\$)		1,541.00		

INSPECTION

Date of Assignment:	04/10/2016	
Date Inspected:	10/10/2016	Inspected At: Progressive Auto Pte Ltd (Kaki Bukit) No.1 Kaki Bukit Ave 6 AutoBay #02-48/50 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** THIN THIN HLAING*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2018)
Parts:	144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT883H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Repair	727.50 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER (CONSISTENT)	Bent	21.00 FL	*21.00 FL
3	1		*FRONT FENDER RH (CONSISTENT)	Dented	419.20 FL	*419.20 FL
4	1		*FRONT FENDER DUST COVER RH (CONSISTENT)	Distorted	78.00 FL	*78.00 FL
5	8		*FRONT FENDER DUST COVER CLIP (CONSISTENT)	Necessary	60.00 FL	*60.00 FL
6	1		*FRONT DOOR RH (CONSISTENT)	Bent / Dented	687.00 FL	*687.00 FL
7	1		*FRONT HINGES RH (TOP) (CONSISTENT)	Not Necessary	38.00 FL	*- FL
8	1		*FRONT HINGES RH (TOP) (CONSISTENT)	Not Necessary	38.00 FL	*- FL
9	1		*LOWER SIDE SKIRT RH (CONSISTENT)	Deformed / Warped	465.20 FL	*465.20 FL
10	1		*FRONT HUB BEARING (CONSISTENT)	Damaged	180.20 FL	*180.20 FL
11	1		*FRONT DOOR GLASS FRAME STICKER (CONSISTENT)	Necessary	86.20 FL	*86.20 FL
12	1		*FRONT RIM (CONSISTENT)	Dented	594.40 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,394.70	2,296.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	560.06	399.36
Total Parts (\$\$)	2,834.64	1,897.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	800.00	450.00
2	CHECK WIRING.	New	60.00	20.00
3	TO REMOVE & REFIT DOOR ACCESSORIES.	New	80.00	60.00
4	ALIGNMENT ADJUSTMENT.	New	50.00	50.00
5	TO REMOVE & REPLACE UNDER CARRIAGE.	New	150.00	100.00
6	SPRAY PAINTING.	New	750.00	720.00
Gross Labour Cost (\$\$)			1,890.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >