

RECEIVED 02 JAN 2013

10/08/11/13) wef

A&S REC. BY:

REF: ICS

ASSIGNMENT

From:

Date:

23/07/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKC 5169T

at Workshop m/s

Performance

of

303 Alexander Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

2pm @ owner waiting
Inthiran

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

- %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKC 5169T

Yr Regn:

20/11/84

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X5

c.c

2977

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

57848

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA EV420002492004

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/50R19

R:

7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/07/18 21:45

Survey held at

PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P: H.20.40 (RED: 7.4.61.95 25%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-a

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796501 (AfterSales)
64796524 (Motorrad)



GST REG. NO : M2 - 0020081 - X

17 JUL 2018

E S T I M A T E

Estimate No. : b1 47708
Date Estimated : 17/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

CCIC Singapore Pte Ltd
81 SCIENCE PARK DRIVE
#03-02 Chadwick, The
Singapore 118257

- ACCOUNT -

144674

ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower
Singapore 038987

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC5169T	L492294	02/09/2011	X5 xDRIVE35i	0

DESCRIPTION

To replace rear bumper, tailgate lower, attachments,
repair tailgate upper and repair tail panel.

2975 ✓
~~2585~~ VALUE
4,250.00

Painting rear bumper, tailgate lower, tailgate upper and
tail panel.

3345 ✓ 3,717.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

451 ✓ 531.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 ✓ 271.00

To transfer lock mechanism from old to new bootlid
including conduct checks on new bootlid central locking
system for proper function.

451 ✓ 531.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 ✓ 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ✓ 177.00

To carry out body cavity preservation.
(Per panel).

100 ✓ 118.00

Sundries.

all ✓ 150.00

Total Labour 1: 9,922.00

DESCRIPTION

Installation
TAILPIPE TIP CHROME
REAR SILENCER WITH EXHAUST FLAP
BOOTLID BOTTOM

QTY	PRIC
1	135.15
1	110.95
1	2,326.40
1	1,649.35

un X 135.15
at ✓ 110.95
bt ✓ 2,326.40
bt ✓ 1,649.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401859M GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

286, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47708
Date Estimated : 17/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC5169T	L492294	02/09/2011	X5 xDRIVE35i	0

DESCRIPTION	QTY	PRIC	VALUE
Set of mount	1	31.00	31.00
EXPANDING NUT	4	1.10	4.40
RR BUMPER CARRIER	1	707.10	707.10
REAR BUMPER LH CORNER MOUNT	1	72.85	72.85
REAR BUMPER RH CORNER MOUNT	1	72.85	72.85
LH SUPPORT	1	26.15	26.15
RH SUPPORT	1	26.15	26.15
MOUNT BUMPER RR CENTRE	1	198.30	198.30
MOUNT BUMPER RR LH	1	142.55	142.55
MOUNT BUMPER RR RH	1	142.55	142.55
TRIM PANEL BUMPER RR BOTTOM (PDC)	1	260.90	260.90
RR BUMPER PRIMED	1	1,508.35	1,508.35
UNDERRIDE PROTECTION (ALU MATT/AHV)	1	146.70	146.70
TRIM PANEL BUMPER BOTTOM LH (SCHWAR	1	118.35	118.35
TRIM PANEL BUMPER BOTTOM RH (SCHWAR	1	118.35	118.35
SET TRIMS TOWING LUG PRIMED	1	41.80	41.80
EMBLEM GROMMET	2	0.80	1.60
EMBLEM REAR	1	69.50	69.50
EMBLEM X5 ADHERED	1	62.55	62.55
HEAT INSULATOR REAR SILENCER	1	263.25	263.25
EXPANDING RIVET	4	1.35	5.40
RR BUMPER LH REFLECTOR	1	34.15	34.15
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BUMPER PDC SENSOR - ELBOW	4	236.85	947.40

Total Parts : 9,244.25

Claims GD / 3rd Party / Uninsured losses / Direct Settlement

Rage No. Claim No.

Date/Time 23/7/18 1445 Excess \$

Surveyor's Name Sign

Surveyor's Tel. 97495449 Authorised Yes/No

Awarded Date 'wp' Time

REQUIREMENTS PHOTO BY SURVEYOR (Y/N) On/Off

Surveyor's Email tanphir@khantoon

Time 7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1	:	9,922.00
Parts	:	9,244.25

Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,341.64

Grand Total : 20,507.89

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47708
Date Estimated : 17/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
CCIC Singapore Pte Ltd
B1 SCIENCE PARK DRIVE
#03-02 Chadwick, The

- ACCOUNT - 144674
ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower C
Singapore 038987

Singapore 118257

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKC5169T	L492294	02/09/2011	X5 xDRIVE35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH *	66.80	1.00		66.80 <i>bide</i>
# WIRING SET PDC REAR *	97.95	1.00		97.95 <i>cup</i>
# PIN TERMINAL 6 POL Z CODE *	5.55	1.00		5.55 <i>de</i>

Total Labour :	
Total Parts :	170.30
Total Labour & Parts :	170.30

Performance Motors Limited

A member of the Sirel Darty Group
Co. Reg. No. 197401509W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47708
Date Estimated : 17/07/2018
Prepared By : Inthiran A/L Thurassamy

Page No. :

REPAIR FOR -
CCIC Singapore Pte Ltd
81 SCIENCE PARK DRIVE
#03-02 Chadwick, The

- ACCOUNT - 144674
ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower C
Singapore 038987

Singapore 118257

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKC5169T	L492294	02/09/2011	X5 xDRIVE35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid bottom include making good the upper tailgate, tail end panel and knocking out dents caused by the accident	2975.00		2,975.00	
To spray paint rear bumper, tailgate lower, tailgate upper and tail end panel	3345.00		3,345.00	
* To replace rear exhaust silencer including alignment system and conduct checks for leak.	451.00		451.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	
* To diagnose and replace rear PDC wiring set include include conducting checks for proper function	226.00		226.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH *	66.80	1.00		66.80
TAILPIPE TIP CHROME	110.95	1.00		110.95
REAR SILENCER WITH EXHAUST FLAP	2,326.40	1.00		2,326.40
BOOTLID BOTTOM	1,649.35	1.00		1,649.35
REAR BUMPER LH CORNER MOUNT	73.85	1.00		73.85
MOUNT BUMPER RR CENTRE	198.30	1.00		198.30
TRIM PANEL BUMPER RR BOTTOM (PDC)	260.90	1.00		260.90
RR BUMPER PRIMED	1,508.35	1.00		1,508.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-J



FINAL REPORT

UNDERRIDE PROTECTION (ALU MATT/AHV)	146.70	1.00	146.70
EMBLEM GROMMET	0.80	2.00	1.60
EMBLEM REAR	69.50	1.00	69.50
EMBLEM X5 ADHERED	62.55	1.00	62.55
EXPANDING RIVET	1.35	10.00	13.50
# WIRING SET PDC REAR *	97.95	1.00	97.95
# PIN TERMINAL 6 POL Z CODE *	5.55	1.00	5.55
RR BUMPER LH REFLECTOR	34.15	1.00	34.15

SUPPLEMENTARY ITEMS

Total Labour :	8,078.00
Total Parts :	6,626.40
Total Labour & Parts :	14,704.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	14,704.40
GST @7%:	1,029.31
Grand Total :	15,733.71

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CC4/ICS18013043/eb3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 18-07-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 3049X	Veh. Inspected	SKC 5169T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/07/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2019 11:47 Edit Reg		17 Jul 2018 00:00 Edit Adj Rpt	S\$14,704.40 Edit Estimates	S\$14,704.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SIAM ENG TECK , ID: S1663399B, Email: www.abcd@com.sg								
Main Claimant:	CCIC SINGAPORE PTE LTD , Co. Reg. No.: 19895118G								
Vehicle Reg. No.:	SKC5169T	Date of Loss:	14/07/2018 19:00 - :59 [82 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / DMPC1800286H	Policy/Cover Note No.:	MPC18A00197200						
Vehicle Reg. No. (Insured):	SJX3049X	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC5169T (DMPC1800286H)
[SJX3049X]
TP
CCIC SINGAPORE PTE LTD
Jul 14 2018 7:00PM
[SIAK ENG TECK]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	24/07/18 14:51	Adjuster Immediate Advice							1 Load HTM			
									3 per page		☒	
Photos/Images												
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	21/12/18 15:12	Odometer Reading							1 Load JPG		☒	
2	21/12/18 15:12	Chassis Number							1 Load JPG		☒	
3	21/12/18 15:12	General View							1 Load JPG		☒	
4	21/12/18 15:12	General View							1 Load JPG		☒	
5	21/12/18 15:12	General View							1 Load JPG		☒	
6	21/12/18 15:12	General View							1 Load JPG		☒	
7	21/12/18 15:12	General View							1 Load JPG		☒	
8	21/12/18 15:12	General View							1 Load JPG		☒	
9	21/12/18 15:12	General View							1 Load JPG		☒	
10	21/12/18 15:12	General View							1 Load JPG		☒	
11	21/12/18 15:12	General View							1 Load JPG		☒	
12	21/12/18 15:12	General View							1 Load JPG		☒	
13	21/12/18 15:12	General View							1 Load JPG		☒	
14	21/12/18 15:12	General View							1 Load JPG		☒	
15	21/12/18 15:12	General View							1 Load JPG		☒	
16	21/12/18 15:12	General View							1 Load JPG		☒	
17	21/12/18 15:12	General View							1 Load JPG		☒	
18	21/12/18 15:12	General View							1 Load JPG		☒	
19	21/12/18 15:12	General View							1 Load JPG		☒	
20	21/12/18 15:12	General View							1 Load JPG		☒	
21	21/12/18 15:12	General View							1 Load JPG		☒	
22	21/12/18 15:12	General View							1 Load JPG		☒	
23	21/12/18 15:12	General View							1 Load JPG		☒	
24	21/12/18 15:12	General View							1 Load JPG		☒	
25	21/12/18 15:12	General View							1 Load JPG		☒	
26	21/12/18 15:12	General View							1 Load JPG		☒	
27	21/12/18 15:12	General View							1 Load JPG		☒	
28	21/12/18 15:12	General View							1 Load JPG		☒	
29	21/12/18 15:12	General View							1 Load JPG		☒	
30	21/12/18 15:12	General View							1 Load JPG		☒	
31	21/12/18 15:12	General View							1 Load JPG		☒	
32	21/12/18 15:12	General View							1 Load JPG		☒	
33	21/12/18 15:12	General View							1 Load JPG		☒	
34	21/12/18 15:12	General View							1 Load JPG			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	21/12/18 15:12	General View	 Load JPG	☒
36	21/12/18 15:12	General View	 Load JPG	☒
37	21/12/18 15:12	General View	 Load JPG	☒
38	21/12/18 15:12	General View	 Load JPG	☒
39	21/12/18 15:12	General View	 Load JPG	☒
40	21/12/18 15:12	General View	 Load JPG	☒
41	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
42	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
43	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
44	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
45	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
46	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
47	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
48	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
49	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
50	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
51	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
52	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
53	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
54	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
55	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
56	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
57	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
58	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
59	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
60	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
61	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
62	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
63	21/12/18 15:12	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 14:37	EMAIL FROM ICS DD 17072018	 Load PDF	
2	18/07/18 14:37	TP ESTIMATE	 Load TIF	
3	18/07/18 14:37	TP GIA REPORT	 Load PDF	
4	19/07/18 10:06	OI GIA REPORT	 Load PDF	
5	24/07/18 17:07	TP ESTIMATE- MARKED	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/ICS18013043/T1EB3Q2

Date: 08/01/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC18A00197200

Claimant Vehicle No: SKC5169T Insured Vehicle No: SJX3049X

Date of Loss: 14/07/2018 Nature of Claim: TP Claim No: DMPC1800286H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC5169T

Make & Model: BMW X5, 3.0 (A)

Reg. Date: 02/09/2011 (Man. Year: 2011)

Colour: White

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: HIDDEN

Chassis No: WBAZV42000L492294

Odometer: 57848 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R19

Front Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Tyre Size: 255/50 R19

Rear Left Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,573.65	6,776.40	2,797.25	29.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,772.00	7,928.00	1,844.00	18.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,345.65	14,704.40	4,641.25	23.99
+ GST 7.00/7.00% (S\$)	1,354.20	1,029.31	324.89	23.99
Nett Amount (S\$)	20,699.85	15,733.71	4,966.14	23.99
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/07/2018

Date Inspected: 22/07/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts:	M1-SUV	BMW X5 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC5169T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*INSTALLATION	Not Necessary	135.15 FS	*- FS
3	1		*TAILPIPE TIP CHROME	Cut	110.95 FS	*110.95 FS
4	1		*REAR SILENCER WITH EXHAUST FLAP	Bent	2,326.40 FS	*2,326.40 FS
5	1		*BOOTLID BOTTOM	Bent	1,649.35 FS	*1,649.35 FS
6	1		*SET OF MOUNT	Not Necessary	31.00 FS	*- FS
7	4		*EXPANDING NUT	Not Necessary	4.40 FS	*- FS
8	1		*RR BUMPER CARRIER	Not Necessary	707.10 FS	*- FS
9	1		*REAR BUMPER LH CORNER MOUNT	Necessary	73.85 FS	*73.85 FS
10	1		*REAR BUMPER RH CORNER MOUNT	Not Necessary	72.85 FS	*- FS
11	1		*LH SUPPORT	Not Necessary	26.15 FS	*- FS
12	1		*RH SUPPORT	Not Necessary	26.15 FS	*- FS
13	1		*MOUNT BUMPER RR CENTRE	Deformed	198.30 FS	*198.30 FS
14	1		*MOUNT BUMPER RR LH	Not Necessary	142.55 FS	*- FS
15	1		*MOUNT BUMPER RR RH	Not Necessary	142.55 FS	*- FS
16	1		*TRIM PANEL BUMPER RR BOTTOM (PDC)	Cut	260.90 FS	*260.90 FS
17	1		*RR BUMPER PRIMED	Deformed	1,508.35 FS	*1,508.35 FS
18	1		*UNDERRIDE PROTECTION (ALU MATT/AHV)	Deformed	146.70 FS	*146.70 FS
19	1		*TRIM PANEL BUMPER BOTTOM LH (SCHWAR)	Not Necessary	118.35 FS	*- FS
20	1		*TRIM PANEL BUMPER BOTTOM RH (SCHWAR)	Not Necessary	118.35 FS	*- FS
21	1		*SET TRIMS TOWING LUG PRIMED	Not Necessary	41.80 FS	*- FS
22	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
23	1		*EMBLEM REAR	Necessary	69.50 FS	*69.50 FS
24	1		*EMBLEM X5 ADHERED	Necessary	62.55 FS	*62.55 FS
25	1		*HEAT INSULATOR REAR SILENCER	Not Necessary	263.25 FS	*- FS
26	10		*EXPANDING RIVET	Necessary	13.50 FS	*13.50 FS
27	1		*RR BUMPER LH REFLECTOR	Cut	34.15 FS	*34.15 FS
28	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
29	4		*BUMPER PDC SENSOR -ELBOW	Not Necessary	947.40 FS	*- FS
30	1		*CLAMPING BUSH	Deformed	66.80 FS	*66.80 FS
31	1		*WIRING SET PDC REAR	Cut	97.95 FS	*97.95 FS
32	1		*PIN TERMINAL 6 POL Z CODE	Deformed	5.55 FS	*5.55 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,573.65	6,776.40
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,TAILGATE LOWER ,ATTACHMENTS,REPAIR TAILGATE UPPER AND REPAIR TAIL PANEL	New	4,250.00	2,975.00
2	PAINTING REAR BUMPER ,TAILGATE LOWER ,TAILGATE UPPER AND TAIL PANEL	New	3,717.00	3,345.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
6	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	226.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			9,772.00	7,928.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >