

ASS. REC. BY:

REF:

CS/FCI18013067/Dg,d3n2

Special Instruction:

Survivor:

CWS

Bryen

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

18/7/18 @ 12:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SHD 6532B

Insured:

SHC 7843C

at Workshop m/s

Chunni Motor

Tel:

64836016

of

Amk Autopoint #01-05/06

Policy No:

9/18088937MF8H

Claim No:

D1800 5492MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:37pm @ 18/7/18

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 6532B - NS/INC17019450/K/qbn2 DOA: 10/10/2017

SHC 7843C - CS/FCI14020459/Rqbk3 DOA: 28/10/2014

14/7/18 @ 2:20pm raised to SITHARA by email.

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHD 6532 B Yr Regn: 2014 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 448575 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDDU361373

G/No: KMHLB41UMEU059831

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: - 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 17/07/2018 D.O.I. 18/07/2018

Survey held at Churni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Report SHC 7843C

23/08/18 for the 4/5 17,800/- with 10 days of rep
check 6/7/20, 24/10/18

RECEIVED 31 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 31/8/18

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B. (\$) : 17800

Survey Fee:

Transportation

S + RS: 51

Photos: 550

Others: 3/1/18

TOTAL: 558

170 + 210

50

50 + 50

208

138

14X15: 210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013067/Dqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7843C	Veh. Inspected	SHD 6532B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005492MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	18/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/07/2018	Inspection Date	18/07/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005492MFSH
Our Ref: CS/FCI18013067/Dqd3

Date: 24 July 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 6532B.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/07/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>25,070.30</u>
Revised Estimate Amount	: S\$ <u>22,271.66</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the front & rear portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	17-07-2018	Our Ref No.	D18005492MFSH
Accident Date	17-07-2018	Claim Type.	Third Party
Insured Vehicle	SHC7843C	Third Party Vehicle.	SHD6532B
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06		
Contact Person.	LYNN OR IRENE		
Contact No.	64836016/ 0	Fax No.	65426039
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242469)



PRI Documents



Close



PRI Header Details

Claim No	D18005492MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 Mobile: 0 , Phone: 64836016 , Fax: 65426039 EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7843C	TP Vehicle No	SHD6532B
PRI Recieved Date	17-07-2018 09:25:20 PM	Surveyor Appointed Date	18-07-2018 12:12:37 PM	Surveyor Accept Date	18-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 24 July 2018 2:20 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005492MFSH/1
Attachments: CSFCI18013067Dqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SHD 6532B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Wednesday, 18 July 2018 12:39 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18005492MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 18 July 2018 12:13 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005492MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

CHUNNI MOTOR WORK PTE LTD

To Survey by LCC

REPAIR ESTIMATE*

VEHICLE NO : SHD 6532B

DATE : 17.07.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Dented</i>			\$ 1,526.00	✓
	Radiator Grille <i>broken</i>			\$ 294.35	✓
	Radiator Grille H Emblem <i>new</i>			\$ 113.65	✓
	Front Bumper Cover <i>torn</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>torn</i>			\$ 142.20	✓
	Front Bumper Reinforcement <i>? Dented</i>			\$ 526.10	✓
	Front Bumper Grille (LH/RH) <i>side mounting crack</i>	\$	285.50	\$ 571.00	✓
	Front Bumper Centre Grille <i>deformed</i>			\$ 178.60	✓
	Front Bumper Lip <i>new</i>			\$ 62.50	X
	Front Bumper Bracket Top (LH/RH) <i>svc</i>	\$	22.40	\$ 44.80	X
	Front Bumper Centre Grille Top Garnish (LH/RH) <i>deformed</i>	\$	80.00	\$ 160.00	✓
	Front Bumper Retainer Mounting (LH/RH) <i>svc</i>	\$	9.20	\$ 18.40	X
	Headlamp Support Top Cover <i>crack</i>			\$ 398.00	✓
	Headlamp Support Panel Assy (LH/RH) <i>? broken</i>	\$	1,067.50	\$ 2,135.00	✓
	Headlamp (LH/RH) <i>crack mounting</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>? bt</i>			\$ 850.20	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>? crack</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>new</i>	\$	6.50	\$ 13.00	X
	Radiator Hose Upper <i>new</i>			\$ 47.40	X
	Radiator Hose Lower <i>new</i>			\$ 47.40	X
	Horn Unit (LH/RH) <i>new Dam</i>	\$	86.75	\$ 173.50	X
	Horn Wire <i>new torn</i>			\$ 156.50	X
	Front Fender Retainer (LH/RH) <i>svc</i>	\$	9.20	\$ 18.40	X
	Aircon Condenser <i>? bt</i>			\$ 1,137.35	✓
	Inter Cooler <i>? bt</i>			\$ 921.90	✓
	SUB TOTAL			\$ 14,157.40	
	LESS 20%			\$ 2,831.48	
	DISCOUNTED TOTAL			\$ 11,325.92	
	Labour Charge				
	Panel Beating			\$ 200.00	600/-
	Spray Painting Charge			\$ 600.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 80.00	30/-
	Towing Charge			\$ 50.00	new
	Remove/Refix Aircon & Refill Gas			\$ 80.00	80/-
	TOTAL LABOUR			\$ 1,760.00	

12838.00

10270.40

1240/-

VEHICLE NO : SHD 6532B

DATE : 17.07.2018

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>Distorted</i>			\$ 1,681.40	✓
	Boot Lid Rubber <i>deformed</i>			\$ 115.80	✓
	Boot Lid Lock Upper <i>1st</i>			\$ 137.90	✓
	Boot Lid Lock Lower <i>2nd</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>new</i>			\$ 27.20	✓
	Boot Lid CRDI Plate <i>new</i>			\$ 41.00	✓
	Boot Lid Lamp (LH/RH) <i>change</i>		\$ 556.80	\$ 1,113.60	✓
	Boot Lid Trimboard <i>torn</i>			\$ 172.70	✓
	Boot Lid Trimboard Clips (10pcs) <i>new</i>			\$ 11.00	✓
	Bootlid Moulding <i>svc</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>new</i>			\$ 41.00	X
	Bootlid Lower Garnish <i>svc</i>			\$ 398.00	X
	Rear Bumper <i>distorted</i>			\$ 603.60	✓
	Rear Bumper Reinforcement <i>new</i>			\$ 504.35	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>1st</i>		\$ 180.00	\$ 360.00	✓
	Rear Bumper Clip 10 pcs <i>new</i>			\$ 22.00	✓
	Rear Bumper Sponge <i>new</i>			\$ 143.40	✓
	Rear Bumper Under Cover <i>distorted</i>			\$ 225.00	✓
	Rear Bumper Reflector Lamp (LH/RH) <i>svc</i>		\$ 32.00	\$ 64.00	X
	Tail Lamp (LH/RH) <i>change</i>		\$ 565.60	\$ 1,131.20	✓
	Rear Panel <i>Distorted</i>			\$ 592.30	✓
	Rear Panel Garnish <i>deformed</i>			\$ 57.70	✓
	Rear Panel Inner Panel <i>new</i>			\$ 495.50	✓
	Exhaust Pipe Insulator <i>new</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>new</i>		\$ 954.00	\$ 1,908.00	✓
	Exhaust Pipe Hanger <i>new</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>new</i>			\$ 1,150.30	X
			10493.95		
			8395.16		
	SUB TOTAL			\$ 11,347.85	
	LESS 20%			\$ 2,269.57	
	DISCOUNTED TOTAL			\$ 9,078.28	
	Boot Lid Comfort Logo & Tel No. Sticker <i>new</i>			\$ 30.00	Nett ✓
	Rear Bumper Reverse Sensor <i>new</i>			\$ 135.70	Nett ✓
	Rear Bumper Rubber Mat <i>new</i>			\$ 50.00	Nett ✓
			215.70		
				\$ 215.70	
	Labour Charge			\$ 1,000.00	600/-
	Panel Beating <i>supp</i>			\$ 600.00	500/-
	Spray Painting Charge			\$ 50.00	30/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	30/-
			1160/-		
			12038.26		
			990.40		
			13028.66		
	18/07/2018 @ 1515hr			\$ 1,700.00	
	Not Antenna 10				
	45mm 8 days.				
	TOTAL LABOUR			\$ 24,079.90	
	ESTIMATE TOTAL				
					24216.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for confirmation
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

18/07/2018 @ 1515hr

Not Antenna 10

45mm 8 days.

T

21281.26

990.40

22271.66

41517800/-

TOTAL LABOUR

ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

24079.30

1/1 Bee Koll

FAX : 6542 6039

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013067/Dqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-09-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7843C	Veh. Inspected	SHD 6532B	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005492MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU059831	Colour	BLUE	
Odometer	448575	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2018	Inspection Date	18/07/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6532B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	1,526.00	1,526.00
1	RADIATOR GRILLE	BROKEN	294.35	294.35
1	RADIATOR GRILLE H EMBLEM	NECESSARY	113.65	113.65
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	142.20	142.20
1	FRONT BUMPER REINFORCEMENT	DENTED	526.10	526.10
2	FRONT BUMPER GRILLE (LH/RH) @\$285.50	MOUNTING CRACKED	571.00	571.00
1	FRONT BUMPER CENTRE GRILLE	DEFORMED	178.60	178.60
1	FRONT BUMPER LIP	NOT NECESSARY	62.50	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER CENTRE GRILLE TOP GARNISH (LH/RH) @\$80.00	DEFORMED	160.00	160.00
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$9.20	SERVICEABLE	18.40	-
1	HEADLAMP SUPPORT TOP COVER	CRACKED	398.00	398.00
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,067.50	1,067.50
2	HEADLAMP (LH/RH) @\$1388.00	MOUNTING CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	850.20	850.20
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	CRACKED	792.95	792.95
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
1	RADIATOR HOSE UPPER	NOT NECESSARY	47.40	-
1	RADIATOR HOSE LOWER	NOT NECESSARY	47.40	-
2	HORN UNIT (LH/RH) @\$86.75	DAMAGED	173.50	173.50
1	HORN WIRE	TORN	156.50	156.50
2	FRONT FENDER RETAINER (LH/RH) @\$9.20	SERVICEABLE	18.40	-
1	AIRCON CONDENSER	BENT	1,137.35	1,137.35
1	INTER COOLER	BENT	921.90	921.90
1	BOOT LID	DENTED	1,681.40	1,681.40
1	BOOT LID RUBBER	DEFORMED	115.80	115.80
1	BOOT LID LOCK UPPER	BENT	137.90	137.90

Report Ref No. CS/FCI18013067/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID "H" EMBLEM	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE	NECESSARY	41.00	41.00
2	BOOT LID LAMP (LH/RH) @\$556.80	CRACKED	1,113.60	1,113.60
1	BOOT LID TRIMBOARD	TORN	172.70	172.70
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	SERVICEABLE	41.00	-
1	BOOTLID LOWER GARNISH	SERVICEABLE	398.00	-
1	REAR BUMPER	DISTORTED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	CRACKED	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	BENT	360.00	360.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	DISTORTED	225.00	225.00
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$32.00	SERVICEABLE	64.00	-
2	TAIL LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	REAR PANEL	DENTED	592.30	592.30
1	REAR PANEL GARNISH	DEFORMED	57.70	57.70
1	REAR PANEL INNER PANEL	DENTED	495.50	495.50
2	EXHAUST PIPE INSULATOT @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$954.00	BENT	1,908.00	1,908.00
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	BENT	1,150.30	1,150.30
2	FRONT FENDER (LH/RH) @\$619.00 (ADDITIONAL)	DENTED	1,238.00	1,238.00
	LESS 20% DISCOUNT		-5,135.15	-4,913.99
			20,540.60	19,655.96
	SPECIAL NETT ITEMS			
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70

Report Ref No. CS/FCI18013067/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			215.70	215.70
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER.	NOT NECESSARY	1,900.00	1,200.00
	SPRAY PAINTING CHARGE.		1,200.00	1,000.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		130.00	60.00
	TOWING CHARGE.		50.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		80.00	80.00
			3,460.00	2,400.00
GRAND TOTAL			24,216.30	22,271.66
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				17,800.00

Report Ref No. CS/FCI18013067/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.