

REF: CS3/SPF18013068/0462

ASSIGNMENT (Office)

From (Person): Maimy Abdul Rahman of SPT Date/Time: 13072018

Estimated Cost: SLN 7760C Insured: Qx 555M

To Inspect Vehicle No. MS. Panel Beating Tel: 9735 1788

at Workshop m/s 2 Kaki Bukit Ave 2

of MS. Panel Beating Claim No. AEAD/105/009/2018/087

Policy No. 18072018 Excess: 14072018

Sum Insured: 19.07.2018 D.O.A. 14072018

Make of Veh. (Client's Record) Pauline H.O.D. Endorsement: Vehicle IN OUT

CA / REV / REP. / REV 24 HRS 'top' Person Contacted: Pauline

Date/Time: 18/7/2018 3:40pm

Date/Time	Action/Instruction (X) Estimate	Ref
	SLN 7760C - NM / T1183/12700/24	Ref: 14072018
	Qx 555M - CS3/SPF1706246/T1183-1	Ref: 14072018
20/7/18	Submitted	DAR?
	Submit DAR Report Lump Sum 147501	Exp 2

15K-18K

re-open case include upper range

\$15K-18K

Celine 14/3/19

20/3/19 re-open ref only * 1st DOR 6/9/18 * ↓

(08/11/13) wef

ASS. REC. BY: marcusREF: SPF**ASSIGNMENT**

From: _____ Date: 19/7/18

Estimated Cost: _____

ON TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 7760C

at Workshop m/s M-S. Panel Beating

of 2 kaki Bkt Ave 2 #02-17

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 7760C Yr Regn: 2017, May 17

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CPMake: Toyota CHR c.c. 1797Colour: maroon A/C: Insured / Std / NI / NASp. Reading: 34355 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 21X10 2012634Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mm

D.O.A. _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 19/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No settlement.16 - 20Range 22K - 24KRepair days 14

RECEIVED 28 AUG 2018

TOTUMlin 21/8/18

Date/Time, File Pass to?

☐

: Preli. Report

☒

: Final Report

1) 2018 Typist

Date/Time, File Return to?

2) _____

Days Of Repair: 14Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 280

Transportation

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 147501-)

Condition (1) OK (2) Item (3) Discontinued (4) Cracked (5) Cut (6) Scratched (7) Defective (8) Stuffed (9) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn (14) Incomplete (15) Not Working

MOTOR CAR (RH)

ACTION (A/C) (1) Replace (✓) (2) Repair (X) (3) Check (C) (4) Not Contained (NC)

Vehicle No: SLN 7760 C

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
994070		Roof Top Panel			
994098		Roof Top Moulding			
994085		Roof Top Air-bag			
994084		Roof Top Air-bag Sensor			
994083		Roof Top Air-bag Control Unit			
992958		Rear Bumper			
992976		Rear Bumper Bracket			
993068		Rear Bumper Side Retainer			
993045		Rear Bumper Reinforcement			
993077		Rear Bumper Sponge			
993040		Rear Bumper Protector			
993026		Rear Bumper Moulding			
993023		Rear Bumper Lower Spoiler			
995116		Rear RH Taillamp			
993456		Rear RH Fender			
993450		Rear RH Fender Protector			
990247		Sticker			
Labour					
1. check electric functions					
2. To remove and install all affected parts					
3. To provide materials, spray paint the affected parts					
4. To provide undercoating and rust proofing of affected parts					

No of Items:

Assessor:

Parts & Labour 22339.65

Repair days 14



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18013068/Uths2

ACCIDENT CLAIM SECTION (SINGAPORE POLICE Date: 04-09-2018

FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD

POLICE ACADEMY SINGAPORE 298333

ATTN: ABDUL RAHMAN

Code: SPF



1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 555M	Veh. Inspected	SLN 7760C
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/087	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CHR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102012634	Colour	MAROON
Odometer	34359 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R17	BRIDGESTONE	7 mm
L/H Front Tyre	215/60R17	BRIDGESTONE	7 mm
R/H Rear Tyre	215/60R17	BRIDGESTONE	7 mm
L/H Rear Tyre	215/60R17	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2018	Inspect Date / Time	19/07/2018 (10:51 AM)
Survey held at	M.S. PANEL BEATING WORKSHOP 2 KAKI BUKIT AVENUE 2 #02-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$18,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------