

20/07/2001

ASS. REC. BY:

REF: CS/FCI18013087/R1+d3 n2

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Eileen lee

of FCI

Date/Time: 18/7/18 @ 2:31pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 3251L

Insured: SHD 6828Z

at Workshop m/s: Volkswagen

Tel: 9386 7833

at 1 Kempong Ampet off Macpherson Road

Policy No:

Claim No: D18005466MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/07/2018

19/07/18 @ 3:30pm under writing

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:48pm @ 18/7/18

Person Contacted:

Chunmeire

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 3251L - X
	SHD 6828Z - NS INC 17024550 / Kl vbn 2 DOA: 26/12/2017
	Part by Part \$7392.63 (Red. 9016.60 : 54%)

(08/11/13) wef

ASS. REC. BY: Pasul

REF:

FCI

Y002F

ASSIGNMENT

From: _____ Date: 26/07/18

Estimated Cost: _____

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLM 3251Lat Workshop m/s volkswagenof 1 Kampong Ampat off Macpherson Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS cup

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLM 3251L Yr Regn: 2017 / mngzType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen JETTA 1.4 TSI c.c. 1390Colour: grey A/C: Insured / Std / NI / NASp. Reading: 12396 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WUW 222162GM 01662Gen. Cond: Good ☒ Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 14/07/18D.O.I. 26/07/18Survey held at Volkswagen KA AmpatDes. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 AUG 2018

Date/Time, File Pass to?

1) 618 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

6x15=90

170+90

50

50

66

426

Report Format: TPLump Sum / I.B.: (\$ 7392.63)

MOTOR SURVEY ASSIGNMENT

Date	17-07-2018	Our Ref No. D18005466MFSH
Accident Date	14-07-2018	Claim Type. Third Party
Insured Vehicle	SHD6828Z	Third Party Vehicle. SLM3251L
Survey Location	1 KAMPONG AMPAT	
Contact Person.	TANG SHU SHI	
Contact No.	69223502/ 93867833	Fax No. 62858620
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VOLKSWAGEN CENTRE SINGAPORE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242436)



PRI Documents



Close



PRI Header Details

Claim No	D18005466MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VOLKSWA
Workshop Name	VOLKSWAGEN CENTRE SINGAPORE (Contact Person : TANG SHU SHI)	Survey Location & Contact Details	1 KAMPONG AMPAT Mobile: 93867833 , Phone: 69223502 , Fax: 62858621 EmailId: SHUSHI.TANG@VW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6828Z	TP Vehicle No	SLM3251L
PRI Recieved Date	17-07-2018 03:55:27 PM	Surveyor Appointed Date	18-07-2018 02:30:12 PM	Surveyor Accept Date	18-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013087/R1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6828Z	Veh. Inspected	SLM 3251L
Policy No.		Coverage (\$)	0.00
Claim No.	D180054666MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/07/2018	Inspection Date	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7964002F



Name

JIA WEI

贾巍

Race

CHINESE

Date of birth

20-11-1979

Country/Place of birth

CHINA

Sex


F

S7964002F



3629250

NRIC No. S7964002F



Date of issue

29-07-2016

Address

APT BLK 331 SEMBAWANG CLOSE
#10-359
SINGAPORE 750331

REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number S7964002F

Name

JIA WEI

Birth Date 20 Nov 1979

Issue Date 25 Jul 2014




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars= $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 25 Jul 2014

NP 42BA





PDI TUAS

PDI TUAS

JIA WEI
331 SEMBAWANG CLOSE
#10-359
Singapore, 750331
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV036919
Quote No. SER/QUO/1801143
QuoteDate 16/07/18
Salesperson Jacqueline Yong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	10,459	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLM3251L	WVWZZZ16ZGM016662	27/03/17	Jacqueline Yong
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F83897	1634G7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	6	UNIT		1680 5,040.00
P B&P MACP PAINT	SPRAY PAINT	6	UNIT		1600 4,800.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		84 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
	Sum Labor				10,680.00
P 5C6805706J	FRT BUMPER CENTRE BRACKET	1	Pieces		100.89
P 5C6807109C	REINFORCEMENT	1	Pieces		573.69
P 5C6807183A	FRT BUMPER SIDE BRACKET LH	1	Pieces		32.26
P 5C6807184A	FRT BUMPER SIDE BRACKET RH	1	Pieces		31.11
P 5C6807217Q GRU	FRT BUMPER	1	Pieces		852.00
P 5C6807248G	FOAM RH	1	Pieces		103.80
P 5C6807248H	FOAM LH	1	Pieces		103.80
P 5C6807251F	FOAM	1	Pieces		164.13
P 5C6807305	REAR REINFORCEMENT	1	Pieces		514.20
P 5C6807375	REAR BUMPER SIDE BRACKET L	1	Pieces		96.13
P 5C6807376	REAR BUMPER SIDE BRACKET	1	Pieces		96.13
P 5C6807421H GRU	COVER	1	Pieces		1,452.28
P 5C6807433J	Predecessor 5C6807417J GRU- SPOILER	1	Pieces		476.26
P 5C6807863B	REAR CENTRE BRACKET	1	Pieces		111.91
P 5C6853630F ULM	VW SIGN	1	Pieces		125.10
P 5C6853671P 9B9	FRT CENTRE GRILLE	1	Pieces		200.82
	Use Predecessor 5C6853671H 9B-				

Sum carried forward

15,714.51

Payments to: - BBN: - Acc.-No.:



PDI TUAS

PDI TUAS

JIA WEI
331 SEMBAWANG CLOSE
#10-359
Singapore, 750331
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV036919
Quote No. SER/QUO/1801143
QuoteDate 16/07/18
Salesperson Jacqueline Yong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	10,459	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLM3251L	WVWZZZ16ZGM016662	27/03/17	Jacqueline Yong
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F83897	1634G7

Continued

15,714.51

P 5C6853675APGQF	NAME PLATE TSI	1 Pieces
P 5C6853687 739	NAME PLATE JETTA	1 Pieces
P 5C6919491D	SENSOR BRACKET	1 Pieces
P 5C6919491E	SENSOR BRACKET	2 Pieces
P 5C6919492D	SENSOR BRACKET	1 Pieces
P 5C6919493A	SENSOR BRACKET	1 Pieces
P 5C6919494A	SENSOR BRACKET	1 Pieces
P 5Q0919275B GRU	SENSOR	1 Pieces
	Use Predecessor 5Q0919275 GR	
P D 180KU2A1	2KADHESIVE	1 Pieces
P D 822150A1	BONDAGENT	1 Pieces
	Sum Item	

an } X	57.33
	76.11
	27.45
	54.90
nan }	27.45
	53.52
	53.52
su x	166.62
	103.66
	74.16
	5,729.23

16468.72

Sum Labor	10,680.00
Sum Item	5,729.23

Total SGD	16,409.23
7% GST	1,148.65
Total SGD Incl. GST	17,557.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: **Explanations**

Date: P = Proportionately Charged

Payment Terms

No Credit

Payments to:

- BBN: - Acc.-No...

Param
Hp 90010068

4 days

26/07/18

P1530

Resurvey before paint

27/7/18

Service Order Confirmation

SERVICE ORDER NO: 18IP1920

CUSTOMER NO.: CV036919

CUSTOMER NAME: JIA WEI

TELEPHONE NO.:

ADDRESS: 331 SEMBAWANG CLOSE #10-359

Singapore

VEH No.: SLM3251L

Order Date: 26/07/18

Reg Date: 27/03/17

KM: 12,538

VIN NO.: WVVZZZ16ZGM016662

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		280
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
3	B&P MACP LABOUR LABOUR FRT & REAR	2	UNIT	840		1,680
4	B&P MACP PAINT SPRAY PAINT FRT & REAR	2	UNIT	800		1,600
5	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		80
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
8	5C6807217Q GRU FRT BUMPER	1	PCS	852.00		852.00
9	5C6919494A SENSOR BRACKET	1	PCS	53.52		53.52
10	5C6919493A SENSOR BRACKET	1	PCS	53.52		53.52
11	D 180KU2A1 2KADHESIVE	1	PCS	103.66		103.66
12	D 822150A1 BONDAGENT	1	PCS	74.16		74.16
13	5C6807421H GRU REAR BUMPER	1	PCS	1,452.28		1,452.28
14	5C6919491D SENSOR BRACKET	1	PCS	27.45		27.45
15	5C6919491E SENSOR BRACKET	2	PCS	27.45		54.90
16	5C6919492D SENSOR BRACKET	1	PCS	27.45		27.45
17	5C6807109C FRT REINFORCEMENT	1	PCS	573.69		573.69

Remarks : MS FIRST CAPITAL DIRECT SETTLEMENT

DOA:14/07/2018

TP VEHICLE: SHD6828Z

SURVEY BY: RASUL (LKK)

Service Order Confirmation

SERVICE ORDER NO: 18IP1920

CUSTOMER NO.: CV036919

CUSTOMER NAME: JIA WEI

TELEPHONE NO.:

ADDRESS: 331 SEMBAWANG CLOSE #10-359

Singapore

VEH No.: SLM3251L

Order Date: 26/07/18

Reg Date: 27/03/17 KM: 12,538

VIN NO.: WVVZZZ16ZGM016662 ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	7,392.63
-------	----------

GST AMOUNT	517.48
------------	--------

TOTAL AMOUNT	7,910.11
--------------	----------

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013087/R1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6828Z	Veh. Inspected	SLM 3251L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005466MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA 1.4 TSI	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WWWZZZ16ZGM016662	Colour	GREY	
Odometer	12396	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/07/2018	Inspection Date	26/07/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 3251L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER CENTRE BRACKET (SN)	SERVICEABLE	100.89	-
1	REINFORCEMENT (SN)	SERVICEABLE	573.69	-
1	FRT BUMPER SIDE BRACKET LH (SN)	SERVICEABLE	32.26	-
1	FRT BUMPER SIDE BRACKET RH (SN)	SERVICEABLE	31.11	-
1	FRT BUMPER (SN)	DEFORMED	852.00	852.00
1	FOAM RH (SN)	SERVICEABLE	103.80	-
1	FOAM LH (SN)	SERVICEABLE	103.80	-
1	FOAM (SN)	SERVICEABLE	164.13	-
1	REAR REINFORCEMENT (SN)	CRACKED	573.69	573.69
1	REAR BUMPER SIDE BRACKET L (SN)	SERVICEABLE	96.13	-
1	REAR BUMPER SIDE BRACKET (SN)	SERVICEABLE	96.13	-
1	COVER (SN)	DEFORMED	1,452.28	1,452.28
1	SPOILER (SN)	SERVICEABLE	476.26	-
1	REAR CENTRE BRACKET (SN)	SERVICEABLE	111.91	-
1	VW SIGN (SN)	NOT NECESSARY	125.10	-
1	FRT CENTRE GRILLE (SN)	SERVICEABLE	200.82	-
1	NAME PLATE TSI (SN)	NOT NECESSARY	57.33	-
1	NAME PLATE JETTA (SN)	NOT NECESSARY	76.11	-
1	SENSOR BRACKET (SN)	NECESSARY	27.45	27.45
2	SENSOR BRACKET (SN)	NECESSARY	54.90	54.90
1	SENSOR BRACKET (SN)	NECESSARY	27.45	27.45
1	SENSOR BRACKET (SN)	NECESSARY	53.52	53.52
1	SENSOR BRACKET (SN)	NECESSARY	53.52	53.52
1	SENSOR (SN)	SERVICEABLE	166.62	-
1	2KADHESIVE (SN)	NECESSARY	103.66	103.66
1	BONDAGENT (SN)	NECESSARY	74.16	74.16
1	B&P NUMBER PLATE (SN)	BENT	80.00	80.00
			5,868.72	3,352.63
LABOUR				
LABOUR.			5,040.00	1,680.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		4,800.00	1,600.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
	CHECK WIRE HARNESS, ECU, S.		280.00	280.00
			10,600.00	4,040.00
GRAND TOTAL			16,468.72	7,392.63
RECOMMENDED COST OF REPAIRS				7,392.63

Report Ref No. CS/FCI18013087/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.