

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : GX 4292 MMake & Model : KIA PREGIOYear of Manufacture : Chassis No. : KNCTB241247151986Engine No. : Policy No. : Time of Accident : Unit : Vehicle Type : Suggested Days of Repair : 10Contractor : INDECO**Repair Estimates**Parts (a) Cost / List Price Items \$ 7,145.20Plus/Less 10% \$ 714.52Total of Cost / List \$ 6,430.68(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 710.00Total Parts Cost (Appendix A) \$ 7,140.68Labour (Appendix B) \$ 4,850.00Total Repair Cost \$ 11,990.68*The above total will be subjected to 7% G.S.T.*Name of Surveyor : Company : Survey conducted on :  at **Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair :  day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor :  Date:



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736

ANSON 85114276 FAX:62860908

### ESTIMATED REPAIR COST DETAILS

Vehicle No : GX 4292 M Case Owner : 0

Make & Model : KIA PREGIO Year Manufacture : 0

Chassis No : KNCTB241247151986 Engine No : TP

Date & Time : \_\_\_\_\_ Supplier : JAE KOW

Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description         | QTY | Cost Price | List Price  | Nett Price | S/N       |
|------|--------------------------|-----|------------|-------------|------------|-----------|
| 1    | REAR WINDSCREEN MOULDING | 1   |            | \$ 758.00   |            |           |
| 2    | SEALANT                  | 1   |            |             |            | \$ 40.00  |
| 3    | LOGO KIA                 | 1   |            | \$ 42.00    |            |           |
| 4    | 70 KM STICKER            | 1   |            |             |            | \$ 20.00  |
| 5    | GREEN SPOT STICKER       | 1   |            |             |            | \$ 20.00  |
| 6    | INDECO STICKER           | 1   |            |             |            | \$ 80.00  |
| 7    | COMPANY ART WORK STICKER | 1   |            |             |            | \$ 150.00 |
| 8    | TAILGATE                 | 1   |            | \$ 1,356.00 |            |           |
| 9    | TAILGATE DAMPER RH       | 1   |            | \$ 122.00   |            |           |
| 10   | TAILGATE DAMPER LH       | 1   |            | \$ 122.00   |            |           |
| 11   | TAILGATE LOCK            | 1   |            | \$ 121.00   |            |           |
| 12   | TAILGATE LOCK CATCH      | 1   |            | \$ 29.00    |            |           |
| 13   | TAILGATE LAMP LH         | 1   |            | \$ 144.00   |            |           |
| 14   | TAILGATE LAMP RH         | 1   |            | \$ 144.00   |            |           |
| 15   | REAR NUMBER PLATE        | 1   |            |             |            | \$ 45.00  |
| 16   | REAR BUMPER              | 1   |            | \$ 595.00   |            |           |
| 17   | REAR BUMPER RETAINER RH  | 1   |            | \$ 56.10    |            |           |
| 18   | REAR BUMPER RETAINER LH  | 1   |            | \$ 56.10    |            |           |
| 19   | REAR BUMPER REINFORCMENT | 1   |            | \$ 350.00   |            |           |
| 20   | REVERSE SENSOR           | 1   |            |             |            | \$ 250.00 |
| 21   | REAR END PANEL           | 1   |            | \$ 762.00   |            |           |
| 22   | BONNET                   | 1   |            | \$ 285.00   |            |           |
| 23   | BONNET HINGE RH          | 1   |            | \$ 39.00    |            |           |
| 24   | BONNET HINGE LH          | 1   |            | \$ 39.00    |            |           |
| 25   | BONNET LOCK              | 1   |            | \$ 54.00    |            |           |
| 26   | BONNET LOCK CATCH        | 1   |            | \$ 36.00    |            |           |
| 27   | FRT GRILLE               | 1   |            | \$ 338.00   |            |           |
| 28   | HEADLAMP RH              | 1   |            | \$ 314.00   |            |           |
| 29   | SIDE RH                  | 1   |            | \$ 91.00    |            |           |
| 30   | HEADLAMP LH              | 1   |            | \$ 314.00   |            |           |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**

\$ - \$ 6,167.20 \$ - \$ 605.00



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No : GX 4292 M

Case Owner : 0

Make & Model : KIA PREGIO

Year Manufacture : 0

Chassis No : KNCTB241247151986

Engine No : TP

Date & Time : 0

Supplier : JAE KOW

Order By : 0

Type of Claim : TP

| S/No | Part Description          | QTY | Cost Price | List Price | Nett Price | S/N      |
|------|---------------------------|-----|------------|------------|------------|----------|
| 31   | SIDE LAMP LH              | 1   |            | \$ 91.00   |            |          |
| 32   | FRT BUMPER                | 1   |            | \$ 365.00  |            |          |
| 33   | FRT BUMPER RETAINER RH    | 1   |            | \$ 17.00   |            |          |
| 34   | FRT BUMPER RETAINER LH    | 1   |            | \$ 17.00   |            |          |
| 35   | FRT BUMPER REINFORCEMENT  | 1   |            | \$ 488.00  |            |          |
| 36   | FRT NUMBER PLATE          | 1   |            |            |            | \$ 45.00 |
| 37   | RHF DOOR ROC STICKER      | 1   |            |            |            | \$ 20.00 |
| 38   | LHF DOOR ROC STICKER      | 1   |            |            |            | \$ 20.00 |
| 39   | BONNET GREEN SPOT STICKER | 1   |            |            |            | \$ 20.00 |
| 40   | 0                         | 1   |            |            |            |          |
| 41   | 0                         | 1   |            |            |            |          |
| 42   | 0                         | 1   |            |            |            |          |
| 43   | 0                         | 1   |            |            |            |          |
| 44   | 0                         | 1   |            |            |            |          |
| 45   | 0                         | 1   |            |            |            |          |
| 46   | 0                         | 1   |            |            |            |          |
| 47   | 0                         | 1   |            |            |            |          |
| 48   | 0                         | 1   |            |            |            |          |
| 49   | 0                         | 1   |            |            |            |          |
| 50   | 0                         | 1   |            |            |            |          |
| 51   | 0                         | 1   |            |            |            |          |
| 52   | 0                         | 1   |            |            |            |          |
| 53   | 0                         | 1   |            |            |            |          |
| 54   | 0                         | 1   |            |            |            |          |
| 55   | 0                         | 1   |            |            |            |          |
| 56   | 0                         | 1   |            |            |            |          |
| 57   | 0                         | 1   |            |            |            |          |
| 58   | 0                         | 1   |            |            |            |          |
| 59   | 0                         | 1   |            |            |            |          |
| 60   | 0                         | 1   |            |            |            |          |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL** \$ - \$ 978.00 \$ - \$ 105.00



No . 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES &amp; EQUIPMENT DIVISION

Tel: (65) 382 2736 FAX: (65) 6382 2817

## Labour

Vehicle No. : **GX 4292 M**

Case Owner 0

Make & Model : KIA PREGIO

Year of Manufacture : 0

| S/No  | Labour Description                                                                                                                                             | Estimated Price | Adjusted Price |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|----------------|
| 1     | TO PANEL BEAT,REPAIR,REPLACE ON TAILGATE,REAR END PANEL,<br>REAR BUMPER,RHR BODY PANEL,BONNET,FRT BUMPER, RHF<br>DOOR,LHF DOOR,REINFORCEMENT AND AFFECTED AREA | \$2,000.00      |                |
| 2     | TO PUTTY AND RESPRAY ON TAILGATE,REAR END PANEL,<br>REAR BUMPER,RHR BODY PANEL,BONNET,FRT BUMPER, RHF<br>DOOR,LHF DOOR,REINFORCEMENT AND AFFECTED AREA         | \$2,200.00      |                |
| 3     | TO INSTALL REVERSE SENSOR                                                                                                                                      | \$200.00        |                |
| 4     | TO APPLY TUFF KOTE                                                                                                                                             | \$100.00        |                |
| 5     | TO REMOVE AND REFIX REAR WINSCREEN                                                                                                                             | \$150.00        |                |
| 6     | TO REMOVE AND REFIX REAR UPHOISTERY TO ASSIST WORK                                                                                                             | \$200.00        |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
|       |                                                                                                                                                                |                 |                |
| TOTAL |                                                                                                                                                                | \$4,850.00      |                |

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*