

ASS. REC. BY

REF

CS/FCI18013095/Dcd3ⁿ²

Special Instruction:

Surveyor

CWS

Bryon
Scherer

ASSIGNMENT (Office)

FCI

Date/Time 18/7/18 @ 1pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 6677A

Insured:

SHA 1239Y

at Workshop m/s

Karz Work Solutions

Tel:

6844 6938

of

53 ubi Ave 1 #01-23

Policy No:

Claim No:

D18005474 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

14/07/2018

CA / REV / REP. / REV 24 HRS

CDS

19/07/2018

H.O.D. Endorsement:

Date/Time:

2:36pm @ 18/7/18

Person Contacted:

Danah

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLV 6677A - NA/MSG18012870/h4	DOA: 14/7/18
	SHA 1239Y - NA/MSG18012870/h4	DOA: 14/7/18

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: SLV 6677 A Yr Regn: Nov 2017
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Volkswagen Golf c.c. 1197Colour: Blue A/C Insured / Std / NI / NASp. Reading: 10826 T/Radio: Insured / Std / NI / NAEng/No: CYV515035C/No: WVWZZZAUZH121951Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R18R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Goodyear

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 14/07/2018 D.O.I. 18/07/2018Survey held at Kery Work Pay-ubiDes. of Damages: Frt Good / Rear Good / O/S / N/S / U/C / Rooftop orFront & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
First Capital SHA1239X

02/01/19 Jinnah 2/S 600/- with 4 days of work (Red. 14,422.60, 69%)

RECEIVED 2 JAN 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

) S + RS. SI

) Photo

) Others

OSP3/1/19

TOTAL

Report Format: TP
 Lump Sum / I.B.F. (\$ 6200/-)

10x15= 150

170+150

50

50+50

116

586



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005474MFSH
Our Ref: CS/FCI18013095/Dcd3

Date: 02 January 2019

The Motor Claims Department
MS First Capital Insurance Limited

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 6677A


We thank you for the instruction on 18/07/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/07/2018 at the premises of M/s Karz Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 20,622.60
Revised Estimate Amount (Lump Sum)	: S\$ 6,200.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages Consistent

Yours faithfully

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	17-07-2018	Our Ref No. D18005474MFSH
Accident Date	14-07-2018	Claim Type. Third Party
Insured Vehicle	SHA1239Y	Third Party Vehicle. SLV6677A
Survey Location	53 UBI AVENUE 1 #01-23 PAYA UBI INDUSTRIAL PARK	
Contact Person.	DARREN NG	
Contact No.	68445938/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO EST. PROVIDED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KARZ WORK SOLUTIONS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242446)



PRI Documents



Close



PRI Header Details

Claim No	D18005474MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & KARZ WO RUI ROY]
Workshop Name	KARZ WORK SOLUTIONS (Contact Person : DARREN NG)	Survey Location & Contact Details	53 UBI AVENUE 1 #01-23 PAYA UBI INDUSTRIAL PARK Mobile: 0 , Phone: 68445938 , Fax: 68442474 EmailId: KARZWORKS.SG@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM PROVIDED)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1239Y	TP Vehicle No	SLV6677A
PRI Recieved Date	17-07-2018 04:47:27 PM	Surveyor Appointed Date	18-07-2018 12:59:14 PM	Surveyor Accept Date	18-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4382Z
Vehicle Details	
Vehicle No.:	SLV6677A
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.2 TSI AT 5G12BZ
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CYV515035
Chassis No.:	WVWZZZAUZHW121951
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,773.00
Original Registration Date:	29 Nov 2017
First Registration Date:	29 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,773.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2027
PARF Rebate Amount:	\$4,329.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$41,669.00
Total Rebate Amount:	\$45,998.00

The information contained herein is correct as at 02 Jan 2019

OK

KARZ WORK PTE LTD

53 Ubi Avenue 1 #01-23 Spore, 408934

Paya Ubi Industrial Park

Tel : 6844 5938 2474

E-mail : karzwork.sg@gmail.com

3RD PARTY CLAIM ESTIMATION

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Vehicle number	SLV6677A
Make / Model	VOLKSWAGEN / GOLF
Chassis number	WVWZZZAUZH121951
Accident date	14 July 2018
Reference	K1807-01

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER distorted / mounting crack	1152.82
2	FRONT BUMPER BRACKET Svc	1276.45 ✓
1	FRONT BUMPER REINFORCEMENT Bt	79.30 X
2	FRONT BUMPER INNER BRACKET Svc	688.50 ✓
1	FRONT BUMPER TOW COVER Htl	172.63 X
1	FRONT BUMPER LOWER GRILLE deformed	55.45 X
1	FRONT BUMPER LOWER GRILLE INNER BRACKET broken	268.95 ✓
2	FRONT FOG LAMP Htl	61.25 ✓
2	FRONT FOG LAMP COVER Htl	886.20 X
1	FRONT GRILLE crack mounting	119.60 X
1	FRONT GRILLE EMBLEM Htl	651.20 ✓
1	SUPPORT PANEL Htl	147.75 ✓
2	FRONT HEADLAMP mounting crack	1048.36 X
2	FRONT HEADLAMP BALLAST Htl	2490.00 4555.50 ✓
2	HEADLAMP LOWER BRACKET Htl	1949.70 X
1	AIRCON CONDENSER Htl	18.40 X
1	AIR INTER COOLER Htl	997.85 X
1	REAR BUMPER distorted	741.50 X
2	REAR BUMPER RETAINER Svc	673.94 ✓
1	REAR BUMPER CENTRE GUIDE deformed	64.00 X
1	REAR BUMPER REINFORCEMENT Dentist	142.30 ✓
1	END PANEL reg	434.20 ✓
1	END PANEL TOP GARNISH Htl	549.57 X
1	SPARE TYRE TOP BOARD Htl	164.40 X
1	REAR EXHAUST SILENCER Htl	162.34 X
1	REAR EXHAUST HEAT SHIELD Htl	1309.00 Y
1	REAR EXHAUST MOUNTING Htl	113.00 X
4	REAR BUMPER SENSOR Down	40.00 X
		276.00 220/- SN
		18147.33
Less 10%		1814.73
Subtotal		16332.60
Balance C/F		16332.60

6710.91

6039.81

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	16332.60
1 SET	FRONT BUMPER CLIP H/c	50.00 45/- 30/-
1	FRONT NUMBER PLATE W/r	80.00 45/-
1 SET	REAR BUMPER CLIP H/c	50.00 30/-
1	JOINT SEALANT H/A	150.00 X
1 BOT	COOLANT H/A	50.00 X
	Subtotal	380.00
	Balance C/F	16712.60
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	16712.60
1	CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND RENEW CONDENSER AND TOP UP GAS	150.00 H/A
3	REMOVE AND RENEW RADIATOR AND TOP UP COOLANT	150.00 H/A
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	300.00 H/A
5	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
6	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 H/A
7	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
8	PANEL BEATING ON AFFECTED AREAS	1400.00 700/-
9	SPRAY PAINTING ON AFFECTED AREAS	1200.00 600/-
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3910.00
	Grand total	20622.60

18/17/2018 @ 1100hrs

H/A Antenna

1/10/18

4 days.

LKK Auto

7854.81

4/5 600/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013095/Dcd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1239Y	Veh. Inspected	SLV 6677A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005474MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WWWZZZAUZHW121951	Colour	BLUE	
Odometer	10826	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	5 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	5 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	5 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/07/2018	Inspection Date	18/07/2018	
Survey held at	KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6677A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED / MOUNTING CRACKED	1,276.45	1,152.82
2	FRONT BUMPER BRACKET	SERVICEABLE	79.30	-
1	FRONT BUMPER REINFORCEMENT	BENT	688.50	688.50
2	FRONT BUMPER INNER BRACKET	SERVICEABLE	172.63	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	55.45	-
1	FRONT BUMPER LOWER GRILLE	DEFORMED	268.95	268.95
1	FRONT BUMPER LOWER GRILLE INNER BRACKET	BROKEN	61.25	61.25
2	FRONT FOG LAMP	NOT NECESSARY	886.20	-
2	FRONT FOG LAMP COVER	NOT NECESSARY	119.60	-
1	FRONT GRILLE	MOUNTING CRACKED	651.20	651.20
1	FRONT GRILLE EMBLEM	NECESSARY	147.75	147.75
1	SUPPORT PANEL	NOT NECESSARY	1,048.36	-
2	FRONT HEADLAMP	MOUNTING CRACKED	4,555.50	2,490.00
2	FRONT HEADLAMP BALLAST	NOT NECESSARY	1,949.70	-
2	HEADLAMP LOWER BRACKET	NOT NECESSARY	18.40	-
1	AIRCON CONDENSER	NOT NECESSARY	997.85	-
1	AIR INTER COOLER	NOT NECESSARY	741.50	-
1	REAR BUMPER	DISTORTED	673.94	673.94
2	REAR BUMPER RETAINER	SERVICEABLE	64.00	-
1	REAR BUMPER CENTRE GUIDE	DEFORMED	142.30	142.30
1	REAR BUMPER REINFORCEMENT	DENTED	434.20	434.20
1	END PANEL	TO REPAIR SEE LABOUR	549.57	-
1	END PANEL TOP GARNISH	NOT NECESSARY	164.40	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	162.34	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,309.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	113.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	40.00	-

Report Ref No. CS/FCI18013095/Dcd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,737.14	-671.09
			15,634.20	6,039.82
4	REAR BUMPER SENSOR (SN)	DAMAGED	776.00	220.00
	LESS 10% DISCOUNT		-77.60	-
			698.40	220.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	FRONT NUMBER PLATE (SN)	BENT	80.00	45.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	JOINT SEALANT (SN)	NOT NECESSARY	150.00	-
1	BOT COOLANT (SN)	NOT NECESSARY	50.00	-
			380.00	105.00
	<u>LABOUR</u>			
	CHECK FRONT,REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND RENEW CONDENSER AND TOP UP GAS.	NOT NECESSARY	150.00	-
	REMOVE AND RENEW RADIATOR AND TOP UP COOLANT.	NOT NECESSARY	150.00	-
	DIAGNOIS CHECK AND CLEAR FAULT CODE.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR EXHAUST ASSY.	NOT NECESSARY	150.00	-
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF END PANEL.		1,400.00	700.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
	-		-	-
	-		-	-
	-		-	-
			3,910.00	1,490.00
	GRAND TOTAL		20,622.60	7,854.82

Report Ref No. CS/FCI18013095/Dcd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,200.00
---	--	--	----------

Report Ref No. CS/FCI18013095/Dcd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.