

22/03/2002

ASS. REC. BY:

REF:

CS/SPF18013115/Grb2

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPF

Date/Time:

18/07/2018 326pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 887E

Insured:

at Workshop m/s

Indeco Engineers

Tel:

of

39 De La Lave 12

Policy No:

Claim No:

HOMSPFETB17300218

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle (IN) / OUT

Date/Time

Action/Instruction (✓) Estimate

26/7

QX 887E - X

Revert thru email

23/8/18

Contact Perry to check whether can submit the report or not

REF: SPF

ASSIGNMENT

From: Date: 19072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: QX 887E

at Workshop m/s

of 39 Defu Lane 12.

Insured: Anson - 85114276

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: QX887E Yr Regn: -

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or police car

Make: Volvo S80 c.c. -

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YVIA547HBD 1168770

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245 / 40 R18

R: 11" Fnt.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental (rear)

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 19-07-18

Survey held at w/s 5:30 pm

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/7 112 Hrs with Anson

Parts : \$17,676.24 (check item : \$13,789.48)

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: -

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18013115/Grb

CONTRACT MANAGEMENT SECTION

(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 19-07-2018



Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 887E
Policy No.	Coverage (\$)	0.00
Claim No. HOMSPFETQ17300218	Excess (\$)	0.00
Assign From PERRY HE	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date	19/07/2018
Survey held at INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	ROOF PANEL	1	BUCKED	\$2,554.70	\$2,554.70	
1.2	ROOF LINING	1	DENTED	\$1,486.80	\$1,486.80	
1.3	REAR WINDSCREEN	1	SMASHED	\$1,144.60	\$1,144.60	
1.4	REAR SPEAKER BOARD	1	CUT	\$503.86	\$503.86	
1.5	REAR SPEAKER BOARD PANEL ASSY	1	UNCONFIRM	\$722.16	\$722.16	
1.6	RHR FENDER	1	DISTORTED	\$1,510.40	\$1,510.40	
1.7	RHR FENDER INNER TRIM	1	UNCONFIRM	\$375.24	\$375.24	
1.8	RHR FENDER INNER SHIELD	1	DEFORMED	\$182.90	\$182.90	
1.9	BOOT SIDE DRAIN RH	1	BENT	\$218.30	\$218.30	
1.10	BOOT SIDE DRAIN LH	1	UNCONFIRM	\$218.30	\$218.30	
1.11	RHR FENDER LOWER PANEL (wheel house)	1	UNCONFIRM	\$1,126.90	\$1,126.90	
1.12	RHR FENDER BRACKET	1	UNCONFIRM	\$47.20	\$47.20	
1.13	BOOT LID	1	BUCKED	\$1,534.00	\$1,534.00	
1.14	BOOT HINGE RH	1	BENT	\$128.62	\$128.62	
1.15	BOOT HINGE LH	1	BENT	\$128.62	\$128.62	
1.16	BOOT DAMPER RH	1	UNCONFIRM	\$96.76	\$96.76	
1.17	BOOT DAMPER LH	1	UNCONFIRM	\$96.76	\$96.76	
1.18	BOOT WEATHER STRIP	1	TWISTED	\$51.92	\$51.92	
1.19	REAR WINDSCREEN MEMBER PANEL	1	UNCONFIRM	\$232.46	\$232.46	
1.20	BOOT LOCK ASSY	1	BENT	\$247.80	\$247.80	
1.21	BOOT LOCK CATCH ASSY	1	NOT NECESSARY	\$9.44		
1.22	BOOT OUTER CHROME MOULDING	1	DEFORMED	\$129.80	\$129.80	
1.23	BOOT OUTER LOCK HANDLE	1	UNCONFIRM	\$226.56	\$226.56	
1.24	KEYLESS ENTRY SENSOR CLIP	1	NECESSARY	\$11.80	\$11.80	
1.25	BOOT KEYLESS ENTRY SENSOR	1	UNCONFIRM	\$68.44	\$68.44	
1.26	BOOT INSULATOR	1	DEFORMED	\$151.04	\$151.04	
1.27	BOOT INSULATOR HANDLE	1	UNCONFIRM	\$10.62	\$10.62	
1.28	TAILAMP RH ASSY	1	CRACKED	\$486.16	\$486.16	
1.29	TAILAMP PANEL RH	1	BUCKED	\$280.84	\$280.84	
1.30	REAR BUMPER	1	CRACKED	\$1,142.24	\$1,142.24	
1.31	REAR BUMPER RETAINER RH	1	NECESSARY	\$41.30	\$41.30	
1.32	REAR BUMPER RETAINER LH	1	NECESSARY	\$41.30	\$41.30	
1.33	REAR BUMPER BRACKET RH	1	UNCONFIRM	\$21.24	\$21.24	
1.34	REAR BUMPER BRACKET LH	1	UNCONFIRM	\$21.24	\$21.24	
1.35	REAR BUMPER LOWER SPOILER	1	UNCONFIRM	\$326.86	\$326.86	
1.36	REAR BUMPER SENSOR	4	UNCONFIRM	\$136.88	\$547.52	
1.37	REAR BUMPER REINFORCEMENT	1	BENT	\$666.70	\$666.70	
1.38	REAR BUMPER SPONGE	1	UNCONFIRM	\$64.90	\$64.90	
1.39	REAR END PANEL	1	BUCKED	\$595.90	\$595.90	
1.40	REAR END PANEL GARNISH	1	UNCONFIRM	\$318.60	\$318.60	
1.41	SPARE TYRE WELL	1	UNCONFIRM	\$761.10	\$761.10	
1.42	REAR BUMPER TOW COVER	1	UNCONFIRM	\$40.12	\$40.12	
1.43	EXHAUST MUFFLER ASY RH	1	DENTED	\$696.20	\$696.20	
1.44	EXHAUST MUFFLER MOUNTING RH	2	BENT	\$23.60	\$47.20	
1.45	REAR EXHAUST MUFFLER HEAT PLATE RH	1	BENT	\$118.00	\$118.00	
1.46	FUEL TANK COVER	1	MISSING	\$108.56	\$108.56	
1.47	FUEL TANK COVER LOCK	1	NECESSARY	\$221.84	\$221.84	
1.48	FUEL TANK NECK	1	CUT	\$234.82	\$234.82	

1.49	FUEL TANK	1	UNCONFIRM	\$1,871.48	\$1,871.48	
1.50	REAR SENSOR WIREHANESS ASSY	1	UNCONFIRM	\$147.50	\$147.50	
1.51	REAR SPEAKER BOARD CLIPS	4	NECESSARY	\$5.31	\$21.24	
1.52	RHR INNER FENDER UPPER REINFORCEMENT	1	UNCONFIRM	\$338.66	\$338.66	
1.53	TAILLAMP LOWER CHROME RH	1	NECESSARY	\$101.48	\$101.48	
1.54	SPARE TYRE BOARD ASSY	1	UNCONFIRM	\$408.28	\$408.28	
1.55	SPARE TYRE BOARD OUTER HANDLE(with 1.54)	1	UNCONFIRM	\$0.00	\$0.00	
1.56	REAR WINDSCREEN INNER GARNISH RH	1	UNCONFIRM	\$120.36	\$120.36	
1.57	RHR DOOR	1	REPAIR	\$1,543.44		
1.58	RHR DOOR RIVET	20	REPAIR	\$2.36		
1.59	RH SIDE SKIRT ASSY	1	DEFORMED	\$558.14	\$558.14	
1.60	RHR DOOR LOCK	1	NOT NECESSARY	\$472.00		
1.61	RHR DOOR LOCK CATCH	1	NOT NECESSARY	\$25.96		
1.62	BOOT LID WEATHER STRIP	1	NOT NECESSARY	\$129.80		
1.63	RHR FENDER AIR VENT	1	DISTORTED	\$69.62	\$69.62	
1.64	RHR CHASSIS ASSY	1	UNCONFIRM	\$2,369.44	\$2,369.44	
1.65	TAILLAMP LOWER BEAM RH	1	MISSING	\$122.72	\$122.72	
1.66	RHR SPORTS RIM 18"	1	CUT	\$1,285.02	\$1,285.02	
1.67	RHR S/ABSORBER	1	UNCONFIRM	\$300.90	\$300.90	
1.68	RHR LOWER ARM	1	UNCONFIRM	\$69.62	\$69.62	
1.69	RHR KNUCKLE ARM	1	UNCONFIRM	\$647.82	\$647.82	
1.70	RHR WHEEL BEARING	1	UNCONFIRM	\$377.60	\$377.60	
1.71	RHR TRAILING ARM	1	UNCONFIRM	\$265.50	\$265.50	
1.72	RHR UPPER ARM	1	UNCONFIRM	\$182.90	\$182.90	
1.73	RHR TYRE 245/40/18	1	TORN	\$430.54	\$430.54	
1.74	SPARE TYRE WELL SIDE PANEL RH	1	UNCONFIRM	\$518.02	\$518.02	
1.75	SPARE TYRE WELL SIDE PANEL LH	1	UNCONFIRM	\$518.02	\$518.02	
1.76	RHR DOOR FRAME PANEL	1	UNCONFIRM	\$562.86	\$562.86	
1.77	INNER TAPE	1	NECESSARY	\$35.40	\$35.40	
1.78	SEALANT	2	NECESSARY	\$23.60	\$47.20	
1.79	REAR NUMBER PLATE	1	BENT	\$35.40	\$35.40	
2	ADDITIONAL SERVICES					
2.10	WHEEL ALIGHMENT	1	NECESSARY	\$70.80	\$70.80	
3	LABOUR					
3.1	TO REPAIR AND RESPRAY LHR FENDER INCLUDING REFLECTIVE STICKER					8
3.2	TO REPAIR AND RESPRAY RHR FENDER INCLUDING REFLECTIVE STICKER					11
3.3	TO REPLACE AND RESPRAY RHR WHEEL HOUSE					12
3.4	TO REPLACE AND RESPRAY LHR WHEEL HOUSE					4
3.5	TO REPAIR, ALIGN, RESPRAY RHR DOOR INCLUDING REFLECTIVE STICKE					7
3.6	TO REPAIR AND RESPRAY REAR SPEAKER PANEL					6
3.7	TO REPLACE AND RESPRAY REAR END PANEL					6
3.8	TO REPLACE AND RESPRAY SPARE TYRE WELL					6
3.9	TO REMOVE AND REFIX UPHOISTERY AND REAR SEAT TO ASSIST WORK					3
3.10	TO REPLACE AND RESPRAY BOOT LID INCLUDING REFLECTIVES STICKER					6
3.11	TO REPLACE REAR WINDSCREEN INCLUDING REFLECTIVE STICKER					6
3.12	TO REPLACE AND RESPRAY REAR BUMPER INCLUDING REFLECTIVE STICKER					8
3.13	TO REMOVE AND REFIX REAR UNDERCARRIAGE TO ASSIST WORK					4
3.14	TO REPLACE, ALIGN, RESPRAY REAR CHASSIS					
3.15	TO APPLY TUFF KOTE					1

3.16	TO PERFORM WHEEL ALIGNMENT				1
3.17	TO REMOVE AND REFIX PETROL TANK TO ASSIST WORK				2
3.18	TO REPLACE WIRE HARNESS, RESET FAULT CODE, CHECK WIRING SYSTEM				2
3.19	TO REPLACE EXHAUST MUFFLER				2
3.20	TO REPLACE AND RESPRAY ROOF PANEL				9
3.21	TO REMOVE AND REFIXBAR LIGHT, CAMERA ROOF LINING				8
		TOTAL PARTS COST			\$31,465.72
		TOTAL MAN-HOUR			112

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	ROOF PANEL	1	BUCKED	\$2,554.70	\$2,554.70	
1.2	ROOF LINING	1	DENTED	\$1,486.80	\$1,486.80	
1.3	REAR WINDSCREEN	1	SMASHED	\$1,144.60	\$1,144.60	
1.4	REAR SPEAKER BOARD	1	CUT	\$503.86	\$503.86	
1.5	REAR SPEAKER BOARD PANEL ASSY	1	UNCONFIRM	\$722.16	\$722.16	
1.6	RHR FENDER	1	DISTORTED	\$1,510.40	\$1,510.40	
1.7	RHR FENDER INNER TRIM	1	UNCONFIRM	\$375.24	\$375.24	
1.8	RHR FENDER INNER SHIELD	1	DEFORMED	\$182.90	\$182.90	
1.9	BOOT SIDE DRAIN RH	1	BENT	\$218.30	\$218.30	
1.10	BOOT SIDE DRAIN LH	1	UNCONFIRM	\$218.30	\$218.30	
1.11	RHR FENDER LOWER PANEL (wheel house)	1	UNCONFIRM	\$1,126.90	\$1,126.90	
1.12	RHR FENDER BRACKET	1	UNCONFIRM	\$47.20	\$47.20	
1.13	BOOT LID	1	BUCKED	\$1,534.00	\$1,534.00	
1.14	BOOT HINGE RH	1	BENT	\$128.62	\$128.62	
1.15	BOOT HINGE LH	1	BENT	\$128.62	\$128.62	
1.16	BOOT DAMPER RH	1	UNCONFIRM	\$96.76	\$96.76	
1.17	BOOT DAMPER LH	1	UNCONFIRM	\$96.76	\$96.76	
1.18	BOOT WEATHER STRIP	1	TWISTED	\$51.92	\$51.92	
1.19	REAR WINDSCREEN MEMBER PANEL	1	UNCONFIRM	\$232.46	\$232.46	
1.20	BOOT LOCK ASSY	1	BENT	\$247.80	\$247.80	
1.21	BOOT LOCK CATCH ASSY	1	NOT NECESSARY	\$9.44		
1.22	BOOT OUTER CHROME MOULDING	1	DEFORMED	\$129.80	\$129.80	
1.23	BOOT OUTER LOCK HANDLE	1	UNCONFIRM	\$226.56	\$226.56	
1.24	KEYLESS ENTRY SENSOR CLIP	1	NECESSARY	\$11.80	\$11.80	
1.25	BOOT KEYLESS ENTRY SENSOR	1	UNCONFIRM	\$68.44	\$68.44	
1.26	BOOT INSULATOR	1	DEFORMED	\$151.04	\$151.04	
1.27	BOOT INSULATOR HANDLE	1	UNCONFIRM	\$10.62	\$10.62	
1.28	TAILAMP RH ASSY	1	CRACKED	\$486.16	\$486.16	
1.29	TAILAMP PANEL RH	1	BUCKED	\$280.84	\$280.84	
1.30	REAR BUMPER	1	CRACKED	\$1,142.24	\$1,142.24	
1.31	REAR BUMPER RETAINER RH	1	NECESSARY	\$41.30	\$41.30	
1.32	REAR BUMPER RETAINER LH	1	NECESSARY	\$41.30	\$41.30	
1.33	REAR BUMPER BRACKET RH	1	UNCONFIRM	\$21.24	\$21.24	
1.34	REAR BUMPER BRACKET LH	1	UNCONFIRM	\$21.24	\$21.24	
1.35	REAR BUMPER LOWER SPOILER	1	UNCONFIRM	\$326.86	\$326.86	
1.36	REAR BUMPER SENSOR	1	UNCONFIRM	\$136.88	\$136.88	
1.37	REAR BUMPER REINFORCEMENT	1	BENT	\$666.70	\$666.70	
1.38	REAR BUMPER SPONGE	1	UNCONFIRM	\$64.90	\$64.90	

1.39	REAR END PANEL	1	BUCKED	\$595.90	\$595.90	
1.40	REAR END PANEL GARNISH	1	UNCONFIRM	\$318.60	\$318.60	
1.41	SPARE TYRE WELL	1	UNCONFIRM	\$761.10	\$761.10	
1.42	REAR BUMPER TOW COVER	1	UNCONFIRM	\$40.12	\$40.12	
1.43	EXHAUST MUFFLER ASY RH	1	DENTED	\$696.20	\$696.20	
1.44	EXHAUST MUFFLER MOUNTING RH	2	BENT	\$23.60	\$47.20	
1.45	REAR EXHAUST MUFFLER HEAT PLATE RH	1	BENT	\$118.00	\$118.00	
1.46	FUEL TANK COVER	1	MISSING	\$108.56	\$108.56	
1.47	FUEL TANK COVER LOCK	1	NECESSARY	\$221.84	\$221.84	
1.48	FUEL TANK NECK	1	CUT	\$234.82	\$234.82	
1.49	FUEL TANK	1	UNCONFIRM	\$1,871.48	\$1,871.48	
1.50	REAR SENSOR WIREHANESS ASSY	1	UNCONFIRM	\$147.50	\$147.50	
1.51	REAR SPEAKER BOARD CLIPS	4	NECESSARY	\$5.31	\$21.24	
1.52	RHR INNER FENDER UPPER REINFORCEMENT	1	UNCONFIRM	\$338.66	\$338.66	
1.53	TAILLAMP LOWER CHROME RH	1	NECESSARY	\$101.48	\$101.48	
1.54	SPARE TYRE BOARD ASSY	1	UNCONFIRM	\$408.28	\$408.28	
1.55	SPARE TYRE BOARD OUTER HANDLE(with 1.54)	1	UNCONFIRM	\$0.00	\$0.00	
1.56	REAR WINDSCREEN INNER GARNISH RH	1	UNCONFIRM	\$120.36	\$120.36	
1.57	RHR DOOR	1	REPAIR	\$1,543.44		
1.58	RHR DOOR RIVET	1	REPAIR	\$2.36	\$2.36	✓
1.59	RH SIDE SKIRT ASSY	1	DEFORMED	\$558.14	\$558.14	
1.60	RHR DOOR LOCK	1	NOT NECESSARY	\$472.00		
1.61	RHR DOOR LOCK CATCH	1	NOT NECESSARY	\$25.96		
1.62	BOOT LID WEATHER STRIP	1	NOT NECESSARY	\$129.80		
1.63	RHR FENDER AIR VENT	1	DISTORTED	\$69.62	\$69.62	
1.64	RHR CHASSIS ASSY	1	UNCONFIRM	\$2,369.44	\$2,369.44	
1.65	TAILLAMP LOWER BEAM RH	1	MISSING	\$122.72	\$122.72	
1.66	RHR SPORTS RIM 18"	1	CUT	\$1,285.02	\$1,285.02	
1.67	RHR S/ABSORBER	1	UNCONFIRM	\$300.90	\$300.90	
1.68	RHR LOWER ARM	1	UNCONFIRM	\$69.62	\$69.62	
1.69	RHR KNUCKLE ARM	1	UNCONFIRM	\$647.82	\$647.82	
1.70	RHR WHEEL BEARING	1	UNCONFIRM	\$377.60	\$377.60	
1.71	RHR TRAILING ARM	1	UNCONFIRM	\$265.50	\$265.50	
1.72	RHR UPPER ARM	1	UNCONFIRM	\$182.90	\$182.90	
1.73	RHR TYRE 245/40/18	1	TORN	\$430.54	\$430.54	
1.74	SPARE TYRE WELL SIDE PANEL RH	1	UNCONFIRM	\$518.02	\$518.02	
1.75	SPARE TYRE WELL SIDE PANEL LH	1	UNCONFIRM	\$518.02	\$518.02	
1.76	RHR DOOR FRAME PANEL	1	UNCONFIRM	\$562.86	\$562.86	
1.77	INNER TAPE	1	NECESSARY	\$35.40	\$35.40	
1.78	SEALANT	2	NECESSARY	\$23.60	\$47.20	
1.79	REAR NUMBER PLATE	1	BENT	\$35.40	\$35.40	

2	ADDITIONAL SERVICES					
2.10	WHEEL ALIGNMENT	1	NECESSARY	\$70.80	\$70.80	
3	LABOUR					
3.1	TO REPAIR AND RESPRAY LHR FENDER INCLUDING REFLECTIVE STICKER					8
3.2	TO REPAIR AND RESPRAY RHR FENDER INCLUDING REFLECTIVE STICKER					11
3.3	TO REPLACE AND RESPRAY RHR WHEEL HOUSE					12
3.4	TO REPLACE AND RESPRAY LHR WHEEL HOUSE					4
3.5	TO REPAIR, ALIGN, RESPRAY RHR DOOR INCLUDING REFLECTIVE STICKE					7
3.6	TO REPAIR AND RESPRAY REAR SPEAKER PANEL					6
3.7	TO REPLACE AND RESPRAY REAR END PANEL					6
3.8	TO REPLACE AND RESPRAY SPARE TYRE WELL					6
3.9	TO REMOVE AND REFIX UPHOISTERY AND REAR SEAT TO ASSIST WORK					3
3.10	TO REPLACE AND RESPRAY BOOT LID INCLUDING REFLECTIVES STICKER					6
3.11	TO REPLACE REAR WINDSCREEN INCLUDING REFLECTIVE STICKER					6
3.12	TO REPLACE AND RESPRAY REAR BUMPER INCLUDING REFLECTIVE STICKER					8
3.13	TO REMOVE AND REFIX REAR UNDERCARRIAGE TO ASSIST WORK					4
3.14	TO REPLACE, ALIGN, RESPRAY REAR CHASSIS		UNCONFIRM			10
3.15	TO APPLY TUFF KOTE					1
3.16	TO PERFORM WHEEL ALIGNMENT					1
3.17	TO REMOVE AND REFIX PETROL TANK TO ASSIST WORK					2
3.18	TO REPLACE WIRE HARNESS, RESET FAULT CODE, CHECK WIRING SYSTEM					2
3.19	TO REPLACE EXHAUST MUFFLER					2
3.20	TO REPLACE AND RESPRAY ROOF PANEL					9
3.21	TO REMOVE AND REFIXBAR LIGHT, CAMERA ROOF LINING					8
		TOTAL PARTS COST			\$31,057.44	
		TOTAL MAN-HOUR				122

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, July 26, 2018 3:48 PM
To: 'Perry HE (SPF)'
Cc: 'Wei Yea LIM (SPF)'; 'Kwee Huat TAN (SPF)'; 'Kim Pang CHAY (SPF)'
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX887E
Attachments: QX 887E.xls; QX 887E INSPECTION PHOTO.pdf

Hi Perry,

Please find enclosed.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, July 23, 2018 5:42 PM
To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; SUR <sur@lkkauto.com>
Cc: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX887E

Dear Sir/Mdm,

Thank you for the email.

Dear Janice,

Kindly assist.

FYNA Our Ref : CS/SPF18013115/Grb

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Monday, 23 July 2018 5:33 PM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 18 July, 2018 3:26 PM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX887E

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO

Vehicle No: QX887E

Parts

- 1.1 ROOF PANEL
- 1.2 ROOF LINING
- 1.3 REAR WINDSCREEN
- 1.4 REAR SPEAKER BOARD
- 1.5 REAR SPEAKER BOARD PANEL ASSY
- 1.6 RHR FENDER
- 1.7 RHR FENDER INNER TRIM
- 1.8 RHR FENDER INNER SHIELD
- 1.9 BOOT SIDE DRAIN RH
- 1.10 BOOT SIDE DRAIN LH
- 1.11 RHR FENDER LOWER PANEL (wheel house)
- 1.12 RHR FENDER BRACKET
- 1.13 BOOT LID
- 1.14 BOOT HINGE RH
- 1.15 BOOT HINGE LH
- 1.16 BOOT DAMPER RH
- 1.17 BOOT DAMPER LH
- 1.18 BOOT WEATHER STRIP
- 1.19 REAR WINDSCREEN MEMBER PANEL
- 1.20 BOOT LOCK ASSY
- 1.21 BOOT LOCK CATCH ASSY
- 1.22 BOOT OUTER CHROME MOULDING
- 1.23 BOOT OUTER LOCK HANDLE
- 1.24 KEYLESS ENTRY SENSOR CLIP
- 1.25 BOOT KEYLESS ENTRY SENSOR
- 1.26 BOOT INSULATOR
- 1.27 BOOT INSULATOR HANDLE
- 1.28 TAILLAMP RH ASSY
- 1.29 TAILLAMP PANEL RH
- 1.30 REAR BUMPER
- 1.31 REAR BUMPER RETAINER RH
- 1.32 REAR BUMPER RETAINER LH
- 1.33 REAR BUMPER BRACKET RH
- 1.34 REAR BUMPER BRACKET LH
- 1.35 REAR BUMPER LOWER SPOILER
- 1.36 REAR BUMPER SENSOR
- 1.37 REAR BUMPER REINFORCEMENT
- 1.38 REAR BUMPER SPONGE

- 1.39 REAR END PANEL
- 1.40 REAR END PANEL GARNISH
- 1.41 SPARE TYRE WELL
- 1.42 REAR BUMPER TOW COVER
- 1.43 EXHAUST MUFFLER ASSY RH
- 1.44 EXHAUST MUFFLER MOUNTING RH
- 1.45 REAR EXHAUST MUFFLER HEAT PLATE RH
- 1.46 FUEL TANK COVER
- 1.47 FUEL TANK COVER LOCK
- 1.48 FUEL TANK NECK
- 1.49 FUEL TANK
- 1.50 REAR SENSOR WIREHANESS ASSY
- 1.51 REAR SPEAKER BOARD CLIPS
- 1.52 RHR INNER FENDER UPPER REINFORCEMENT
- 1.53 TAILLAMP LOWER CHROME RH
- 1.54 SPARE TYRE BOARD ASSY
- 1.55 SPARE TYRE BOARD OUTER HANDLE (with 1.54)
- 1.56 REAR WINDSCREEN INNER GARNISH RH
- 1.57 RHR DOOR
- 1.58 RHR DOOR RIVET
- 1.59 RH SIDE SKIRT ASSY
- 1.60 RHR DOOR LOCK
- 1.61 RHR DOOR LOCK CATCH
- 1.62 BOOT LID WEATHER STRIP
- 1.63 RHR FENDER AIR VENT
- 1.64 RHR CHASSIS ASSY
- 1.65 TAILLAMP LOWER BEAM RH
- 1.66 RHR SPORTS RIM 18"
- 1.67 RHR S/ABSORBER
- 1.68 RHR LOWER ARM
- 1.69 RHR KNUCKLE ARM
- 1.70 RHR WHEEL BEARING
- 1.71 RHR TRAILING ARM
- 1.72 RHR UPPER ARM
- 1.73 RHR TYRE 245/40/18 (SOR)
- 1.74 SPARE TYRE WELL SIDE PANEL RH
- 1.75 SPARE TYRE WELL SIDE PANEL LH
- 1.76 RHR DOOR FRAME PANEL
- 1.77 INNER TAPE
- 1.78 SEALANT
- 1.79 REAR NUMBER PLATE

Service

WHEEL ALIGHMENT

Labour

- 1.1 TO REPAIR AND RESPRAY LHR FENDER INCLUDING REFLECTIVE STICKER
- 1.2 TO REPLACE AND RESPRAY RHR FENDER INCLUDING REFLECTIVE STICKER
- 1.3 TO REPLACE AND RESPRAY RHR WHEEL HOUSE
- 1.4 TO REPAIR AND RESPRAY LHR WHEEL HOUSE
- 1.5 TO REPAIR, ALIGN, RESPRAY RHR DOOR INCLUDING REFLECTIVE STICKER

- 1.6 TO REPLACE AND RESPRAY REAR SPEAKER
PANEL
- 1.7 TO REPLACE AND RESPRAY REAR END
PANEL
- 1.8 TO REPLACE AND RESPRAY SPARE TYRE
WELL
- 1.9 TO REMOVE AND REFIX UPHOISTERY AND REAR SEAT TO ASSIST
WORK
- 1.10 TO REPLACE AND RESPRAY BOOT LID INCLUDING REFLECTIVE
STICKER
- 1.11 TO REPLACE REAR WINDSCREEN INCLUDING REFLECTIVE
STICKER
- 1.12 TO REPLACE AND RESPRAY REAR BUMPER INCLUDING REFLECTIVE
STICKER
- 1.13 TO REMOVE AND REFIX REAR UNDERCARRIAGE TO ASSIST
WORK
- 1.14 TO REPLACE, ALIGN, RESPRAY REAR
CHASSIS
- 1.15 TO APPLY TUFF KOTE
- 1.16 TO PERFORM WHEEL
ALIGNMENT
- 1.17 TO REMOVE AND REFIX PETROL TANK TO ASSIST
WORK
- 1.18 TO REPLACE WIRE HARNESS, RESET FAULT CODE, CHECK WIRING
SYSTEM
- 1.19 TO REPLACE EXHAUST MUFFLER
- 1.20 TO REPLACE AND RESPRAY ROOF
PANEL
- 1.21 TO REMOVE AND REFIX BAR LIGHT, CAMERA ROOF
LINING

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 18 July, 2018 3:26 PM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX887E

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO

Vehicle No: QX887E

Parts

- 1.1 ROOF PANEL
- 1.2 ROOF LINING
- 1.3 REAR WINDSCREEN
- 1.4 REAR SPEAKER BOARD
- 1.5 REAR SPEAKER BOARD PANEL ASSY
- 1.6 RHR FENDER
- 1.7 RHR FENDER INNER TRIM
- 1.8 RHR FENDER INNER SHIELD
- 1.9 BOOT SIDE DRAIN RH
- 1.10 BOOT SIDE DRAIN LH
- 1.11 RHR FENDER LOWER PANEL (wheel house)
- 1.12 RHR FENDER BRACKET
- 1.13 BOOT LID
- 1.14 BOOT HINGE RH
- 1.15 BOOT HINGE LH
- 1.16 BOOT DAMPER RH
- 1.17 BOOT DAMPER LH
- 1.18 BOOT WEATHER STRIP
- 1.19 REAR WINDSCREEN MEMBER PANEL
- 1.20 BOOT LOCK ASSY
- 1.21 BOOT LOCK CATCH ASSY
- 1.22 BOOT OUTER CHROME MOULDING
- 1.23 BOOT OUTER LOCK HANDLE
- 1.24 KEYLESS ENTRY SENSOR CLIP
- 1.25 BOOT KEYLESS ENTRY SENSOR
- 1.26 BOOT INSULATOR
- 1.27 BOOT INSULATOR HANDLE
- 1.28 TAILLAMP RH ASSY
- 1.29 TAILLAMP PANEL RH
- 1.30 REAR BUMPER
- 1.31 REAR BUMPER RETAINER RH
- 1.32 REAR BUMPER RETAINER LH
- 1.33 REAR BUMPER BRACKET RH
- 1.34 REAR BUMPER BRACKET LH
- 1.35 REAR BUMPER LOWER SPOILER
- 1.36 REAR BUMPER SENSOR
- 1.37 REAR BUMPER REINFORCEMENT
- 1.38 REAR BUMPER SPOILER

- 1.39 REAR END PANEL
- 1.40 REAR END PANEL GARNISH
- 1.41 SPARE TYRE WELL
- 1.42 REAR BUMPER TOW COVER
- 1.43 EXHAUST MUFFLER ASSY RH
- 1.44 EXHAUST MUFFLER MOUNTING RH
- 1.45 REAR EXHAUST MUFFLER HEAT PLATE RH
- 1.46 FUEL TANK COVER
- 1.47 FUEL TANK COVER LOCK
- 1.48 FUEL TANK NECK
- 1.49 FUEL TANK
- 1.50 REAR SENSOR WIREHANESS ASSY
- 1.51 REAR SPEAKER BOARD CLIPS
- 1.52 RHR INNER FENDER UPPER REINFORCEMENT
- 1.53 TAILLAMP LOWER CHROME RH
- 1.54 SPARE TYRE BOARD ASSY
- 1.55 SPARE TYRE BOARD OUTER HANDLE (with 1.54)
- 1.56 REAR WINDSCREEN INNER GARNISH RH
- 1.57 RHR DOOR
- 1.58 RHR DOOR RIVET
- 1.59 RH SIDE SKIRT ASSY
- 1.60 RHR DOOR LOCK
- 1.61 RHR DOOR LOCK CATCH
- 1.62 BOOT LID WEATHER STRIP
- 1.63 RHR FENDER AIR VENT
- 1.64 RHR CHASSIS ASSY
- 1.65 TAILLAMP LOWER BEAM RH
- 1.66 RHR SPORTS RIM 18"
- 1.67 RHR S/ABSORBER
- 1.68 RHR LOWER ARM
- 1.69 RHR KNUCKLE ARM
- 1.70 RHR WHEEL BEARING
- 1.71 RHR TRAILING ARM
- 1.72 RHR UPPER ARM
- 1.73 RHR TYRE 245/40/18 (SOR)
- 1.74 SPARE TYRE WELL SIDE PANEL RH
- 1.75 SPARE TYRE WELL SIDE PANEL LH
- 1.76 RHR DOOR FRAME PANEL
- 1.77 INNER TAPE
- 1.78 SEALANT
- 1.79 REAR NUMBER PLATE

Service

WHEEL ALIGHMENT

Labour

- 1.1 TO REPAIR AND RESPRAY LHR FENDER INCLUDING REFLECTIVE STICKER
- 1.2 TO REPLACE AND RESPRAY RHR FENDER INCLUDING REFLECTIVE STICKER
- 1.3 TO REPLACE AND RESPRAY RHR WHEEL HOUSE
- 1.4 TO REPAIR AND RESPRAY LHR WHEEL HOUSE
- 1.5 TO REPAIR, ALIGN, RESPRAY RHR DOOR INCLUDING REFLECTIVE STICKER

- 1.6 TO REPLACE AND RESPRAY REAR SPEAKER
PANEL
- 1.7 TO REPLACE AND RESPRAY REAR END
PANEL
- 1.8 TO REPLACE AND RESPRAY SPARE TYRE
WELL
- 1.9 TO REMOVE AND REFIX UPHOISTERY AND REAR SEAT TO ASSIST
WORK
- 1.10 TO REPLACE AND RESPRAY BOOT LID INCLUDING REFLECTIVE
STICKER
- 1.11 TO REPLACE REAR WINDSCREEN INCLUDING REFLECTIVE
STICKER
- 1.12 TO REPLACE AND RESPRAY REAR BUMPER INCLUDING REFLECTIVE
STICKER
- 1.13 TO REMOVE AND REFIX REAR UNDERCARRIAGE TO ASSIST
WORK
- 1.14 TO REPLACE, ALIGN, RESPRAY REAR
CHASSIS
- 1.15 TO APPLY TUFF KOTE
- 1.16 TO PERFORM WHEEL
ALIGNMENT
- 1.17 TO REMOVE AND REFIX PETROL TANK TO ASSIST
WORK
- 1.18 TO REPLACE WIRE HARNESS, RESET FAULT CODE, CHECK WIRING
SYSTEM
- 1.19 TO REPLACE EXHAUST MUFFLER
- 1.20 TO REPLACE AND RESPRAY ROOF
PANEL
- 1.21 TO REMOVE AND REFIX BAR LIGHT, CAMERA ROOF
LINING

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error.



Scope Of Work
Home Team Agency

Eno Qiang
UKK
19/7/18

SCOPE OF WORK

I provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP
VEH NO :	QX887E	MARKED	REPAIR TYPE:	ACCIDENT
VEH MAKE/MODEL	VOLVO S80		Mileage:	245720

Reference No.
MHA/SPF/2018/07-0019 1100008087

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	ROOF PANEL / Buc	2165.00	1	18%	2554.70	2554.70
1.2	ROOF LINING / de	1260.00	1	18%	1486.80	1486.80
1.3	REAR WINDSCREEN / SM	970.00	1	18%	1144.60	1144.60
1.4	REAR SPEAKER BOARD / Cut	427.00	1	18%	503.86	503.86
1.5	REAR SPEAKER BOARD PANEL ASSY ?	612.00	1	18%	722.16	722.16
1.6	RHR FENDER / Dis	1280.00	1	18%	1510.40	1510.40
1.7	RHR FENDER INNER TRIM ?	318.00	1	18%	375.24	375.24
1.8	RHR FENDER INNER SHIELD	155.00	1	18%	182.90	182.90
1.9	BOOT SIDE DRAIN RH / BT de	185.00	1	18%	218.30	218.30
1.10	BOOT SIDE DRAIN LH	185.00	1	18%	218.30	218.30
1.11	RHR FENDER LOWER PANEL (wheel house) ?	955.00	1	18%	1126.90	1126.90
1.12	RHR FENDER BRACKET ?	40.00	1	18%	47.20	47.20
1.13	BOOT LID / Buc	1300.00	1	18%	1534.00	1534.00
1.14	BOOT HINGE RH = 4AT	109.00	1	18%	128.62	128.62
1.15	BOOT HINGE LH	109.00	1	18%	128.62	128.62
1.16	BOOT DAMPER RH ?	82.00	1	18%	96.76	96.76
1.17	BOOT DAMPER LH ?	82.00	1	18%	96.76	96.76
1.18	BOOT WEATHER STRIP - Twi	44.00	1	18%	51.92	51.92
1.19	REAR WINDSCREEN MEMBER PANEL ?	197.00	1	18%	232.46	232.46
1.20	BOOT LOCK ASSY / BT	210.00	1	18%	247.80	247.80
1.21	BOOT LOCK CATCH ASSY X NN	8.00	1	18%	9.44	9.44
1.22	BOOT OUTER CHROME MOULDING / de	110.00	1	18%	129.80	129.80
1.23	BOOT OUTER LOCK HANDLE ?	192.00	1	18%	226.56	226.56
1.24	KEYLESS ENTRY SENSOR CLIP / de	10.00	1	18%	11.80	11.80
1.25	BOOT KEYLESS ENTRY SENSOR ?	58.00	1	18%	68.44	68.44
1.26	BOOT INSULATOR / de	128.00	1	18%	151.04	151.04
1.27	BOOT INSULATOR HANDLE	9.00	1	18%	10.62	10.62
1.28	TAILLAMP RH ASSY - CAA	412.00	1	18%	486.16	486.16
1.29	TAILLAMP PANEL RH / Buc	238.00	1	18%	280.84	280.84
1.30	REAR BUMPER - CAA	968.00	1	18%	1142.24	1142.24
1.31	REAR BUMPER RETAINER RH / de	35.00	1	18%	41.30	41.30
1.32	REAR BUMPER RETAINER LH / de	35.00	1	18%	41.30	41.30
1.33	REAR BUMPER BRACKET RH ?	18.00	1	18%	21.24	21.24
1.34	REAR BUMPER BRACKET LH ?	18.00	1	18%	21.24	21.24
1.35	REAR BUMPER LOWER SPOILER ?	277.00	1	18%	326.86	326.86
1.36	REAR BUMPER SENSOR ?	116.00	4	18%	136.88	547.52
1.37	REAR BUMPER REINFORCEMENT / BT	565.00	1	18%	666.70	666.70
1.38	REAR BUMPER SPONGE ?	55.00	1	18%	64.90	64.90
1.39	REAR END PANEL / Buc	505.00	1	18%	595.90	595.90
1.40	REAR END PANEL GARNISH ?	270.00	1	18%	318.60	318.60
1.41	SPARE TYRE WELL X de ?	645.00	1	18%	761.10	761.10
1.42	REAR BUMPER TOW COVER ?	34.00	1	18%	40.12	40.12
1.43	EXHAUST MUFFLER ASSY RH / de	590.00	1	18%	696.20	696.20
1.44	EXHAUST MUFFLER MOUNTING RH / BT	20.00	2	18%	23.60	47.20
1.45	REAR EXHAUST MUFFLER HEAT PLATE RH / BT	100.00	1	18%	118.00	118.00
1.46	FUEL TANK COVER / de	92.00	1	18%	108.56	108.56
1.47	FUEL TANK COVER LOCK / de	188.00	1	18%	221.84	221.84
1.48	FUEL TANK NECK / de	199.00	1	18%	234.82	234.82
1.49	FUEL TANK ?	1586.00	1	18%	1871.48	1871.48
1.50	REAR SENSOR WIREHANESS ASSY ?	125.00	1	18%	147.50	147.50
1.51	REAR SPEAKER BOARD CLIPS / de	4.50	4	18%	5.31	21.24
1.52	RHR INNER FENDER UPPER REINFORCEMENT ?	287.00	1	18%	338.66	338.66
1.53	TAILLAMP LOWER CHROME RH / de	86.00	1	18%	101.48	101.48
1.54	SPARE TYRE BOARD ASSY ?	346.00	1	18%	408.28	408.28
1.55	SPARE TYRE BOARD OUTER HANDLE (with 1.54) ?	0.00	1	18%	0.00	0.00
1.56	REAR WINDSCREEN INNER GARNISH RH ?	102.00	1	18%	120.36	120.36
1.57	RHR DOOR X de	1308.00	1	18%	1543.44	1543.44
1.58	RHR DOOR RIVET X	2.00	20	18%	2.36	47.20
1.59	RH SIDE SKIRT ASSY / de	473.00	1	18%	558.14	558.14
1.60	RHR DOOR LOCK X	400.00	1	18%	472.00	472.00
1.61	RHR DOOR LOCK CATCH X NN	22.00	1	18%	25.96	25.96
1.62	BOOT LID WEATHER STRIP X	110.00	1	18%	129.80	129.80
1.63	RHR FENDER AIR VENT / de	59.00	1	18%	69.62	69.62
1.64	RHR CHASSIS ASSY X de ?	2008.00	1	18%	2369.44	2369.44

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.65	TAILLAMP LOWER BEAM RH <i>MS</i>	104.00	1	18%	122.72	122.72
1.66	RHR SPORTS RIM 18" <i>1 unit</i>	1089.00	1	18%	1285.02	1285.02
1.67	RHR S/ABSORBER ?	255.00	1	18%	300.90	300.90
1.68	RHR LOWER ARM ?	59.00	1	18%	69.62	69.62
1.69	RHR KNUCKLE ARM ?	549.00	1	18%	647.82	647.82
1.70	RHR WHEEL BEARING ?	320.00	1	18%	377.60	377.60
1.71	RHR TRAILING ARM ?	225.00	1	18%	265.50	265.50
1.72	RHR UPPER ARM ?	155.00	1	18%	182.90	182.90
1.73	RHR TYRE 245/40/18 (SOR) <i>1 TN</i>	430.54	1	0%	430.54	430.54
1.74	SPARE TYRE WELL SIDE PANEL RH ?	439.00	1	18%	518.02	518.02
1.75	SPARE TYRE WELL SIDE PANEL LH ?	439.00	1	18%	518.02	518.02
1.76	RHR DOOR FRAME PANEL ?	477.00	1	18%	562.86	562.86
1.77	INNER TAPE <i>1 msc</i>	30.00	1	18%	35.40	35.40
1.78	SEALANT <i>1 BT</i>	20.00	2	18%	23.60	47.20
1.79	REAR NUMBER PLATE <i>1 BT</i>	30.00	1	18%	35.40	35.40
2	Additional Services					
2.1	WHEEL ALIGNMENT <i>1 msc</i>	60.00	1	18%	70.80	70.80
Remarks: SUBJECT TO PARTS AVAILABILITY BY AIR 3 TO 4 WEEKS		Parts Total:		\$ 33,693.56		

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO REPAIR AND RESPRAY LHR FENDER INCLUDING REFLECTIVE STICKER	53.80	8	430.40
1.2	TO REPLACE AND RESPRAY RHR FENDER INCLUDING REFLECTIVE STICKER	53.80	12	645.60
1.3	TO REPLACE AND RESPRAY RHR WHEEL HOUSE	53.80	12	645.60
1.4	TO REPAIR AND RESPRAY LHR WHEEL HOUSE	53.80	4	215.20
1.5	TO REPAIR, ALIGN, RESPRAY RHR DOOR INCLUDING REFLECTIVE STICKER	53.80	7	376.60
1.6	TO REPLACE AND RESPRAY REAR SPEAKER PANEL	53.80	6	322.80
1.7	TO REPLACE AND RESPRAY REAR END PANEL	53.80	6	322.80
1.8	TO REPLACE AND RESPRAY SPARE TYRE WELL	53.80	6	322.80
1.9	TO REMOVE AND REFIX UPHOISTERY AND REAR SEAT TO ASSIST WORK	53.80	3	161.40
1.10	TO REPLACE AND RESPRAY BOOT LID INCLUDING REFLECTIVE STICKER	53.80	6	322.80
1.11	TO REPLACE REAR WINDSCREEN INCLUDING REFLECTIVE STICKER	53.80	6	322.80
1.12	TO REPLACE AND RESPRAY REAR BUMPER INCLUDING REFLECTIVE STICKER	53.80	8	430.40
1.13	TO REMOVE AND REFIX REAR UNDERCARRIAGE TO ASSIST WORK	53.80	4	215.20
1.14	TO REPLACE, ALIGN, RESPRAY REAR CHASSIS	53.80	10	538.00
1.15	TO APPLY TUFF KOTE	53.80	1	53.80
1.16	TO PERFORM WHEEL ALIGNMENT	53.80	1	53.80
1.17	TO REMOVE AND REFIX PETROL TANK TO ASSIST WORK	53.80	2	107.60
1.18	TO REPLACE WIRE HARNESS, RESET FAULT CODE, CHECK WIRING SYSTEM	53.80	2	107.60
1.19	TO REPLACE EXHAUST MUFFLER	53.80	2	107.60
1.20	TO REPLACE AND RESPRAY ROOF PANEL	53.80	10	538.00
1.21	TO REMOVE AND REFIX BAR LIGHT, CAMERA ROOF LINING	53.80	8	430.40
2	Additional Services			
		Labour Total:	\$ 6,671.20	
		GRAND TOTAL :	\$40,364.76	
Contractor shall complete the entire repair within 30 working days upon quotation approved date.				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	Gan Hup Tiong	Name:		Name:	
Date:	16/7/18	Date:		Date:	
Sign:	<i>[Signature]</i>	Sign:		Sign:	
<p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey PA prices are subject to confirmation 					
Contractor QC		Home Team QC / Fleet Manager / On a "Without Home Team Contract / Fleet Manager Appointed Surveyor" Confirmation(s) is allowed			
Name:		Name:	* Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
Date:		Date:			
Sign:		Sign:			
		Acknowledged by Repairer			
		Signature:		Sign:	
		Date:			

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made



ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

ILMS Notification No	110008087	Division/Unit	TP
Vehicle No	BX287E	Date	11/7/16
Vehicle Type (e.g. IRC, minibus)	M/2V V6/V6	Mileage (km)	245720
Vehicle Make & Model	J90		




Description	Pin tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)	<input checked="" type="checkbox"/>	NP168 13080710/2170
NP168 (Accident do not involve 3 rd Party)	<input type="checkbox"/>	
NP299 Discovered Damage	<input type="checkbox"/>	
NP299 Vandalism	<input type="checkbox"/>	
Ad hoc, pls specify		

Description of affected area/required works (e.g. dented, cracked, grazed etc)

1) RAC body badly dented 2) Rear right bumper badly dented
3) Rear right side of body badly scratched 4) RAC right rim damaged
5) Rear right lamp/indicator broken 6) Rear mirror damaged & dented

Pls mark affected area with

X right rear damaged
2) 1- check if impact
with repair



Rank/Name
Sgt Lillian A H Chan

Signature
[Signature]




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18013115/Grbe2		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 03-12-2018		
ATTN : PERRY HE		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	QX 887E	
	Policy No.	Coverage (\$)	0.00	
	Claim No. HOMSPFETQ17300218	Excess (\$)	0.00	
	Assign From PERRY HE	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO S80	c.c	1999
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	YV1AS47HBD1168770	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	PIRELLI	6 mm
	L/H Front Tyre	245/40 R18	PIRELLI	6 mm
	R/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
	L/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	Inspection Date	19/07/2018	
	Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		
5a. Remarks				



Registration No. QX 887E

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	ROOF PANEL	1	BUCKED	\$2,554.70	\$2,554.70	
1.2	ROOF LINING	1	DENTED	\$1,486.80	\$1,486.80	
1.3	REAR WINDSCREEN	1	SMASHED	\$1,144.60	\$1,144.60	
1.4	REAR SPEAKER BOARD	1	CUT	\$503.86	\$503.86	
1.5	REAR SPEAKER BOARD PANEL ASSY	1	UNCONFIRM	\$722.16	\$722.16	
1.6	RHR FENDER	1	DISTORTED	\$1,510.40	\$1,510.40	
1.7	RHR FENDER INNER TRIM	1	UNCONFIRM	\$375.24	\$375.24	
1.8	RHR FENDER INNER SHIELD	1	DEFORMED	\$182.90	\$182.90	
1.9	BOOT SIDE DRAIN RH	1	BENT	\$218.30	\$218.30	
1.10	BOOT SIDE DRAIN LH	1	UNCONFIRM	\$218.30	\$218.30	
1.11	RHR FENDER LOWER PANEL (wheel house)	1	UNCONFIRM	\$1,126.90	\$1,126.90	
1.12	RHR FENDER BRACKET	1	UNCONFIRM	\$47.20	\$47.20	
1.13	BOOT LID	1	BUCKED	\$1,534.00	\$1,534.00	
1.14	BOOT HINGE RH	1	BENT	\$128.62	\$128.62	
1.15	BOOT HINGE LH	1	BENT	\$128.62	\$128.62	
1.16	BOOT DAMPER RH	1	UNCONFIRM	\$96.76	\$96.76	
1.17	BOOT DAMPER LH	1	UNCONFIRM	\$96.76	\$96.76	
1.18	BOOT WEATHER STRIP	1	TWISTED	\$51.92	\$51.92	
1.19	REAR WINDSCREEN MEMBER PANEL	1	UNCONFIRM	\$232.46	\$232.46	
1.20	BOOT LOCK ASSY	1	BENT	\$247.80	\$247.80	
1.21	BOOT LOCK CATCH ASSY	1	NOT NECESSARY	\$9.44		
1.22	BOOT OUTER CHROME MOULDING	1	DEFORMED	\$129.80	\$129.80	
1.23	BOOT OUTER LOCK HANDLE	1	UNCONFIRM	\$226.56	\$226.56	

1.24	KEYLESS ENTRY SENSOR CLIP	1	NECESSARY	\$11.80	\$11.80	
1.25	BOOT KEYLESS ENTRY SENSOR	1	UNCONFIRM	\$68.44	\$68.44	
1.26	BOOT INSULATOR	1	DEFORMED	\$151.04	\$151.04	
1.27	BOOT INSULATOR HANDLE	1	UNCONFIRM	\$10.62	\$10.62	
1.28	TAILAMP RH ASSY	1	CRACKED	\$486.16	\$486.16	
1.29	TAILAMP PANEL RH	1	BUCKED	\$280.84	\$280.84	
1.30	REAR BUMPER	1	CRACKED	\$1,142.24	\$1,142.24	
1.31	REAR BUMPER RETAINER RH	1	NECESSARY	\$41.30	\$41.30	
1.32	REAR BUMPER RETAINER LH	1	NECESSARY	\$41.30	\$41.30	
1.33	REAR BUMPER BRACKET RH	1	UNCONFIRM	\$21.24	\$21.24	
1.34	REAR BUMPER BRACKET LH	1	UNCONFIRM	\$21.24	\$21.24	
1.35	REAR BUMPER LOWER SPOILER	1	UNCONFIRM	\$326.86	\$326.86	
1.36	REAR BUMPER SENSOR	4	UNCONFIRM	\$136.88	\$547.52	
1.37	REAR BUMPER REINFORCEMENT	1	BENT	\$666.70	\$666.70	
1.38	REAR BUMPER SPONGE	1	UNCONFIRM	\$64.90	\$64.90	
1.39	REAR END PANEL	1	BUCKED	\$595.90	\$595.90	
1.40	REAR END PANEL GARNISH	1	UNCONFIRM	\$318.60	\$318.60	
1.41	SPARE TYRE WELL	1	UNCONFIRM	\$761.10	\$761.10	
1.42	REAR BUMPER TOW COVER	1	UNCONFIRM	\$40.12	\$40.12	
1.43	EXHAUST MUFFLER ASY RH	1	DENTED	\$696.20	\$696.20	
1.44	EXHAUST MUFFLER MOUNTING RH	2	BENT	\$23.60	\$47.20	
1.45	REAR EXHAUST MUFFLER HEAT PLATE RH	1	BENT	\$118.00	\$118.00	
1.46	FUEL TANK COVER	1	MISSING	\$108.56	\$108.56	
1.47	FUEL TANK COVER LOCK	1	NECESSARY	\$221.84	\$221.84	
1.48	FUEL TANK NECK	1	CUT	\$234.82	\$234.82	
1.49	FUEL TANK	1	UNCONFIRM	\$1,871.48	\$1,871.48	
1.50	REAR SENSOR WIREHANESS ASSY	1	UNCONFIRM	\$147.50	\$147.50	
1.51	REAR SPEAKER BOARD CLIPS	4	NECESSARY	\$5.31	\$21.24	
1.52	RHR INNER FENDER UPPER REINFORCEMENT	1	UNCONFIRM	\$338.66	\$338.66	
1.53	TAILAMP LOWER CHROME RH	1	NECESSARY	\$101.48	\$101.48	
1.54	SPARE TYRE BOARD ASSY	1	UNCONFIRM	\$408.28	\$408.28	
1.55	SPARE TYRE BOARD OUTER HANDLE(with 1.54)	1	UNCONFIRM	\$0.00	\$0.00	
1.56	REAR WINDSCREEN INNER GARNISH RH	1	UNCONFIRM	\$120.36	\$120.36	
1.57	RHR DOOR	1	REPAIR	\$1,543.44		
1.58	RHR DOOR RIVET	20	REPAIR	\$2.36		
1.59	RH SIDE SKIRT ASSY	1	DEFORMED	\$558.14	\$558.14	
1.60	RHR DOOR LOCK	1	NOT NECESSARY	\$472.00		
1.61	RHR DOOR LOCK CATCH	1	NOT	\$25.96		

			NECESSARY			
1.62	BOOT LID WEATHER STRIP	1	NOT NECESSARY	\$129.80		
1.63	RHR FENDER AIR VENT	1	DISTORTED	\$69.62	\$69.62	
1.64	RHR CHASSIS ASSY	1	UNCONFIRM	\$2,369.44	\$2,369.44	
1.65	TAILLAMP LOWER BEAM RH	1	MISSING	\$122.72	\$122.72	
1.66	RHR SPORTS RIM 18"	1	CUT	\$1,285.02	\$1,285.02	
1.67	RHR S/ABSORBER	1	UNCONFIRM	\$300.90	\$300.90	
1.68	RHR LOWER ARM	1	UNCONFIRM	\$69.62	\$69.62	
1.69	RHR KNUCKLE ARM	1	UNCONFIRM	\$647.82	\$647.82	
1.70	RHR WHEEL BEARING	1	UNCONFIRM	\$377.60	\$377.60	
1.71	RHR TRAILING ARM	1	UNCONFIRM	\$265.50	\$265.50	
1.72	RHR UPPER ARM	1	UNCONFIRM	\$182.90	\$182.90	
1.73	RHR TYRE 245/40/18	1	TORN	\$430.54	\$430.54	
1.74	SPARE TYRE WELL SIDE PANEL RH	1	UNCONFIRM	\$518.02	\$518.02	
1.75	SPARE TYRE WELL SIDE PANEL LH	1	UNCONFIRM	\$518.02	\$518.02	
1.76	RHR DOOR FRAME PANEL	1	UNCONFIRM	\$562.86	\$562.86	
1.77	INNER TAPE	1	NECESSARY	\$35.40	\$35.40	
1.78	SEALANT	2	NECESSARY	\$23.60	\$47.20	
1.79	REAR NUMBER PLATE	1	BENT	\$35.40	\$35.40	
2	ADDITIONAL SERVICES					
2.10	WHEEL ALIGNMENT	1	NECESSARY	\$70.80	\$70.80	
3	LABOUR					
3.1	TO REPAIR AND RESPRAY LHR FENDER INCLUDING REFLECTIVE STICKER					8
3.2	TO REPAIR AND RESPRAY RHR FENDER INCLUDING REFLECTIVE STICKER					11
3.3	TO REPLACE AND RESPRAY RHR WHEEL HOUSE					12
3.4	TO REPLACE AND RESPRAY LHR WHEEL HOUSE					4
3.5	TO REPAIR, ALIGN, RESPRAY RHR DOOR INCLUDING REFLECTIVE STICKE					7
3.6	TO REPAIR AND RESPRAY REAR SPEAKER PANEL					6
3.7	TO REPLACE AND RESPRAY REAR END PANEL					6
3.8	TO REPLACE AND RESPRAY SPARE TYRE WELL					6
3.9	TO REMOVE AND REFIX UPHOISTERY AND REAR SEAT TO ASSIST WORK					3

3.10	TO REPLACE AND RESPRAY BOOT LID INCLUDING REFLECTIVES STICKER					6
3.11	TO REPLACE REAR WINDSCREEN INCLUDING REFLECTIVE STICKER					6
3.12	TO REPLACE AND RESPRAY REAR BUMPER INCLUDING REFLECTIVE STICKER					8
3.13	TO REMOVE AND REFIX REAR UNDERCARRIAGE TO ASSIST WORK					4
3.14	TO REPLACE, ALIGN, RESPRAY REAR CHASSIS					
3.15	TO APPLY TUFF KOTE					1
3.16	TO PERFORM WHEEL ALIGNMENT					1
3.17	TO REMOVE AND REFIX PETROL TANK TO ASSIST WORK					2
3.18	TO REPLACE WIRE HARNESS, RESET FAULT CODE, CHECK WIRING SYSTEM					2
3.19	TO REPLACE EXHAUST MUFFLER					2
3.20	TO REPLACE AND RESPRAY ROOF PANEL					9
3.21	TO REMOVE AND REFIX BAR LIGHT, CAMERA ROOF LINING					8
		TOTAL PARTS COST			\$31,465.72	
		TOTAL MAN-HOUR				112

Registration No. QX 887E

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.