

range & days.

REF CS3/FWD17019821/TSB-1

ASSIGNMENT (Office)

minim Tauhikh

From (Driver) Clara Li

FWD

19072018

OD (H) WS/TP RES / OD RES / EVA / INV / MV / C

To Inspect Vehicle No SLG 3693B Insured SKS 7359P

at Workshop no V-Tech Auto Id 6264 6211

at No 1 Soon Lee Street #06-04 Pioneer Centre, G27 605

Policy No 1201700006612

Make of Veh

(Client's Record) D.O.A 11/10/2017

CA / REV / REP. / REV 24 HRS 'up'

Date Time 16/10/17 @ 10:57am Contacted Ms. Chong

Vehicle IN OUT

| Date Time | Action/Instruction (X) Estimate |
|-----------|--|
| | SLG 3693B - X |
| | SKS 7359P - CS/FWD 17019821 / Hub D.O.A 11/10/17 |
| | Dismantle Part: 17.10.2017 |
| | After Repair: 24.10.2017 |

- * - MV at D.O.A: 11.10.2017
- LIA Rebate
- Repair Margin
- Estimate Number of Days

8800h

8 days

10 day

US 7500h

20% wt m km

25/7/18

(\$ 3,900.00 Fed - 31%)

RECEIVED 01 AUG 2018

Surveyor: *Taylor*

REF: *201 FWD.*

ASSIGNMENT

COE 2017 NOV

From: _____ Date: *16.10.2017*

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLG3693B* Yr Regn: *2007 NOV*

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: *Toyota Rush*

cc 1495

Colour: *Red*

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: *152896*

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: *J200E0016066*

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: *215/65R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Uamah*

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. _____

D.O.I. *16/10/17*

Survey held at *V-Teen*

3:45pm

Des. of Damages: ☒ Fr / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *To check MV*

11K - 12K, 12 days.

RECEIVED 16 NOV 2017

Date/Time: File Pass to?

☐

: Preli. Report

1) *16.11.2017*

☐

: Final Report

Date/Time: File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

) *S + RS* \$

) Photos

) Others

TOTAL

Report Format: *PRS*

Lump Sum / I.B.I: (\$ _____)

Catherine Chong (LKK Auto)

From: clara.li@fwd.com
Sent: Thursday, 19 July, 2018 11:39 AM
To: admin-d@lkkauto.com
Cc: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; motorclaims.sg@fwd.com
Subject: Paper Resurvey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612 TPV: SLG3693B
Attachments: TP Survey Report & Photos.pdf

Hi Catherine,

We haven't heard from your surveyor since our email dated 08 March 2018 on the required information.

Please provide us with the following information / documents on an urgent basis and in the meantime, please conduct a paper resurvey for vehicle SLG3693B.

1. Pre-Accident Market Value of the TPV: SLG3693B as at DOA: 11 October 2017
2. LTA Rebate
3. Repair Margin
4. Estimated Number of Days for Repair

Attached is the relevant documents (in 3 emails)

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg

FWD
insurance

With FWD, you get to keep your
50% NCD for Life. No matter what.
get a quick quote now >



FWD
insurance

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 8 March, 2018 2:00 PM
To: Motor Claims SG - SG Common
Cc: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com
Subject: RE: Pre-Repair Survey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612 TPV: SLG3693B

Dear Clara,

Thank you for your email.

We will check and revert to you shortly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorclaims.sg@fwd.com [mailto:motorclaims.sg@fwd.com]
Sent: Thursday, 8 March, 2018 1:43 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com
Subject: RE: Pre-Repair Survey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612 TPV: SLG3693B
Importance: High

Hi Catherine,

We refer to the above matter which surveyed by Mr Mohd Taufikh at V-Tech Auto Service.

Please provide us with the following information / documents:-

1. Pre-Accident Market Value of the TPV: SLG3693B as at DOA: 11 October 2017
2. LTA Rebate
3. Repair Margin
4. Estimated Number of Days for Repair

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg





Endowment Plan

Get the biggest guaranteed return for a 3 year plan available online.

Limited time offer!



2.02%
p.a.

fwd.com.sg

save now

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Monday, 16 October, 2017 2:50 PM

To: Motor Claims SG - SG Common; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com

Cc: Belliana - SGUser

Subject: RE: Pre-Repair Survey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612

Dear Clara,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motorclaims.sg@fwd.com [<mailto:motorclaims.sg@fwd.com>]

Sent: Monday, 16 October, 2017 10:29 AM

To: assignments@lkkauto.com; sur@lkkauto.com; admin-d@lkkauto.com; admin-a@lkkauto.com

Cc: belliana@fwd.com

Subject: FW: Pre-Repair Survey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Attached is the TP GIA report.

Thank you.

Clara Li

Senior Executive, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower 4, Singapore 038986

T +65 6727 5722

E clara.li@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.

get a quick quote now »



F
ins

From: Motor Claims SG - SG Common

Sent: Monday, 16 October, 2017 10:27 AM

To: 'Ong & Shan LLC'

Subject: RE: Pre-Repair Survey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612

WITHOUT PREJUDICE

Dear Mr Chen,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle, SLG3693B. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Thank you.

Clara Li

Senior Executive, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986

T +65 6727 5722
E clara.li@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.

get a quick quote now »



F
ins

From: Ong & Shan LLC [<mailto:ongshanllc@gmail.com>]

Sent: Monday, 16 October, 2017 9:51 AM

To: Motor Claims SG - SG Common

Subject: Re: Pre-Repair Survey - Your Ref: SRSTP.8032.17.CM Our Ref: 1201700006612

Dear Sirs,

We refer to the above matter and your letter on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

- | | |
|--|---|
| 1. Dennis Yap Teck Wee (Pal's Appraiser Pte Ltd) | 2. Dixon Yeo(Treasure Appraisal Services) |
| 3. Yap Teck Lee (LCW Appraiser Pte Ltd) | 4. Mark (United Appraisal & Management Pte Ltd) |
| 5. Yap Teck Chye (MC. Coy Appraiser Pte Ltd) | 6. Andrew How (Prominent Appraiser Services) |
| 7. T.T Rajan (ST Appraisal Services) | 8. Amas Ong (Aeon Auto Consultants LLP) |
| 9. Alan Cheong (CL Appraiser Pte Ltd) | 10. Sebastian Lim (Constant Appraiser Services) |

Please be informed that the said vehicle can be inspected at:-

| | |
|------------------|--|
| Name of workshop | M/s. V-Tech Auto Service |
| Address | No. 1 Soon Lee Street #06-04/05/06/07 Pioneer Centre Singapore 627605 |
| Contact person | Ms. Chong |
| Telephone | 6-2646211 |
| Fax no | 6-2646233 |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "Single Joint Expert".

We will accordingly inform you who the "Single Joint Expert" is to be facilitate your conduct of a pre-repair survey.

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-repair survey.

Warmest Regards,

CM Chen

M/s Ong & Shan LLC

Block 184 Toa Payoh Central

#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261

Email: ongshanllc@gmail.com

On Fri, Oct 13, 2017 at 3:16 PM, <motorclaims.sg@fwd.com> wrote:

Please reply via Email - motorclaims.sg@fwd.com

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to your letter dated 13 October 2017 of the PRI Notice of your client's vehicle SLG3693B.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Clara Li

Senior Executive, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower 4, Singapore 038986

T [+65 6727 5722](tel:+6567275722)

E clara.li@fwd.com

With FWD, you get to keep your
50% NCD For Life. No matter what.

[get a quick quote now >](#)



F
in

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

PAL'S

APPRAISER PTE LTD
No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201090268D

Report Reference : TP / 10-17030/AY / 2017
Date of Report : 1 Nov 2017

Peh Hai Yam
c/o No.1 Soon Lee Street
#06-04/05/06/07 Pioneer Centre
Singapore 627605

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 11 Oct 2017

As per your instruction dated 14 Oct 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLG 3693 B . We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLG 3693 B
Model : Toyota Rush
Year / Capacity : 2007/1495
Chassis No : J200E0016066
Engine No : 3SZ1894394
Mileage : 152896
Colour : Red

2. TYRES CONDITION

| | | | <u>Size</u> | <u>Made</u> | <u>Balance</u> | | <u>Rim</u> |
|-------|-----|---|-------------|-------------|----------------|----|------------|
| FRONT | O/S | : | 215/65 R16 | Kumho | 4.00 | mm | Sport |
| REAR | O/S | : | 215/65 R16 | Kumho | 4.00 | mm | Sport |
| FRONT | N/S | : | 215/65 R16 | Kumho | 4.00 | mm | Sport |
| REAR | N/S | : | 215/65 R16 | Kumho | 4.00 | mm | Sport |

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 3181 3802 Fax: 6747 1017
Registration No.: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : V-Tech Auto Service
No.1 Soon Lee Street
#06-04/05/06/07 Pioneer Centre
Singapore 627605

5. Estimated normal period of repair : 10 working days to complete.

6. Enclosed number of photograph : 189 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SLG 3693 B**
 Report No: **TP/ 10-17030/AY / 2017**


SPARE PARTS

| Qty | Parts Description | Condition | Workshop's Estimation | Our Revised Estimation |
|---------------------------|-------------------------------------|-----------|-----------------------|------------------------|
| <u>List Items</u> | | | | |
| 1 | Bonnet | Damage | \$ 1227.15 | \$ 1227.15 <i>Rx</i> |
| 1 | Bonnet lock | Damage | \$ 80.43 | \$ 80.43 <i>Rx</i> |
| 1 | Bonnet rubber | Necessary | \$ 13.09 | \$ 13.09 <i>mx</i> |
| 2 | Front headlamps | Damage | \$ 2579.44 | \$ 2579.44 |
| 1 | Front grille | Damage | \$ 554.64 | \$ 554.64 |
| 1 | Front grille logo | Necessary | \$ 61.83 | \$ 61.83 |
| 1 | Front bumper | Damage | \$ 1650.99 | \$ 1650.99 |
| 1 | Front bumper reinforcement | Damage | \$ 469.20 | \$ 469.20 <i>Rx</i> |
| 2 | Front bumper side retainers | Damage | \$ 87.92 | \$ 87.92 |
| 1 | Front support panel | Damage | \$ 687.80 | \$ 687.80 <i>Rx</i> |
| 1 | Front brace panel | Damage | \$ 82.77 | \$ 82.77 <i>Rx</i> |
| 1 | Rear tail door | Damage | \$ 1602.41 | \$ 1602.41 |
| 1 | Rear tail door inner board | Intact | \$ 364.38 | \$ |
| 1 | Rear tail door lock | Damage | \$ 422.90 | \$ 422.90 <i>Rx</i> |
| 1 | Rear tail door rubber | Necessary | \$ 239.90 | \$ 239.90 |
| 1 | Rear tail door 'RUSH' emblem | Necessary | \$ 103.82 | \$ 103.82 |
| 2 | Rear taillamps | Damage | \$ 1036.66 | \$ 1036.66 |
| 1 | Rear end panel | Damage | \$ 513.51 | \$ 513.51 <i>Rx</i> |
| 1 | Rear end panel inner garnish | Intact | \$ 489.71 | \$ |
| 1 | Rear bumper | Damage | \$ 1524.99 | \$ 1524.99 |
| 1 | Rear bumper n/s reflector | Intact | \$ 59.19 | \$ |
| 1 | Rear bumper side retainer - n/s | Necessary | \$ 44.97 | \$ 44.97 |
| 1 | Rear bumper side retainer - o/s | Necessary | \$ 86.95 | \$ 86.95 |
| 1 | Rear number plate lamp (1 set) | Damage | \$ 105.50 | \$ 105.50 |
| 1 | Rear spare tyre base (inner cover) | Damage | \$ 655.03 | \$ 655.03 <i>2Vcx</i> |
| 1 | Rear spare tyre bracket | Necessary | \$ 209.95 | \$ 209.95 <i>Rx</i> |
| 1 | Rear spare tyre cover (outer cover) | Damage | \$ 1507.14 | \$ 1507.14 <i>BR ✓</i> |
| | | | \$ 16462.27 | \$ 15548.99 |
| | Discount | 25.0% | \$ 4115.57 | \$ 3887.25 |
| | | | \$ 12346.70 | \$ 11661.74 |
| <u>Special Nett Items</u> | | | | |
| 1 | Front number plate | Damage | \$ 45.00 | \$ 45.00 |
| 1 | Rear windscreen sealant | Necessary | \$ 60.00 | \$ 50.00 |
| 1 | Rear windscreen inner foam tape | Necessary | \$ 65.00 | \$ 65.00 |
| 1 | Rear bumper clip (1 set) | Necessary | \$ 30.00 | \$ 30.00 |
| 1 | Rear number plate | Damage | \$ 45.00 | \$ 45.00 |
| 1 | Rear reverse sensor (1 set) | Damage | \$ 280.00 | \$ 280.00 |
| | | | \$ 525.00 | \$ 515.00 |
| | Spare Parts Total | | \$ 12871.70 | \$ 12176.74 |

Vehicle No: **SLG 3693 B**
 Report No: **TP/ 10-17030/AY / 2017**

LABOUR COST

| S/No | Job Descriptions | Workshop's Estimation | Our Revised Estimation |
|--------------|---|-----------------------|------------------------|
| | Spare Parts Total c/f | \$ 12871.70 | \$ 12176.74 |
| 1 | To remove and refit damage parts, test for proper functioning and focus of headlamps. | \$ 50.00 | \$ 40.00 30 |
| 2 | To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning. | \$ 50.00 | \$ 40.00 30 |
| 3 | To remove and refit inner trims, inner garnishes, to facilitate the repairs. | \$ 100.00 | \$ 80.00 60 |
| 4 | To remove and refit rear bumper sensor. | \$ 100.00 | \$ 80.00 60 |
| 5 | To remove and replace air-con system, refill gas and test for leakages. | \$ 200.00 | \$ 120.00 80. |
| 6 | To remove and refit rear windscreen glass. | \$ 200.00 | \$ 120.00 80 |
| 7 | To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings. | \$ 100.00 | Not Required |
| 8 | To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools. | \$ 1800.00 | \$ 1320.00 1000 9 |
| 9 | To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available. | \$ 2200.00 | \$ 1760.00 1200 |
| 10 | To apply undercoating on the repaired and replaced panels for rust protection. | \$ 200.00 | \$ 120.00 100 80 |
| Total | | \$ 17871.70 | \$ 15856.74 |



Repair days 10 days

Vehicle No: **SLG 3693 B**
Report No: **TP/ 10-17030/AY / 2017**

LABOUR COST

| S/No | Job Descriptions | Workshop's Estimation | Our Revised Estimation |
|------|------------------|-----------------------|------------------------|
|------|------------------|-----------------------|------------------------|

Total c/f \$ 17871.70 \$ 15856.74

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 12700.00

SDLS: TWELVE THOUSAND SEVEN HUNDRED ONLY



Qualified Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|-------------------------------|---|
| FWD SINGAPORE PTE LTD | | Ref : CS3/FWD17019821/Lsbs2-1 | |
| 6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986 | | Date : 01-08-2018 |  |
| | | Code : FWD | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SKS 7359P | Veh. Inspected | SLG 3693B |
| Policy No. | PNPV2017-00002539 | Coverage (\$) | 0.00 |
| Claim No. | 1201700006612 | Excess (\$) | 0.00 |
| Assign From | CLARA LI | Assign Date | 19/07/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA RUSH | c.c | 1495 |
| Engine No. | HIDDEN | Year of Reg. | 2007 |
| Chassis No. | J200E0016066 | Colour | RED |
| Odometer | 152896 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 215/65R16 | KUMHO | 6 mm |
| L/H Front Tyre | 215/65R16 | KUMHO | 6 mm |
| R/H Rear Tyre | 215/65R16 | KUMHO | 6 mm |
| L/H Rear Tyre | 215/65R16 | KUMHO | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 11/10/2017 | Inspection Date | 16/10/2017 |
| Survey held at | V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 8 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3693B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | BONNET | TO REPAIR SEE LABOUR | 1,227.15 | - |
| 1 | BONNET LOCK | TO REPAIR SEE LABOUR | 80.43 | - |
| 1 | BONNET RUBBER | NOT NECESSARY | 13.09 | - |
| 2 | FRONT HEADLAMPS | DAMAGED | 2,579.44 | 2,579.44 |
| 1 | FRONT GRILLE | DAMAGED | 554.64 | 554.64 |
| 1 | FRONT GRILLE LOGO | NECESSARY | 61.83 | 61.83 |
| 1 | FRONT BUMPER | DAMAGED | 1,650.99 | 1,650.99 |
| 1 | FRONT BUMPER REINFORCEMENT | TO REPAIR SEE LABOUR | 469.20 | - |
| 2 | FRONT BUMPER SIDE RETAINERS | DAMAGED | 87.92 | 87.92 |
| 1 | FRONT SUPPORT PANEL | TO REPAIR SEE LABOUR | 687.80 | - |
| 1 | FRONT BRACE PANEL | TO REPAIR SEE LABOUR | 82.77 | - |
| 1 | REAR TAIL DOOR | DAMAGED | 1,602.41 | 1,602.41 |
| 1 | REAR TAIL DOOR INNER BOARD | INTACT | 364.38 | - |
| 1 | REAR TAIL DOOR LOCK | TO REPAIR SEE LABOUR | 422.90 | - |
| 1 | REAR TAIL DOOR RUBBER | NECESSARY | 239.90 | 239.90 |
| 1 | REAR TAIL DOOR 'RUSH' EMBLEM | NECESSARY | 103.82 | 103.82 |
| 2 | REAR TAILLAMPS | DAMAGED | 1,036.66 | 1,036.66 |
| 1 | REAR END PANEL | TO REPAIR SEE LABOUR | 513.51 | - |
| 1 | REAR END PANEL INNER GARNISH | INTACT | 489.71 | - |
| 1 | REAR BUMPER | DAMAGED | 1,524.99 | 1,524.99 |
| 1 | REAR BUMPER N/S REFLECTOR | INTACT | 59.19 | - |
| 1 | REAR BUMPER SIDE RETAINER - N/S | NECESSARY | 44.97 | 44.97 |
| 1 | REAR BUMPER SIDE RETAINER - O/S | NECESSARY | 86.95 | 86.95 |
| 1 | SET REAR NUMBER PLATE LAMP | DAMAGED | 105.50 | 105.50 |
| 1 | REAR SPARE TYRE BASE (INNER COVER) | SERVICEABLE | 655.03 | - |
| 1 | REAR SPARE TYRE BRACKET | TO REPAIR SEE LABOUR | 209.95 | - |

Report Ref No. CS3/FWD17019821/Lsbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| 1 | REAR SPARE TYRE COVER (OUTER COVER) | BROKEN | 1,507.14 | 1,035.70 |
| | LESS 25% DISCOUNT | | -4,115.57 | -2,678.93 |
| | | | 12,346.70 | 8,036.79 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT NUMBER PLATE (SN) | DAMAGED | 45.00 | 45.00 |
| 1 | REAR WINDSCREEN SEALANT (SN) | NECESSARY | 60.00 | 50.00 |
| 1 | REAR WINDSCREEN INNER FOAM TAPE (SN) | NECESSARY | 65.00 | 65.00 |
| 1 | SET REAR BUMPER CLIP (SN) | NECESSARY | 30.00 | 30.00 |
| 1 | REAR NUMBER PLATE (SN) | DAMAGED | 45.00 | 45.00 |
| 1 | SET REAR REVERSE SENSOR (SN) | DAMAGED | 280.00 | 280.00 |
| | | | 525.00 | 515.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS. | | 50.00 | 30.00 |
| | TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING. | | 50.00 | 30.00 |
| | TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS. | | 100.00 | 60.00 |
| | TO REMOVE AND REFIT REAR BUMPER SENSOR. | | 100.00 | 60.00 |
| | TO REMOVE AND REPLACE AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGE. | | 200.00 | 80.00 |
| | TO REMOVE AND REFIT REAR WINDSCREEN GLASS. | | 200.00 | 80.00 |
| | TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXGHAUST SILENCER AND MOUNTINGS. | NOT NECESSARY | 100.00 | - |
| | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF BONNET, BONNET LOCK, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL, FRONT BRACE PANEL, REAR TAIL DOOR LOCK, REAR END PANEL AND REAR SPARE TYRE BRACKET. | | 1,800.00 | 1,000.00 |

Report Ref No. CS3/FWD17019821/Lsbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|---|-----------|---------------------------|-------------------|
| | TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE. | | 2,200.00 | 1,200.00 |
| | TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION. | | 200.00 | 100.00 |
| | | | 5,000.00 | 2,640.00 |
| GRAND TOTAL | | | 17,871.70 | 11,191.79 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 8,800.00 |

Report Ref No. CS3/FWD17019821/Lsbs2-1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.