

ASS. REC. BY:

REF:

CG/C7218013137/Kfbn2

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

Name (Person):

Irene Tay

of

C71

Date/Time:

19072018 1:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDX 2161G

Insured:

SLD 4236Y

at Workshop m/s

Optima Werkz

Tel:

6484 9919

of

9A Serangoun North Ave 5

Policy No:

DMPCSN 31159 331802

Claim No:

SNM18703400C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09072018

CA / REV / REP. / REV 24 HRS wpi

23.072018 @ 2 pm

H.O.D. Endorsement:

Date/Time:

19072018 1:47pm

Person Contacted:

Riza

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SDX 2161G - CGC/ALH15006997/m1pc332

Def: 1-10415

SLD 4236Y - X

20/10-

8 7722.68 emal (Red: 2090-70: 21%)

(08/11/13) wef

REF: CFI

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 23/07/18

Estimated Cost: _____

On: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDX 2161G

at Workshop m/s Optima Werkz

of 9A Serangoon North Ave S

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 2pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lwp}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDX 2161G Yr Regn: 07, 17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Mark X c.c. 2499

Colour: 2. Black A/C: Insured / Std / NI / NA

Sp. Reading: 249 T/Radio: Insured / Std / NI / NA

Eng/No: 27121

C/No: GRX13-06091354

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/40R19

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 9/7/18

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/7 File pass to Cc machine

RECEIVED 01 NOV 2018

Date/Time, File Pass to?

1) 11/11 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / B.I. (\$) 7722.68

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2018		19 Jul 2018 13:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NOR SYAFIQ BIN SUPINGI, ID: S8441895A		
Main Claimant:	LIM REN WEI, ID: S8318078A		
Vehicle Reg. No.:	SDX2161G	Date of Loss:	09/07/2018 18:00 - :59
Claim Type:	TP / SNM18D03400C02	Policy/Cover Note No.:	DMPCSN3059331802 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD4236Y	Policy No. (Claimant):	CN840930
		Excess:	S\$0.00
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/07/2018]		
Driver/Custodian (Insured):	NOR SYAFIQ BIN SUPINGI (33 / Male), NRIC: S8441895A		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Kenneth Kong (LKKAUTO)

From: puitheng.chong@ow.sg
Sent: Saturday, 20 October, 2018 2:01 PM
To: Kenneth Kong (LKKAUTO)
Cc: 'Winson Ng'; azman@ow.sg; lily.loi@ow.sg; 'Sharon'; 'Jason Ang'
Subject: RE: TP CLAIMS - SDX2161G TOYOTA MARK X DOA 9 JULY 2018

Hi Kenneth,

Confirmed part by part @ \$7,722.68 & 3 days to close file.

Thank you very much.

Best regards,
Pei Ting (Ms)
Motor Claims Dept.

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 |
Branch: 9A Serangoon North Ave 5 Singapore 554500 | Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011 |
Branch: 551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 |

www.ow.sg

www.facebook.com/optimawerkz

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Friday, 19 October 2018 9:25 AM
To: puitheng.chong@ow.sg
Subject: RE: TP CLAIMS - SDX2161G TOYOTA MARK X DOA 9 JULY 2018

Already email \$7722.68 to you.

From: puitheng.chong@ow.sg [mailto:puitheng.chong@ow.sg]
Sent: Saturday, 13 October, 2018 1:33 PM
To: Kenneth Kong (LKKAUTO)
Subject: RE: TP CLAIMS - SDX2161G TOYOTA MARK X DOA 9 JULY 2018

Hi Kenneth,

Any status of the finalise.

Our calculation as per below:

S/P - \$7,196.18

L - \$600.00

Part by part - \$7,796.18 & 3 days

Thank you very much.

Best regards,
Pei Ting (Ms)
Motor Claims Dept.

OPTIMA WERKZ PTE LTD

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8078A

Vehicle Details

Vehicle No.:	SDX2161G
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	MARK X 250G S-PACKAGE G'S A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	4GR1035995
Chassis No.:	GRX1306091354
Maximum Power Output:	149.0 kW (199 bhp)
Open Market Value:	\$34,103.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$39,745.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2027
PARF Rebate Amount:	\$29,808.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$45,121.00
Total Rebate Amount:	\$74,929.00

The information contained herein is correct as at 11 Jul 2018

OK

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 13 JULY 2018

Third Party Insurer:

CHINA TAIPING

Vehicle No: SDX2161G

Third Party Veh No:

SLD4236Y

Model: TOYOTA MARK X 250G

Date of Accident:

9 JULY 2018

Chassis: GRX1306091354

NOT Authored
Resurvey by paint

87722-68

3 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH → 3710-2		mgcm \$3,730.00
1	FRONT HEADLAMP GARNISH LH		Sm \$50.00
1	FRONT BUMPER → 3580-40		Bm \$3,600.00
2	FRONT BUMPER SIDE RETAINER LH/RH	N/S Div \$90.00	\$180.00
1	FRONT BUMPER INNER SPONGE		cm \$360.00
1	FRONT BUMPER TOP CHROME MOULDING		mgcm \$262.50
1	FRONT BUMPER TOW HOOK COVER MOULDING		cm \$60.00
2	FRONT BUMPER LED LAMP CHROME GARNISH LH/RH	mgcm \$320.00	N/S Red \$640.00
1	FRONT BUMPER LOWER CENTER GRILLE		Re \$750.00
1	FRONT BUMPER LOWER CENTER GRILLE TOW HOOK COVER		Re \$44.00
1	FRONT BUMPER LOWER BRACKET LH		R \$48.00
SUB TOTAL			\$9,724.50
Less 25%			-\$2,431.13
PARTS TOTAL			\$7,293.38

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	FRONT PARKING SENSOR		Sm \$250.00
1	FRONT BUMPER LOWER LIP CARBON FIBRE		Sm \$880.00
S/N TOTAL			\$1,130.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

2501
\$750.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

2801
\$500.00

TO CHECK WIRING WITH WATER LEAKAGE TEST

201
\$60.00

TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR

501
\$80.00

LABOUR TOTAL \$1,390.00

PUI THENG

TOTAL \$9,813.38

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013137/KTBN2

Date: 02/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3059331802
Claimant Vehicle No :	SDX2161G	Insured Vehicle No :	SLD4236Y
Date of Loss:	09/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03400C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDX2161G	Engine No:	4GR1035995
Make & Model:	TOYOTA MARK X, 2.5 (A)	Chassis No:	GRX1306091354
Reg. Date:	21/07/2017 (Man. Year: 2015)	Odometer:	27121 km
Colour:	Metallic Black		
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40R19	Rear Tyre Size:	235/40R19
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,423.37	7,122.67	1,300.70	15.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	600.00	790.00	56.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,813.37	7,722.67	2,090.70	21.30
+ GST 7.00/7.00% (S\$)	686.94	540.59	146.35	21.30
Nett Amount (S\$)	10,500.31	8,263.26	2,237.05	21.30

INSPECTION

Date of Assignment:	19/07/2018	Inspected At:	Optima Werkz Pte Ltd (HQ)
Date Inspected:	23/07/2018		9A Serangoon North Ave 5
			Singapore 554500
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents- finalise confirm amount: \$7722.68

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2018)
Parts:	143	TOYOTA MARK X 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDX2161G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Mtg Cracked	3,730.00 FL	*3,710.00 FL
2	1		*FRONT HEADLAMP GARNISH LH	Serviceable	50.00 FL	*- FL
3	1		*FRONT BUMPER	Buckled	3,600.00 FL	*3,580.40 FL
4	1		*FRONT BUMPER SIDE RETAINER LH/RH	N/s Distorted	180.00 FL	*90.00 FL
5	1		*FRONT BUMPER INNER SPONGE	Cracked	360.00 FL	*360.00 FL
6	1		*FRONT BUMPER TOP CHROME MOULDING	Mtg Cracked	262.50 FL	*262.50 FL
7	1		*FRONT BUMPER TOW HOOK COVER MOULDING	Cracked	60.00 FL	*60.00 FL
8	2		*FRONT BUMPER LED LAMP CHROME GARNISH LH/RH	N/s Dented/O/s Cracked	640.00 FL	*640.00 FL
9	1		*FRONT BUMPER LOWER CENTER GRILLE	Dented	750.00 FL	*750.00 FL
10	1		*FRONT BUMPER LOWER CENTER GRILLE TOW HOOK COVER	Dented	44.00 FL	*44.00 FL
11	1		*FRONT BUMPER LOWER BRACKET LH	Repair	48.00 FL	*- FL
12	1		*FRONT PARKING SENSOR	Serviceable	250.00 FS	*- FS
13	1		*FRONT BUMPER LOWER LIP CARBON FIBRE	Serviceable	880.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,854.50	9,496.90
- List Item Discount on L Items 25.00/25.00% (S\$)	2,431.13	2,374.23
Total Parts (S\$)	8,423.37	7,122.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	750.00	250.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	500.00	280.00
3	TO CHECK WIRING WITH WATER LEAKAGE TEST	New	60.00	20.00
4	TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (S\$)			1,390.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >