

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$S

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
7/7/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
30/7/18	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

Reject Case

By (staff): SHC

Approved by: YCU

Date: 10-05-19

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$S	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% 0	(Agreed / Assessed) BOLA S/N No.: NIL	
Repair Cost:	\$S	TP: WAS CHARGED FOR INCONSIDERATE DRIVING.	
Loss of Rental (LOR):	\$S	(days)	
Loss of Use (LOU):	\$S	(\$ x days)	
Loss of Income (LOI):	\$S	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]
GIA/LTA Search	\$S		
Medical:	\$S		
Disbursement:	\$S	(e.g. Tow/ Independent)	
Legal Cost	\$S		
Total:	\$S	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$S	Name 1:	
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

ASS. REC. BY:

REF: TU /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5250B Yr Regn: 02, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Pengait Latitude c.c. 1995Colour: M. White / Red A/C: Insured / Std / NI / NASp. Reading: 475598 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1ABL15AUC 276863Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16R: King KongBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO orFront 2 King Kong Rear 2R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 18/7/18 D.O.I. 18/7/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S / R / L / R

The UIC / Chassis frame & Body Structure affected due to collision. ✓

Date / Time Action / Instruction

18/7 File pass to Catherine45.1 + 35.450 (RED: 67.068.98 65% EXCLUDE GREY TMM + 34.831.70

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fixes

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5250B**AAD1807-155***Not Authorized*
L/Sing S

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5250B

VF1ABL15AUC276863

RENAULT

LATITUDE

16.7.2018

III**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bz</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>CM</i> 181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>MIV</i> 394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>DIT</i> 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> CM 123.88	X
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i> L 150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>DIT</i> 123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i> 472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>CM</i> 266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>CM</i> 207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21	X
12	1	BUMPER BEAM FRT	\$	<i>Bz</i> 914.08	✓
13	1	TOW COVER FRT	\$	<i>Sm</i> 28.61	X
14	1	RADIATOR GRILLE	\$	<i>MIV</i> 1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>MIV</i> 225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	<i>Bz</i> 1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Bz</i> 89.79	✓
19	1	FRONT BRACE PANEL	\$	<i>Bz</i> 177.22	✓
20	1	HORN	\$	<i>Sm</i> 314.17	X
21	1	HORN BRACKET	\$	<i>R</i> 40.45	X
22	1	HEADLAMP LH	\$	<i>CM</i> 1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>Sm</i> 928.29	✓
22	1	HEADLAMP RH	\$	<i>MIV</i> 1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>Sm</i> 928.29	X
22	1	HEADLAMP PANEL FRT LH	\$	<i>Bz</i> 152.15	✓
25	1	HEADLAMP PANEL FRT RH	\$	<i>DIT</i> 152.15	✓
26	1	BONNET	\$	<i>Bz</i> 1,941.63	✓

Trans-cab Auto Services Pte Ltd

AAD1807-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5250B

27	1	BONNET INSULATOR	\$	Sm	405.73	X
28	1	BONNET STRUT LH	\$	Pu	88.61	—
29	1	BONNET STRUT RH	\$	Pu	88.61	—
30	1	BONNET HINGE LH	\$	B	348.31	—
31	1	BONNET HINGE RH	\$	B	348.31	—
32	1	BONNET LOCK	\$	B	305.48	—
33	1	BONNET CABLE	\$	Sm	119.19	X
34	1	BONNET CABLE COVER	\$	Sm	161.03	X
35	1	BONNET SEAL OUTER	\$	Sm	92.36	X
36	1	BONNET SEAL INNER	\$	Sm	157.28	X
37	1	FENDER PANEL FRT LH	\$	B	783.83	—
38	1	FENDER PANEL FRT RH	\$	B	783.83	—
39	1	WHEELARCH FRT LH	\$	CM	278.84	—
40	1	WHEELARCH FRT RH	\$	CM	278.84	—
41	1	FENDER BRACKET LOWER LH	\$	R	15.79	X
42	1	FENDER BRACKET LOWER RH	\$	R	15.79	X
43	1	FENDER INSULATOR LH	\$	Sm	130.84	X
44	1	FENDER INSULATOR RH	\$	Sm	130.84	X
45	1	WIPER RESERVOIR	\$		348.25	?
46	1	WIPER RESERVOIR NECK	\$		136.11	?
47	1	WIPER RESERVOIR MOTOR	\$		270.06	?
48	1	AIR CLEANER LOWER	\$	CM	271.26	—
49	1	AIR CLEANER HOSE	\$		76.14	?
55	1	ENGINE TOP COVER 2.0	\$	Sm	555.12	X
56	1	ENGINE OIL SUMP	\$		484.67	?
58	1	BASE BATTERY TRAY	\$		363.40	?
59	1	AIR CLEANER BOX	\$		464.20	?
60	1	TURBO DUCT	\$		1,027.80	?
61	1	A/C HEATER VALVE	\$		484.50	?
63	1	SUBFRAME OUTER FRT	\$		2,652.45	?
64	1	SUBFRAME BRACKET OUTER LH	\$		92.36	?
65	1	SUBFRAME BRACKET OUTER RH	\$		92.36	?
66	1	ENGINE UNDERTRAY	\$		564.98	?
67	1	A/C CONDENSER	\$	Pu	2,020.37	—
68	1	A/C CONDENSER GARNISH LH UPPER	\$		39.67	?
69	1	A/C CONDENSER GARNISH RH UPPER	\$		39.67	?
70	1	A/C CONDENSER GARNISH LH	\$		58.81	?
71	1	A/C CONDENSER GARNISH RH	\$		59.60	?

Trans-cab Auto Services Pte Ltd**AAD1807-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5250B

72	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	<i>Sm</i>	208.39	X
73	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	<i>Sm</i>	658.72	X
74	1	A/C PIPE COMPRESSOR	\$	<i>Sm</i>	334.29	X
75	1	A/C PIPE	\$	<i>Sm</i>	658.72	X
76	1	A/C COMRPESSOR	\$	<i>Sm</i>	2,684.61	X
77	1	AIR COOLER	\$	<i>Sm</i>	792.60	X
78	1	AIR INTERCOOLER HOSE (LONG)	\$		1,014.13	?
79	1	AIR INTERCOOLER HOSE (Short)	\$		375.14	?
80	1	TRANSMISSION COOLER	\$		1,219.30	?
81	1	TRANSMISSION COOLER PAD	\$		17.96	?
82	1	RADIATOR	\$	<i>Bt</i>	1,202.20	✓
83	2	RADIATOR STUD UPPER	\$	<i>Sm</i>	14.41	X
84	2	RADIATOR BUSH UPPER	\$	<i>Sm</i>	50.12	X
85	2	RADIATOR MTG LOWER	\$	<i>Sm</i>	55.85	X
86	1	RADAITOR FAN COWLING	\$		820.54	?
87	1	RADIATOR FAN MOTOR LH	\$		967.36	?
88	1	RADIATOR FAN MOTOR RH	\$		1,479.46	?
89	1	RADIATOR TANK	\$	<i>Sm</i>	324.62	X
90	1	RADIATOR HOSE UPPER	\$		240.56	?
91	1	RADIATOR HOSE LOWER	\$		491.18	?
92	1	RADIATOR TANK HOSE	\$		61.18	?
93	1	WINDSCREEN FRT	\$	<i>cm</i>	1,364.06	✓
94	1	AUTO COMPUTER	\$	<i>cm</i>	5,032.17	✓
95	1	INJECTION COMPUTER	\$	<i>cm</i>	4,706.30	✓
96	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$		5,154.52	?
97	1	STEERING PUMP ELECTRIC	\$		2,306.90	?
98	1	STEERING PINION RACK	\$		4,413.11	?
99	1	ENGINE HARNESS	\$		4,084.54	?
100	1	SEATBELT LH L70Y	\$	<i>Tn</i>	2,937.80	✓
101	1	SEATBELT RH L70Y	\$		2,925.37	?
102	1	SEATBELT BUCKLE LH L70Y	\$		984.13	?
103	1	SEATBELT BUCKLE RH L70Y	\$		949.80	?
104	1	PASSENGER AIRBAG L70Y	\$	<i>Arm</i>	3,412.40	✓
105	1	STEERING AIRBAG L70Y	\$	<i>~</i>	2,525.75	✓
106	1	AIRBAG COMPUTER L70Y	\$	<i>ne</i>	1,259.82	✓
107	1	AIRBAG SENSOR L70Y	\$	<i>ne</i>	724.63	✓
108	1	AIRBAG SENSOR L70Y	\$	<i>ne</i>	289.30	✓

Trans-cab Auto Services Pte Ltd

AAD1807-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5250B

109	1	LOWER ARM RH L70Y	\$	685.76	?
110	1	KUNCKLE ARM RH L70Y	\$	<i>R</i> 846.98	✓
111	1	KUNCKLE HUB+BEARING LH/RH L70Y	\$	<i>R</i> 497.69	✓
112	1	KUNCKLE ARM SHIELD RH L70Y	\$	131.43	?
113	1	KUNCKLE ARM PLATE RH L70Y	\$	174.05	?
114	1	ABSORBER FRT RH L70Y	\$	360.54	?
115	1	STABILIZER BAR FRT L70Y	\$	604.65	?
116	2	STABILIZER LINK FRT L70Y	\$	117.22	?

TOTAL	\$	90,273.87
10%	\$	9,027.39
	\$	81,246.48

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i> 52.00	✓
2	1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i> 12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i> 10.50	X
7	1	TOW COVER FRT	\$	<i>na</i> 14.50	X
8	1SET	RADAIOR GRILLE SCREW	\$	<i>na</i> 16.00	X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	✓
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00	X
21	1	Windscreen moulding	\$	<i>na</i> 100.00	✓
22	1SET	Front licence plate with holder	\$	<i>R</i> 80.00	255a
22	1	FRONT RIGHT TYRE	\$	<i>R</i> 330.00	602a
22	1	FRONT RIGHT TYRE RIM	\$	<i>R</i> 380.00	✓

TOTAL	\$	1,272.50
--------------	-----------	-----------------

TOTAL PARTS	\$	82,518.98
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd**AAD1807-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5250B

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	9,000.00 ¹⁶⁰⁰
Towing Fees.	\$	120.00 ⁵⁰
To apply paint protection system (PPS) maintain and enhancement	\$	^{na} 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 ¹⁵⁴⁰
To rust-proofing of the affected areas.	\$	170.00 ¹⁵⁰
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	^{na} 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 ⁶⁰
To transfer of tire, rim and on wheel balancing.	\$	170.00 ²⁰
To Check Electrical Lighting Concerned.	\$	170.00 ³⁰
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00
To lift-up engine with gear box and refit.	\$	440.00 ³⁰⁰
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 ⁸⁰

Trans-cab Auto Services Pte Ltd**AAD1807-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5250B

To remove and refit air bag system and reset.	\$	480.00 <i>200</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>100</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>50</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>50</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	20,000.00
--------------	-----------	------------------

Over All Total	\$	102,518.98
-----------------------	-----------	-------------------

Repair Days (LUMP SUM)**30 DAYS***21 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Received Message

This mail is associated with :

***SHC5250B (MCT18070487)**
[SHC3702C]

TP

TRANS-CAB SERVICES PTE LTD
Jul 16 2018 5:00PM

Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 14/11/2018 11:55 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SHC5250B - Claim Handler: Sherini Pillai

Approved:0.00:Pls reject

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 8 May 2019 5:43 PM
To: claims@transcab.com.sg; Ng Wai Yin; jasminetan@transcab.com.sg
Subject: Your Ref: AAD1807-155, ACCIDENT INVOLVING SHC 5250B AND SHC 3702C ON 16/07/2018
Attachments: OI SKETCH PLAN.pdf; OI PIR.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: AAD1807-155

Our Ref: CC3/III18013141/Kea3

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SHC 5250B AND SHC 3702C ON 16/07/2018

We attached here with a copy of our insured's accident statement and our insured police investigation result for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client was charged by the traffic police for Inconsiderate Driving.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 Edit Reg		18 Jul 2018 00:00 Edit Adj Rpt	\$335,450.00 Edit Estimates	\$335,450.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5250B	Date of Loss:	16/07/2018 17:00 - :59 [52 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18070487	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC3702C	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (14/11/2018): Alert - Adj Mandate Approved (\$0.00) - SHC5250B - Claim Handler: Sherini Pillai
- III_SG (26/07/2018): Alert - Adj Mandate Maintained - SHC5250B - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHC5250B (MCT18070487)**
[SHC3702C]
TP
TRANS-CAB SERVICES PTE LTD
Jul 16 2018 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 17:44	General View	 Load JPG	☒
2	08/05/19 17:44	General View	 Load JPG	☒
3	08/05/19 17:44	General View	 Load JPG	☒
4	08/05/19 17:44	General View	 Load JPG	☒
5	08/05/19 17:44	General View	 Load JPG	☒
6	08/05/19 17:44	General View	 Load JPG	☒
7	08/05/19 17:44	General View	 Load JPG	☒
8	08/05/19 17:44	General View	 Load JPG	☒
9	08/05/19 17:44	General View	 Load JPG	☒
10	08/05/19 17:44	General View	 Load JPG	☒
11	08/05/19 17:44	General View	 Load JPG	☒
12	08/05/19 17:44	General View	 Load JPG	☒
13	08/05/19 17:44	General View	 Load JPG	☒
14	08/05/19 17:44	General View	 Load JPG	☒
15	08/05/19 17:44	General View	 Load JPG	☒
16	08/05/19 17:44	General View	 Load JPG	☒
17	08/05/19 17:44	General View	 Load JPG	☒
18	08/05/19 17:44	General View	 Load JPG	☒
19	08/05/19 17:44	General View	 Load JPG	☒
20	08/05/19 17:44	General View	 Load JPG	☒
21	08/05/19 17:44	General View	 Load JPG	☒
22	08/05/19 17:44	General View	 Load JPG	☒
23	08/05/19 17:44	General View	 Load JPG	☒
24	08/05/19 17:44	General View	 Load JPG	☒
25	08/05/19 17:44	General View	 Load JPG	☒
26	08/05/19 17:44	General View	 Load JPG	☒
27	08/05/19 17:44	General View	 Load JPG	☒
28	08/05/19 17:44	General View	 Load JPG	☒
29	08/05/19 17:44	General View	 Load JPG	☒
30	08/05/19 17:44	General View	 Load JPG	☒
31	08/05/19 17:44	General View	 Load JPG	☒
32	08/05/19 17:44	General View	 Load JPG	☒
33	08/05/19 17:44	General View	 Load JPG	☒
34	08/05/19 17:44	General View	 Load JPG	☒
35	08/05/19 17:44	General View	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	08/05/19 17:44	General View	1 Load JPG	✓
37	08/05/19 17:44	General View	1 Load JPG	✓
38	08/05/19 17:44	General View	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/07/18 09:01	TP ESTIMATE - MARKED	1 Load PDF	
2	20/07/18 09:01	TP GIA REPORT	1 Load PDF	
3	14/11/18 11:33	OI PIR	1 Load PDF	
4	08/05/19 17:43	EMAIL WSP TO REJECT TP CLAIM	1 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/07/18 08:47	Singapore Accident Statement	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18013141/KEA3S2
Date: 23/07/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No :	SHC5250B	Insured Vehicle No :	SHC3702C	
Date of Loss:	16/07/2018	Nature of Claim:	TP	Claim No: MCT18070487

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5250B		Engine No:	M9R8839C000915
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)		Chassis No:	VF1ABL15AUC276863
Reg. Date:	19/02/2014 (Man. Year: 2013)		Odometer:	475598 km
Colour:	Metallic White/Red			
Engine Capacity:	1995 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Linglong 8 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	82,518.98	39,863.53	42,655.45	51.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,000.00	4,460.00	15,540.00	77.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	102,518.98	44,323.53	58,195.45	56.77
Approved Total (Overridden) (S\$)		35,450.00		
(S\$)	102,518.98	35,450.00	67,068.98	65.42
+ GST 7.00/7.00% (S\$)	7,176.33	2,481.50	4,694.83	65.42
Nett Amount (S\$)	109,695.31	37,931.50	71,763.81	65.42

INSPECTION

Date of Assignment:	18/07/2018		Trans-cab Auto Services Pte Ltd
Date Inspected:	18/07/2018	Inspected At:	No 2 Ang Mo Kio Street 63
Estimated Period of Repair:	21.0 days		Singapore 569111

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

7/23/2019

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

7/23/2019

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$33,150.47 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2019)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5250B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Bent	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Cracked	181.75 FL	*181.75 FL
3	1		*BUMPER ABSORBER FRT	Missing	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Cracked	150.77 FL	*150.77 FL
7	1		*BUMPER SUPPORT FRT	Distorted	123.88 FL	*123.88 FL
8	1		*BUMPER UNDERTRAY FRT	Cracked	472.83 FL	*472.83 FL
9	1		*BUMPER GRILLE LOWER FRT	Crumpled	266.80 FL	*266.80 FL
10	1		*BUMPER FOG LAMP GRILLE LH	Damaged	207.21 FL	*207.21 FL
11	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
13	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
14	1		*RADIATOR GRILLE	Missing	1,707.78 FL	*1,707.78 FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Missing	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME	Broken	1,353.75 FL	*1,353.75 FL
17	1		*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
18	1		*FRAME FULL SUPPORT BRACKET	Bent	89.79 FL	*89.79 FL
19	1		*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
20	1		*HORN	Serviceable	314.17 FL	*- FL
21	1		*HORN BRACKET	Repair	40.45 FL	*- FL
22	1		*HEADLAMP LH	Cracked	1,184.43 FL	*1,184.43 FL
23	1		*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
24	1		*HEADLAMP RH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
25	1		*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
26	1		*HEADLAMP PANEL FRT LH	Bent	152.15 FL	*152.15 FL
27	1		*HEADLAMP PANEL FRT RH	Distorted	152.15 FL	*152.15 FL
28	1		*BONNET	Bent	1,941.63 FL	*1,941.63 FL
29	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
30	1		*BONNET STRUT LH	Punctured	88.61 FL	*88.61 FL
31	1		*BONNET STRUT RH	Punctured	88.61 FL	*88.61 FL
32	1		*BONNET HINGE LH	Bent	348.31 FL	*348.31 FL
33	1		*BONNET HINGE RH	Bent	348.31 FL	*348.31 FL
34	1		*BONNET LOCK	Bent	305.48 FL	*305.48 FL
35	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
36	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
37	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
38	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
39	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
40	1		*FENDER PANEL FRT RH	Buckled	783.83 FL	*783.83 FL
41	1		*WHEELARCH FRT LH	Cracked	278.84 FL	*278.84 FL
42	1		*WHEELARCH FRT RH	Cracked	278.84 FL	*278.84 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FENDER BRACKET LOWER LH	Repair	15.79 FL	*- FL
44	1		*FENDER BRACKET LOWER RH	Repair	15.79 FL	*- FL
45	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
46	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
47	1		*WIPER RESERVOIR	*Check	348.25 FL	*- FL
48	1		*WIPER RESERVOIR NECK	*Check	136.11 FL	*- FL
49	1		*WIPER RESERVOIR MOTOR	*Check	270.06 FL	*- FL
50	1		*AIR CLEANER LOWER	Cracked	271.26 FL	*271.26 FL
51	1		*AIR CLEANER HOSE	*Check	76.14 FL	*- FL
52	1		*ENGINE TOP COVER 2.0	Serviceable	555.12 FL	*- FL
53	1		*ENGINE OIL SUMP	*Check	484.67 FL	*- FL
54	1		*BASE BATTERY TRAY	*Check	363.40 FL	*- FL
55	1		*AIR CLEANER BOX	*Check	464.20 FL	*- FL
56	1		*TURBO DUCT	*Check	1,027.80 FL	*- FL
57	1		*A/C HEAT VALVE	*Check	484.50 FL	*- FL
58	1		*SUBFRAME OUTER FRT	*Check	2,652.45 FL	*- FL
59	1		*SUBFRAME BRACKET OUTER LH	*Check	92.36 FL	*- FL
60	1		*SUBFRAME BRACKET OUTER RH	*Check	92.36 FL	*- FL
61	1		*ENGINE UNDERTRAY	*Check	564.98 FL	*- FL
62	1		*A/C CONDENSER	Punctured	2,020.37 FL	*2,020.37 FL
63	1		*A/C CONDENSER GARNISH LH UPPER	*Check	39.67 FL	*- FL
64	1		*A/C CONDENSER GARNISH RH UPPER	*Check	39.67 FL	*- FL
65	1		*A/C CONDENSER GARNISH LH	*Check	58.81 FL	*- FL
66	1		*A/C CONDENSER GARNISH RH	*Check	59.60 FL	*- FL
67	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
68	1		*A/C PIPE CONDENSER TO EXPANSION VALVE	Serviceable	658.72 FL	*- FL
69	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
70	1		*A/C PIPE	Serviceable	658.72 FL	*- FL
71	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
72	1		*AIR COOLER	Serviceable	792.60 FL	*- FL
73	1		*AIR INTERCOOLER HOSE (LONG)	*Check	1,014.13 FL	*- FL
74	1		*AIR INTERCOOLER HOSE (SHORT)	*Check	375.14 FL	*- FL
75	1		*TRANSMISSION COOLER	*Check	1,219.30 FL	*- FL
76	1		*TRANSMISSION COOLER PAD	*Check	17.96 FL	*- FL
77	1		*RADIATOR	Bent	1,202.20 FL	*1,202.20 FL
78	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
79	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
80	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
81	1		*RADIATOR FAN COWLING	*Check	820.54 FL	*- FL
82	1		*RADIATOR FAN MOTOR LH	*Check	967.36 FL	*- FL
83	1		*RADIATOR FAN MOTOR RH	*Check	1,479.46 FL	*- FL
84	1		*RADIATOR TANK	Serviceable	324.62 FL	*- FL
85	1		*RADIATOR HOSE UPPER	*Check	240.56 FL	*- FL
86	1		*RADIATOR HOSE LOWER	*Check	491.18 FL	*- FL
87	1		*RADIATOR TANK HOSE	*Check	61.18 FL	*- FL
88	1		*WINDSCREEN FRT	Cracked	1,364.06 FL	*1,364.06 FL
89	1		*AUTO COMPUTER	Cracked	5,032.17 FL	*5,032.17 FL
90	1		*INJECTION COMPUTER	Cracked	4,706.30 FL	*4,706.30 FL
91	1		*RHD HYDRAULIC POWER (ROCK & PINION)	*Check	5,154.52 FL	*- FL
92	1		*STEERING PUMP ELECTRIC	*Check	2,306.90 FL	*- FL
93	1		*STEERING PINION RACK	*Check	4,413.11 FL	*- FL
94	1		*ENGINE HARNESS	*Check	4,084.54 FL	*- FL
95	1		*SEATBELT LH L70Y	Jammed	2,937.80 FL	*2,937.80 FL
96	1		*SEATBELT RH L70Y	*Check	2,925.37 FL	*- FL
97	1		*SEATBELT BUCKLE LH L70Y	*Check	984.13 FL	*- FL
98	1		*SEATBELT BUCKLE RH L70Y	*Check	949.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	1		*PASSENGER AIRBAG L70Y	Burst	3,412.40 FL	*3,412.40 FL
100	1		*STEERING AIRBAG L70Y	Burst	2,525.75 FL	*2,525.75 FL
101	1		*AIRBAG COMPUTER L70Y	Necessary	1,259.82 FL	*1,259.82 FL
102	1		*AIRBAG SENSOR L70Y	Necessary	724.63 FL	*724.63 FL
103	1		*AIRBAG SENSOR L70Y	Necessary	289.30 FL	*289.30 FL
104	1		*LOWER ARM RH L70Y	*Check	685.76 FL	*- FL
105	1		*KNUCKLE ARM RH L70Y	Bent	846.98 FL	*846.98 FL
106	1		*KNUCKLE HUB+BEARING LH/RH L70Y	Bent	497.69 FL	*497.69 FL
107	1		*KNUCKLE ARM SHIELD RH L70Y	*Check	131.43 FL	*- FL
108	1		*KNUCKLE ARM PLATE RH L70Y	*Check	174.05 FL	*- FL
109	1		*ABSORBER FRT RH L70Y	*Check	360.54 FL	*- FL
110	1		*STABILIZER BAR FRT L70Y	*Check	604.65 FL	*- FL
111	2		*STABILIZER LINK FRT L70Y	*Check	117.22 FL	*- FL
112	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
113	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
114	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
115	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
116	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
117	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
118	1		*TOW COVER FRT	Not Necessary	14.50 FS	*- FS
119	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
120	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
121	1		*SET FRAME FULL SUPPORT PANEL CLIP	Necessary	70.00 FS	*70.00 FS
122	2		*FRAME FULL SUPPORT PANEL NUT	Serviceable	20.00 FS	*- FS
123	2		*FRAME FULL SUPPORT PANEL STUD	Serviceable	30.00 FS	*- FS
124	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
125	1		*SET FRONT LICENCE PLATE WITH HOLDER	Bent	80.00 FS	*25.00 FS
126	1		*FRONT RIGHT TYRE (60%)	Punctured	330.00 FS	*198.00 FS
127	1		*FRONT RIGHT TYRE RIM	Bent	380.00 FS	*380.00 FS
					Sub Total (\$\$)	91,546.37 44,193.81
					- List Item Discount on L Items 10.00/10.00% (\$\$)	9,027.39 4,330.28
					Total Parts (\$\$)	82,518.98 39,863.53

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	9,000.00	1,600.00
2	TOWING FEES.	New	120.00	50.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	1,540.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	150.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
8	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	20.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	30.00
10	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }	New	380.00	250.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. }	New	380.00	0.00
12	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	New	440.00	300.00
13	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	New	440.00	60.00
14	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	New	480.00	200.00
15	TO DROP DIESEL TANK PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	0.00
16	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	100.00
17	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00
18	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
19	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (\$\$)			20,000.00	4,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >