

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: S7M002OD Date: 28th Aug 2018

Our Ref: CS3/ASM17019695/R1rbe2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower Singapore 068811 (The Motor Claims Department)

Attn: Ruth Chua

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLQ 5754T

INSURED VEHICLE: GQ 414S ACCIDENT DATE: 07/10/2017

We thank you for your instruction on 18/07/2018.

We acknowledge receipt of the following documents:-

- Automobile Inspection Report of SLQ 5754T from M/s Lee Automobile Appraisers Services.
- b) Singapore Accident Statement of Vehicles SLQ 5754T.
- c) Final Repair Bill of SLQ 5754T from Car Laboratories Pte Ltd.
- d) Colour damaged vehicle photographs of SLQ 5754T.

Pre-Repair Inspection Date: 13/10/2017 at M/s Car Laboratories Pte Ltd, No. 1 Bukit Batok Crescent, #04-56 Wcega Plaza, Singapore 658064.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLQ5754T

Make & Model : TOYOTA TANK 1.0G CVT

Year of Registration : 2017

Chassis Number : M900A0025868

Engine Capacity : 996 cc

- We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Workshop Details **General Details Total Rebate Amount** Involving TPVD TOYOTA TANK 1.0G CVT (SLQ5754T) 0 Date of Loss **Nett Loss Amount** 7 October 2017 \$0.00 Time of Loss Assigned Workshop 9.15 LKK AUTO CONSULTANTS PTE LTD (TP) Loss Description Target Date of Completion * GQ414S (INSD) C/W SLQ5754T 17/09/2018 Comment Days of work completion * 61

MESSAGES

CLAIMS

General & Workshop [Details Vehicle & D	river Details Vehicle Condition	Taxes & Ratio Parts & Labou	ır Miscellaneous Summ	ary
Vehicle & Driver Det	tails				
Vehicle Registration#	SLQ5754T		Purchase Date	dd/mm/yyyy	ش
Registration State	SINGAPORE		Registration Date *	14/07/2017	#
Mileage 5119			Age of Vehicle	0	
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	Driver Details		
Manufacturing		2017	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Year		2017	Driver Name	CHEE MING AW	
Make	TPVD TOYOTA	ТОУОТА			
Model	TANK 1.0G CVT	TANK 1.0G CVT	Date of Birth	9 November 1972	dd/mm/yyyy 🋗
Model	1ANK 1.00 CV1	IANK 1.05 CVT	Age	45	
Туре		•	Occupation	Unknown	
Type of Paint			Education		
			Qualification	Other	•
Chassis No		M900A0025868	Driving Experience	27	
Engine No		1KR1750211	Driver License		
Engine Canacity		996	#		
Engine Capacity		770			


CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION			
Sum Insured		0			
Market Value		0			

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Type		•
License Issue Date	28 June 1991	dd/mm/yyyy 🎬
License Expiration Date		dd/mm/yyyy ##
Address	BLK 270 BANGKIT ROAD, 670270, Singapore	
Address type	Personal Correspondence	•
Gender	Male	•
Marital status	Married	•
Identification #	S7271768F	

MESSAGES

CLAIMS





SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
Tax Eligibility & Additional I	Deduction for Parts						
Depr./Bttr%			Salva	ge%			
Discount%	25		Settle	ement%	100		
Paint Labour/Material Ratio							
Paint Labour Ratio	20		Paint	Material Ratio	80		
Cash Loss		Yes	No				
Part Supplied by AXA		Yes	No				

Add	Ар	ргоче	Deny	Submit All												
	ЕПП	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOV
j	,	1	1			FRONT WINDSCREEN GLASS			Cracked	3552.5		25		2664.38	Reviewing	ı
ì	,	2	1			FRONT WINDSCREEN GLASS MOULDING			Damaged	178		25		133.5	Reviewing	ŵ
)	,	3	1			FRONT DOOR			Cut	2573.5		25		1930.13	Reviewing	ŵ
j	,	4	1			FRONT DOOR OUTER HANDLE			Bent	195		25		146.25	Reviewing	ŵ
)	,	5	1			FRONT DOOR WINDOW CHANNEL			Serviceable	0	0	0	0	0	Deny	ŵ
)	,	6	1			FRONT DOOR OUTER KEY LOCK			Damaged	105		25		78,75	Reviewing	1111
1	,	7	1			FRONT DOOR RUBBER			Damaged	275		25		206.25	Reviewing	d
)	,	8	1			FRONT DOOR INNER LOCK			Bent	498		25		373.5	Reviewing	ŵ
)	,	9	1			FRONT DOOR WINDOW GEAR			Bent	186		25		139,5	Reviewing	Ħ
)	,	10	1			FRONT DOOR WINDOW GEAR MOTOR			Serviceable	0	0	0	0	0	Deny	ŵ
1	,	11	1			CENTRE DOOR PILLAR			Repair	0	0	0	0	0	Deny	<u> </u>
	,	12	1			REAR SLIDING			Cut	2573.5		25		1930.13	Reviewing	ŵ

	EDIT	SR NO	QUAN	MATERIAL SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	,	13	1		REAR SLIDING DOOR RUBBER			Damaged	324		25		243	Reviewing	ŵ
D	,	14	1		REAR SLIDING DOOR INNER LOCK			Bent	498		25		373.5	Reviewing	â
	,	15	1		REAR SLIDING DOOR OUTER HANDLE			Cracked	195		25		146.25	Reviewing	m
	,	16	1		REAR SLIDING DOOR HINGE- LOWER			Bent	98		25		73.5	Reviewing	â
В	,	17	1		REAR SLIDING DOOR WINDOW GEAR MOTOR			Serviceable	0	0	0	0	0	Deny	m
	,	18	1		REAR SLIDING DOOR WINDOW GEAR			Bent	798		25		598.5	Reviewing	ŵ
	,	19	1		REAR FENDER			Repair	0	0	0	0	0	Deny	m
0	,	20	1		REAR WHEEL RIM "ORIGINAL"			Bent	1550		25		1162.5	Reviewing	ů
В	,	21	1		REAR BUMPER			Serviceable	0	0	0	0	0	Deny	d
	,	22	1		REAR AXLE			Serviceable	0	0	0	0	0	Deny	i
8	,	23	1		REAR WHEEL HUB C/W BEARING			Serviceable	0	0	0	0	0	Deny	a
Labour															
Add	App EDIT	prove	Deny SR NO	Submit All REPAIR/REPLACE (LABO	DUR) PART NA	ME	LABOUR	R&R LAI	BOUR REPAIR	PAINT	ACTIO	N (LABOUR)	COMMENT	REMOVE	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	,	1		TO CHECK WIRING AND FUNCTION	40	0	0	Reviewing		1111
0	-	2		TO REMOVE & REFIX REAR UNDERCARRIAGE	0	0	0	Deny		m
ш	-	3		TO CHECK REAR WHEEL ALIGNMENT	80	0	0	Reviewing		m
ш	,	4		LABOUR CHARGES AS RECOMMENDED FOR REPAIRED & REPLACED DAMAGED PARTS	700	0	0	Reviewing		â
п	,	5		TO REMOVE & REFIX BOTH DOOR FITTING & MECHANISM, ETC	120	0	0	Reviewing		m
	-	6		TO REMOVE & REFIX FRONT WINDSCREEN GLASS	120	Ō	0	Reviewing		ŵ
0	,	7		TO PUTTY AND SPRAY PAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS	800	0	0	Reviewing		d
0	,	8		TO REMOVE & REFIX REAR FENDER WINDOW GLASS TO FACILITATE REPAIR	0	0	0	Deny		ŵ
		9		TO APPLY RUSTPROOF TREATMENT TO THE REPAIRED / REPLACED PANELS	100	0	0	Reviewing		a

General	& Worksh	nop Details	Vehicle & Driver D	etails Vehicle	e Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	
Add	Ар		Deny Submit A	.H						
	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE			
	,	1	DAYS OF REPAIR : 8 DAYS	Reviewing			ш			
ii)	,	2	FRONT WINDSCREEN GLASS SEALANT	Reviewing	60	ESSENTIAL	â			
	,	3	REAR FENDER WINDOW GLASS SEALANT	Deny	0	SERVICEABLE	= 1			
	Add	Add Ap	EDIT SR NO	General & Workshop Details Vehicle & Driver D Add Approve Deny Submit A EDIT SR NAME DAYS OF REPAIR: 8 DAYS PRONT WINDSCREEN GLASS SEALANT REAR FENDER WINDOW GLASS GLASS	General & Workshop Details	Add Approve Deny Submit All	General & Workshop Details			

General & Workshop Detail	ls Vehicle & Driver Details		& Labour Miscellaneous Summar		
Claim Amount	\$12,219.64	Claim Amo	sunt \$12,219.64		
CATEGORY	ESTIMATE	REVISED AMOUNT			
Labour	\$1,960.00	\$1,960.00			
Miscellaneous	\$60.00	\$60.00			
Spare Parts	\$10,199.64	\$10,199.64			
				Submit for Review	

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary
Add Approve Deny Submit All
EDIT SR NAME ACTION AMOUNT COMMENT REMOVE
FINAL LUMP Reviewing 9750

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio Parts &	Labour Miscellaneous	Summary	
Claim Amount	\$9,750.00		Claim Amou	unt \$9,750.00	0	
CATEGORY	ESTIMATE	REVISED AM	OUNT			
Miscellaneous	\$9,750.00	\$9,750.00				
					Submit for Review	