

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G8B657X.

Yr Regn:

2008, Jne.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Pick Up

Make:

Ssangyong Actyon.

C.C 1998

Colour

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading

239615.

T/Radio: Insured / Std / NI / NA

Eng/No:

KPADA1EKS8P044887

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/75R16C.

R:

225/75R16C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fireenza.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

20/07/18.

Survey held at

Ryder.

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/11/18

TP on Pgc.

WE Expiry: 25/06/23.

Confirm US \$9800.00 with 9 working days

MV: ~~26.5K~~ 26.5K.

PV: 16.6K

Nett: ~~9.9K~~ 9.9K.(RD-#66) 2 SP
40%.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18013153/Awb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-07-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 8264S	Veh. Inspected	GBB 657X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/07/2018	Inspection Date	20/07/2018	
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: ryderautoworkshop@gmail.com

Fax: 64815390

ESTIMATE OF REPAIR

TP Long Pac.

Vivian

(Without Prejudice)

Veh # : GBB657X Model : SSANGYONG ACTYON SPORTS

KPADAIEKS8P044887

Date Of Accident: 17/7/2018

Location : YISHUN AVE 7 TOWARDS AVE 2

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	List Items				
1 pc	Rear bumper <i>replaced.</i>			820.00	✓
1 pc	Rear bumper enforcement <i>Best</i>			340.00	✓
10 pcs	Rear bumper clips <i>new</i>			95.00 → 30.	
2 pcs	Rear bumper o/s & n/s bracket <i>new</i>			220.00	✓
2 pcs	Rear bumper o/s & n/s reflector <i>new</i>			240.00	✓
2 pcs	Rear bumper o/s & n/s corner garnish <i>new</i>			580.00	✓
2 pcs	Rear bumper o/s & n/s reverse sensor <i>new</i>			380.00 200 (SN)	
1 pc	Rear tail-gate <i>replaced.</i>			<u>1,920.00</u>	1250
1 pc	Rear tail-gate emblem			82.00	✓
1 pc	Rear tail-gate Acton emblem			68.00	✓
1 pc	Rear tail-gate Sports emblem			67.00	✓
1 pc	Rear tail-gate Ssangyong emblem			81.00	✓
1 pc	Rear tail-gate moulding <i>replaced</i>			270.00	✓
4 pcs	Rear tail-gate moulding clips <i>new</i>			38.00	✓
2 pcs	Rear tail-gate regn. no. plate lamp <i>new</i>			<u>280.00</u>	98
2 pcs	Rear tail-gate o/s & n/s hinges <i>Best</i>			420.00	210
2 pcs	Rear tail-gate o/s & n/s lock <i>new</i>			450.00	✓
2 pcs	Rear tail-gate o/s & n/s stopper <i>new</i>			82.00	✓
1 pc	Rear tail-gate lock handle (Outer) <i>new</i>			180.00	✓
1 pc	Rear tail-gate inner cover <i>new</i>			420.00	✓
20 pcs	Rear tail-gate inner cover clips <i>new</i>			190.00	50
1 pc	Rear tail-gate lower panel <i>Repair</i>			780.00	7
2 pcs	Rear o/s & n/s tail-lamp <i>new</i>			820.00	640
2 pcs	Rear o/s & n/s tail-lamp seal <i>new</i>			100.00	✓
4 pcs	Rear o/s & n/s tail-lamp clips <i>new</i>			38.00	✓
1 pc	Rear spare wheel bracket assy <i>new</i>			490.00	✓

Auto Pte Ltd

Email: ryderautoworkshop@gmail.com

Fax: 64815390

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
1 pc	Front bumper <i>Delnd</i>			<u>1,200.00</u>	✓
10 pcs	Front bumper clips <i>new</i>			95.00	30
1 pc	Front bumper lower moulding <i>new</i>			380.00	x
1 pc	Front bumper enforcement <i>Bent</i>			390.00	2
2 pcs	Front bumper o/s & n/s garnish <i>Delnd</i>			620.00	20
2 pcs	Front bumper o/s & n/s fog lamp <i>LH cracked</i>			720.00	360
2 pcs	Front bumper o/s & n/s corner clips <i>new</i>			260.00	7
1 pc	Front grille <i>cracked</i>			480.00	2
4 pcs	Front grille clips <i>new</i>			38.00	2
1 pc	Front bonnet <i>Dented.</i>			920.00	-
2 pc	Front bonnet o/s & n/s hinges <i>new</i>			470.00	x
1 pc	Front bonnet lock (Lower) <i>2nd.</i>			280.00	85
1 pc	Front bonnet moulding <i>at</i>			<u>390.00</u>	165
1 pc	Front bonnet moulding emblem <i>new</i>			82.00	✓
2 pcs	Front o/s & n/s head-lamp <i>Cracked</i>			<u>2,120.00</u>	160
4 pcs	Front o/s & n/s head-lamp clips <i>new</i>			38.00	2
	Sub-Total			17,934.00	
	After -10%			16,140.60	
	Special Nett Items				
1 pc	Rear regn. no. plate <i>cracked</i>			45.00	30
1 pc	Rear regn. no. plate bracket <i>Delnd</i>			29.00	-
1 pc	Front regn. no. plate <i>cracked</i>			45.00	30
1 pc	Front regn. no. plate bracket <i>Delnd</i>			29.00	✓
	Sub-Total			148.00	
	Labour:				
1	To straighten and welding.			1,800.00	130
2	To spray painting (Metallic Paint).			1,600.00	1000
3	To remove and replace rear spare wheel bracket.			200.00	x
4	To remove and replace rear reverse sensor.			140.00	50
5	To remove and replace rear tail-gate.			180.00	x
6	To check wiring.			120.00	60
7	To re-seal anti-rust.			200.00	50
	Sub-Total			4,240.00	
	Total			20,528.60	
	After -20%			16,422.88	

	<u>Labour</u>
1	To straighten and welding
2	To spray painting (Metallizing)
3	To remove and replace rear
4	To remove and replace rear
5	To remove and replace rear
6	To check wiring.
7	To re-seal anti-rust.

total: 10283.80
L/S: 9.8K

Adrian L
L/S 20/07/18. Adrian King. 09 Days. 96893735.

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 18 July 2018 2:16 PM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: PRE-REPAIR INSPECTION - Your Vehicle SKT8264S; Our Vehicle: GBB657X
Accident involving GBB657X & SKT8264S On 17 July 2018

2.51pm @ 18/7/18
vehicle in
person @ orson

Our Ref : 17/18/18/VP05/020761

Dear Catherine,

Kindly proceed as proposed by the workshop.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]
Sent: Wednesday, 18 July, 2018 2:11 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: PRE-REPAIR INSPECTION - Your Vehicle SKT8264S; Our Vehicle: GBB657X Accident involving GBB657X & SKT8264S On 17 July 2018

Dear Sir,

Kindly assign marcus.

Thank You

Best regards

Orson

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390

On Wed, Jul 18, 2018 at 12:19 PM, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

WITHOUT PREJUDICE

Our Ref : 17/18/18/VP05/020761

Dear June,

Please see attached and let us hear from you.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ryder Auto workshop [<mailto:ryderautoworkshop@gmail.com>]

Sent: Wednesday, 18 July, 2018 11:22 AM

To: MT_Claim_SG

Subject: PRE-REPAIR INSPECTION - Your Vehicle SKT8264S; Our Vehicle: GBB657X Accident involving GBB657X & SKT8264S On 17 July 2018

Dear Sir,

We refer to the above matter.

Kindly find attached pre-repair inspection notice for your necessary action.

Thank you.

Best regards

June

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390

 **BOK SENG**
(heavy vehicles, marine vessels)

 **Bluwel 2088** 
(motorbike, cars, light vehicles)

 **i1d**
Authorised Workshop
Authorised Reporting Centre

 **8778 1999**
24 hr accident call



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18013153/Awb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 05-11-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 8264S	Veh. Inspected	GBB 657X	
Policy No.	Z/17/VP05/015486	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020761	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	SSANGYONG ACTYON	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	KPADA1EKS8P044887	Colour	SILVER	
Odometer	239615	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/75R16C	FIRENZA	6 mm	
L/H Front Tyre	225/75R16C	FIRENZA	6 mm	
R/H Rear Tyre	225/75R16C	FIRENZA	6 mm	
L/H Rear Tyre	225/75R16C	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2018	Inspection Date	20/07/2018	
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 657X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	820.00	820.00
1	REAR BUMPER REINFORCEMENT	BENT	340.00	340.00
10	REAR BUMPER CLIPS	NECESSARY	95.00	30.00
2	REAR BUMPER O/S & N/S BRACKET	NECESSARY	220.00	220.00
2	REAR BUMPER O/S & N/S REFLECTOR	CRACKED	240.00	240.00
2	REAR BUMPER O/S & N/S CORNER GARNISH	NOT NECESSARY	580.00	-
1	REAR TAIL-GATE	DENTED	1,920.00	1,250.00
1	REAR TAIL-GATE EMBLEM	NECESSARY	82.00	82.00
1	REAR TAIL-GATE ACTON EMBLEM	NECESSARY	68.00	68.00
1	REAR TAIL-GATE SPORTS EMBLEM	NECESSARY	67.00	67.00
1	REAR TAIL-GATE SSANGYONG EMBLEM	NECESSARY	81.00	81.00
1	REAR TAIL-GATE MOULDING	CRACKED	270.00	270.00
4	REAR TAIL-GATE MOULDING CLIPS	NECESSARY	38.00	38.00
2	REAR TAIL-GATE REGN. NO. PLATE LAMP	CRACKED	280.00	98.00
2	REAR TAIL-GATE O/S & N/S HINGES	BENT	420.00	210.00
2	REAR TAIL-GATE O/S & N/S LOCK	DAMAGED	450.00	450.00
2	REAR TAIL-GATE O/S & N/S STOPPER	NOT NECESSARY	82.00	-
1	REAR TAIL-GATE LOCK HANDLE (OUTER)	NOT NECESSARY	180.00	-
1	REAR TAIL-GATE INNER COVER	NOT NECESSARY	420.00	-
20	REAR TAIL-GATE INNER COVER CLIPS	NECESSARY	190.00	50.00
1	REAR TAIL-GATE LOWER PANEL	TO REPAIR SEE LABOUR	780.00	-
2	REAR O/S & N/S TAIL-LAMP	CRACKED	820.00	640.00
2	REAR O/S & N/S TAIL-LAMP SEAL	NOT NECESSARY	100.00	-
4	REAR O/S & N/S TAIL-LAMP CLIPS	NOT NECESSARY	38.00	-
1	REAR SPARE WHEEL BRACKET ASSY	NOT NECESSARY	490.00	-
1	FRONT BUMPER	DEFORMED	1,200.00	1,200.00
10	FRONT BUMPER CLIPS	NECESSARY	95.00	30.00
1	FRONT BUMPER LOWER MOULDING	NOT NECESSARY	380.00	-
1	FRONT BUMPER ENFORCEMENT	BENT	390.00	390.00
2	FRONT BUMPER O/S & N/S GARNISH	DEFORMED	620.00	220.00

Report Ref No. CC4/LPC18013153/Awb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER O/S & N/S FOG LAMP	N/S CRACKED	720.00	360.00
2	FRONT BUMPER O/S & N/S CORNER CLIPS	NOT NECESSARY	260.00	-
1	FRONT GRILLE	CRACKED	480.00	480.00
4	FRONT GRILLE CLIPS	NECESSARY	38.00	38.00
1	FRONT BONNET	DENTED	920.00	920.00
2	FRONT BONNET O/S & N/S HINGES	NOT NECESSARY	470.00	-
1	FRONT BONNET LOCK (LOWER)	DAMAGED	280.00	85.00
1	FRONT BONNET MOULDING	CUT	390.00	165.00
1	FRONT BONNET MOULDING EMBLEM	NECESSARY	82.00	82.00
2	FRONT O/S & N/S HEAD-LAMP	CRACKED	2,120.00	1,600.00
4	FRONT O/S & N/S HEAD-LAMP CLIPS	NECESSARY	38.00	38.00
	LESS 10% DISCOUNT		-1,755.40	-1,056.20
			15,798.60	9,505.80
2	REAR BUMPER O/S & N/S REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
	LESS 10% DISCOUNT		-38.00	-
			342.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REGN. NO. PLATE (SN)	CRACKED	45.00	30.00
1	REAR REGN. NO. PLATE BRACKET (SN)	DEFORMED	29.00	29.00
1	FRONT REGN. NO. PLATE (SN)	CRACKED	45.00	30.00
1	FRONT REGN. NO. PLATE BRACKET (SN)	DEFORMED	29.00	29.00
			148.00	118.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND WELDING. INCLUSIVE OF THE REPAIR OF REAR TAIL-GATE LOWER PANEL.		1,800.00	1,300.00
	TO SPRAY PAINTING (METALLIC PAINT)		1,600.00	1,000.00
	TO REMOVE AND REPLACE REAR SPARE WHEEL BRACKET.	NOT NECESSARY	200.00	-
	TO REMOVE AND REPLACE REAR REVERSE SENSOR.		140.00	50.00
	TO REMOVE AND REPLACE REAR TAIL-GATE.	NOT NECESSARY	180.00	-
	TO CHECK WIRING.		120.00	60.00

Report Ref No. CC4/LPC18013153/Awb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SEAL ANTI RUST.		200.00	50.00
			4,240.00	2,460.00
	GRAND TOTAL		20,528.60	12,283.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,800.00

Report Ref No. CC4/LPC18013153/Awb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.