



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
Mr NORLI BIN ISMAIL Blk 124 Tampines St 11 #10-422 Singapore 521124 Contact No Mobile: 90694122	Cust No/Name	/Mr Norli Bin Ismail
	Reg No/Reg Date	SLC6083M*1F / 20/05/2016
	Date In/Mileage	19/07/2018/ 0
	Chassis No	JMYXTGF3WGJ000138
	Engine No	4B12RB2867
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim	X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	19/07/2018/ 14:26	DS	218 / MarsLer	61562
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	60			80.00
S MIPNT88088	SCANNING / DIAGNOSTIC	1			250.00
S MIPNT88088	TO REMOVE AND RE-INSTALL REAR TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	300			600.00
S MIPNT88088	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS	300			600.00
S MIPNT88088	TO REPLACE REAR REVERSE CAMERA LENS	1 X			350.00
S MIPNT88088	REVERSE SENSOR SET	shld			280.00
S MIPNT88088	TO REPLACE TAILGATE GLASS	1			300.00
M SUNDRY	SEALANT KIT ON TAILGATE GLASS	1			100.00
S MIPNT88088	TO INSTALL RIKECOOL SOLAR FILM ON TAILGATE GLASS	1 X			220.00
S MIPNT88088	TO REPLACE REAR BUMPER, REINFORCEMENT, TAILGATE, ETC - CUT & RE-WELD REAR END PANEL - TO REPAIR REAR FLOOR PAN STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	1800			3600.00
S MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL	150			300.00
S MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1680			2940.00
M SUNDRY	C & C LOGO	1			35.00
M SUNDRY	MIVEC EMBLEM	1			45.00

Confirm & accepted by

Not Actual
to be ph to before party.
Gdy.
25/7/18

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr NORLI BIN ISMAIL Blk 124 Tampines St 11 #10-422 Singapore 521124 Contact No Mobile: 90694122	Cust No/Name /Mr Norli Bin Ismail
	Reg No/Reg Date SLC6083M*1F / 20/05/2016
	Date In/Mileage 19/07/2018/ 0
	Chassis No JMYXTGF3WVGJ000138
	Engine No 4B12RB2867
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	19/07/2018/ 14:26	DS	218 / MarsLer	61562
Description of Goods / Services.		Qty	Unit Price	Disc%	Amount
P JJ6410D243	FACE, RR BUMPER W/FL	1.00	873.00	0.00	873.00
P JJMU488006	CLIP,RR BUMPER	10.00	2.00	0.00	20.00
P JJMR200300	CLIP, RR BUMPER	10.00	2.00	0.00	20.00
M JJ6410D336	LH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
M JJ6410D337	RH BRACKET, RR BUMPE	1.00	12.00	0.00	12.00
M JJ6410B895	LH REINFORCEMENT,RR	1.00	78.00	0.00	78.00
M JJ6410B896	RH REINFORCEMENT,RR	1.00	78.00	0.00	78.00
M JJ6415A061	EXTENSION, RR BUMPER	1.00	230.00	0.00	230.00
M JJ6512A681	INR CLIP, RR BUMPER	10.00	3.00	0.00	30.00
M JJ7407A303	LH WHEEL ARCH MOULDI	1.00	197.00	0.00	197.00
M JJ7407A317	LH MOULDING, RR BUMP	1.00	105.00	0.00	105.00
M JJ7407A318	RH MOULDING, RR BUMP	1.00	105.00	0.00	105.00
M JJ8637A176	BUZZER, KEYLESS OPER	1.00	90.00	0.00	90.00
M JJ8637B115	ANTENNA, KEYLESS OPE	1.00	95.00	0.00	95.00
M JJ8330B173	LHR LAMP ASSY, COMBI	1.00	594.00	0.00	594.00
P JJ8331A179	LH TAIL LAMP ASSY	1.00	501.00	0.00	501.00
M JJ8336A153	LH REFLECTOR, TAIL L	1.00	99.00	0.00	99.00
M JJ5257A879	PANEL,RR END	1.00	235.00	0.00	235.00
M JJ5257A605	LH INR PANEL, RR END	1.00	141.00	0.00	141.00
P JJ5801B675	TAILGATE PANEL ASSY	1.00	924.00	0.00	924.00
M JJ5805A306	GLASS,TAILGATE WINDO	1.00	743.00	0.00	743.00
M JJ5805A316	UPR DAM,TAILGATE	1.00	12.00	0.00	12.00
M JJ5805A317	LWR DAM,TAIL GATE	1.00	41.00	0.00	41.00
M JJ5805A315	SIDE DAM,TAILGATE	2.00	27.00	0.00	54.00
M JJMR462285	STOPPER,WINDSHIELD G	2.00	3.00	0.00	6.00
M JJMB814447	FASTENER,WINDSHIELD	4.00	6.00	0.00	24.00
M JJ5815A067	WEATHERSTRIP, TAILGA	1.00	211.00	0.00	211.00
M JJ7240A135XA	TRIM,RR END	1.00	122.00	0.00	122.00
M JJ7415A401	MARK,OUTLANDER	1.00	94.00	0.00	94.00
Z	NOTES				
ACCIDENT ON 17/07/2018 ALONG PIE TOWARDS CHANGI AIRPORT					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT CAR					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
Mr NORLI BIN ISMAIL Blk 124 Tampines St 11 #10-422 Singapore 521124 Contact No Mobile: 90694122	Cust No/Name	/Mr Norli Bin Ismail
	Reg No/Reg Date	SLC6083M*1F / 20/05/2016
	Date In/Mileage	19/07/2018/ 0
	Chassis No	JMYXTGF3WGJ000138
	Engine No	4B12RB2867
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim	X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	19/07/2018/ 14:26	DS	218 / MarsLer	61562

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TP # SHA7675G TP INS : I.I.I				
<h1>Estimate</h1> <div style="border: 1px solid black; padding: 10px; margin: 20px auto; width: 80%;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				

Confirm & accepted by

Parts	5,746.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,520.00
Others (Lub, etc)	0.00
Sundry	180.00
Total (w/o GST)	15,446.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.