

ASS. REC. P. | PEP CS3/EQ17024459/LSB-1  
 From Person: Rasul | ASSIGNMENT (Office)  
Justin Wong | EQI | 17072018  
 Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_  
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS  
 To Inspect Vehicle No: YM 3C Insured: YM 672X  
 at Workshop no: N-51 Automotive Tel: 68420051  
 of 2 Kalki Bkt Ave 2 # 01-17  
 Policy No: \_\_\_\_\_ Claim No: DM17H002922 / FN  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_ B.O.A. 22/12/17  
 (Client's Record)  
 CA / REV / RLP. / REV 24 HRS 'wp' B.O.D. Endorsement: \_\_\_\_\_  
 Date/Time: 10:02am @ 27/12/17 Person Contacted: Melody Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Example	
	YM 3C - NA / IN / 17024320 / Y	B.O.A. : 22/12/17
	YM 672X - NA / IN / 17020 / Y	B.O.A. : 22/12/17
	After repair: 5/1/2018	
	Discontinue: 29/12/2017	
	( \$ 19,000 Red - 68% )	

RECEIVED 31 JUL 2018



**Catherine Chong (LKK Auto)**

---

**From:** Elaine (LKK Auto) <report@lkkauto.com>  
**Sent:** Tuesday, 17 July, 2018 1:30 PM  
**To:** assignments@lkkauto.com  
**Subject:** FW: Assignment of Paper Re-survey on Vehicle YM3C; EQ REF: DM17HO02922/FN; [YM672X]  
**Attachments:** LKKPreRepairInspection-YM 3C.PDF

Dear Catherine,

Pls Assist.

---

**From:** Justin Wong [mailto:justin.wong@eqinsurance.com.sg]  
**Sent:** Monday, 16 July 2018 10:45 AM  
**To:** report@lkkauto.com  
**Cc:** sur@lkkauto.com  
**Subject:** Assignment of Paper Re-survey on Vehicle YM3C; EQ REF: DM17HO02922/FN; [YM672X]

Dear Elaine,

Kindly assist to conduct paper re-survey on third-party vehicle no: YM3C.

<https://www.dropbox.com/s/2sprmu2lbtckq2u/vision%20lod%20-%20YM3C.pdf?dl=0>

Thank you.

Regards,  
**Justin Wong**  
Executive | Claims

**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately.*

---

**From:** Elaine (LKK Auto) [mailto:report@lkkauto.com]  
**Sent:** Thursday, June 7, 2018 4:35 PM  
**To:** Francis Ng  
**Cc:** sur@lkkauto.com  
**Subject:** Survey Report & Invoice of Vehicle YM3C; EQ REF: DM17HO02922/FN; [YM672X]

Dear Sir / Madam,

Enclose PRS Survey Report of YM 3C.

Thank you.

Best Regards,

**ELAINE** | Reports

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,


**CARLINK CONSULTANCY**60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

**ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

Our Ref: CLM13963TP/T

<b>1 REFERENCE</b>			
Date of request	:	28th December 2017	
Requested by	:	M/S BikeBalance C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17 Singapore 417921	
Type of claim	:	Third party	
Workshop	:	M/S Twincar Automotive Pte Ltd Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17 Singapore 417921	
Date of survey	:	28th December 2017	
Accident date	:	22nd December 2017	
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	:	YM 3 C	
Make & Model	:	Nissan Atlas 5MT 2WD Single Cab	
Engine No.	:	ZD30347551K	
Chassis No.	:	SZ2F24052548	
Year of Registration	:	18th July 2015	
Speedometer reading	:	136114 Km	
Transmission	:	Manual	
Colour	:	Silver	
<b>3 STATIC CHECK</b>			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
<b>4 TYRE CONDITION</b>			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	6mm/Falken	6mm/Falken      : 205/65 R15
Rear tyre	:	6mm/Yokohama	6mm/Yokohama      : 165 R13C
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

BIKEBULANCE .  
9D YUAN CHING ROAD #03-38  
SINGAPORE 618646

Contact : 64255333 90233228

## TAX INVOICE

Date : 09/06/2018  
Date in : 22/12/2017  
Vehicle Num. : YM3C  
Make/Model : NISSAN ATLAS 5MT 2WD SINGLE CAB-2014  
Chassis/Eng# : SZ2F24052548/ZD30347551K  
Accident Date : 22/12/2017  
Claim No : CLM13963  
Reference : DEC-20/2017  
Policy No. : 2100475407-01000 (17/07/2018)

---

LUMPSUM REPAIR BILL	Amount S\$
AS PER SURVEYOR REPORT	28,000.00
REF : <u>CLM13963TP/T</u> DATED <u>19/05/2018</u>	
BY CARLINK CONSULTANCY	

---

E. & O.E.	Sub S\$ :	28,000.00
	Add GST ( 7 % ) S\$ :	1,960.00
	Total Amount S\$ :	<u>29,960.00</u>

---



---

for TWINCAR AUTOMOTIVE PTE LTD

# CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009  
Fax: 62874788 Tel: 62856178

## INVOICE

M/S BikeBalance  
C/o Kaki Bukit Autohub  
2 Kaki Bukit Avenue 2, #01-17  
Singapore 417921

Invoice No: CLM13963TP/T


Date: 19th May 2018

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: YM 3 C</u> Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (photographs - 96 copies)			\$1,321.00
<b>Total:</b>				<b>\$1,321.00</b>

Mod

ex(er

We thank you for the opportunity to serve you and assure you of our best at all times



PATRICK NG  
Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

Report No.

CLM13963TP/T

Vehicle No. YM3C

**Parts and Labour Assessment**

**PARTS**

Description of part	Repairer's Qty	Qty	Condition	Repairer's estimate	Our adjustment
HYDRAULIC CYLINDER JACK HINGE BRACKET LH	1	1	DENTED/DISTORTED	430.00	430.00 <i>SVCX</i>
HYDRAULIC CYLINDER JACK HINGE BRACKET RH	1	1	DENTED/DISTORTED	430.00	430.00 <i>SVCX</i>
HYDRAULIC CYLINDER JACK LOWER PIVOT PIN	4	4	NECESSARY	480.00	480.00 <i>SVCX</i>
HYDRAULIC CYLINDER JACK TOP PIVOT PIN	4	4	NECESSARY	480.00	480.00 <i>SVCX</i>
LIFT PLATFORM "5 METER/STAY CLEAR" STICKER	1	1	NECESSARY	120.00	120.00
LIFT PLATFORM "60KM/H" STICKER	1	1	NECESSARY	12.00	12.00
LIFT PLATFORM "COMPANY NAME & TEL" STICKER	1	1	NECESSARY	50.00	50.00
LIFT PLATFORM "WARNING/STAY CLEAR" STICKER	1	1	NECESSARY	120.00	120.00
LIFT PLATFORM ASSY C/W MOTORCYCLE RAMP	1	1	DENTED/DISTORTED/CUT	15,000.00	15,000.00 <i>Rx</i>
LIFT PLATFORM CAUTION STRIPE STICKER (YELLOW/RED)	2	2	NECESSARY	220.00	220.00
LIFT PLATFORM CENTRE HINGE ARM ASSY	1	1	DENTED/BENT	1,950.00	1,950.00
LIFT PLATFORM CENTRE HINGE ARM ASSY PIVOT PIN (LONG)	2	2	NECESSARY	420.00	420.00 <i>SVCX</i>
LIFT PLATFORM CENTRE HINGE ARM ASSY PIVOT PIN (SHORT)	2	2	NECESSARY	360.00	360.00 <i>SVCX</i>
LIFT PLATFORM LH INNER HYDRAULIC CYLINDER JACK	1	1	BENT/LEAKED	1,700.00	1,700.00
LIFT PLATFORM LH OUTER HYDRAULIC CYLINDER JACK	1	1	BENT/LEAKED	1,700.00	1,700.00
LIFT PLATFORM RH INNER HYDRAULIC CYLINDER JACK	1	1	BENT/LEAKED	1,700.00	1,700.00
LIFT PLATFORM RH OUTER HYDRAULIC CYLINDER JACK	1	1	BENT/LEAKED	1,700.00	1,700.00
LIFT PLATFORM CENTRE HINGE ARM YELLOW/RED STICKER	1	1	NECESSARY	210.00	210.00
REAR NUMBER PLATE	1	1	DENTED/GRAZED	30.00	30.00
TAIL BOARD LOWER PANEL	1	1	BENT	880.00	880.00 <i>Rx</i>
TAILLAMP LH	1	1	GCRACKED	210.00	210.00
Subtotal before discount				S\$ 28,202.00	S\$ 28,202.00
<b>Sub-total</b>				<b>S\$ 28,202.00</b>	<b>S\$ 28,202.00</b>
<b>Parts-total</b>				<b>S\$ 28,202.00</b>	<b>S\$ 28,202.00</b>

*Us \$ 9000 h*  
*20% let me know* *9,969.60*

**LABOUR**

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,500.00	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,100.00	1,800.00
Labour to dismantle/replace hydraulic cylinder jacks,pivot pin,lift platform centre hinge arm assy and etc.	2,000.00	1,600.00
To apply anti-rust chemical on repaired and replaced panel.	150.00	100.00
To check wiring system and light.	150.00	80.00
<b>Labour Total</b>	<b>SS 5,900.00</b>	<b>SS 4,780.00</b>


8 600  
1000  
1000  
80  
60


**Parts & Labour Total**    **SS 34,102.00**    **SS 32,982.00**

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : **SS 28,000.00**  
and the recommended number of working days for the repairs is within 14 day(s).



  
PATRICK (SURVEYOR)  
Automotive Appraiser

8 days



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS3/EQ117024459/Lsbe2-1	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 01-08-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 672X	Veh. Inspected	YM 3C
Policy No.		Coverage (\$)	0.00
Claim No.	DH17HO02922/FN	Excess (\$)	0.00
Assign From	JUSTIN WONG	Assign Date	17/07/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NISSAN ATLAS	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SZ2F24052548	Colour	GREY
Odometer	136114	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	FALKEN	7 mm
L/H Front Tyre	205/65 R15	FALKEN	7 mm
R/H Rear Tyre	165 R13C (D)	FALKEN	5/5 mm
L/H Rear Tyre	165 R13C (D)	FALKEN	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/12/2017	Inspection Date	28/12/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 3C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HYDRAULIC CYLINDER JACK HINGE BRACKET LH	SERVICEABLE	430.00	-
1	HYDRAULIC CYLINDER JACK HINGE BRACKET RH	SERVICEABLE	430.00	-
4	HYDRAULIC CYLINDER JACK LOWER PIVOT PIN	SERVICEABLE	480.00	-
4	HYDRAULIC CYLINDER JACK TOP PIVOT PIN	SERVICEABLE	480.00	-
1	LIFT PLATFORM "5 METER/STAY CLEAR" STICKER	NECESSARY	120.00	120.00
1	LIFT PLATFORM "60KM/H" STICKER	NECESSARY	12.00	12.00
1	LIFT PLATFORM "COMPANY NAME & TEL" STICKER	NECESSARY	50.00	50.00
1	LIFT PLATFORM "WARNING/STAY CLEAR" STICKER	NECESSARY	120.00	120.00
1	LIFT PLATFORM ASSY C/W MOTORCYCLE RAMP	TO REPAIR SEE LABOUR	15,000.00	-
2	LIFT PLATFORM CAUTION STRIPE STICKER (YELLOW/RED)	NECESSARY	220.00	220.00
1	LIFT PLATFORM CENTRE HINGE ARM ASSY	DENTED / BENT	1,950.00	1,950.00
2	LIFT PLATFORM CENTRE HINGE ARM ASSY PIVOT PIN (LONG)	SERVICEABLE	420.00	-
2	LIFT PLATFORM CENTRE HINGE ARM ASSY PIVOT PIN (SHORT)	SERVICEABLE	360.00	-
1	LIFT PLATFORM LH INNER HYDRAULIC CYLINDER JACK	BENT / LEAKED	1,700.00	1,700.00
1	LIFT PLATFORM LH OUTER HYDRAULIC CYLINDER JACK	BENT / LEAKED	1,700.00	1,700.00
1	LIFT PLATFORM RH INNER HYDRAULIC CYLINDER JACK	BENT / LEAKED	1,700.00	1,700.00
1	LIFT PLATFORM RH OUTER HYDRAULIC CYLINDER JACK	BENT / LEAKED	1,700.00	1,700.00
1	LIFT PLATFORM CENTRE HINGE ARM YELLOW / RED STICKER	NECESSARY	210.00	210.00
1	REAR NUMBER PLATE	DENTED / GRAZED	30.00	30.00
1	TAIL BOARD LOWER PANEL	TO REPAIR SEE LABOUR	880.00	-
1	TAILLAMP LH	CRACKED	210.00	210.00
			<b>28,202.00</b>	<b>9,722.00</b>
<b>LABOUR</b>				
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.			1,500.00	600.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF LIFT PLATFORM ASSY C/W MOTORCYCLE RAMP AND TAIL BOARD LOWER PANEL.		2,100.00	1,000.00
	LABOUR TO DISMANTLE / REPLACE HYDRAULIC CYLINDER JACKS, PIVOT PIN, LIFT PLATFORM CENTRE HINGE ARM ASSY AND ETC.		2,000.00	1,000.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	80.00
	TO CHECK WIRING SYSTEM AND LIGHT.		150.00	60.00
			5,900.00	2,740.00
	<b>GRAND TOTAL</b>		<b>34,102.00</b>	<b>12,462.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UN-CONFIRMED)</b>			<b>9,000.00</b>

Report Ref No. CS3/EQ117024459/Lsbe2-1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.