

AXA Insured's Veh No : SKQ6560R

Date of Accident : 19 July 2018



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

not Authorized

aka

23/7/18

1/5 \$3000/?

40%
the photo after repair

Mr Muhammad Fareed bin Abubakar

Date : 20 July 2018

Estimate To Repair SLJ7281P - Honda JAZZ 1.3 CVT ABS D/AIRBAG 2WD

Chassis No : JHMGK3850HX200215

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear hatch door <i>body</i>	\$ 716.30
02	1 pc	rear hatch door Jazz badge <i>rec</i>	\$ 10.50
03	1 pc	rear hatch door lock <i>11</i>	\$ 172.30
04	1 pc	rear hatch door lock sticker <i>11</i>	\$ 27.50
05	1 ps	rear hatch door weatherstrip <i>11</i>	\$ 92.30
06	1 pc	rear windsheild glass weatherstrip <i>rec</i>	\$ 95.00
07	1 pc	rear end panel	\$ 314.00
08	1 pc	rear end panel inner trim <i>11</i>	\$ 60.80
09	1 pc	rear bumper <i>m/rec</i>	\$ 492.70
10	2 pc	rear bumper side retainer @ \$11.50 <i>11</i>	\$ 23.00
11	2 pc	rear bumper side holder @ \$14.00 <i>11</i>	\$ 28.00
12	10 pc	rear bumper clips @ \$3.20 <i>rec</i>	\$ 32.00
13	2 pc	rear bumper end splashield cover @ \$54.90 <i>11</i>	\$ 109.80
14	2 pc	rear bumper side garnish @ \$14.00 <i>11</i>	\$ 28.00
15	2 pc	rear lamp @ \$217.40 <i>11</i>	\$ 434.80
16	4 pc	rear lamp clip holder @ \$3.50 <i>11</i>	\$ 14.00
			\$ 2,651.00
Less 20 %			\$ 530.20
			\$ 2,120.80
<u>SPECIAL NETT ITEMS</u>			
17	1 pc	rear windshield glass sealant <i>rec</i>	\$ 120.00
18	1 pc	rear windshield glass sponge seal <i>rec</i>	\$ 40.00
19	1 ps	rear bumper parking sensor <i>short</i>	\$ 500.00
20	1 ps	rear bumper side lip <i>11</i>	\$ 600.00
21	1 pc	rear bumper centre diffuser <i>2c/dage</i>	\$ 1,200.00
22	1 pc	rear bumper centre diffuser brake light	\$ 300.00
			\$ 2,760.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear windscreen glass.	\$ 180.00
02		To rust-proofing of the affected areas.	\$ 250.00
03		To repair and realign rear exhaust box.	\$ 160.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 180.00
06		To reinstall of rear bumper parking sensor.	\$ 120.00
07		To check electrical lighting concerned.	\$ 60.00

11
11
4
x
x
1
x
x
1
x
x
1
x
x
x
x
1346.50
1071.20
40
✓
200
x
800
x
120
30
x
60
60
50
20



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SKQ6560R

Date of Accident : 19 July 2018

Mr Muhammad Fareed bin Abubakar

Date : 20 July 2018

Estimate To Repair SLJ7281P - Honda JAZZ 1.3 CVT ABS D/AIRBAG 2WD
Chassis No : JHMGK3850HX200215

S/No	Quantity	Description	Amount
		<u>LABOUR & MISC. CHARGES</u>	
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
09		Putty and spray painting of the affected portion.	\$ 950.00
			\$ 2,950.00
		Total	\$ 7,830.80

480

800

P- 1346.50

202

1077.20

S.N - 1080

Labour - 1620

3777.20

2070

3021.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: