

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013245/AQD3E2
Date: 11/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3075961700
Claimant Vehicle No : SFP886E **Insured Vehicle No :** YN8881B
Date of Loss: 18/07/2018 **Nature of Claim:** TP **Claim No:** SNM18D03565C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFP886E**
 Make & Model: LEXUS ES250, 2.5 (A) Engine No: 2ARE746673
 Reg. Date: 22/11/2013 (Man. Year: 2013) Chassis No: JTHBJ1GG202034832
 Colour: White Odometer: 120840 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,878.65	10,985.62	4,893.03	30.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,980.00	1,240.00	29.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,098.65	13,965.62	6,133.03	30.51
Approved Total (Overridden) (S\$)		11,100.00		
(S\$)	20,098.65	11,100.00	8,998.65	44.77
+ GST 7.00/7.00% (S\$)	1,406.91	777.00	629.91	44.77
Nett Amount (S\$)	21,505.56	11,877.00	9,628.56	44.77

INSPECTION

Date of Assignment: 20/07/2018
 Date Inspected: 23/07/2018 Inspected At: KAI MOTOR TRADING (HQ)
 Estimated Period of Repair: 9.0 days BLK 3007 UBI ROAD 1, #01-440
 Singapore 408701

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2018)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SFP886E/11/03/2019 09:58	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Distorted	985.10 FL	*985.10 FL
2	1		*REAR BOOT COVER INNER LOCK	Damaged	478.40 FL	*478.40 FL
3	1		*REAR BOOT COVER LOGO	Necessary	95.70 FL	*95.70 FL
4	1		*REAR BOOT COVER RUBBER	Cut	256.70 FL	*256.70 FL
5	1		*REAR BOOT COVER LEXUS EMBLEM	Necessary	131.10 FL	*131.10 FL
6	1		*REAR BOOT COVER ES 2500 EMBLEM	Necessary	148.60 FL	*148.60 FL
7	1		*REAR BOOT COVER LAMP	Cut	460.35 FL	*460.35 FL
8	1		*REAR BOOT COVER MOULDING	Cracked	151.00 FL	*151.00 FL
9	1		*REAR BOOT COVER INSULATOR	Deformed	498.60 FL	*498.60 FL
10	8		*REAR BOOT COVER INSULATOR CLIPS	Necessary	50.00 FL	*30.00 FL
11	1		*REAR BOOT COVER HINGE	Bent	139.60 FL	*139.60 FL
12	1		*REAR ANTENNA ELE	Damaged	480.00 FL	*480.00 FL
13	1		*REAR LAMP RH	Cracked	751.60 FL	*751.60 FL
14	1		*REAR FENDER RH	Repair	1,155.10 FL	*- FL
15	1		*REAR LAMP PANEL RH	Dented	138.10 FL	*138.10 FL
16	1		*REAR PANEL	Distorted	801.60 FL	*801.60 FL
17	1		*REAR PANEL INNER GARNISH	Deformed	248.10 FL	*248.10 FL
18	1		*REAR BUMPER	Distorted	899.70 FL	*899.70 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	303.20 FL	*303.20 FL
20	1		*REAR BUMPER CENTER SPONG GR	Cracked	215.60 FL	*215.60 FL
21	2		*REAR BUMPER REINFORCEMENT	Bent	623.40 FL	*623.40 FL
22	8		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
23	1		*REAR SPARE TYRE BOX	Not Necessary	496.80 FL	*- FL
24	1		*REAR SPARE PANEL COVER	Deformed	455.60 FL	*455.60 FL
25	1		*SET REVERSE SENSOR	Damaged	1,969.60 FL	*560.00 FL
26	1		*REAR BOOT COVER REVERSE CAM	Damaged	680.00 FS	*380.00 FS
27	1		*REAR WINDSCREEN GLASS SEAL	Not Necessary	150.00 FS	*- FS
28	1		*REAR NUMBER PLATE	Bent	65.00 FS	*65.00 FS
29	1		*REAR LAMP LH	Cut	751.60 FL	*751.60 FL
30	1		*REAR BOOT COVER LAMP	Cut	460.35 FL	*460.35 FL
31	1		*REAR BOOT INN/FL LUGGAGE MAT	Not Necessary	423.50 FL	*- FL
32	1		*REAR BOOT COVER HINGE	Bent	139.60 FL	*139.60 FL
33	1		*REAR SPARE WHEEL TRAY COVER	Repeated	408.60 FL	*- FL
34	1		*REAR FLOOR SP/WH PANEL	Buckled	765.80 FL	*765.80 FL
35	1		*REAR EX PIPE	Repair	598.50 FL	*- FL
36	1		*REAR EX PIPE TOP MUFF / INSULATER	Not Necessary	215.30 FL	*- FL
37	1		*REAR FENDER INNER TRIM	Crumpled	683.50 FL	*494.20 FL
38	1		*REAR SP/WH SIDE TOOL BOARD RH	Deformed	218.20 FL	*218.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,543.50	12,156.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,664.85	1,171.18
Total Parts (\$\$)	15,878.65	10,985.62

LKK Auto Consultants Pte Ltd/SFP886E/11/03/2019 09:58. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY	New	1,500.00	1,400.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,680.00	1,300.00
3	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN	New	150.00	0.00
4	TO REMOVE SPARY TUFF COST	New	200.00	50.00
5	TO COMPUTER WHEEL ALIGNMENT	New	120.00	0.00
6	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
7	TO REMOVE REVERSE SENSOR	New	150.00	60.00
8	TO REMOVE & REFIT CAR CAUSHION	New	120.00	60.00
9	TO REMOVE EXHAUST PIPE	New	200.00	80.00
Gross Labour Cost (\$\$)			4,220.00	2,980.00

LKK Auto Consultants Pte Ltd/SFP886E/11/03/2019 09:58. Not valid without Reference section.

< END OF ESTIMATES >