

TUESDAY

ASS. REC. BY:

REF

CS/FCI 18013262 / Klqdzⁿ²

Special Instruction:

Surveyor

CWS

Kalvin

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

20/7/18 @ 2:19pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHD 1292B

Insured:

8HB 6727S

at Workshop m/s:

Premier Automotive

Tel:

6544 6689

of

23 chengji south Ave 2 #03-02

Policy No:

Claim No:

D18005555MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

5:07pm @ 20/7/18

Person Contacted:

Vineent

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 1292B-NA/INC15009769/d2

DOA: 11/06/2015

8HB 6727S-NA/INC18005116/h1

DOA: 17/03/2018

24/7/18 @ 2:31pm revised to Joanne Yong by email.

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 1292B Yr Regn: 30 Apr 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~axi~~ / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1680Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 305830 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH M41 XME 54 62642

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 19/7/8 D.O.I. 23/7/8Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/8/8	Extend 4/5 \$1950 / 3 Rys. (Red 99 (99250, 51%))
	FCZ 45
	RECEIVED 8 AUG 2018

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 3

1) 03/8 2013

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

130

50

50

34

264

Report Format: 7PLump Sum / J.B.I: (\$ 1950)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013262/K1qd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 20-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6727S	Veh. Inspected	SHD 1292B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005555MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/07/2018	Inspection Date	23/07/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005555MFSH

Date: 24 July 2018

Our Ref: CS/FCI18013262/K1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1292B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/07/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,942.50</u>
Revised Estimate Amount	: S\$ <u>1,809.80</u>
"Check" Items Amount	: S\$ <u>154.80</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-07-2018	Our Ref No. D18005555MFSH
Accident Date	19-07-2018	Claim Type. Third Party
Insured Vehicle	SHB6727S	Third Party Vehicle. SHD1292B
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 24 July 2018 2:31 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005555MFSH/1
Attachments: CSFCI18013262K1qd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHD 1292B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 23 July 2018 10:15 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005555MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 20 July 2018 2:19 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005555MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	30 Apr 2014 / 09:58:13	Receipt No.:	AACCK001-AX239-140430-000004
Asset Type:	Vehicle	Transaction Amount:	\$72,769.00
Asset ID:	SHD1292B	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140430095813491007		

Vehicle No.:	SHD1292B
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	30 Apr 2014
Original Registration Date:	30 Apr 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5462642
Engine No.:	D4FDDH307994
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$20,184.00
Minimum PARF Benefit:	\$7,654.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	30 Apr 2014 09:58:13
COE No.:	2014043001001111Z
COE Expiry Date:	29 Apr 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$59,871.00
Lifespan Expiry Date:	29 Apr 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1292 B

1 pc	Rear bumper <i>Rehul</i>	\$	696.00
1 pc	Rear bumper lower cover <i>cl</i>	\$	206.00
2 pcs	Rear bumper side bracket n/s & o/s @ \$29.00 <i>X su</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>2 tan</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>2 can</i>	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00 <i>X su</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X su</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X su</i>	\$	36.00
1 pc	Rear bumper o/s reflector @ \$46.00 <i>X su</i>	\$	46.00
	<i>Rear Bootlid X Ryan</i>	\$	1,905.00
	Less 10%	\$	190.50
		\$	1,714.50

S/NETT

1 set	Rear bumper clips <i>2 pc</i>	\$	48.00
1 set	Reverse sensor <i>slide</i>	\$	280.00 20.00
1 set	Bootlid stickers <i>X</i>	\$	100.00
1 pc	Rear bumper top protector <i>tan</i>	\$	80.00 50.00
	Sundry <i>new</i>	\$	50.00 20.00
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X 1
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.	\$	650.00 300.00
	To putty and spray painting on rear bumper, bootlid lower garnish, end panel <i>X</i>	\$	600.00 360.00
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 X 1
		\$	3,942.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 10000
23/7/18 1100 hrs
3 hrs
45
After Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013262/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6727S	Veh. Inspected	SHD 1292B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005555MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	20/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5462642	Colour	SILVER	
Odometer	305830	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2018	Inspection Date	23/07/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1292B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET N/S & O/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER N/S & O/S STAY @\$53.00	SERVICEABLE	106.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
1	REAR BUMPER O/S REFLECTOR	SERVICEABLE	46.00	-
1	REAR BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-190.50	-162.30
			1,714.50	1,460.70
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			558.00	318.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, ETC. INCLUSIVE OF THE REPAIR OF REAR BOOTLID.		650.00	300.00

Report Ref No. CS/FC118013262/K1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,BOOTLID LOWER GARNISH,END PANEL.	NOT NECESSARY	600.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	-
			1,670.00	680.00
GRAND TOTAL			3,942.50	2,458.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS/FCI18013262/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.