

ASS. REC. BY:

REF: CS/FCI/18013265/Dtd3n2

Special Instruction:

Surveyor
CWS

Bryan
Sithelera

ASSIGNMENT (Office)

From (Person):

of FCI

Date/Time: 20/7/18 @ 12:29pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 68804

Insured:

SHA 9731P

at Workshop in/s

Chunni Motor

Tel:

64836016

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D18005552MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time: 3:01pm @ 20/07/18

Person Contacted:

Irene

Vehicle IN / OUT


Date/Time	Action/Instruction
	(✓) Estimate
	SH 68804 - CS/FCI/18013122/-113 DOA: 18/7/18
	SHA 9731P - CS/FCI/17024047/K/qd3n2 DOA: 15/12/2017
3/7-	Revert via email preli advice

Surveyor

ASSIGNMENT

COE 2019 June

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5H 6880U Yr Regn: 2011 June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or
 Make: Hyundai Sonata C.C 1991
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp.Reading: 332215 T/Radio: Insured / Std / NI / NA
 Eng/No: D4EAB935815
 C/No: KM HET 4VM B A B 11739
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 18/07/2018 D.O.I. 20/07/2018
 Survey held at Chunnai AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.
 Front & Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/8/18	First Capital SHA 9731 P Insured R/S 11,000/- with 12 days 2 rep. (Red: 2226042:66%)
31/8	Double check with Denise (is RS \$11,000)
RECEIVED 30 AUG 2018	

Date/Time, File Pass to? ☐ Preli. Report

1130/8 Typist ☒ Final Report

Date/Time, File Return to?

2)

Report Format : TP

Lump Sum / I.B.I: (\$ 11,000/-)

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation: \$ + RS. \$
 Photos: 580
 Other: 88P

TOTAL 30/8/18

23x15=345

1704 345
50
30+50
178
843



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013265/Dtd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 20-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9731P	Veh. Inspected	SH 6880U
Policy No.		Coverage (\$)	0.00
Claim No.	D18005552MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/07/2018	Inspection Date	20/07/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005552MFSH

Date: 31/7/2018

Our Ref: CS/FC118013265/Dtd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SH 6880U

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/7/2018 at the premises of M/s Chun Ni and have the following to report: -

Workshop Estimate Amount	: S\$ <u>33,260.42</u>
Revised Estimate Amount	: S\$ <u>21,790.46</u>
"Check" Items Amount	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
Front and rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Bryan
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-07-2018	Our Ref No. D18005552MFSH
Accident Date	18-07-2018	Claim Type. Third Party
Insured Vehicle	SHA9731P	Third Party Vehicle. SH6880U
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE	
Contact No.	64836016/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 31 July 2018 12:11 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005552MFSH/1
Attachments: PRELI ADVISED SH 6880U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SH 6880U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 20 July 2018 1:41 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005552MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 20 July 2018 12:29 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005552MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

REPAIR ESTIMATE*

VEHICLE NO : SH 6880U

DATE : 19.07.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>fit</i>			\$ 1,151.80 ✓
	Bonnet Hinge (LH/RH) <i>new</i>		\$ 87.50	\$ 175.00 X
	Bonnet Moulding <i>src</i>			\$ 120.90 X
	Bonnet Lock <i>vt</i>			\$ 48.80 ✓
	Radiator Grille <i>broken</i>			\$ 282.10 ✓
	Radiator Grille U Moulding <i>broken</i>			\$ 108.90 ✓
	Front Bumper Cover <i>Replaced</i>			\$ 538.80 ✓
	Front Bumper Sponge <i>& torn</i>			\$ 136.30 ✓
	Front Bumper Reinforcement <i>& vt</i>			\$ 504.10 ✓
	Front Bumper Centre Grille <i>broken</i>			\$ 131.10 ✓
	Front Bumper Lip <i>new</i>			\$ 59.90 X
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80 X
	Front Bumper Protector (LH/RH) <i>vt</i>	\$	29.20	\$ 58.40 ✓
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	20.10	\$ 40.20 X
	Headlamp Support Panel Assy <i>Replaced</i>			\$ 1,023.00 ✓
	Headlamp (LH/RH) <i>broken</i>	\$	797.90	\$ 1,595.80 ✓
	Radiator <i>& vt</i>			\$ 814.80 ✓
	Radiator Fan Blade, Cowling, Motor Assy <i>& work</i>			\$ 651.30 ✓
	Aircon Condenser <i>& vt</i>			\$ 1,089.90 ✓
	Inter Cooler <i>& vt</i>			\$ 771.50 ✓
	Wiring-ECM <i>new</i>			\$ 3,107.80 X
			8906.60	
			7125.28	
	SUB TOTAL			\$ 12,455.20
	LESS 20%			\$ 2,491.04
	DISCOUNTED TOTAL			\$ 9,964.16
	Front Number Plate <i>dislodged</i>			\$ 25.00 Nett ✓
	Front No Plate Trim Cover <i>Don</i>			\$ 30.00 Nett ✓
	Front Fender Advertisement Logo (LH/RH) <i>new</i>	\$	100.00	\$ 200.00 Nett ✓
	New Battery <i>new</i>			\$ 207.00 Nett X
			255/-	
				\$ 462.00
	Labour Charge			
	Panel Beating			\$ 1,200.00 700/-
	Spray Painting Charge			\$ 1,000.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 30/-
	Towing Charge			\$ 50.00 new
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Dashboard			\$ 450.00 new
	Remove/Refix Fuse Box			\$ 180.00 new
			1440/-	
	TOTAL LABOUR			\$ 3,130.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>bnc</i>			\$ 1,349.50	✓
	Boot Lid Rubber <i>deformed</i>			\$ 110.90	✓
	Boot Lid Hinge (LH/RH) <i>ren</i>	S	170.60	\$ 341.20	×
	Boot Lid Lock Upper <i>Dam</i>			\$ 132.10	✓
	Boot Lid Lock Lower <i>Dam</i>			\$ 30.30	✓
	Boot Lid Key Lock <i>HH</i>			\$ 78.20	×
	Boot Lid Sonata Plate <i>Hec</i>			\$ 43.60	✓
	Boot Lid Hyundai Plate <i>Hec</i>			\$ 24.20	✓
	Boot Lid 'H' Emblem <i>Hec</i>			\$ 26.10	✓
	Boot Lid CRDI Plate <i>Hec</i>			\$ 22.70	✓
	Boot Lid Lamp (LH/RH) <i>broken</i>	S	230.20	\$ 460.40	✓
	Boot Lid Trimboard <i>horn</i>			\$ 165.40	✓
	Boot Lid Trimboard Clips (11pcs) <i>Hec</i>			\$ 11.00	✓
	Rear Bumper <i>bnc</i>			\$ 578.40	✓
	Rear Bumper Reinforcement <i>broken</i>			\$ 483.30	✓
	Rear Bumper Clip <i>Hec</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>svu</i>	S	49.00	\$ 98.00	×
	Rear Bumper Sponge <i>horn</i>			\$ 137.40	✓
	Rear Bumper Under Cover <i>horn</i>			\$ 185.80	✓
	Rear Bumper Protector (LH/RH) <i>But</i>	S	38.00	\$ 76.00	✓
	Tail Lamp (LH/RH) <i>broken</i>	S	344.00	\$ 688.00	✓
	Tail Lamp Quarter Panel (LH/RH) <i>Dented</i>	S	93.80	\$ 187.60	✓
	Rear Panel <i>bnc</i>			\$ 391.80	✓
	Rear Panel Garnish <i>deformed</i>			\$ 95.80	✓
	Spare Tyre Holder <i>HH</i>			\$ 27.60	×
	Tail Lamp Panel Top (LH/RH) <i>ren</i>	S	217.40	\$ 434.80	×
	Spare Tyre Panel <i>bnc</i>			\$ 863.00	✓
	Spare Tyre Panel Cushion <i>svu</i>			\$ 200.30	×
	Rear Towing Hook <i>HH</i>			\$ 135.30	×
	Member Assy- Rear Floor Centre <i>HH</i>			\$ 163.60	×
	Panel Assy-Rear Floor Side (LH/RH) <i>HH</i>	S	88.55	\$ 177.10	×
	Rear Floor Chassis Member <i>HH Bnc</i>			\$ 1,280.50	✓
	Exhaust Pipe Insulator <i>HH</i>			\$ 56.10	×
	Exhaust Silencer <i>1st</i>			\$ 723.00	✓
	Exhaust Pipe Hanger <i>HH</i>			\$ 56.10	×
	Rear Fender (LH/RH) <i>Bnc</i>	S	1,935.90	\$ 3,871.80	✓
	Rear Fender Inner Lining (LH/RH) <i>svu</i>	S	74.10	\$ 148.20	×
	Rear Fender Corner Hardboard Cover (LH) <i>1st</i>			\$ 204.30	✓
	Rear Fender Air-Duct <i>HH</i>			\$ 49.40	×
	Rear Fender Mudflap (LH) <i>HH</i>			\$ 15.50	×
	Rear Fender Trim Board (LH/RH) <i>deformed</i>	S	180.90	\$ 361.80	✓
	Rear Windscreen Moulding <i>Hec</i>			\$ 60.00	✓
	Rear Door Lock Assy <i>ren</i>			\$ 308.40	×
	Fuel Tank Sub Hose <i>HH</i>			\$ 78.20	×
	Fuel Tank Upper Neck <i>HH</i>			\$ 221.60	×
	Rear Wiring Assy <i>HH</i>			\$ 1,458.00	×
			12586.70		
			10069.36		
	SUB TOTAL			\$ 16,634.30	
	LESS 20%			\$ 3,326.86	
	DISCOUNTED TOTAL			\$ 13,307.44	

SH 6880U

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>hlec</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>hlec</i>			\$ 100.00	Nett ✓
	Rear No. Plate <i>chale</i>			\$ 25.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Don</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>hlec</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>hlec</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>hlec</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>hlec</i>			\$ 56.12	Nett ✓
	Rear Door Advertisement Logo (LH) <i>hlec</i>			\$ 100.00	Nett ✓
	Rear Door Tel No. Sticker (LH) <i>hlec</i>			\$ 10.00	Nett ✓
				\$ 756.82	
	Labour Charge				
	Panel Beating			\$ 2,600.00	1200/-
	Spray Painting Charge			\$ 1,800.00	1000/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Rear Chassis Alignment Charge			\$ 400.00	150/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	40/-
	Remove/Refix Exhaust Pipe			\$ 150.00	60/-
	TOTAL LABOUR			\$ 5,640.00	
	ESTIMATE TOTAL			\$ 33,260.42	
	<i>20/07/2018 @ 1630h</i>			<i>22326.46</i>	
	<i>hvt Arun</i>			<i>7/311,000/-</i>	
	<i>2/5mm</i>			<i>vehicle</i>	
	<i>12 dgs</i>			<i>hvt 11 months</i>	
	<i>T. Ryan</i>				
	<i>LKK Auto</i>				
	LKK Auto Consultants hence notify the Repairer of the following:				
	• To resurvey before/after spray painting				
	• To display damaged part(s) during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairer				
	Signature:				
	Date:				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013265/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9731P	Veh. Inspected	SH 6880U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005552MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	20/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHET41VMBA811739	Colour	BLUE	
Odometer	332215	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	5 mm	
L/H Front Tyre	215/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/07/2018	Inspection Date	20/07/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6880U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT	1,151.80	1,151.80
2	BONNET HINGE (LH/RH) @\$87.50	TO REPAIR SEE LABOUR	175.00	-
1	BONNET MOULDING	SERVICEABLE	120.90	-
1	BONNET LOCK	BENT	48.80	48.80
1	RADIATOR GRILLE	BROKEN	282.10	282.10
1	RADIATOR GRILLE U MOULDING	BROKEN	108.90	108.90
1	FRONT BUMPER COVER	DENTED	538.80	538.80
1	FRONT BUMPER SPONGE	TORN	136.30	136.30
1	FRONT BUMPER REINFORCEMENT	BENT	504.10	504.10
1	FRONT BUMPER CENTRE GRILLE	BROKEN	131.10	131.10
1	FRONT BUMPER LIP	NOT NECESSARY	59.90	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER PROTECTOR (LH/RH) @\$29.20	BENT	58.40	58.40
2	FRONT BUMPER BRACKET (LH/RH) @\$20.10	NOT NECESSARY	40.20	-
1	HEADLAMP SUPPORT PANEL ASSY	DENTED	1,023.00	1,023.00
2	HEADLAMP (LH/RH) @\$797.90	BROKEN	1,595.80	1,595.80
1	RADIATOR	BENT	814.80	814.80
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	CRACKED	651.30	651.30
1	AIRCON CONDENSER	BENT	1,089.90	1,089.90
1	INTER COOLER	BENT	771.50	771.50
1	WIRING-ECM	NOT NECESSARY	3,107.80	-
1	BOOT LID	BUCKLED	1,349.50	1,349.50
1	BOOT LID RUBBER	DEFORMED	110.90	110.90
2	BOOT LID HINGE (LH/RH) @\$170.60	TO REPAIR SEE LABOUR	341.20	-
1	BOOT LID LOCK UPPER	DAMAGED	132.10	132.10
1	BOOT LID LOWER LOWER	DAMAGED	30.30	30.30
1	BOOT LID KEY LOCK	NOT NECESSARY	78.20	-
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20

Report Ref No. CS/FCI18013265/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID "H" EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP (LH/RH) @\$230.20	BROKEN	460.40	460.40
1	BOOT LID TRIMBOARD	TORN	165.40	165.40
11	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	REAR BUMPER	BUCKLED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	BROKEN	483.30	483.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	SERVICEABLE	98.00	-
1	REAR BUMPER SPONGE	TORN	137.40	137.40
1	REAR BUMPER UNDER COVER	TORN	185.80	185.80
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	BENT	76.00	76.00
2	TAIL LAMP (LH/RH) @\$344.00	BROKEN	688.00	688.00
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$93.80	DENTED	187.60	187.60
1	REAR PANEL	BUCKLED	391.80	391.80
1	REAR PANEL GARNISH	DEFORMED	95.80	95.80
1	SPARE TYRE HOLDER	NOT NECESSARY	27.60	-
2	TAIL LAMP PANEL TOP (LH/RH) @\$217.40	TO REPAIR SEE LABOUR	434.80	-
1	SPARE TYRE PANEL	BUCKLED	863.00	863.00
1	SPARE TYRE PANEL CUSHION	SERVICEABLE	200.30	-
1	REAR TOWING HOOK	NOT NECESSARY	135.30	-
1	MEMBER ASSY-REAR FLOOR CENTRE	NOT NECESSARY	163.60	-
2	PANEL ASSY-REAR FLOOR SIDE (LH/RH) @\$88.55	NOT NECESSARY	177.10	-
1	REAR FLOOR CHASSIS MEMBER N/S	BUCKLED	1,280.50	1,280.50
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	56.10	-
1	EXHAUST SILENCER	BENT	723.00	723.00
1	EXHAUST PIPE HANGER	NOT NECESSARY	56.10	-
2	REAR FENDER (LH/RH) @\$1935.90	BUCKLED	3,871.80	3,871.80
2	REAR FENDER INNER LINING (LH/RH) @\$74.10	SERVICEABLE	148.20	-
1	REAR FENDER CORNER HARDBOARD COVER (LH)	BENT	204.30	204.30
1	REAR FENDER AIR-DUCT	NOT NECESSARY	49.40	-
1	REAR FENDER MUDFLAP (LH)	NOT NECESSARY	15.50	-

Report Ref No. CS/FCI18013265/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER TRIM BOARD (LH/RH) @\$180.90	DEFORMED	361.80	361.80
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR LOCK ASSY	TO REPAIR SEE LABOUR	308.40	-
1	FUEL TANK SUB HOSE	NOT NECESSARY	78.20	-
1	FUEL TANK UPPER NECK	NOT NECESSARY	221.60	-
1	REAR WIRING ASSY	NOT NECESSARY	1,458.00	-
	LESS 20% DISCOUNT		-5,817.90	-4,298.66
			23,271.60	17,194.64
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	DISTORTED	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	DAMAGED	30.00	30.00
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	NEW BATTERY (SN)	NOT NECESSARY	207.00	-
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR NO PLATE (SN)	CRACKED	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	56.12	56.12
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR TEL NO STICKER (LH)(SN)	NECESSARY	10.00	10.00
			1,218.82	1,011.82
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET HINGE (LH/RH),BOOT LID HINGE (LH/RH),TAIL LAMP PANEL TOP (LH/RH) AND REAR DOOR LOCK ASSY.		3,800.00	1,900.00
	SPRAY PAINTING CHARGE.		2,800.00	1,600.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		150.00	70.00

Report Ref No. CS/FCI18013265/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE/REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	180.00	-
	REAR CHASSIS ALIGNMENT CHARGE.		400.00	150.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
			8,770.00	4,120.00
GRAND TOTAL			33,260.42	22,326.46

RECOMMENDED COST OF REPAIR SUM				11,000.00
--------------------------------	--	--	--	-----------

Report Ref No. CS/FCI18013265/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.