1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date: 23/7/2018

SKU2447R Reference:

CHEVROLET

CRUZE NB 1.4D

Make:

6AT

To Whom It May Concern

TPA16 Vic.

Dear Sir,

RE: VEHICLE .: SKU2447R

CHASSIS NO.:KL1JA6989EK626352 ENGINE NO.:A14NET143580021

Name of insured .: Alpine Car Rental Pte Ltd

Date of accident.: 17/07/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

| No. | Qty | , Part | Description | Price (SGD) | | |
|-----------|-----|-----------------------------------|-------------|-------------|----------|--|
| 1 | 1 | FRT BUMPER | | \$ | 1,338.00 | |
| 2 | 1 | FRT BUMPER TOW COVER /H | n | \$ | 25.00 | |
| 3 | 1 | FRT BUMPER LOGO | | \$ | 145.00 | |
| 4 | 1 | FRT BUMPER SIDE RETAINER LH | Nu | \$ | 65.00 | |
| <u>5</u> | 1 | FRT BUMPER SIDE RETAINER RH | of men | \$ | 65.00 | |
| <u>6</u> | 1 | LH HEADLAMP CX | | \$ | 1,041.00 | |
| 7 | 1 | FRT FOG LAMP LH | N | \$ | 315.00 | |
| 8 | 1 | FRT FOG LAMP COVER LH 4 | M | \$ | 105.00 | |
| 9 | 1 | FRT FENDER LH Distonted | | \$ | 991.00 | |
| <u>10</u> | 1 | FRT FENDER INNERSHIELD LH | Nen | \$ | 120.00 | |
| <u>11</u> | 1 | FRT FENDER BRACKET LH | Best | \$ | 65.00 | |
| <u>12</u> | 1 | FRT HORN LH | 7 | \$ | 103.00 | |
| 13 | 1 | WIPER WASHER TANK with Motor/Pump | I NE | \$ | 191.00 * | |
| 14 | | WIPER WASHER TANK NECK | ਨ | \$ | 35.00 → | |

3645

Parts Total: \$

4,604.00

3280-50

Less10%: \$

460.40

Total: \$

4,143.60

Labour

Labour Description

No.

Price (SGD)

Front portion

| 1 | To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts. (\$550 per day) | \$ 2,200.00 | 1100. |
|---|--|----------------|-------|
| 2 | Carry out spray painting on accident affected area (\$450 per panel) | \$ 1,800.00 | 900 |
| 3 | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair | \$ 30.00 | / |
| 4 | To refocus headlamp | \$ 80.00 | 4. |

2030

Labour Total: \$ 4,110.00

Others

Other Description

| No. | Qty | | | | Price (SGD) | | | |
|-----|-----|-------------------------|------|----|--------------|----|-------------------|----|
| | | Front portion | | | | | | |
| 1 | 10 | Front bumper clip | avec | | | \$ | 6 5.00 | 30 |
| 2 | 3 | Front fender liner clip | Nen | | | \$ | 19.50 | x |
| | | | | 30 | Other Total: | \$ | 84.50 | , |
| / | | | | | | | | |

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Suhaimi Ong

Service Executive Suhaimi Ong

HP: 8298 8933 Fax:6844 5185

Adrian Lung totu: 534050 2/1 20/07/18- 45: 4250

GRAND TOTAL: \$

8,338.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: