



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 6855K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	CUT	1,480.00	1,480.00
10	REAR BUMPER CLIPS @\$8.95 (CONSISTENT)	NECESSARY	89.50	89.50
1	REAR BUMPER SIDE HOLDER (RH) (CONSISTENT)	SERVICEABLE	180.00	-
1	REAR FENDER (RH) (CONSISTENT)	TO REPAIR SEE LABOUR	6,650.00	-
1	RH REAR FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	520.00	-
1	REAR TAILLAMP (RH) (CONSISTENT)	NOT NECESSARY	390.00	-
	LESS 10% DISCOUNT		-	-156.95
			9,309.50	1,412.55
	<u>LABOUR</u>			
	LABOUR TO REPLACE ABOVE PARTS ,PANEL BEAT ,REPAIR & RE-ALIGN DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER (RH) .		700.00	400.00
	TO SPRAY PAINT REAR BUMPER & RH REAR FENDER.		600.00	400.00
			1,300.00	800.00
GRAND TOTAL			10,609.50	2,212.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CC4/ASM18013331/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.