

(08/11/13) wef

ASS. REC. BY:

REF: AXA

ASSIGNMENT

From:

Date:

24/07/18

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SJO 39G

at Workshop m/s

SK Automobile

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJO 39G

Yr Regn:

2016, July

Type: ☒ M.Car☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

c.c

2356

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

42543

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMR18906C204290

Gen. Cond:

☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering:

☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake:

☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi:

Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

215/35R17

R:

215/35R17

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

24/07/18

Survey held at

S.K.

Des. of Damages:

Frt / ☒ Rear /☐ O/S /☐ N/S /☐ U/C /

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA.

MV: 118K

PV: 73K.

Net: 45K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)